Architects & Engineers

APURBA BORAH

A STATE OF THE STA		Architect	's Certificate [°]		
Report for quarter ending 31 March 2020					
Subjec	ct		Certificate of progress of construction work		
L/We have undertaken assignment as architect below mentioned project as per the approved project.			ect for certifying progress of construction work in the ed plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	Project Area 11302.54 sq mtr , Commercial Cum Residential Colony		
	2.	Location	Village Bhatola, Sector-79, Faridabad		
161	3.	Licensed area in acres	2.09 acres & 8.571 acres		
	4.	Area for registration in acres	2.97 acres		
	5.	HARERA registration no.	124 of 2017		
	6.	Name of licensee	Robust Buildwell Private Limited		
	7.	Name of collaborator			
	8.	Name of developer	Robust Buildwell Private Limited		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection			
	2.	Name of Architect/ Architect's firm	Bee Bee Architects		
	3.	Date of site inspection			

APURBA BORAH Reg. Architect CA/2013/61618

() whom

Architects & Engineers

APURBA BORAH

3.	Follow	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name			
	1.	Site engineer	Mr. D.C Pant			
	2.	Structural consultant	Mr. Pankaj Varshney			
	3.	Proof consultant				
	4.	MEP consultant	Mr, Dharmendra Singh			
	5.	Site incharge	Mr. D.C Pant			
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard a envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.					
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tow of the real estate project/phase of the project under HARERA is as per table A and table B given here below. The percentage of the work executed with respect to each of the activity of the entire project phase is detailed in table A and table B.					

Date

Yours faithfully,

Place: New Delhi

Signature & name (in block letters) with stamp of architect

Council of Architects (CoA) Registration No

: CA/2013/61618

Council of Architects (CoA) Registration valid till (date) :

APURBA BORAH Reg. Architect CA/2013/61618

C) of the way

Architects & Engineers

APURBA BORAH

-					
	a	h	P	-	4

Building/ Tower no.

(to be prepared separately for each building/tower in the project/phase of the project)

Al Cumulative progress of the project/phase at the end of the quarter.

Sr. No.	Proje	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	(inclu	structure nsive of excavation, foundation, nents, water proofing, etc.)	-	11.73 CR	100%
2.	(slabs	r structure s, brick work, block work, stair case, ells, machine rooms, water tank, etc.)	•	22.78 CR	100%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			,
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finis	hing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	60 LACS	2.00 CR	25.26%
	4.2	External (plaster, painting, facade, etc.)	30 LACS	1.27 CR	19.2%

APURBA BORAH Reg. Architect CA/2013/61618

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assan 781006

Architects & Engineers

APURBA BORAH

Sr. No.	-	Tasks/ Activity	The second secon	n of work ne		ge of total
210.		Sub-Structure Status			proposed work	
1	Exca	vation	Completed		10	0%
2.	Layir	ng of foundation	s		*	
	(i)	Raft	Comp	oleted	10	0%
	(ii)	Pile		*		
3.	Num	ber of basement(s)				
	(i)	Basement Level 1	Comp	oleted	10	0%
	(ii)	Basement level 2*	Comp	oleted	10	0%
4.		rproofing of the above sub-structure rever applicable)	M.	IP	89	9%
		Super-Structure Status				
5.	Total	floors in the tower/building	4	8		
6.	Total	area on each floor	18816	SFT		
7.	Stilt	floor/ ground floor	31243	SFT		
8.	Statu	s of laying of slabs floor wise	4	8		
		ulative number of slabs in the building				
9.	Statu	s of construction				
	(i)	Walls on floors	WIP		8%	
	(ii)	Staircase	WIP		5	%
	(iii)	Lift wells along with water proofing	WIP		61	8 1/0
	(iv)	Lift lobbies/ common areas floor wise	WIP		6%	
10.	Fixin units	g of door and window frames in flats/	W	WIP		%
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	W	P		
	(ii)	Electrical works including wiring	W	WIP		
	(iii)	Plumbing works	W	IP		
12.	Statu	s of wall plastering				
	(i)	External plaster	Completed			
	(ii)	Internal plaster	Completed			
13.	Statu	s of wall tiling				
	(i)	In bathroom	Balance			
	(ii)	In kitchen	Balance			
14	Statu	s of flooring			APUF	RBA BORA
	(i)	Common areas	Balance		Reg	1. Architect
	(ii)	Units/ flats	Bala	ınce	GA/2	2013/61618

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

Architects & Engineers

APURBA BORAH

Sr.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total	
No.			done	proposed work	
15.	Status	s of white washing			
	(i)	Internal walls			
	(ii)	External walls		<u>, </u>	
16.	Status	of finishing			
	(i)	Staircase with railing	•		
	(ii)	Lift wells	-		
	(iii)	Lift lobbies/ common areas floor wise	*		
17.	Status	s of installation			
	(withi	in flat/unit)			
	(i)	Doors and windows panels	-		
	(ii)	Sanitary fixtures	•		
	(iii)	Modular kitchen	*		
	(iv)	Electrical fittings/ lighting	•		
	(v)	Gas piping (if any)	•		
	(other	than flat/units)		-	
	(vi)	Lifts installation	•		
	(vii)	Overhead tanks	-		
	(viii)	Underground water tank	Completed	100%	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	•		
	(x)	Electrical fittings in common areas	-		
	(xi)	Compliance to conditions of environment/ CRZ NOC	-		
18.	Water	rproofing of terraces	_		
19.	Entra	nce lobby finishing	WIP		
20.	Status	s of construction of compound wall	±		

Note: (*) extend rows as per requirement.

APURBA BORAH Reg. Architect CA/2013/61618

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

Architects & Engineers

APIIDRA RODAH

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of remarks work done
B-1	Services		
1.	Internal roads & pavements	YES	9%
2.	Parking		
	Covered no	YES	0%
	Open no	YES	0%
3.	Water supply	YES	0%
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	0%
5.	Storm water drains	YES	0%
6.	Landscaping & tree plantation	YES	0%
7.	Parks and playgrounds	YES	0%
	Fixing of children play equipment's	YES	0%
	Benches	YES	0%
8.	Shopping area	YES	0%
9.	Street lighting/ electrification	YES	0%
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%
11.	Solid waste management & disposal	-	
12.	Water conservation, rain water, harvesting, percolating well/pit	•	
13.	Energy management (solar)	-	
14.	Fire protection and fire safety requirements	YES	0%
15.	Electrical meter room, sub-station, receiving station	YES	0%
16.	Other (option to add more)	YES	0%
B-2	Community building to be transferred to RWA		
17.	Community centre	YES	0%
18.	others	YES	0%
B-3	Community buildings not to be transferred to RWA/competent authority		1
19.	Schools	-	
20.	Dispensary	*	
21.	Club	-	· ·
22.	Others	-	
B-4	Services/ facilities to be transferred to competent authority		
23.	*		1 ma

Note: (*) extend as per requirement

APURBA BORAH Reg. Architect CA/2013/61618