BEE BEE ARCHITECTS

Architects & Engineers

APURBA BORAH

Annexure A

		Architect'	's Certificate*			
Report	for quar	ter ending	30 JUNE 2020			
Subjec	Subject		Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Project Area 28384.54 sq mtr , Commercial Cum Residential Colony, SCO Phase 1			
	2.	Location	Village Bhatola, Sector-79, Faridabad			
	3.	Licensed area in acres	2.09 acres & 8.571 acres			
	4.	Area for registration in acres	7.01 acres			
	5.	HARERA registration no.	129 of 2017			
	6.	Name of licensee	Robust Buildwell Private Limited			
	7.	Name of collaborator				
	8.	Name of developer	Robust Buildwell Private Limited			
2.	Details	related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	15.07.2020			
	2.	Name of Architect/ Architect's firm	BEE BEE Architects			
	3.	Date of site inspection	15.07.200			



Architects & Engineers

APURBA BORAH

3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name		
	1.	Site engineer	Mr. D.C Pant		
	2.	Structural consultant	Mr. Pankaj Varshney		
	3.	Proof consultant			
	4.	MEP consultant	Mr, Dharmendra Singh		
	5.	Site incharge	Mr. D.C Pant		
4.	Haryar constru envisas	a Building Code, 2017/ National Building infrastructure works and interest in the state of the s	as per approved drawings, statutory/ mandatory approvals, ilding Code (wherever applicable) and the material used in the rnal development works are as per the projected standard as publication material and other documents shared with the		
5.	of the below.	real estate project/phase of the project	age of work done in the project for each of the building/ tower ct under HARERA is as per table A and table B given herein ted with respect to each of the activity of the entire project/		

Date

Yours faithfully,

Signature & name (in block letters) with stamp of architect

APURBA BORALL

Place

Council of architects (CoA) registration no. : CA/2013/61618 Council of architects (CoA) registration valid till (date)

Apurba Borah Regd. Architect Regd. 13161518

BEE BEE ARCHITECTS

Architects & Engineers

APURBA BORAH

			Table – A		
(to be	prepare	wer no. ed separately for each building/ tower / phase of the project)			
A1	Cumi	ulative progress of the project/phase a	nt the end of the qua	rter.	
Sr. No.	Project components Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.			-	15 CR	
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		.4 CR	30.00	95.5%
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			
4.	Finis	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	40 LACS	15.4 CR	94.8%
	4.2	External (plaster, painting, facade, etc.)	20 LACS	8.2 CR	95.34%



Architects & Engineers

APURBA BORAH

Sr.	Tasks/ Activity		Description of work		Percentage of total	
No.		Sub-Structure Status	done		proposed work	
1.	Excav	vation	Completed		100%	
2.	Layin	g of foundation				
	(i)	Raft	Completed		100%	
	(ii)	Pile	N/A			
3.	Number of basement(s) 1					0
	(i) Basement Level 1		Completed		100%	
	(ii)	Basement level 2*	N/A			
4.		proofing of the above sub-structure ever applicable)	Completed		100%	×
		Super-Structure Status				
5.	Total	floors in the tower/ building	3			
6.	Total	area on each floor	113550 SFT			
7.	Stilt f	loor/ ground floor	113550 SFT	- 2		
8.	Status	s of laying of slabs floor wise	Completed		100%	
		lative number of slabs in the building/ laid by end of quarter				
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	-			
	(iv)	Lift lobbies/ common areas floor wise	-			3
10.	Fixing	g of door and window frames in flats/	Completed		100%	
11.	Status	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	-			
	(ii)	Electrical works including wiring	-			
	(iii)	Plumbing works	- ,	- 3	2 4	
12.	Status	s of wall plastering				
	(i)	External plaster	Completed		100%	
	(ii)	Internal plaster	Completed		100%	
13.	Status	s of wall tiling	ψ.	8		
	(i)	In bathroom	-			
	(ii)	In kitchen	-	2		
14.	Status	s of flooring				
	(i)	Common areas	WIP		1000	ne
	(ii)	Units/ flats	-		1 be	YE G

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

BEE BEE ARCHITECTS

Architects & Engineers

APURBA BORAH

Sr.	Tasks/ Activity Sub-Structure Status		Description of work done	Percentage of total proposed work	
No.			done	proposed work	
15.	Status of white washing				
	(i)	Iliteriiai walis	Completed	100%	
	(ii)	External walls	Completed	100%	
16.	Status of finishing				
	(i)	Staircase with railing	Completed	100%	
	(ii)	Lift wells	N/A		
	(iii)	Lift lobbies/ common areas floor wise	N/A		
17.	Status	of installation			
	(within	n flat/unit)	2		
	(i)	Doors and windows panels	Completed	100%	
	(ii)	Sanitary fixtures	N/A		
	(iii)	Modular kitchen	N/A		
	(iv)	Electrical fittings/ lighting	N/A		
	(v)	Gas piping (if any)	N/A		
	(other	than flat/units)			
	(vi)	Lifts installation	N/A		
	(vii)	Overhead tanks	N/A		
	(viii)	Underground water tank	N/A		
	(ix)	Firefighting fitting and equipment's as per CFO NOC	N/A		
	(x)	Electrical fittings in common areas	N/A	*	
	(xi)	Compliance to conditions of environment/ CRZ NOC	N/A		
18.	Water	proofing of terraces	Completed	100%	
19.	Entra	nce lobby finishing	N/A		
20.	Status	s of construction of compound wall	-		

Note: (*) extend rows as per requirement.



Architects & Engineers

APURBA BORAH

Table - B

r. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services		-	
1.	Internal roads & pavements	YES	96%	
2.	Parking			
	Covered no	YES	96%	
	Open no	YES	96%	
3.	Water supply	YES	96%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	96%	
5.	Storm water drains	YES	96%	
6.	Landscaping & tree plantation	YES	96%	
7.	Parks and playgrounds	N/A		
	Fixing of children play equipment's	N/A		
	Benches	N/A	7	
8.	Shopping area	YES	96%	
9.	Street lighting/ electrification	YES	96%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	96%	
11.	Solid waste management & disposal	N/A		
12.	Water conservation, rain water, harvesting, percolating well/ pit	N/A		
13.	Energy management (solar)	N/A		
14.	Fire protection and fire safety requirements	N/A		
15.	Electrical meter room, sub-station, receiving station	N/A	4. 4.	
16.	Other (option to add more)	N/A		
B-2	Community building to be transferred to RWA			
17.	Community centre	N/A		
18.	others	N/A		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	N/A		
20.	Dispensary	N/A		
21.	Club	N/A		
22.	Others	N/A		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

