Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

*	Architect's Certificate ¹				
Repo	Report for quarter ended Subject		31st December 2023		
Subje			Certificate of progress of construction work		
1 .			nt as architect for certifying progress of ntioned project as per the approved plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	Elevate Phase – I		
	2.	Location	Village Behrampur, Sector-59, Gurugram		
	3.	Licensed area in acres	8.91875		
	4.	Area for registration in acres	5.95		
	5.	HARERA registration no.	19 of 2019		
	6.	Name of licensee	License no. 16 of 2008 : 1) BTVS Buildwell Pvt. Ltd.		
		1	ciates chih Alam Architect		



Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Page **1** of **25**

		1	
			2) Adson Software Pvt. Ltd. 3) Bulls Realtors Pvt. Ltd. 4) Commander Realtors Pvt. Ltd. 5) Fiverivers Developers Pvt. Ltd. 6) Fiverivers Townships Pvt. Ltd. 7) Ornamental Realtors Pvt. Ltd. 8) Aspirant Builders Pvt. Ltd. License no. 28 of 2008: 1) BTVS Buildwell Pvt. Ltd. 2) Golden View Builders Pvt. Ltd. 3) Hi Energy Realtors Pvt. Ltd. 4) Base Exports Pvt. Ltd. 5) Adson Software Pvt. Ltd. 6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. License no. 44 of 2011: 1) Commander Realtors Pvt. Ltd. 2) BTVS Buildwell Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd. 7) Bulls Realtors Pvt. Ltd.
	7.	Name of collaborator	Heritage Max Realtech Pvt. Ltd.
		ivalife of collabol ator	Heritage Max Reditecti FVt. Ltu.
	8.	Name of developer	Heritage Max Realtech Pvt. Ltd.
2.	Detail	s related to inspection are as	under
	1.	Date of certifying of percentage of construction work/ site inspection	31st December 2023
	l	L	1 Office of the second

2.	Name of Architect/ Architect's firm	Arcop associates Private Limited
3.	Date of site inspection	31st December 2023

3.	Follov	Following technical professionals are appointed by promoter: - (as applicable)		
-	Sr. No.	Consultants	Name	
	1.	Site engineer	Vijayant Singh	
	2.	Structural consultant	Vintech Consultant (Mr. Vinod Jain)	
	3.	Proof consultant	Mehro Consultants	
	4.	MEP consultant	Sanelac Consultants Pvt Ltd	
	5.	Site supervisor/incharge	Avinash Nagpal	
4.	I certify that the work has been executed as per approved drawings, statutory mandatory approvals, Haryana Building Code, 2017/National Building Code (whereve applicable) and the material used in the construction, infrastructure works and internatevelopment works are as per the projected standard as envisaged in the registratio and brochure, publication material and other documents shared with the buyers in this regard.		ng Code, 2017/ National Building Code (wherever e construction, infrastructure works and internal ojected standard as envisaged in the registration	
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with			

respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date : Yours faithfully,

Place :

Signature & name (in block letters) with stamp of architect

Council of architects (CoA):

registration no.

Labib Alam, Architect

Council of Architecture

Registration No.: CA/2001/27447

Council of architects (CoA) : 31-12-2027 registration valid till (date)

Page **4** of **25**

		•	Гable – А		
(to build	be p	Tower no. repared separately for each tower in the project/ phase of t)	Tower-A		
A1	Cun	nulative progress of the projec	t/phase at the er	nd of the quarter	r.
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	(incl	structure usive of excavation, dation, basements, water ofing, etc.)	0	35.00	100%
2.	(slat	er structure os, brick work, block work, case, lift wells, machine rooms, er tank, etc.)	0	56.00	100%
3.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	0.01	15.52	100 %
*	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.9	7.71	97 %

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.01	8.65	95%
4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2	12.84	98%
	4.2	External (plaster, painting, facade, etc.)	2.18	9.10	95%

Sr. No.		Tasks/ Activity	Description of work done	Percentage of total proposed work
		Sub-Structure Status		
1.	Exca	vation	Complete	100 %
2.	Layi	ng of foundation		
	(i)	Raft	Complete	100 %
	(ii)	Pile	NA	NA
3.	Num	ber of basement(s)		
	(i)	Basement Level 1	Structure under Tower Footprint Complete	100%
	(ii)	Basement level 2*	Structure under Tower Footprint Complete	100%
4.	1	erproofing of the above sub- cture (wherever applicable)	Above deck waterproofing	100%

		Super-Structure Status		
5.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 31 Apt Floors	100%
6.	Tota	l area on each floor	785 Sqm	100%
7.	Stilt	floor/ ground floor	Structure Tower Entrance	100%
8.	Statu	is of laying of slabs floor wise	Upto terrace Level Completed	100%
	Cumulative number of slabs in the		Total Slabs	100%
	building/ tower laid by end of quarter		1Stilt+1Service Floor+31 Apt Floor	
9.	Status of construction			8
•	(i)	Blockwork	100% Completed	100%
	(ii)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(iii)	Lift Well including Machine room	100% Completed	100%
-	(iv)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
10.		g of door and window frames in units		
11.	Statu	s of MEP	Internal (within flat)	External works
	(i)	NA	NA	0
	(ii)	Apartment Electrical Wiring	100% Completed	100%
	(iii)	UPVC/ RWP Piping	100% Completed	100%
12.	Statu	s of wall plastering		.0.

	(i)	RCC External Wall	NA	0
	(ii)	Gypsum Plaster	100% (31 of 31 Floor completed)	100%
13.	Statı	us of wall tiling		
i	(i)	Bathroom Tiles	100% Completed	
	(ii)	Kitchen Wall Tile	100% Completed	
14.	Statı	us of flooring		
	(i)	Lift Lobby Flooring	100% Completed	2
	(ii)	Apt Stone Flooring	100% Completed	
15.	Statı	us of white washing		
	(i)	Apartment Prefinal Paint	80% Completed	
	(ii)	Putty+1stCoat+2nd Coat	91% Completed	
16.	Statu	us of finishing		
	(i)	MS Railing		100% Completed in staircase
	(ii)	Lift Well HO for Lift Installation	100% Completed	
	(iii)	Lobby Wall Tiling	100% Completed	
17.	Statu	s of installation		
	(with	nin flat/unit)		
	(i)	UPVC Windows	100% Completed	
	(ii)	Bathroom Chinaware	7% Completed	
	(iii)	Modular Kitchen Cabinet Installation (Without Panels)	50% Completed	0
	•			ONE

	(iv)	Switch & Sockets	70% Completed	
	(v)	NA	NA	0
	(othe	er than flat/units)		
	(vi)	Guide Rail+ Floor Door+ Car Installation	100%	
	(vii)	RCC Work	100% Completed	0
	(viii)	RCC Work	100% Completed	0
	(ix)	Fire Pump Installation	100% Completed	0
	(x)	Staircase & Lobby Wiring	100% Completed	0
	(xi)	Six Monthly Compliance	100% Compliance	0
18.	Wate	rproofing of terraces	PU Waterproofing	100% Completed
19.	Entra	nce lobby finishing	Gypsum False ceiling	100% Completed
20.	Statu wall	s of construction of compound	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower-A

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks
B-1	Services .	1		
1.	Internal roads & pavements	Yes	80%	
2.	Parking	Yes		
	Covered no	Yes	100%	
	Open no	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	80%	
7.	Parks and playgrounds	Yes	80%	
	Fixing of children play equipment's	Yes	50%	
	Benches	Yes	80%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	80%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	90%	

16.	Other (option to add more)	NA		
B-2	Community building to be transferred	to RWA		
17.	Community centre	Yes	80%	
18.	others	NA		
В-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	Yes	100%	
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	NA		
23.	*			

Note: (*) extend as per requirement

	Table - A						
(to buil	be p	Tower no. repared separately for each tower in the project/ phase of t)					
A1	Cumulative progress of the project/phase at the end of the quarter.						
Sr. No.	Pro	ject components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
5.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0	35.00	100%		
6.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0	60.05	100%		
7.	МЕР)					
	3.1	Mechanical (lifts, ventilation, etc.)	0.01	13.50	100%		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.01	7.66	97%		

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.01	8.51	95%
8.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2	12.95	98%
	4.2	External (plaster, painting, facade, etc.)	1.96	8.86	95%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status			
21.	Exca	vation	Complete	100 %	
22.	Laying of foundation				
	(iii)	Complete	100 %	100 %	
	(iv)	NA	NA	0	
23.	Number of basement(s)				
	(iii)	Structure under Tower Footprint Complete	Complete	100%	
	(iv)	Structure under Tower Footprint Complete	Complete	100%	
24.	1	erproofing of the above sub- ture (wherever applicable)	Deck Water Proofing	100%	
	Super-Structure Status		· .	1 110	

25.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 33 Apt Floors	100%
26.	Total area on each floor		772 Sqm	100%
27.	Stilt	floor/ ground floor	Structure Tower Entrance	100% Completed
28.	Statı	us of laying of slabs floor wise	Upto terrace Level Completed	100%
	Cumulative number of slabs in the building/ tower laid by end of quarter		Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
29.	Statu	s of construction		
	(v)	Blockwork	Completed	100%
*	(vi)	Staircase Concreting upto Terrace Slab		100%
	(vii)	Lift Well including Machine room		100%
	(viii)	Structure lift lobbies and other common area upto 31 Floor		100%
30.	1	g of door and window frames in units	Door Frame	100% Completed
31.	Statu	s of MEP	Internal (within flat)	External works
	(iv)	NA	NA	
	(v)	Apartment Electrical Wiring	88% Completed	88% Completed
	(vi)	UPVC/ RWP Piping	100% Completed	
32.	Statu	s of wall plastering		
	(iii)	RCC External Wall	NA	
			V VV	J

	(iv)	Gypsum Plaster	100%	
33.	Statı	us of wall tiling		
	(iii)	Bathroom Tiles	100% Completed	-
	(iv)	Kitchen Wall Tile	100% Completed	
34.	Statu	is of flooring		•
	(iii)	Lift Lobby Flooring	100% Completed	
	(iv)	Apt Stone Flooring	100% Completed	
35.	Statu	s of white washing		
2	(iii)	Apartment Prefinal Paint	70% Completed	
	(iv)	Putty+1stCoat+2nd Coat	90% Completed	
36.	Statu	s of finishing		
	(iv)	MS Railing	100% Completed	
	(v)	Lift Well HO for Lift Installation	100% Completed	
	(vi)	Lobby Wall Tiling	100% Completed	
37.	Statu	s of installation		(a)
	(with	in flat/unit)		
	(xii)	UPVC Windows	95% Completed	
	(xiii)	Bathroom Chinaware	6% Completed	
	(xiv)	Modular Kitchen Cabinet Installation (Without Panels)	50% Completed	
	(xv)	Switch & Sockets	70% Completed	
	(xvi)	NA	NA	
	(othe	r than flat/units)		

	(xvii) Guide Rail+ Installation	Floor Door+	Car	100 % Complete	
	(xviii RCC Work (xix) RCC Work		100% Completed		
			100% Completed		
	(xx) Fire Pump Ins	tallation		100% Completed	
	(xxi) Staircase & Lo	obby Wiring		100% Completed	
	(xxii) Six Monthly C	ompliance		100% Compliance	
38.	Waterproofing of to	erraces		PU Waterproofing	100% Completed
39.	Entrance lobby fini	shing		Gypsum False ceiling	100% Completed
40.	Status of construction of compound wall		ınd	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services	F3	1	
24.	Internal roads & pavements	Yes	80%	
25.	Parking	Yes		
	Covered no	Yes	100%	
	Open no	Yes	100%	
26.	Water supply	Yes	100%	
27.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
28.	Storm water drains	Yes	100%	
29.	Landscaping & tree plantation	Yes	80%	
30.	Parks and playgrounds	Yes	80%	
	Fixing of children play equipment's	Yes	50%	
	Benches	Yes	80%	
31.	Shopping area	Yes	0%	_
32.	Street lighting/ electrification	Yes.	80%	
33.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	30000 000 8
34.	Solid waste management & disposal	Yes	100%	
35.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
36.	Energy management (solar)	Yes	100%	
37.	Fire protection and fire safety requirements	Yes	100%	
38.	Electrical meter room, sub-station, receiving station	Yes	90%	

39.	Other (option to add more)	NA		
B-2	Community building to be transferred	to RWA	<u> </u>	
40.	Community centre	Yes	80%	
41.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
42.	Schools	NA		
43.	Dispensary	NA		
44.	Club	Yes	100%	
45.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	NA		
46.	*			

Note: (*) extend as per requirement

		ר	Γable - A		
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower-C			
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Pro	ject components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
9.	(incl	structure lusive of excavation, idation, basements, water ofing, etc.)	0	24.96	100%
10.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0	40.02	100%
11.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)	0.02	8.79	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.02	6.33	95%

3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.02	6.96	95%
Fini	shing			
4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.2	10.78	100%
4.2	External (plaster, painting, facade, etc.)	0.02	4.43	95%
	Fini : 4.1	(piping, pumps and pump room, fixtures, etc.) Finishing 4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas) 4.2 External (plaster, painting, facade,	(piping, pumps and pump room, fixtures, etc.) Finishing 4.1 Internal 0.2 (plaster, tilling, flooring, painting, etc. within units and common areas) 4.2 External 0.02 (plaster, painting, facade,	(piping, pumps and pump room, fixtures, etc.) Finishing 4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas) 4.2 External (plaster, painting, facade, painting, facade,

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	:	Sub-Structure Status		
41.	Excavation		Complete	100 %
42.	Laying of foundation			
61	(v)	Complete		100%
	(vi)	NA	NA	0
43.	Num	ber of basement(s)		
	(v)	Structure under Tower Footprint Complete		100%
	(vi)	Structure under Tower Footprint Complete		100%
44.	Waterproofing of the above substructure (wherever applicable)		Deck Water Proofing	100%
		Super-Structure Status		en

45.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 30 Apt Floors	100%
46.	Total area on each floor		549 Sqm	100%
47.	Stilt	floor/ ground floor	Structure Tower Entrance	100% Completed
48.	Status of laying of slabs floor wise Cumulative number of slabs in the building/ tower laid by end of quarter		Upto terrace Level Completed	100%
			Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
49.	Statu	s of construction		-
	(ix)	Blockwork	100% Completed	
	(x)	Staircase Concreting upto Terrace Slab	100% Completed	
	(xi)	Lift Well including Machine room	100% Completed	
	(xii)	Structure lift lobbies and other common area upto 30 Floor	100% Completed	
50.	1	g of door and window frames in units	Door Frame	100% Completed
51.	Statu	s of MEP	Internal (within flat)	External works
	(vii)	NA	NA	
	(viii)	Apartment Electrical Wiring	100% Completed	100% Completed
	(ix)	UPVC/ RWP Piping	100% Completed	
52.	Statu	s of wall plastering		,
	(v)	RCC External Wall	NA	

abib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447
Page 21 of 25

	(vi)	Gypsum Plaster	100%	
53.	Status of wall tiling			
	(v)	Bathroom Tiles	100% Completed	
	(vi)	Kitchen Wall Tile	95% Completed	
54.	Statu	as of flooring		
	(v)	Lift Lobby Flooring	100% Completed	
	(vi)	Apt Stone Flooring	100% Completed	
55.	Statu	is of white washing		
	(v)	Apartment Prefinal Paint	100% Completed	
	(vi)	Putty+1stCoat+2nd Coat	100% Completed	
56.	Status of finishing			
	(vii)	MS Railing	100% Completed	
	(viii)	Lift Well HO for Lift Installation	100% Completed	
	(ix)	Lobby Wall Tiling	100% Completed	
57.	Statu	s of installation		
	(with	in flat/unit)		
	(xxiii	UPVC Windows	100% Completed	
	(xxiv	Bathroom Chinaware	17%	
	(xxv)	Modular Kitchen Cabinet Installation (Without Panels)	50%	
	(xxvi	Switch & Sockets	80% Completed	
	(xxvi	NA	NA	N WA
	(othe	r than flat/units)		Labib Alam, Architect

Registration No.: CA/2001/27447

	(xxvi Guide Rail+ Floor Door+ Ca Installation	100% Complete	
	(xxix RCC Work	100% Completed	
	(xxx) RCC Work	100% Completed	
	(xxxi Fire Pump Installation	100% Completed	
	(xxxi Staircase & Lobby Wiring	100% Completed	
	(xxxi Six Monthly Compliance	100% Compliance	
58.	Waterproofing of terraces	PU Waterproofing	100% Completed
59.	Entrance lobby finishing	Gypsum False ceiling	100% Completed
60.	Status of construction of compound wall	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower C

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services	1		
47.	Internal roads & pavements	Yes	80%	
48.	Parking	Yes	8	
	Covered no	Yes	100%	
	Open no	Yes	100%	
49.	Water supply	Yes	100%	
50.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
51.	Storm water drains	Yes	100%	
52.	Landscaping & tree plantation	Yes	80%	
53.	Parks and playgrounds	Yes	80%	
	Fixing of children play equipment's	Yes	50%	1
	Benches	Yes	80%	
54.	Shopping area	Yes	0%	
55.	Street lighting/ electrification	Yes	80%	
56.	Treatment and disposal of sewage and sullage water/STP	Yes	100%	
57.	Solid waste management & disposal	Yes	100%	
58.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
59.	Energy management (solar)	Yes	100%	
60.	Fire protection and fire safety requirements	Yes	100%	
61.	Electrical meter room, sub-station, receiving station	Yes	90%	<u> </u>

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Page **24** of **25**

62.	Other (option to add more)	NA			
B-2	Community building to be transferred to RWA				
63.	Community centre	Yes	80%		
64.	others	NA			
B-3	Community buildings not to be transferred to RWA/competent authority				
65.	Schools	NA			
66.	Dispensary	NA			
67.	Club	Yes	100%		
68.	Others	NA	á á		
B-4	Services/ facilities to be transferred to competent authority	NA			
69.	*				

Note: (*) extend as per requirement