

Renor	t for ans	rter ending	Dec 2023				
Subje			Certificate of progress of construction work				
1.	I/We ł	nave undertaken assignment as archit mentioned project as per the approve	ect for certifying progress of construction work in the				
	Sr. Particulars No.		Information				
	1.	1. Project/Phase of the project South Avenue					
	2.	Location	Sector 92, Gurgaon				
	3.	Licensed area in acres	2.45625 Acres				
	4.	Area for registration in acres	2.45625 Acres				
	5.	HARERA registration No.	23 of 2020				
			GLS Infraprojects Pvt Ltd				
	8.	Name of developer	GLS Infraprojects Pvt Ltd				
2.	Details related to inspection are as under						
	1.	Date of certifying of percentage of construction work/ site inspection	04/01/2024				
	2.	Name of Architect/ Architect"s firm	Design Forum International				
	3.	Date of site inspection	04/01/2024				
3.	Follow	ing technical professionals are appoin	nted by promoter: - (as applicable)				
	Sr. No.	Consultants	Name				
	1.	Site engineer	Mr. Rakesh Kumar				
	2.	Structural consultant	Keen Associates Pvt Ltd, New Delhi				
	3.	Proof consultant	BMSF Design Consultants Pvt Ltd, Gurugram				
2	4.	MEP consultant	Innovative Consulting Engineers, New Delhi				
	5.	Site supervisor/incharge	Mr Rakesh Kumar ANOJ TEVA B. Arch (H CA/95/18				



• ARCHITECTURE • URBAN DESIGN • TOWN PLANNING •

construction, infrastructure works and internal development works are as per the projected servisaged in the registration and brochure, publication material and other documents share buyers in this regard.	
n	visaged in the registration and brochure, publication material and other documents share

I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and table B.

Yours faithfully,
ANOJ TEVATIA
B. Arch (Hons)

Signature & hame (in block letters) with

stamp of architect

Date

5.

: 04/01/2024

Place

: DELHI

Council of architects (CoA)

registration No.

: CA/95/18739

Council of architects (CoA) registration valid till (date)

Table –A

Building/ Tower No. - Tower K, L,M, N

(to be prepared separately for each building/ tower in the project/ phase of the project)

A 1	Cumulative Progress of the project/phase at the end of the quarter.						
S. No.	Pro	jects Components	Work done Value during the Quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1	(Inc	Structure clusive of excavation, Foundation, ements, Water proofing etc.)	0	10	10		
2.	(slal	ber Structure bs, brick work, block work, stair e, lift wells, machine rooms, water as etc.)	0	50	50		
3.	ME	P					
	3.1	Mechanical (Lifts Ventilation etc.)	0	0	0		
	3.2	Electrical (conducting wiring, fixtures)	0	3	3		
	3.3	Plumbing & firefighting (piping, pumps and pump room, fixtures etc.)	0	10	10		
4	Fini	shing					
	4.1	Internal (Plaster, tilling, flooring, painting etc. within units and common areas)	0	3	3		
	4.2	External (Plaster Painting façade etc.)	0	1	1		

S. No.		ks/ Activity Structure Status	Description of work done	% of total proposed work
1.	Exc	avation	3	3
2.	Lay	ing of foundation	and that that	
	i	Raft	N/A	
	ii	Pile	2	2
3	Nur	nber of basements		
	i	Basement level 1	N/A	

Arest

	ii	Basement level 2	N	I/A	- Nove			
4.		terproofing of the above sub acture (Wherever applicable)		0		2		
		per Structure Status						
5		Total Floors in the tower/ Building		S+11		7		
6	Tot	al Area on each floor	5146.763 Sqft		-			
7	Stil	t floor/ ground floor	6096.815 Sqft			10		
8	Sta wis	tus of laying of slabs floor se		0	0			
	the	mulative number of slabs in building/ tower_13_ laid by l of the quarter	-		_			
9		tus of construction	-			nga, sam Jan		
	i	Walls on floors		0		4		
	ii	Staircase		0	0.	.25		
	iii	Lift wells along with water proofing	0		0.25		0.25	
	iv	Lift lobbies/common area floor wise		0	0.25			
10		ing of door and window nes in flats/units		0	0			
11	Sta	tus of MEP	Internal (Within flats)	External works	Internal (Within flats)	External works		
	i	Mechanical Works		0		0		
	ii	Electrical works including wiring		0		0		
	iii	Plumbing works	2	0		0		
12	Sta	tus of Wall Plastering						
	i	External Plaster			0			
	ii	Internal Plaster			0		0	
13	Sta	tus of wall tiling						
	i	In bathroom		0		0		
	ii	In Kitchen		0	0			
14	Sta	Status of flooring		98 tut 44 nii				
	i	Common Areas		0		0		
	ii	Units/ Flats		0		0		
15	Sta	tus of white washing						




16		i	Internal walls	0	0
i Staircase with railing 0 0 ii Lift wells 0 0 iii Lift lobbies /common areas floor wise 0 0 17 Status of installation (within flat /Unit		ii	External Walls	0	0
iii Lift wells iii Lift lobbies /common	16	Stati	us of finishing		
iii Lift lobbies /common areas floor wise 17 Status of installation (within flat /Unit i Doors and window Panels 0 0 ii Sanitary fixtures 0 0 iii Modular Kitchen iv Electrical fitting/ lighting v Gas Piping(If any) Other than Flats/Units vi Lifts Installation 0 0 vii Overhead tanks 0 0 viii Underground Water tanks 0 0 ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 19 Entrance lobby finishing 0 20 Status of construction of 0		i	Staircase with railing	0	0
areas floor wise 17 Status of installation (within flat /Unit i Doors and window Panels 0 0 0 ii Sanitary fixtures 0 0 0 iii Modular Kitchen iv Electrical fitting/ lighting v Gas Piping(If any) Other than Flats/Units vi Lifts Installation 0 0 0 vii Overhead tanks 0 0 0 viii Underground Water tanks 0 0 0 ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 0 19 Entrance lobby finishing 0 0 0 20 Status of construction of 0 0		ii	Lift wells	0	0
(within flat /Unit i Doors and window Panels 0 0 0 ii Sanitary fixtures 0 0 0 iii Modular Kitchen iv Electrical fitting/ lighting v Gas Piping(If any) vi Lifts Installation 0 0 0 vii Overhead tanks 0 0 0 viii Underground Water tanks 0 0 0 ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 0 19 Entrance lobby finishing 0 0 0 Status of construction of 0 0 0		iii		0	0
i Doors and window Panels ii Sanitary fixtures 0 0 0 iii Modular Kitchen iv Electrical fitting/ lighting v Gas Piping(If any) Other than Flats/Units vi Lifts Installation vii Overhead tanks viii Underground Water tanks viii Underground Water tanks ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 Status of construction of 0 0 0 0 0 0 0 0 0 0 0 0 0 0	17	Statı	us of installation		
iii Sanitary fixtures iii Modular Kitchen iv Electrical fitting/ lighting v Gas Piping(If any) Other than Flats/Units vi Lifts Installation vii Overhead tanks viii Underground Water tanks ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0000000000000000000000000000000000		(within flat /Unit			
iii Modular Kitchen iv Electrical fitting/ lighting v Gas Piping(If any) Other than Flats/Units vi Lifts Installation 0 0 vii Overhead tanks 0 0 viii Underground Water tanks 0 0 ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 Status of construction of 0 0 Status of construction of 0 0		i	Doors and window Panels	0	0
iv Electrical fitting/ lighting v Gas Piping(If any) Other than Flats/Units vi Lifts Installation vii Overhead tanks viii Underground Water tanks ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0000000000000000000000000000000000		ii	Sanitary fixtures	0	0
v Gas Piping(If any)		iii	Modular Kitchen		
Other than Flats/Units vi Lifts Installation vii Overhead tanks 0 viii Underground Water tanks 0 ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 0 0 0 0 0 0 0 0 0 0 0		iv	Electrical fitting/ lighting		
vi Lifts Installation 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		v	Gas Piping(If any)		
viii Overhead tanks viii Underground Water tanks ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 0 19 Entrance lobby finishing 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		Othe	er than Flats/Units		
viii Underground Water tanks 0 0 0 ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 0 19 Entrance lobby finishing 0 0 0 20 Status of construction of 0 0		vi	Lifts Installation	0	0
ix Firefighting fitting and equipment's as per CFO NOC x Electrical fitting in common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 19 Entrance lobby finishing 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		vii	Overhead tanks	0	- 0
equipment's as per CFO NOC x Electrical fitting in 0 0 common area xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 19 Entrance lobby finishing 0 0 20 Status of construction of 0 0		viii	Underground Water tanks	0	0
xi Compliance to conditions of environment/ CRZ NOC 18 Water proofing of terraces 0 0 0 19 Entrance lobby finishing 0 0 20 Status of construction of 0 0		ix	equipment's as per CFO	0	0
of environment/ CRZ NOC 18 Water proofing of terraces 0 0 19 Entrance lobby finishing 0 0 20 Status of construction of 0 0		X		0	0
19 Entrance lobby finishing 0 0 20 Status of construction of 0 0		xi	of environment/ CRZ	vid dis Jan dan Sal	514 No. 100 SE
20 Status of construction of 0 0	18	Wate	er proofing of terraces	0	0
	19	Entr	ance lobby finishing	0	0
	20			0	0

hof

TABLE - B

	TABLE -	- B		
Sr. No.	Common area & facilities amenities	Proposed (Yes/No)	% of work done	Remarks
B-1	Services			
1	Internal roads & Pavements	Yes	50%	
2	Parking Two Wheeler	Yes	0%	
	Covered No			
	Open No 1632			
3	Water Supply	Yes	70%	
4	Sewerage (Chamber, Lines, septic tanks, STP	Yes	70%	
5	Storm water drains	Yes	70%	
6	Landscaping & tree plantation	Yes	0%	
7	Parks & Playground	Yes	0%	
	Fixing of children play equipment's	Yes	0%	
	Benches	Yes	0%	
8	Shopping Area	Yes	0%	
9	Street Lighting & electrification	Yes	0%	
10	Treatment & disposal of sewage & sullage water/ STP	Yes	0%	
11	Solid waste management& disposal	Yes	70%	
12	Water conservation, rain water harvesting, percolating well/ pit	Yes	80%	
13	Energy management (Solar)	Yes	0%	
14	Fire protection and fire safety requirements	Yes	0%	
15	Electrical meter room, sub station, receiving station	Yes	0%	
16	Other (Option to be added)			
B-2	Community Building not to betransferred to RWA			
17	Community Center	No	0%	
18	Others			
B-3	Community Building not to betransferred to RWA/ Competent Authority			
19	Schools	No		
20	Dispensary	No		
21	Club	No		



22	Others		
B-4	Services/ facilities to be transferred to		
	competent authority		
23	Extended as per requirement	No	

Ag