

ACPL Design Ltd

E.24. South Extension I. New Delhi, 110049, India T: +91 11 4823 4444 +91 11 2462 2195 +91 11 2464 6709

F: +91 11 2463 4059

www.acplonline.com

Annexure-A

		Archi	tect's Certificate			
Repor	t for qua	rter ending	31st December 2023			
Subjec	et		Certificate of progress of construction work			
1.	I, KULMEET SHANGARI has undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. Particulars No.		Information			
	1.	Project/Phase of the project	Elan EPIC			
	2.	Location	Sector 70, Gurugram			
	3.	Licensed area in acres	4 Acres			
	4.	Area for registration in acres	3.525 Acres			
	5.	HARERA registration No.	RC/REP/HARERA/GGM/2018/30			
	6.	Name of licensee	Elan Limited			
	7.	Name of collaborator	NA			
	8.	Name of developer	Elan Limited			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	10th January 2024			
	2.	NameofArchitect/Architect's firm	KULMEET SHANGARI (ACPL Design Ltd.)			
	3.	Date of site inspection	31st December 2023			
3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants	Name			
	1.	Site engineer	Anil Kumar Gautam			
	2.	Structural consultant	Perceptive Idea ARCHIEGO CA/97/D474			
	3.	Proof consultant	Isha Consultant (P) Ltd.			
	4.	MEP consultant	CP Vidya Associates, Dew point Consultants Pvt. Ltd., Ampower Consultancy Services.			
	5.	Site supervisor/incharge	Saurabh Gupta			

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	Ialsocertifythatasonthedate, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date

: 10th January 2024

Yours faithfully,

Place

: New Delhi

KULMRET SHANGARI

Councilofarchitects(CoA) registration No.

: CA/97/21741

Councilofarchitects(CoA) registration valid till (date)

: 31.12.2024

Table – A Building/ Tower no. (to be prepared separately for each building/ tower in the project/phase of the project) A1 Cumulative progress of the project/phase at the end of the quarter. (In Lacs) Sr. Project components No. Project components No. Work done value during the quarter value during the quarter value till date value till date

Sr. No.		Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	(inclus	structure sive of excavation, foundation, eents, water proofing, etc.)		5061	
2.	(slabs,	r structure ,brick work,block work,staircase, lift wells, ne rooms, water tank, etc.)		4032	
3.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)		1084	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)		1870	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)		2418	
4.	Finis	hing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	104	1349	
	4.2	External (plaster, painting, facade, etc.)	96	3883	

Sr.	Tasks/ Activity		Description of work	Percentage of total	
No.		Sub-Structure Status	done	proposed work	
1.	Excav	ation	Completed	100%	
2.	Laying	g of foundation			
	(i)	Raft	Completed	100%	
	(ii)	Pile	Completed	100%	
3.	Numb	er of basement(s)			
	(i)	Basement Level 1	Completed	100%	
	(ii)	Basement level 2 & 3	Completed	100%	

JLMEET SHANGARI LARCHITECT CA/97/21741

4.		proofing of the above sub-structure rever applicable)	In Pr	ogress	98	%	
		Super-Structure Status					
5.	Total	floors in the tower/ building	6		6		
6.	Total area on each floor		N	IA	N	4	
7.	Stilt floor/ ground floor		Com	Completed		9%	
8.	Status of laying of slabs floor wise		Com	Completed		100%	
		Cumulative number of slabs in the building/ tower laid by end of quarter		Completed		100%	
9.	Status	of construction					
	(i) Walls on floors		Com	pleted	100	%	
	(ii)	Staircase	Com	pleted	100%		
	(iii)	Lift wells along with water proofing	Com	pleted	100%		
	(iv)	Lift lobbies/ common areas floor wise	Com	pleted	100	%	
10.	Fixing	ofdoorandwindowframes in flats/ units	NIL		NIL		
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works	Comp	oleted	100	%	
	(ii)	Electrical works including wiring	Comp	oleted	100	%	
	(iii)	(iii) Plumbing works		Completed		100%	
12.	Status	of wall plastering					
	(i)	External plaster	Comp	oleted	100%		
	(ii)	Internal plaster	Completed		100%		
13.	Status	of wall tiling					
	(i) In bathroom		In progress		95%		
	(ii)	(ii) In kitchen		NA		NA	
14.	Status	of flooring					
	(i) Common areas		In progress		90%		
	(ii) Units/ flats		NA		NA		
15.	Status	of white washing					
	(i)	Internal walls	TSHANGA		100	%	
	(ii)	External walls	712174 Comp	oleted	100	%	

W ...

16.	Status of finishing					
	(i)	Staircase with railing	Completed	100%		
	(ii)	Lift wells	Completed	100%		
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%		
17.	Status	of installation				
	(within	n flat/unit)				
	(i)	Doors and windows panels	Completed	100%		
	(ii)	Sanitary fixtures	Completed	100%		
	(iii)	Modular kitchen	NA	NA		
	(iv)	Electrical fittings/ lighting	Completed	100%		
	(v)	Gas piping (if any)	NA	NA		
	(other	than flat/units)				
	(vi)	Lifts installation	Completed	100%		
	(vii)	Overhead tanks	Completed	100%		
	(viii)	Underground water tank	Completed	100%		
	(ix)	Firefighting fitting and equipment's as per CFO NOC	In progress	85%		
	(x)	Electrical fittings in common areas	In progress	85%		
	(xi)	Compliance to conditions of environment/ CRZ NOC	NIL	NIL		
18.	Water	proofing of terraces	Completed	100%		
19.	Entran	ce lobby finishing	Completed	100%		
20.	Status	of construction of compound wall	Completed	100%		

Note: (*) extend rows as per requirement.

ARCHITECT CA/97/21741

Table-B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remark
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			
	Covered no572	Yes	100%	
	Open no Nil	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	NA	NIL	
	Fixing of children play equipment's	NA	NIL	
	Benches	NA	NIL	
8.	Shopping area	YES	NIL	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	-
12.	Waterconservation, rainwater, harvesting, percolating well/pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)		NIL	
B-2	Community building to be transferred to RWA	L		
17.	Community centre	NO	NO	
18.	Others			
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NO	NO	
20.	Dispensary	NO	NO	
21.	Club	NO	NO	
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

ARCHITECT CA/97/21741