BEE BEE ARCHITECTS

Architects & Engineers APURBA BORAH

Annexure A

		Architect	's Certificate [*]		
Repor	t for qua	rter ending	30 SEP 2020		
Subjec	Subject		Certificate of progress of construction work		
1.	I/We h	ave undertaken assignment as archit mentioned project as per the approve	e undertaken assignment as architect for certifying progress of construction work in the ntioned project as per the approved plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	Project Area 5.625 Acres, Affordable Residential Plotted Colony		
	2.	Location	Village Maina, Sunari Kalan, Sector-22D, Distric Rohtak Haryana		
	3.	Licensed area in acres	5.625 acres.		
	4.	Area for registration in acres	5.625 acres		
	5.	HARERA registration no.	126 of 2017		
	6.	Name of licensee	Omaxe Limited		
	7.	Name of collaborator			
	8.	Name of developer	Omaxe Limited		
2.	Details	related to inspection are as under			
	1.	Date of certifying of percentage of construction work/ site inspection	16/10/2020 BEE BEE Architects		
	2.	Name of Architect/ Architect's firm	BEE BEE Architects		
	3.	Date of site inspection	10/10/2020		



Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

Architects & Engineers

APURBA BORAH

3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants	Name			
	1.	Site engineer	Mr. Shakti Singh Rathore			
	2.	Structural consultant				
	3.	Proof consultant				
	4.	MEP consultant				
	5.	Site incharge				
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals. Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.					
5.	of the i	real estate project/phase of the project	ge of work done in the project for each of the building/ tower under HARERA is as per table A and table B given herein d with respect to each of the activity of the entire project/			

Date: 16/10/2020

Place : Delhi

Council of architects (CoA) registration no.: CA/2013/61618 Council of architects (CoA) registration valid till (date) Yours faithfully,

Signature & name (in block letters) with stamp of architect

APURBA BORAH

Apurba Borah Regd. Architect CA/2013/61618

BEE BEE ARCHITECTS

Architects & Engineers
APURBA BORAH

			Table – A		
(to be	prepar	ower no. ed separately for each building/ tower t/ phase of the project)			
A1	Cum	ulative progress of the project/phase :	at the end of the qua	rter.	,
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-		
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				
3.	MEP				
	3.1	Mechanical (lifts, ventilation, etc.)			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-		
4.	Finis	hing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			
	4.2	External (plaster, painting, facade, etc.)			



Architects & Engineers

APURBA BORAH

Sr.	Tasks/ Activity Sub-Structure Status		Description of work done		Percentage of total proposed work	
No.						
1.	Excavation					
2.	Layin	g of foundation				
	(i)	Raft				
	(ii)	Pile				
3.	Numb	per of basement(s)				
	(i)	Basement Level 1				
	(ii)	Basement level 2*				
4.		proofing of the above sub-structure ever applicable)				
	Super-Structure Status					550
5.	Total	floors in the tower/ building				
6.	Total	area on each floor				
7.	Stilt f	loor/ ground floor				
8.	Status	s of laying of slabs floor wise				
		ulative number of slabs in the building/ laid by end of quarter				
9.	Status	s of construction				
	(i)	Walls on floors				
	(ii)	Staircase				
	(iii)	Lift wells along with water proofing			2	
	(iv)	Lift lobbies/ common areas floor wise				
10.	Fixing units	g of door and window frames in flats/				
11.	Status	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works				
	(ii)	Electrical works including wiring				
	(iii)	Plumbing works				
12.	Status	s of wall plastering				
	(i)	External plaster				
	(ii)	Internal plaster				
13.	Status	s of wall tiling				
	(i)	In bathroom				
	(ii)	In kitchen		15		
14.	Status	s of flooring				
	(i)	Common areas				
	(ii)	Units/ flats			am	h .

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

BEE BEE ARCHITECTS

Architects & Engineers
APURBA BORAH

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total proposed work	
			done		
15.	Status of white washing				
	(i)	Internal walls	-		
	(ii)	External walls			
16.	Status	of finishing			
	(i)	Staircase with railing			
	(ii)	Lift wells			
	(iii)	Lift lobbies/ common areas floor wise			
17.	Status	of installation			
	(withi	n flat/unit)			
	(i)	Doors and windows panels			
	(ii)	Sanitary fixtures			
	(iii)	Modular kitchen			
	(iv)	Electrical fittings/ lighting			
	(v)	Gas piping (if any)			
	(other than flat/units)				
	(vi)	Lifts installation			
	(vii)	Overhead tanks			
	(viii)	Underground water tank		= -	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	* *		
	(x)	Electrical fittings in common areas			
	(xi)	Compliance to conditions of environment/ CRZ NOC			
18.	Waterproofing of terraces				
19.	Entrai	nce lobby finishing			
20.	Status	of construction of compound wall			

Note: (*) extend rows as per requirement.

() Emmos

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

Architects & Engineers

APURBA BORAH

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			•
1.	Internal roads & pavements	YES	93	WBM ONLY
2.	Parking			
	Covered no			
	Open no			
3.	Water supply	YES	96	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	100	
5.	Storm water drains	YES	100	
6.	Landscaping & tree plantation	YES	45	A STATE OF THE STA
7.	Parks and playgrounds	YES	-	
	Fixing of children play equipment's	YES	-	
	Benches	YES	-	
8.	Shopping area	YES	-	
9.	Street lighting/ electrification	YES	75	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	85	
11.	Solid waste management & disposal	YES		
12.	Water conservation, rain water, harvesting, percolating well/ pit	YES	-	
13.	Energy management (solar)	-	-	
14.	Fire protection and fire safety requirements	-	-	
15.	Electrical meter room, sub-station, receiving station	YES		
16.	Other (option to add more)			
B-2	Community building to be transferred to RWA			
17.	Community centre	YES		
18.	others			
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools			
20.	Dispensary			
21.	Club			
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

() massin