DADA & PARTNERS

Design and Development Atelier

8 99 Sushant Lok 1, Gurgaon Haryana 122002 India t : +01191 0124 4040076 w: www.dadapartners.com e : contact@dadapartners.com

Annexure A

		Architect	s Certificate*			
Repo	rt for q	uarter ending	Q2 (FY 2020-21)			
Subject			Certificate of progress of construction work			
1.		I/We have undertaken assignment as architect for certifying progress o construction work in the below mentioned project as per the approved plans				
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Godrej Meridien Phase-III			
	2.	Location	Sec 106 , Gurugram , Haryana			
	3.	Licensed area in acres	14.793			
	4.	Area for registration in acres	5.06			
	5.	HARERA registration no.	RC/ REP/ HARERA/ GGM/ 393/125/2020 / 09			
	6.	Name of licensee	Godrej Real View Developers Private Limited			
	7.	Name of collaborator	Not Applicable			
	8.	Name of developer	Godrej Real View Developers Private Limited			
2.	Detai	ls related to inspection are as	under			
	1.	Date of certifying of percentage of construction work/ site inspection	01-Oct-2020			
	2.	Name of Architect/ Architect's firm	M/s DADA & Partners			
	3.	Date of site inspection	01-Oct-2020			

^{*} On the letter head of the architect firm

3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants	Name			
	1.	Site engineer	GPL			
	2.	Structural consultant	M/s BMSF & M/s PPS			
	3.	Proof consultant				
	4.	MEP consultant	M/s PROION			
	5.	Site supervisor/incharge				
4.	mand applic develo and b	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.				
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.					

Date

: 09.10.2020

Place

B-99,SUSHANT LOK : 1,BLOCK C,SECTOR 43,GURUGRAM, HARYANA,122002

Council of architects (CoA) : CA/2000/2571 registration no.

Yours faithfully,

ADITI ARORA Signature & name (in block letters) with stamp of architect 8-99, SUSHANT LOK-1 6 URG & ON-122002 an^o

Council of architects (CoA) : **01/2021** registration valid till (date)

Annexure A

		1	Table – A		
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			4 (2B+G+34)		
A1	Cum	ulative progress of the projec	t/phase at the e	nd of the quarte	r.
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	-	-
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	-	-
3.	MEP	•			
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	
4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	-	
	4.2	External (plaster, painting, facade, etc.)	-	-	

Sr.		Tasks/ Activity	Description of work		Percentage of total	
No.		Sub-Structure Status	do	one	propos	ed work
1.	Exca	vation			0%	
2.	Layii	ng of foundation			0%	
	(i)	Raft				
	(ii)	Pile			NA	
3.	Num	ber of basement(s)				
	(i)	Basement Level 1			0%	
	(ii)	Basement level 2*			0%	
4.		erproofing of the above sub- cture (wherever applicable)			0%	
		Super-Structure Status				
5.	Tota	l floors in the tower/ building			34 excludi	ng Ground
6.	Tota	l area on each floor			796 .65 Se	q m
7.	Stilt	floor/ ground floor			Ground Flo	oor
8.	Statu	is of laying of slabs floor wise				
	build	ulative number of slabs in the ling/ tower laid by of quarter			0	
9.	Statu	is of construction				
	(i)	Walls on floors			0%	
	(ii)	Staircase			0%	
	(iii)	Lift wells along with water proofing			0%	
	(iv)	Lift lobbies/ common areas floor wise			0%	
10.		ng of door and window frames in / units			0%	
11.	Statı	is of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			0%	
	(ii)	Electrical works including wiring			0%	
	(iii)	Plumbing works			0%	
12.	Statu	is of wall plastering			0%	
	(i)	External plaster			0%	
	(ii)	Internal plaster			0%	

13.	Statu	is of wall tiling	
	(i)	In bathroom	0%
	(ii)	In kitchen	0%
14.	Statu	is of flooring	
	(i)	Common areas	0%
	(ii)	Units/ flats	0%
15.	Statu	is of white washing	
	(i)	Internal walls	0%
	(ii)	External walls	0%
16.	Statu	is of finishing	
	(i)	Staircase with railing	0%
	(ii)	Lift wells	0%
	(iii)	Lift lobbies/ common areas floor wise	0%
17.	Statu	is of installation	
	(witl	hin flat/unit)	
	(i)	Doors and windows panels	0%
	(ii)	Sanitary fixtures	0%
	(iii)	Modular kitchen	0%
	(iv)	Electrical fittings/ lighting	0%
	(v)	Gas piping (if any)	NA
	(othe	er than flat/units)	
	(vi)	Lifts installation	0%
	(vii)	Overhead tanks	0%
	(viii)	Underground water tank	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	0%
	(x)	Electrical fittings in common areas	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	100%
18.	Wate	erproofing of terraces	0%
19.	Entra	ance lobby finishing	0%
20.	Statı wall	as of construction of compound	0%

Note: (*) extend rows as per requirement.

		7	Гable – А		
(to buile	be p	Tower no. repared separately for each tower in the project/ phase of t)	5 (B+G+25)		
A1	Cum	ulative progress of the projec	t/phase at the en	d of the quarter	
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
5.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	-	-
6.	(slat stair	e r structure os, brick work, block work, case, lift wells, machine ns, water tank, etc.)	-	-	-
7.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	-
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-	-
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	-
8.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	-	-
	4.2	External (plaster, painting, facade, etc.)	-	-	-

Sr. No.		Tasks/ Activity Description of we done			rk Percentage of total proposed work		
0.1	Sub-Structure Status						
21.		vation			-		
22.		ng of foundation					
	(iii)	Raft			-		
	(iv)	Pile			NA		
23.	Num	ber of basement(s)					
	(iii)	Basement Level 1			-		
	(iv)	Basement level 2*			NA		
24.		erproofing of the above sub- ture (wherever applicable)			-		
		Super-Structure Status					
25.	Tota	floors in the tower/ building			25 excludi	ing Ground	
26.	Tota	area on each floor			714.72 Sq	m	
27.	Stilt	floor/ ground floor			Ground Fl	oor	
28.	Statu	s of laying of slabs floor wise					
	build	ulative number of slabs in the ling/ tower laid by of quarter			-		
29.	Statu	s of construction					
	(v)	Walls on floors			-		
	(vi)	Staircase			-		
	(vii)	Lift wells along with water proofing			-		
	(viii)	Lift lobbies/ common areas floor wise			-		
30.		g of door and window frames in units			-		
31.	Statu	is of MEP	Internal (within flat)	External works	Internal (within flat)	External works	
	(iv)	Mechanical works			-		
	(v)	Electrical works including wiring			-		
	(vi)	Plumbing works			-		
32.	Statu	s of wall plastering					
	(iii)	External plaster			-		

	(iv)	Internal plaster	-
33.	Statu	is of wall tiling	
	(iii)	In bathroom	-
	(iv)	In kitchen	-
34.	Statu	is of flooring	
	(iii)	Common areas	-
	(iv)	Units/ flats	-
35.	Statu	is of white washing	
	(iii)	Internal walls	-
	(iv)	External walls	-
36.	Statu	is of finishing	
	(iv)	Staircase with railing	-
	(v)	Lift wells	-
	(vi)	Lift lobbies/ common areas floor wise	-
37.	Statu	is of installation	-
	(with	nin flat/unit)	
	(xii)	Doors and windows panels	-
	(xiii)	Sanitary fixtures	-
	(xiv)	Modular kitchen	-
	(xv)	Electrical fittings/ lighting	-
	(xvi)	Gas piping (if any)	NA
	(othe	er than flat/units)	
	(xvii]	Lifts installation	-
	(xviii	Overhead tanks	-
	(xix)	Underground water tank	-
	(xx)	Firefighting fitting and equipment's as per CFO NOC	-
	(xxi)	Electrical fittings in common areas	-
	(xxii)	Compliance to conditions of environment/ CRZ NOC	100%
38.	Wate	erproofing of terraces	-
39.	Entra	ance lobby finishing	-
40.	Statu wall	as of construction of compound	 -

]	Table – A		
(to builc	be p	Tower no. repared separately for each tower in the project/ phase of t)	6 (B+G+23)		
A1	Cum	ulative progress of the projec	t/phase at the er	nd of the quarter	
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
9.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	-	-
10.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	-	-
11.	MEP	,			
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	-
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-	-
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	-
12.	Fini	shing			
	4.1	Internal	-	-	-

		(plaster, tilling, flooring, painting, etc. within units and common areas)				
	4.2	External - (plaster, painting, facade, etc.)		-	-	
Sr.		Tasks/ Activity	Doccrinti	on of work	Dorcont	age of total
No.		Sub-Structure Status		one		sed work
41.	Exc	avation			-	
42.	Lay	ing of foundation			-	
	(v)	Raft				
	(vi)	Pile			NA	
43.	Nur	nber of basement(s)				
	(v)	Basement Level 1			-	
	(vi)	Basement level 2*			NA	
44.		erproofing of the above sub- cture (wherever applicable)			-	
		Super-Structure Status				
45.	Tota	al floors in the tower/ building			23 exclud	ing Ground
46.	Tota	al area on each floor			649.74 S	q m
47.	Stilt	floor/ ground floor			Ground F	loor
48.	Stat	us of laying of slabs floor wise				
	buil	nulative number of slabs in the ding/ tower laid by of quarter				
49.	Stat	us of construction				
	(ix)	Walls on floors			-	
	(x)	Staircase			-	
	(xi)	Lift wells along with water proofing			-	
	(xii)	Lift lobbies/ common areas floor wise			-	
50.		ng of door and window frames in s/ units			-	-
51.	Stat	us of MEP	Internal (within flat)	External works	Internal (within flat)	External works

	(vii) Mechanical works		-
	(viii) Electrical works includin	g	-
	wiring		
	(ix) Plumbing works	-	-
52.	Status of wall plastering		-
	(v) External plaster	-	-
	(vi) Internal plaster	-	-
53.	Status of wall tiling		-
	(v) In bathroom		-
	(vi) In kitchen		-
54.	Status of flooring		
	(v) Common areas		-
	(vi) Units/ flats		-
55.	Status of white washing		
	(v) Internal walls		-
	(vi) External walls		-
56.	Status of finishing		
	(vii) Staircase with railing		-
	(viii) Lift wells		-
	(ix) Lift lobbies/ common area floor wise	S	-
57.	Status of installation		
	(within flat/unit)		
	(xxiii Doors and windows panels		-
	(xxiv Sanitary fixtures		-
	(xxv) Modular kitchen		-
	(xxvi Electrical fittings/ lighting		-
	(xxvi Gas piping (if any)		NA
	(other than flat/units)		
	(xxvi Lifts installation		-
	(xxix Overhead tanks		-
	(xxx) Underground water tank		-
	(xxxi Firefighting fitting an equipment's as per CFO NOC	d	-
	(xxxi Electrical fittings in commo areas	n	-

	(xxxi	Compliance to conditions of environment/ CRZ NOC	100%
58.	Wate	erproofing of terraces	-
59.	Entrance lobby finishing		-
60.	Statu wall	is of construction of compound	-

	Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			7 (B+G+19)			
A1	Cum	ulative progress of the projec	t/phase at the en	d of the quarter		
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
13.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	-	-	
14.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	-	-	
15.	МЕР					
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	-	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-	-	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	-	
16. Finishing						

4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	-	-
4.2	External (plaster, painting, facade, etc.)	-	-	-

Sr.	Tasks/ Activity	Description of work	Percentage of total	
No.	Sub-Structure Status	done	proposed work	
61.	Excavation		-	
62.	Laying of foundation		-	
	(vii) Raft			
	(viii) Pile		NA	
63.	Number of basement(s)			
	(vii) Basement Level 1		-	
	(viii) Basement level 2*		NA	
64.	Waterproofing of the above sub- structure (wherever applicable)		-	
	Super-Structure Status			
65.	Total floors in the tower/ building		19 excluding Ground	
66.	Total area on each floor		718.34 Sq m	
67.	Stilt floor/ ground floor		Ground Floor	
68.	Status of laying of slabs floor wise			
	Cumulative number of slabs in the building/ tower laid by end of quarter			
69.	Status of construction			
	(xiii) Walls on floors		-	
	(xiv) Staircase		-	
	(xv) Lift wells along with water proofing		-	
	(xvi) Lift lobbies/ common areas floor wise		-	
70.	Fixing of door and window frames in flats/ units		-	
71.	Status of MEP	Internal External (within works flat)	Internal External (within works flat)	

	(x)	Mechanical works	-
	(xi)	Electrical works including	
	(m)	wiring	
	(xii)	Plumbing works	-
72.	Statu	s of wall plastering	
	(vii)	External plaster	-
	(viii)	Internal plaster	-
73.	Statu	s of wall tiling	
	(vii)	In bathroom	-
	(viii)	In kitchen	-
74.	Statu	s of flooring	
	(vii)	Common areas	-
	(viii)	Units/ flats	-
75.	Statu	s of white washing	
	(vii)	Internal walls	-
	(viii)	External walls	-
76.	Status of finishing		
	(x)	Staircase with railing	-
	(xi)	Lift wells	-
	(xii)	Lift lobbies/ common areas floor wise	-
77.	Statu	s of installation	
	(with	nin flat/unit)	
	(xxxi	Doors and windows panels	-
	(xxxv	Sanitary fixtures	-
	(xxxv	Modular kitchen	-
	(xxxv	Electrical fittings/ lighting	-
	(xxxv	Gas piping (if any)	NA
	(othe	er than flat/units)	
	(xxxi	Lifts installation	-
	(xl)	Overhead tanks	-
	(xli)	Underground water tank	-
	(xlii)	Firefighting fitting and equipment's as per CFO NOC	-
	(xliii	Electrical fittings in common areas	-

	(xliv [†] Compliance to conditions of environment/ CRZ NOC	100%
78.	Waterproofing of terraces	-
79.	Entrance lobby finishing	-
80.	Status of construction of compound wall	-

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			I
1.	Internal roads & pavements	Yes	-	
2.	Parking			
	Covered no	Yes	-	
	Open no	Yes	-	
3.	Water supply	Yes	-	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	-	
5.	Storm water drains	Yes	-	
6.	Landscaping & tree plantation	Yes	-	
7.	Parks and playgrounds	Yes	-	
	Fixing of children play equipment's	Yes	-	
	Benches	Yes	-	
8.	Shopping area	Yes	-	
9.	Street lighting/ electrification	Yes	-	
10.	Treatment and disposal of sewage and sullage water/STP	Yes	-	
11.	Solid waste management & disposal	Yes	-	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	-	
13.	Energy management (solar)	Yes	-	
14.	Fire protection and fire safety requirements	Yes	-	
15.	Electrical meter room, sub-station, receiving station	Yes	-	
16.	Other (option to add more)			
B-2	Community building to be transferred	to RWA		
17.	Community centre	No	-	
18.	others			
B-3	Community buildings not to be transferred to RWA/competent authority			

Table – B

19.	Schools	Yes	-	
20.	Dispensary			
21.	Club			
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	Cumulative Progress		0%	

Note: (*) extend as per requirement

Annexure A