#### BEE BEE ARCHITECTS

### Architects & Engineers APURBA BORAH

Annexure A

		Architect	's Certificate*			
Report	for qua	rter ending	30 SEP 2020			
Subject			Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Project Area 10241.29 sq mtr , Commercial Cum Residential Colony, SCO Phase 3			
	2.	Location	Village Bhatola, Sector-79, Faridabad			
	3.	Licensed area in acres	11.49375 acres			
	4.	Area for registration in acres	2.53 acres			
	5.	HARERA registration no.	117 of 2017			
	6.	Name of licensee	Robust Buildwell Private Limited			
	7.	Name of collaborator				
	8.	Name of developer	Robust Buildwell Private Limited			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	16/10/200			
	2.	Name of Architect/ Architect's firm	BEE BEE Architects			
	3.	Date of site inspection	10/10/2020			



#### Architects & Engineers APURBA BORAH

3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name		
	1.	Site engineer	Mr. D.C Pant		
	2.	Structural consultant	Mr. Pankaj Varshney		
	3.	Proof consultant			
	4.	MEP consultant	Mr, Dharmendra Singh		
	5.	Site incharge	Mr. D.C Pant		
4.	Haryar constru envisag	na Building Code, 2017/ National Buction, infrastructure works and in	ed as per approved drawings, statutory/ mandatory approvals, Building Code (wherever applicable) and the material used in the ternal development works are as per the projected standard as are, publication material and other documents shared with the		
5.	of the below.	real estate project/phase of the pro	entage of work done in the project for each of the building/ tower ject under HARERA is as per table A and table B given herein cuted with respect to each of the activity of the entire project/		

Date 16/10/2020

Place DELHI

Council of architects (CoA) registration no. : CA/2013/61618 Council of architects (CoA) registration valid till (date) Yours faithfully,

Signature & name (in block letters) with stamp of architect

APURBA BORAH

Apurba Borah Regd. Architect 9A/2013/61618

# BEE BEE ARCHITECTS Architects & Engineers

APURBA BORAH

			Table – A			
(to be	prepare	ed separately for each building/ tower // phase of the project)				
<b>A1</b>	Cumulative progress of the project/phase at the end of the quarter.					
Sr. No.	Project components  Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1.			.4 Cr	2 Cr	100%	
2.	(slabs	r structure s, brick work, block work, stair case, ells, machine rooms, water tank, etc.)	.50 CR-	.8 CR-	-	
3.	MEP					
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	-	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-	-	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	-	
4.	Finis	hing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	-	-	
	4.2	External (plaster, painting, facade, etc.)	-	-	-	



<sup>🗣</sup> Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

### Architects & Engineers APURBA BORAH

Sr.	Tasks/ Activity		Description of work		Percentage of total		
No.		Sub-Structure Status		done		proposed work	
1.	Excav	ration	Completed		100%		
2.	Layin	g of foundation					
	(i)	Raft		Completed		100%	
	(ii)	Pile	N/A		N/A		
3.	Number of basement(s) 1						
	(i)	Basement Level 1	Completed		100%		
	(ii)	Basement level 2*	-		-	-	
4.		proofing of the above sub-structure ever applicable)	-	-	-		
		Super-Structure Status					
5.	Total	floors in the tower/ building	3	3			
6.	Total	area on each floor	2754:	5 SFT			
7.	Stilt f	loor/ ground floor	2754:	5 SFT			
8.	Status	s of laying of slabs floor wise					
		lative number of slabs in the building/					
9.	Status	s of construction					
	(i)	Walls on floors		-			
	(ii)	Staircase		-			
	(iii)	Lift wells along with water proofing		-			
	(iv)	Lift lobbies/ common areas floor wise		-			
10.	Fixin units	g of door and window frames in flats/	-				
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works		-			
	(ii)	Electrical works including wiring	-				
	(iii)	Plumbing works	-		H		
12.	Status of wall plastering						
	(i)	External plaster	-				
	(ii)	Internal plaster	-				
13.	Statu	s of wall tiling					
	(i)	In bathroom		-			
	(ii)	In kitchen		-			
14.	Statu	s of flooring				\	
	(i)	Common areas		-		Juno:	
	(ii)	Units/ flats		-		0	

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

#### BEE BEE ARCHITECTS

## Architects & Engineers APURBA BORAH

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total	
			done	proposed work	
15.	Status of white washing				
	(i)	Internal walls	•		
	(ii)	External walls	<del>-</del>		
16.	Status of finishing				
	(i)	Staircase with railing	-		
	(ii)	Lift wells	-		
	(iii)	Lift lobbies/ common areas floor wise	-		
17.	Status	of installation			
	(withi	n flat/unit)			
	(i)	Doors and windows panels	-	-	
	(ii)	Sanitary fixtures	<u>-</u>	-	
	(iii)	Modular kitchen	-	-	
	(iv)	Electrical fittings/ lighting	-	÷	
	(v)	Gas piping (if any)	-	-	
	(other	than flat/units)	*		
	(vi)	Lifts installation	-	-	
	(vii)	Overhead tanks	•	-	
	(viii)	Underground water tank	-	-	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	-	-	
	(x)	Electrical fittings in common areas	<u>-</u>	-	
	(xi)	Compliance to conditions of environment/ CRZ NOC	-	-	
18.	Water	proofing of terraces	-		
19.	Entra	nce lobby finishing	-		
20.	Status	of construction of compound wall	-		

Note: (\*) extend rows as per requirement.



### Architects & Engineers APURBA BORAH

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			···
1.	Internal roads & pavements	YES	0%	
2.	Parking			
	Covered no	YES	0%	
	Open no	YES	0%	
3.	Water supply	YES	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	0%	
5.	Storm water drains	YES	0%	
6.	Landscaping & tree plantation	YES	0%	
7.	Parks and playgrounds	N/A		
	Fixing of children play equipment's	N/A		
	Benches	N/A		
8.	Shopping area	YES	0%	
9.	Street lighting/ electrification	YES	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%	
11.	Solid waste management & disposal	N/A		
12.	Water conservation, rain water, harvesting, percolating well/ pit	-		
13.	Energy management (solar)	-		
14.	Fire protection and fire safety requirements	-		
15.	Electrical meter room, sub-station, receiving station	-		
16.	Other (option to add more)	-		
B-2	Community building to be transferred to RWA			
17.	Community centre	-		
18.	Others	-		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	-		
20.	Dispensary	-		
21.	Club	-		
22.	Others	-		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (\*) extend as per requirement

