BEE BEE ARCHITECTS Architects & Engineers

APURBA BORAH

Annexure A

		Architect	's Certificate*		
Report	for quar	ter ending	30 SEP 2020		
Subjec	:t		Certificate of progress of construction work		
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans				
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	Project Area 8093.7 sq mtr , Commercial Cur Residential Colony		
	2.	Location	Village Bhatola, Sector-79, Faridabad		
	3.	Licensed area in acres	11.49375 acres		
	4.	Area for registration in acres	1.99 acres		
	5.	HARERA registration no.	111 of 2017		
	6.	Name of licensee	Robust Buildwell Private Limited		
	7.	Name of collaborator			
	8.	Name of developer	Robust Buildwell Private Limited		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	16/10/2020		
	2.	Name of Architect/ Architect's firm	BEE BEE Architects		
	3.	Date of site inspection	10/10/2020		



Architects & Engineers APURBA BORAH

	Sr. No.	Consultants	Name		
	1.	Site engineer	Mr. D.C Pant		
	2.	Structural consultant	Mr. Pankaj Varshney		
/	3.	Proof consultant			
	4.	MEP consultant	Mr, Dharmendra Singh		
	5.	Site incharge	Mr. D.C Pant		
l.	Haryar constru envisa	na Building Code, 2017/ National action, infrastructure works and	uted as per approved drawings, statutory/ mandatory approvals l Building Code (wherever applicable) and the material used in the internal development works are as per the projected standard a chure, publication material and other documents shared with the		
5.	of the	real estate project/phase of the r	recentage of work done in the project for each of the building/ tower project under HARERA is as per table A and table B given herei receuted with respect to each of the activity of the entire project		

Date 16/10/2020

Place DRL141

Council of architects (CoA) registration no. : CA/2013/61618 Council of architects (CoA) registration valid till (date) Signature & name in block letters) with stamp of architect

Yours faithfully,

Apurba Borah Regd. Architect CA/2013/61618

BEE BEE ARCHITECTS

Architects & Engineers APURBA BORAH

		,	Table – A			
(to be	prepare	wer no. ed separately for each building/ tower / phase of the project)			work done to the total proposed work	
A1	Cum	ulative progress of the project/phase a	at the end of the quar	ter.		
Sr. No.	Proje	ct components	Work done value during the quarter	Cumulative work done value till date	work done to the total proposed	
1.	(inclu	tructure sive of excavation, foundation, nents, water proofing, etc.)	.80 CR	11.38 CR	13.0%	
2.	(slabs	r structure s, brick work, block work, stair case, ells, machine rooms, water tank, etc.)	-	-		
3.	MEP					
	3.1	Mechanical (lifts, ventilation, etc.)	-	-		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-		
4.	Finis	shing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	•	-		
	4.2	External (plaster, painting, facade, etc.)	-	-		



Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

BEE BEE ARCHITECTS

Architects & Engineers

APURBA BORAH

Sub-Structure Status		done		Percentage of total proposed work		
						Excav
Laying of foundation						
(i)	Raft	Completed		100%		
(ii)	Pile	N/.	A	N/A		
Number of basement(s)						
(i)	Basement Level 1	Comp			%	
(ii)	Basement level 2*	Completed		100%		
(iii)	Basement Level 3	WIP		50%		
(iv)	Basement Level 4	WIP		-		
	Super-Structure Status					
Total	floors in the tower/ building	4		-		
Total	area on each floor	120	000	-		
Stilt f	floor/ ground floor	636	500	-		
Statu	s of laying of slabs floor wise	-		-		
Statu	s of construction					
(i)	Walls on floors	-		-		
(ii)	Staircase	-		-		
(iii)	Lift wells along with water proofing	-	-		-	
(iv)	Lift lobbies/ common areas floor wise	-		•		
Fixin units	g of door and window frames in flats/					
Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works	
(i)	Mechanical works	-				
(ii)	Electrical works including wiring	-				
(iii)	Plumbing works	-				
Statu	s of wall plastering					
(i)	External plaster	-				
(ii)	Internal plaster	-				
Statu	s of wall tiling					
(i)	In bathroom	-				
(ii)	In kitchen	-				
Statu	s of flooring				1 June	
(i)	Common areas		-)Jan-	
(ii)	Units/ flats	-				
	Layin (i) (ii) Numb (ii) (iii) (iii) (iii) (iv) Wate: (when Total Total Statu: Cumi tower Statu: (i) (ii) (iii) (iii) (iii) Statu: (i) (iii)	Excavation Laying of foundation (i) Raft (ii) Pile Number of basement(s)	Excavation Laying of foundation (i) Raft Comp (ii) Pile N/ Number of basement(s)	Excavation Completed	Sub-Structure Status	

BEE BEE ARCHITECTS

Architects & Engineers APURBA BORAH

Sr.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total
No.			done	proposed work
15.	Status of white washing			
	(i)	Internal walls	-	
	(ii)	External walls	-	
16.	Status of finishing			
	(i)	Staircase with railing	-	
	(ii)	Lift wells	-	
	(iii)	Lift lobbies/ common areas floor wise	-	
17.	Status	of installation		
	(withi	n flat/unit)		
	(i)	Doors and windows panels	-	
	(ii)	Sanitary fixtures	•	
	(iii)	Modular kitchen	-	
	(iv)	Electrical fittings/ lighting	-	
	(v)	Gas piping (if any)	-	
	(other than flat/units)			
	(vi)	Lifts installation	-	
	(vii)	Overhead tanks	-	
	(viii)	Underground water tank	-	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	-	
	(x)	Electrical fittings in common areas	-	
	(xi)	Compliance to conditions of environment/ CRZ NOC	-	
18.	Water	rproofing of terraces	-	
19.	Entra	nce lobby finishing	-	
20.	Status	s of construction of compound wall	-	

Note: (*) extend rows as per requirement.

J. man

Architects & Engineers APURBA BORAH

Table - B

r. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements		0%	
2.	Parking	-		
	Covered no	YES	0%	
	Open no	YES	0%	
3.	Water supply	YES	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	0%	
5.	Storm water drains	YES	0%	
6.	Landscaping & tree plantation	YES	0%	
7.	Parks and playgrounds	-		
	Fixing of children play equipment's	-		
	Benches	-		
8.	Shopping area	YES	0%	
9.	Street lighting/ electrification	YES	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%	
11.	Solid waste management & disposal	-		
12.	Water conservation, rain water, harvesting, percolating well/ pit	-		
13.	Energy management (solar)	-		
14.	Fire protection and fire safety requirements	-		
15.	Electrical meter room, sub-station, receiving station	-		
16.	Other (option to add more)	-		
B-2	Community building to be transferred to RWA			
17.	Community center	-		
18.	Others	-		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	-		
20.	Dispensary	-		
21.	Club	-		
·22.	Others	-		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

