M-4/26 B DLF City 2 Gurugram122002 Haryana India
EMAIL:- Anoopkumararchitects@gmail.com
PHONE:- +91-9999555494
Architecture | Interiors | Landscape | Planning

Architect's Certificate[1]

Report for quarter ending	31.12.2023
Subject	Certificate of progress of construction work

1. I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans

Sr. No.	Particulars	Information
1.	Project/Phase of the project	BOULEVARD II
2.	Location	SECTOR 47, VILLAGE TIKRI, GURUGRAM, HARYANA
3.	Licensed area in acres	2.219 Acres
4.	Area for registration in acres	2.219 Acres
5.	HARERA registration no.	387 OF 2017 DATED 19.12.2017
6.	Name of licensee	M/S AUTOMAX UNIT OF M/S OMAXE AUTO LTD
7.	Name of collaborator	M/S AUTOMAX UNIT OF M/S OMAXE AUTO LTD
8.	Name of developer	SPAZE TOWERS PVT. LTD

2. Details related to inspection are as under

1.	Date of certifying of percentage of construction work/ site inspection	31.12.2023

ANOOP KUMAR TAANK
CA/2018/96240
Architect

	2.	Name of Architect/ Architect's firm	Ar. Anoop Kumar Taank
	3.	Date of site inspection	31.12.2023

3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Mr Yashpal Nasa
	2.	Structural consultant	Appointed by Principal Consultants of the project M/s. Sikka Associates Architects.
	3.	Proof consultant	NA
	4.	MEP consultant	Appointed by Principal Consultants of the project M/s. Sikka Associates Architects.
	5.	Site supervisor/in charge	Mr Yashpal Nasa
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		

ANOOP KUMAR TAANK
CA/2018/96240
Architect

5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.	
Date		Yours faithfully Ar. Anoop Kumar Taank ANOOP KUMAR TAANK CA/2018/96240 Architect
Place		
Council of architects (CoA) registration no		
Council of architects (CoA) registration valid till (date)	CA/2018/96240 Architect	

Table – A					
Building/ Tower no.			**Boulevard -II (Single Tower)**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
1	**Sub structure**		-	741.43	100.00%
	(inclusive of excavation, foundation, basements, water proofing, etc.)				
2	**Super structure**		-	1297.50	100.00%
	(slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)				
3	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	-	370.72	100.00%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	185.36	100.00%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	370.72	100.00%
4	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.81	523.45	94.13%
	4.2	External (plaster, painting, facade, etc.)	-	185.36	100.00%

ANOOP KUMAR TAANK
CA/2018/96240
Architect

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
1	Excavation		Completed	100%
2	Laying of foundation		Completed	100%
	i	Raft	Completed	100%
	ii	Pile	NA	NA
3	Number of basement(s)		Completed	100%
	i	Basement Level 1	Completed	100%
	ii	Basement level 2*	Completed	100%
	iii	Basement level 3*	Completed	100%
4	Waterproofing of the above sub-structure (wherever applicable)		Completed	100%
	Super-Structure Status		Completed	100%
5	Total floors in the tower/ building		Ground+12	
6	Total area on each floor (Third Floor to Twelfth Floor)		755.08 each floor	
	Second Floor		289.210	
	First Floor		2666.374	
7	Stilt floor/ ground floor		2868.927	
8	Status of laying of slabs floor wise (Cumulative number of slabs in the building/ tower Ground + 12th)		Completed	100%
9	Status of construction			
	i	Walls on floors	Completed	100%
	ii	Staircase	Completed	100%
	iii	Lift wells along with water proofing	Completed	100%
	iv	Lift lobbies/ common areas floor wise	Completed	100%
10.	Fixing of door and window frames in flats/ units		Completed	100%
11	Status of MEP		Internal (within flat) and External works	Internal (within flat) and External works

ANOOP KUMAR TAANK
CA/2018/96240
Architect

	i	Mechanical works	Completed	100.00%
	ii	Electrical works including wiring	Completed	100.00%
	iii	Plumbing works	Completed	100.00%
12	Status of wall plastering			
	i	Internal plaster	Completed	100.00%
	ii	External plaster	Completed	100.00%
13	Status of wall tiling			
	i	In bathroom	Completed	100%
	ii	In kitchen	NA	NA
14	Status of flooring			
	i	Common areas	Completed	100%
	ii	Units/ flats	Completed	100%
15	Status of white washing			
	i	Internal walls	Completed	100.00%
	ii	External walls	Completed	100.00%
16	Status of finishing			
	i	Staircase with railing	Completed	100%
	ii	Lift wells	Completed	100%
	iii	Lift lobbies/ common areas floor wise	Completed	100%
17	Status of installation		Completed	100%
	(within flat/unit)			
	i	Doors and windows panels	Completed	100%
	ii	Sanitary fixtures	Completed	100%
	iii	Modular kitchen	NA	NA
	iv	Electrical fittings/ lighting	Completed	100.00%
	v	Gas piping (if any)	Completed	100%
	(other than flat/units)			
	vi	Lifts installation	Completed	100%
	vii	Overhead tanks	Completed	100%
	viii	Underground water tank	Completed	100%
	ix	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	x	Electrical fittings in common areas	Completed	100.00%
	xi	Compliance to conditions of environment/ CRZ NOC	Completed	100%

ANOOP KUMAR TAANK
CA/2018/96240
Architect

18	Waterproofing of terraces		Completed	100%
19	Entrance lobby finishing		Completed	100%
20	Status of construction of compound wall		Completed	100%
Total	**Cumulative progress of the project/phase at the end of the quarter.**			
Sr. No.	**Project components**	**Work done value during the quarter**	**Cumulative work done value till date**	**Percentage of work done to the total proposed work**
Total		0.81	3674.52	100.00%

Table – B				
Sr. No.	**Common areas and facilities amenities**	**Proposed (Yes/ No)**	**Percentage of work done**	**Remarks**
B-1	**Services**			
1	Internal roads & pavements	Yes	100%	Completed
2	Water supply, Sewerage, Storm, STP & Rain water harvesting	Yes	100%	Completed
3	Construction of circulation road	Yes	100%	Completed
4	Street light, laying of cable, Renewable of energy system, security & fire-fighting	Yes	100%	Completed
5	Other Internal Development work	Yes	88%	Under-Progress

ANOOP KUMAR TAANK
CA/2018/96240
Architect