

LINE OF FORCE Architects

F-3 FIRST FLOOR, SHARAN APARTMENTS, SOUTH CITY-1, GURGAON, HARYANA
EMAIL : lofarchitectsgurgaon@gmail.com

Annexure A

Architect's Certificate*		
Report for quarter ending		31.12.2023
Subject		Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr. No.	Particulars	Information
1.	Project/Phase of the project	SS HIGH POINT
2.	Location	Vill- Badha, Sector-86, Tehsil-Manesar, Gurugram
3.	Licensed area in acres	2.80625
4.	Area for registration in acres	2.80625
5.	HARERA registration No.	36 of 2019
6.	Name of licensee	Shiva Profins Pvt. Ltd., Matrix Buildwell Pvt. Ltd. North Star Towers Pvt. Ltd.
7.	Name of collaborator	SS Group Pvt. Ltd.
8.	Name of developer	SS Group Pvt. Ltd.
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	03.01.2024
2.	Name of Architect/ Architect's firm	
3.	Date of site inspection	03.01.2024
3.	Following technical professionals are appointed by promoter: - (as applicable)	
Sr. No.	Consultants	Name
1.	Site engineer	Saurabh Joshi
2.	Structural consultant	DESMAN
3.	Proof consultant	Arvind Gupta
4.	MEP consultant	ASHOK GANGWAR (ARK Consultants)
5.	Site supervisor/in charge	Dev Kumar Dutta

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council
of Architecture CA/2003/31608

LINE OF FORCE Architects

F-3 FIRST FLOOR, SHARAN APARTMENTS, SOUTH CITY-I, GURGAON, HARYANA
EMAIL : lofarchitectsgurgaon@gmail.com

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date

Place

Council of Architects (CoA):

Registration No. CA/2003/31608

Council of Architects (CoA) :

Registration valid till (Date) 31st Dec 2031

Ar. KAPIL SINGH
B. Arch.
Regn. No. with Council
of Architects CA/2003/31608

Yours Faithfully

Signature & Name (in block letters)




With stamp of Architect

Ar. KAPIL SINGH

B. Arch.

Regn. No. with Council
of Architecture CA/2003/31608

TABLE-A (SEPT-2023)							
Building No/Tower No.			SS HIGH POINT				
A1	Cumulative Progress of the Project/Phase at the end of the Quarter						
Sr.No	Project Components		Work done value during the Quarter (In Lakh)	Cumulative Work done value till Date (In Lakh)		Percentage of work done to the total proposed work	
1	Sub Structure		0	969		100%	
2	Super Structure		0.00	1086		50%	
3	MEP						
	3.1	Mechanical Work	1.40	337		65.72%	
	3.2	Electrical Work	0	140		50.26%	
	3.3	Plumbing & Fire Fighting Work	0.67	409		56.41%	
4	FINISHING						
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0.70	412		50.00%	
	4.2	External (Plaster, Painting, Façade etc.)	1.71	686		50.00%	
Sr.No.	Tasks/ Activity			Description of work Done		Percentage of total	
	Sub-Structure Status						
1	Excavation			Complete		100%	
2	Laying of Foundation			Complete		100%	
	(i)	Raft		Complete		100%	
3	Number of Basements						
	(i)	Basement Level-1		Complete		100%	
	(ii)	Basement Level-2		Complete		100%	
	(iii)	Basement Level-3		Complete		100%	
4	Water Proofing of the Above Sub-Structure (wherever applicable)			In Progress		50%	
	Super-Structure Status						
5	Total Floors in the Tower/ Building			G+18		50%	
6	Total Area on each floor (Sq.Mtr.)			27600.368		56%	
7	Stilt / Ground Floor			4964.783		100%	
8	Status of Laying of slabs floor wise						
	Cumulative number of the slabs in the Building/Tower...Laid by			5		56%	
9	Status of Construction						
	(i)	Walls on floors		In Progress		50%	
	(ii)	Staircase		In Progress		50%	
	(iii)	Liftwells along with water proofing		In Progress		50%	
	(iv)	Lift Lobbies/Common areas floor wise		In Progress		50%	
10	Fixing of Door & window frames in the Units			In Progress		50%	
11	Status of MEP			Internal (with in Flat)	External Work	Internal (with in Flat)	External Work
	(i)	Mechanical Work		In Progress		66%	
	(ii)	Electrical work including wiring		In Progress		50%	
	(iii)	Plumbing & Fire Fighting Work		In Progress		56%	
12	Status of Wall Plastering						


Ar. KAPIL SINGH
 B. Arch.
 Regn. No with Council
 of Architecture CA/2003/31608

	(i)	External Plaster	In Progress	50%
	(ii)	Internal Plaster	In Progress	50%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Nil	0%
	(ii)	In Kitchen	NA	NA
14	Status of Flooring			
	(i)	Common Areas	Nil	0%
	(ii)	Units/Flats	Nil	0%
15	Status of White Washing			
	(i)	Internal Walls	Nil	0%
	(ii)	External Walls	Nil	0%
16	Status of Finishing			
	(i)	Staircase with Railing	Nil	0%
	(ii)	Lift Wells	Nil	0%
	(iii)	Lift Lobbies/Common areas floor wise	Nil	0%
17	Status of installation			
	(within Flats/ Units)			
	(i)	Doors & Windows Panels	NA	NA
	(ii)	Sanitary Fixtures	NA	NA
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other than Flats/ Units)			
	(vi)	Lift Installations	Nil	0%
	(vii)	Over Head Tanks	Nil	0%
	(viii)	Under Ground Water Tanks	Nil	0%
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	Nil	0%
	(x)	Electrical Fittings in Common Areas	Nil	0%
	(xi)	Compliance to condition of environment/CRZ NOC	NA	NA
18	Water Proofing of Terraces		Nil	0%
19	Entrance Lobby Finishing		Nil	0%
20	Status of Construction of Compound wall		Nil	0%


Ar. KAPIL SINGH
 B. Arch.
 Regn. No with Council
 of Architecture CA/2003/31608

TABLE-B (SSH-DEC-2023)				
Sr.No	Common Areas and Facilities Amenities	Proposed (Yes/No)	Percentage of work done	Remarks
B-1	Services			
1	Internal Roads & Pavements	Yes	50%	
2	Parkings	Yes		
	Covered	Yes	100%	
	Open NoS	NA	0%	
3	Water Supply	Yes	40%	
4	Sewarage(Chambers,Lines,STP,Septic Tanks)	Yes	50%	
5	Storm Water Drains	Yes	40%	
6	Landscaping & Tree Plantations	Yes	5%	
7	Parks & Playgrounds	NA	NA	
8	Shopping Areas	NA	NA	
9	Street Lighting/Electrification	Yes	6%	
10	Treatment & Disposal of Sewage & Sludge water/STP	Yes	0%	
11	Solid waste Management & Disposal	NA	NA	
12	Rain water Harvesting	Yes	25%	
13	Energy Management (Solar)	Yes	0%	
14	Fire Protection & Fire safety Equipments	Yes	16%	
15	Electrical Meter Room,Sub-Station,Receiving Station	Yes	13%	
16	Under Ground Water Tank	Yes	90%	
B-2	Community Building to be Transferred to RWA			
17	Community Center	NA	NA	
18	Others.	NA	NA	
B-2	Community Building not to be Transferred to RWA/Competent Authority			
19	School	NA	NA	
20	Milk Booth	NA	NA	
21	Club/Community Building	NA	NA	


Ar. KAPIL SINGH
 B. Arch.
 Regn. No with Council
 of Architecture CA/2003/31608