Design and Development Atelier

B 99 Sushant Lok 1, Gurgaon Haryana 122002 India

t: + 91 (0)124 4040076 w: www.dadapartners.com

e: contact@dadapartners.com

Annexure A

Architect's Certificate*					
Repo	rt for q	uarter ending	Q1 (FY 2022-23)		
Subject			Certificate of progress of construction work		
1.		nt as architect for certifying progress of ntioned project as per the approved plans			
	Sr. Particulars No.		Information		
	1.	Project/Phase of the project	Godrej Meridien Phase-II		
	Location Licensed area in acres		Sec 106, Gurugram, Haryana 14.793		
	4.	Area for registration in acres	1.113		
	5.	HARERA registration no.	RC/ REP/ HARERA/ GGM/ 2018 / 06		
	6.	Name of licensee	Godrej Real View Developers Private Limited		
	7.	Name of collaborator	Not Applicable		
	8.	Name of developer	Godrej Real View Developers Private Limited		
2.	2. Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	01-July-2022		
	2.	Name of Architect/ Architect's firm	DADA & Partners		
	3.	Date of site inspection	01-July-2022		

3.	Following technical professionals are appointed by promoter: - (as applica				
	Sr. Consultants No.		Name		
	1.	Site engineer	GPL		
	2.	Structural consultant	BMSF & PPS		
	3.	Proof consultant			
	4.	MEP consultant	PROION		
	5.	Site supervisor/incharge			
4.	I certify that the work has been executed as per approved drawings, statutory/mandatory approvals, Haryana Building Code, 2017/National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.				
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.				

Yours faithfully, 07th July 2022 Date

B99, Sushant Lok 1,

BLock C,SUshant Lok Place Phase1, Sector 43,

Gurugram, Haryana

122001

Council of architects (CoA) : CA/ 2000/25713

registration no.

Signature & name (in block letters) with stamp of architect

ADITI ARORA

8-99, SUSHANT LOK-1 6 URG A O N-122002

Council of architects (CoA):

registration valid till (date)

12/2031

		1	Table - A				
Building/Tower no. (to be prepared separately for each building/tower in the project/ phase of the project)			3 (2B+G+34)				
A1	Cum	Cumulative progress of the project/phase at the end of the quarter.					
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0.0 Cr	8.1 Cr	100 %		
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		1.7 Cr	27.3 Cr	95%		
3.	MEP	,					
	3.1	Mechanical (lifts, ventilation, etc.)	-	-			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.4 Cr	0.5 Cr	37%		
4.	Finis	shing					
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.1 Cr	2.1 Cr	19%		
	4.2	External (plaster, painting, facade, etc.)	-	-			

Sr.	Tasks/ Activity		Description of work done		Percentage of total proposed work		
No.	Sub-Structure Status						
1.	Exca	vation			100%		
2.	Layi	ying of foundation			100%		
	(i)	Raft					
	(ii)	Pile			NA		
3.	Num	ber of basement(s)					
	(i)	Basement Level 1			100 %		
	(ii)	Basement level 2*			100%		
4.		erproofing of the above sub- cture (wherever applicable)			100%	100%	
		Super-Structure Status					
5.	Tota	l floors in the tower/ building			34 excludi	ng Ground	
6.	Tota	l area on each floor			805 Sq m		
7.	Stilt	floor/ ground floor			Ground Flo	or	
8.	Statı	atus of laying of slabs floor wise			Terrace Completed	Floor	
	build	ulative number of slabs in the ling/tower2 laid by of quarter					
9.	Statı	us of construction					
	(i)	Walls on floors			100%		
	(ii)	Staircase			100%		
	(iii)	Lift wells along with water proofing			0%		
	(iv)	Lift lobbies/ common areas floor wise			0%		
10.		ng of door and window frames in / units			0%		
11.	Statı	is of MEP	Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works			0%		
	(ii)	Electrical works including wiring			0%		
	(iii)	Plumbing works			37%		
12.	Statı	us of wall plastering			0%		
	(i)	External plaster			0%		
	(ii)	Internal plaster			63%		

13.	Statu	us of wall tiling	
	(i)	In bathroom	4%
	(ii)	In kitchen	4%
14.	Status of flooring		
	(i)	Common areas	0%
	(ii)	Units/ flats	4%
15.	Status of white washing		
	(i)	Internal walls	0%
	(ii)	External walls	0%
16.	Statu	us of finishing	
	(i)	Staircase with railing	43%
	(ii)	Lift wells	0%
	(iii)	Lift lobbies/ common areas floor wise	0%
17.	Status of installation		
	(within flat/unit)		
	(i)	Doors and windows panels	0%
	(ii)	Sanitary fixtures	0%
	(iii)	Modular kitchen	0%
	(iv)	Electrical fittings/ lighting	0%
	(v)	Gas piping (if any)	NA
	(oth	er than flat/units)	
	(vi)	Lifts installation	0%
	(vii)	Overhead tanks	0%
	(viii)	Underground water tank	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	0%
	(x)	Electrical fittings in common areas	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	100%
18.	Wate	erproofing of terraces	0%
19.	Entr	ance lobby finishing	0%
20.	Statu wall	us of construction of compound	0%

Note: (*) extend rows as per requirement.

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	-	
2.	Parking			
	Covered no	Yes	-	
	Open no	Yes	-	
3.	Water supply	Yes	-	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	-	
5.	Storm water drains	Yes	-	
6.	Landscaping & tree plantation	Yes	-	
7.	Parks and playgrounds	Yes	-	
	Fixing of children play equipment's	Yes	-	
	Benches	Yes	-	
8.	Shopping area	Yes	-	
9.	Street lighting/ electrification	Yes	-	
10.	Treatment and disposal of sewage and sullage water/STP	Yes	-	
11.	Solid waste management & disposal	Yes	-	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	-	
13.	Energy management (solar)	Yes	-	
14.	Fire protection and fire safety requirements	Yes	-	
15.	Electrical meter room, sub-station, receiving station	Yes	-	
16.	Other (option to add more)			
B-2	Community building to be transferred	to RWA		
17.	Community centre	No	-	
18.	others			
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	No	-	
20.	Dispensary	No	-	
21.	Club			
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	Cumulative Progress		58%	

Note: (*) extend as per requirement