Design and Development Atelier

B 99 Sushant Lok 1, Gurgaon Haryana 122002 India t: + 91 (0)124 4040076

w: www.dadapartners.com
e: contact@dadapartners.com

Annexure A

	Architect's Certificate*					
Repo	Report for quarter ending Q2 (FY 2022-23)					
Subje	ect		Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Godrej Meridien Phase-III			
	2.	Location	Sec 106, Gurugram, Haryana			
	3.	Licensed area in acres	14.793			
	4.	Area for registration in acres	5.06			
	5.	HARERA registration no.	RC/ REP/ HARERA/ GGM/ 393/125/2020 / 09			
	6.	Name of licensee	Godrej Real View Developers Private Limited			
	7.	Name of collaborator	Not Applicable			
	8.	Name of developer	Godrej Real View Developers Private Limited			
2.	Detai	ls related to inspection are as	under			
	1.	Date of certifying of percentage of construction work/ site inspection	01-Oct-2022			
	2.	Name of Architect/ Architect's firm	M/s DADA & Partners			
	3.	Date of site inspection	01-Oct-2022			

3.	Following technical professionals are appointed by promoter: - (as applicable)		
1	Sr. No.	Consultants	Name
	1.	Site engineer	GPL
	2.	Structural consultant	M/s BMSF & M/s PPS
	3.	Proof consultant	
	4.	MEP consultant	M/s PROION
	5.	Site supervisor/incharge	
4.	I certify that the work has been executed as per approved drawings, statutory/mandatory approvals, Haryana Building Code, 2017/National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Yours faithfully, Date : 14th October 2022

B99, Sushant Lok 1,

BLock C,SUshant Lok

Gurugram, Haryana

Council of architects (CoA)

registration no.

Place

Phase1, Sector 43,

122001

: CA/ 2000/25713

8.99, SUSHANT LOK-1 6 URG A O N-122002

ADITI ARORA

Signature & name (in block letters)

with stamp of architect

Council of architects (CoA) registration valid till (date)

: 12/2031

	Table – A					
(to build	be p	Tower no. repared separately for each tower in the project/ phase of t)	4 (2B+G+34)			
A1	Cum	ulative progress of the projec	t/phase at the er	nd of the quarter	r.	
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
1.	(incl foun	structure usive of excavation, dation, basements, water ofing, etc.)	0.81 Cr	6.01 Cr	100%	
2.	(slab	er structure os, brick work, block work, case, lift wells, machine ns, water tank, etc.)	2.72 Cr	2.72 Cr	11 %	
3.	МЕР	,				
	3.1	Mechanical (lifts, ventilation, etc.)	-	-		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-		
4.	Finis	shing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	-		
	4.2	External (plaster, painting, facade, etc.)	-	-		

Sr.		Tasks/ Activity		on of work		ge of total
No.		Sub-Structure Status	done		proposed work	
1.	Exca	vation			100%	
2.	Layii	ng of foundation			100%	
	(i)	Raft				
	(ii)	Pile			NA	
3.	Num	ber of basement(s) 2				
	(i)	Basement Level 1			100%	
	(ii)	Basement level 2*			100%	
4.		erproofing of the above sub- cture (wherever applicable)			100%	
		Super-Structure Status				
5.	Tota	l floors in the tower/building			34 excludi	ng Ground
6.	Tota	l area on each floor			805 Sq m	
7.	Stilt	floor/ ground floor			Ground Flo	oor
8.	Statu	is of laying of slabs floor wise				
	build	ulative number of slabs in the ling/towerlaid by of quarter			0	
9.	Statı	is of construction				
	(i)	Walls on floors			0%	
	(ii)	Staircase			0%	
	(iii)	Lift wells along with water proofing			0%	
	(iv)	Lift lobbies/ common areas floor wise			0%	
10.		g of door and window frames in / units			0%	
11.	Statu	us of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			0%	
	(ii)	Electrical works including wiring			0%	
	(iii)	Plumbing works			0%	
12.	Statu	us of wall plastering			0%	
	(i)	External plaster			0%	
	(ii)	Internal plaster			0%	

13.	Statu	us of wall tiling	
	(i)	In bathroom	0%
	(ii)	In kitchen	0%
14.	Statu	us of flooring	
	(i)	Common areas	0%
	(ii)	Units/ flats	0%
15.	Statu	is of white washing	
	(i)	Internal walls	0%
	(ii)	External walls	0%
16.	Statu	us of finishing	
	(i)	Staircase with railing	0%
	(ii)	Lift wells	0%
	(iii)	Lift lobbies/ common areas floor wise	0%
17.	Statu	us of installation	
	(with	nin flat/unit)	
	(i)	Doors and windows panels	0%
	(ii)	Sanitary fixtures	0%
	(iii)	Modular kitchen	0%
	(iv)	Electrical fittings/lighting	0%
	(v)	Gas piping (if any)	NA
	(othe	er than flat/units)	
	(vi)	Lifts installation	0%
	(vii)	Overhead tanks	0%
	(viii)	Underground water tank	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	0%
	(x)	Electrical fittings in common areas	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	100%
18.	Wate	erproofing of terraces	0%
19.	Entra	ance lobby finishing	0%
20.	Statu wall	us of construction of compound	0%

Note: (*) extend rows as per requirement.

	Table – A					
(to build	be p	Tower no. repared separately for each tower in the project/ phase of	5 (B+G+25)			
A1	Cum	ulative progress of the projec	t/phase at the en	d of the quarter		
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
5.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		1 Cr	3.23 Cr	100%	
6.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	-	-	
7.	МЕР	,				
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	-	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-	-	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	-	
8.	Fini	shing				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	-	-	
	4.2	External (plaster, painting, facade, etc.)	-	-	-	

Sr.	Tasks/ Activity		_	on of work		ge of total
No.		Sub-Structure Status	do	one	propos	ed work
21.	Exca	vation			-	
22.	Layir	ng of foundation				
	(iii)	Raft			100%	
	(iv)	Pile			NA	
23.	Num	ber of basement(s)				
	(iii)	Basement Level 1			0%	
	(iv)	Basement level 2*			NA	
24.		erproofing of the above sub- eture (wherever applicable)			100%	
		Super-Structure Status				
25.	Tota	l floors in the tower/building			25 excludi	ng Ground
26.	Tota	l area on each floor			714.72 Sq	m
27.	Stilt	floor/ ground floor			Ground Flo	oor
28.	Statu	is of laying of slabs floor wise			0	
	build	ulative number of slabs in the ling/ towerlaid by of quarter			0	
29.	Statu	is of construction				
	(v)	Walls on floors			-	
	(vi)	Staircase			-	
	(vii)	Lift wells along with water proofing			-	
	(viii)	Lift lobbies/ common areas floor wise			-	
30.		g of door and window frames in units			-	
31.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(iv)	Mechanical works			-	
	(v)	Electrical works including wiring			-	
	(vi)	Plumbing works			-	
32.	Statu	s of wall plastering				
	(iii)	External plaster			-	

	(iv)	Internal plaster	-
33.		us of wall tiling	
	(iii)	In bathroom	-
	(iv)	In kitchen	-
34.	Statu	us of flooring	
	(iii)	Common areas	-
	(iv)	Units/ flats	-
35.	Statı	is of white washing	
	(iii)	Internal walls	-
	(iv)	External walls	-
36.	Statu	us of finishing	
	(iv)	Staircase with railing	-
	(v)	Lift wells	-
	(vi)	Lift lobbies/ common areas	-
_	_	floor wise	
37.		us of installation	-
	_	hin flat/unit)	
	(xii)	Doors and windows panels	-
	(xiii)		-
	(xiv)		-
	(xv)	Electrical fittings/lighting	-
		Gas piping (if any)	NA
	_	er than flat/units)	
	_	Lifts installation	-
	_	Overhead tanks	-
	(xix)		-
	(xx)	Firefighting fitting and equipment's as per CFO NOC	-
	(xxi)	Electrical fittings in common areas	-
	(xxii	Compliance to conditions of environment/ CRZ NOC	100%
38.	Wate	erproofing of terraces	-
39.	Entr	ance lobby finishing	-
40.	Statı wall	us of construction of compound	-

	Table – A					
(to build	be p	Tower no. repared separately for each tower in the project/ phase of t)	6 (B+G+23)			
A1	Cum	nulative progress of the projec	t/phase at the en	d of the quarter.		
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
9.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0.78 Cr	3.13 Cr	100%	
10.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	-	-	
11.	MEP	•				
	3.1	Mechanical (lifts, ventilation, etc.)	-	-	-	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	-	-	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	-	-	
12.	Fini	shing				
	4.1	Internal	-	-	-	

		(plaster, tilling, flooring, painting, etc. within units and common areas)				
	4.2	External - (plaster, painting, facade, etc.)		-		-
Sr.		Tasks/ Activity	Description	on of work	Perc	entage of total
No.		Sub-Structure Status	_	ne	l l	oposed work
41.	Exca	avation			-	
42.	Lay	ing of foundation			-	
	(v)	Raft				
	(vi)	Pile			NA	
43.	Nun	nber of basement(s)				
	(v)	Basement Level 1			-	
	(vi)	Basement level 2*			NA	
44.		erproofing of the above sub- cture (wherever applicable)			-	
		Super-Structure Status				
45.	Tota	al floors in the tower/ building			23 ex	cluding Ground
46.	Tota	al area on each floor			699 9	Sq m
47.	Stilt	floor/ ground floor			Groui	nd Floor
48.	Stat	us of laying of slabs floor wise				
	buil	nulative number of slabs in the ding/towerlaid by of quarter				
49.	Stat	us of construction				
	(ix)	Walls on floors			-	
	(x)	Staircase			-	
	(xi)	Lift wells along with water proofing			-	
	(xii)	Lift lobbies/ common areas floor wise			-	
50.		ng of door and window frames in s/ units			-	
51.	Stat	us of MEP	Internal (within flat)	External works	Interi (with flat)	

	(vii) Mechanical works		-
	(viii) Electrical works including	5	-
	wiring		
	(ix) Plumbing works	-	-
52.	Status of wall plastering		-
	(v) External plaster	-	-
	(vi) Internal plaster	-	-
53.	Status of wall tiling		-
	(v) In bathroom		-
	(vi) In kitchen		-
54.	Status of flooring		
	(v) Common areas		-
	(vi) Units/flats		-
55.	Status of white washing		
	(v) Internal walls		-
	(vi) External walls		-
56.	Status of finishing		
	(vii) Staircase with railing		-
	(viii) Lift wells		-
	(ix) Lift lobbies/ common areas floor wise		-
57.	Status of installation		
	(within flat/unit)		
	(xxiii Doors and windows panels		-
	(xxiv Sanitary fixtures		-
	(xxv) Modular kitchen		-
	(xxvi Electrical fittings/ lighting		-
	(xxvi Gas piping (if any)		NA
	(other than flat/units)		
	(xxvi Lifts installation		-
	(xxix Overhead tanks		-
	(xxx) Underground water tank		-
	(xxxi Firefighting fitting and equipment's as per CFO NOC	l	-
	(xxxi Electrical fittings in common areas		-

Annexure A

	(xxxi	Compliance to conditions of environment/ CRZ NOC	100%
58.	Wate	erproofing of terraces	-
59.	Entrance lobby finishing		-
60.	Statu	s of construction of compound	-

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	-	
2.	Parking			
	Covered no	Yes	-	
	Open no	Yes	-	
3.	Water supply	Yes	-	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	-	
5.	Storm water drains	Yes	-	
6.	Landscaping & tree plantation	Yes	-	
7.	Parks and playgrounds	Yes	-	
	Fixing of children play equipment's	Yes	-	
	Benches	Yes	-	
8.	Shopping area	Yes	-	
9.	Street lighting/ electrification	Yes	-	
10.	Treatment and disposal of sewage and sullage water/STP	Yes	-	
11.	Solid waste management & disposal	Yes	-	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	-	
13.	Energy management (solar)	Yes	-	
14.	Fire protection and fire safety requirements	Yes	-	
15.	Electrical meter room, sub-station, receiving station	Yes	-	
16.	Other (option to add more)			
B-2	Community building to be transferred	to RWA		•
17.	Community centre	No	-	
18.	others			
В-3	Community buildings not to be transferred to RWA/competent authority			

19.	Schools	Yes	-	
20.	Dispensary			
21.	Club			
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	Cumulative Progress		15.2 %	

Note: (*) extend as per requirement