

# LINE OF FORCE Architects

F-3 FIRST FLOOR, SHARAN APARTMENTS, SOUTH CITY-1, GURGAON, HARYANA  
EMAIL : [lofarchitectsgurgaon@gmail.com](mailto:lofarchitectsgurgaon@gmail.com)

Annexure A

Architect's Certificate*		
Report for quarter ending	31.12.2023	
Subject	Certificate of progress of construction work	
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr. No.	Particulars	Information
1.	Project/Phase of the project	THE LEAF
2.	Location	VIII- Badha, Sector-85, Tehsil-Manesar, Gurugram
3.	Licensed area in acres	11.093
4.	Area for registration in acres	11.093
5.	HARERA registration No.	23 OF 2019
6.	Name of licensee	Shiva Profins Pvt. Ltd.,
7.	Name of collaborator	NA
8.	Name of developer	SS Group Pvt. Ltd.
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	02.01.2024
2.	Name of Architect/ Architect's firm	
3.	Date of site inspection	02.01.2024
3.	Following technical professionals are appointed by promoter: - (as applicable)	
Sr. No.	Consultants	Name
1.	Site engineer	Mr. Suman Kumar Chaubey
2.	Structural consultant	DESMAN
3.	Proof consultant	DESMAN
4.	MEP consultant	ASHOK GANGWAR (ARK Consultants)
5.	Site supervisor/in charge	Mr. Rajesh Pandey



Ar. KAPIL SINGH

B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31608

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.



Yours Faithfully

Ar. KAPIL SINGH

B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31608  
Signature & Name (in block letters)

With stamp of Architect

Date

Place

Council of Architects (CoA):

Registration No. CA/2003/31608

Council of Architects (CoA) :

Registration valid till (Date) 31<sup>st</sup> Dec 2031

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-T1		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	51	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	1402	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	Nil	303	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	Nil	114	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	Nil	204	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	Nil	647	100%
	4.2	External ( Plaster, Painting, Façade etc.)	Nil	193	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		Complete	100%
	(ii)	Pile		NA	NA
3	Number of Basements ....				
	(i)	Basement Level-1		Complete	100%
	(ii)	Basement Level-2		Complete	100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+25	100%
6	Total Area on each floor ( Sq.Mtr.)			425.192	100%
7	Stilt / Ground Floor			532.506	100%
	Status of Laying of slabs floor wise			Complete	100%

*Kapil Singh*

KAPIL SINGH  
B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608

8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	Complete	100%
9	<b>Status of Construction</b>		
	(i) Walls on floors	Complete	100%
	(ii) Staircase	Complete	100%
	(iii) Liftwells along with water proofing	Complete	100%
	(iv) Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units	Complete	100%
11	<b>Status of MEP</b>	Internal ( with in Flat)	External Work with in Flat)
	(i) Mechanical Works	Complete	100%
	(ii) Electrical work including wiring	Complete	100%
	(iii) Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>		
	(i) External Plaster	Complete	100%
	(ii) Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>		
	(i) In Bath Rooms	Complete	100%
	(ii) In Kitchen	Complete	
14	<b>Status of Flooring</b>		
	(i) Common Areas	Complete	100%
	(ii) Units/Flats	Complete	100%
15	<b>Status of White Washing</b>		
	(i) Internal Walls	Complete	100%
	(ii) External Walls	Complete	100%
16	<b>Status of Finishing</b>		
	(i) Staircase with Railing	Complete	100%
	(ii) Lift Wells	Complete	100%
	(iii) Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation</b>		
	<b>( within Flats/ Units)</b>		
	(i) Doors & Windows Panels	Complete	100%
	(ii) Sanitary Fixtures	Complete	100%
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>		
	(vi) Lift Installations	Complete	100%
	(vii) Over Head Tanks	Complete	100%
	(viii) Under Ground Water Tanks	NA	NA
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x) Electrical Fittings in Common Areas	Complete	100%
	(xi) Compliance to condition of environment/CRZ NOC	NA	NA
18	Water Proofing of Terraces	Complete	100%
19	Entrance Lobby Finishing	Complete	100%
20	Status of Construction of Compound wall	NA	NA


*KAPIL*

Ar. KAPIL SINGH  
B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31608



TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-T2		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	51	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	1402	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	Nil	303	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	Nil	114	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	Nil	204	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	Nil	647	100%
	4.2	External ( Plaster, Painting, Façade etc.)	Nil	193	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete		100%
	(ii)	Pile	NA		NA
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
	(ii)	Basement Level-2	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+25	100%
6	Total Area on each floor ( Sq.Mtr.)			425.192	100%
7	Stilt / Ground Floor			532.506	100%
	Status of Laying of slabs floor wise			Complete	100%


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608

8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	Complete	100%
9	<b>Status of Construction</b>		
	(i) Walls on floors	Complete	100%
	(ii) Staircase	Complete	100%
	(iii) Liftwells along with water proofing	Complete	100%
	(iv) Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units	In Progress	100%
11	<b>Status of MEP</b>	Internal ( with in Flat)	External Work Internal ( with in Flat) External Work
	(i) Mechanical Works	Complete	100%
	(ii) Electrical work including wiring	Complete	100%
	(iii) Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>		
	(i) External Plaster	Complete	100%
	(ii) Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>		
	(i) In Bath Rooms	Complete	100%
	(ii) In Kitchen	Complete	100%
14	<b>Status of Flooring</b>		
	(i) Common Areas	Complete	100%
	(ii) Units/Flats	Complete	100%
15	<b>Status of White Washing</b>		
	(i) Internal Walls	Complete	100%
	(ii) External Walls	Complete	100%
16	<b>Status of Finishing</b>		
	(i) Staircase with Railing	Complete	100%
	(ii) Lift Wells	Complete	100%
	(iii) Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation</b>		
	<b>( within Flats/ Units)</b>		
	(i) Doors & Windows Panels	Complete	100%
	(ii) Sanitary Fixtures	Complete	100%
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping ( if any)	NIL	NA
	<b>( other than Flats/ Units)</b>		
	(vi) Lift Installations	Complete	100%
	(vii) Over Head Tanks	Complete	100%
	(viii) Under Ground Water Tanks	NA	NA
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x) Electrical Fittings in Common Areas	NA	NA
	(xi) Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces	Complete	100%
19	Entrance Lobby Finishing	Complete	100%
20	Status of Construction of Compound wall	NA	NA



Ar. KAPIL SINGH  
B. Arch.

Regn. No. with Council  
of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-T3		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	51	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	1402	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	Nil	303	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	Nil	114	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	Nil	204	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	Nil	647	100%
	4.2	External ( Plaster, Painting, Façade etc.)	Nil	193	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation		Complete		100%
2	Laying of Foundation		Complete		100%
	(i)	Raft	Complete		100%
	(ii)	Pile	NA		NA
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
	(ii)	Basement Level-2	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)		Complete		100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building		S+25		100%
6	Total Area on each floor ( Sq.Mtr.)		425.192		100%
7	Stilt / Ground Floor		532.506		100%
	Status of Laying of slabs floor wise		Complete		100%


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2903/31608



8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	Complete	100%
9	<b>Status of Construction</b>		
	(i) Walls on floors	Complete	100%
	(ii) Staircase	Complete	100%
	(iii) Liftwells along with water proofing	Complete	100%
	(iv) Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units	Complete	100%
11	<b>Status of MEP</b>	Internal ( with in Flat)	External Work with in Flat)
	(i) Mechanical Works	Complete	100%
	(ii) Electrical work including wiring	Complete	100%
	(iii) Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>		
	(i) External Plaster	Complete	100%
	(ii) Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>		
	(i) In Bath Rooms	Complete	100%
	(ii) In Kitchen	Complete	100%
14	<b>Status of Flooring</b>		
	(i) Common Areas	Complete	100%
	(ii) Units/Flats	Complete	100%
15	<b>Status of White Washing</b>		
	(i) Internal Walls	NIL	NIL
	(ii) External Walls	Complete	100%
16	<b>Status of Finishing</b>		
	(i) Staircase with Railing	Complete	100%
	(ii) Lift Wells	Complete	100%
	(iii) Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation</b>		
	<b>( within Flats/ Units)</b>		
	(i) Doors & Windows Panels	Complete	100%
	(ii) Sanitary Fixtures	Complete	100%
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>		
	(vi) Lift Installations	Complete	100%
	(vii) Over Head Tanks	Complete	100%
	(viii) Under Ground Water Tanks	NA	NA
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	NA	NA
	(x) Electrical Fittings in Common Areas	Complete	100%
	(xi) Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces	Complete	100%
19	Entrance Lobby Finishing	Complete	100%
20	Status of Construction of Compound wall	NA	NA

*K. Singh*


Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31608



TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B1		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	32	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	585	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	129	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	48	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	87	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	275	100%
	4.2	External ( Plaster, Painting, Façade etc.)	0	82	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete		100%
	(ii)	Pile	NA		NA
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
	(ii)	Basement Level-2	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+14	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-302.85 ,LPH-227.46, UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608

8	<b>Status of Laying of slabs floor wise</b>		Complete		100%	
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete		100%	
9	<b>Status of Construction</b>					
	(i)	Walls on floors	Complete		100%	
	(ii)	Staircase	Complete		100%	
	(iii)	Liftwells along with water proofing	Complete		100%	
	(iv)	Lift Lobbies/Common areas floor wise	Complete		100%	
10	Fixing of Door & window frames in the Flats/Units		Complete		100%	
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work	Internal ( with in Flat)	External Work
	(i)	Mechanical Works	Complete		100%	
	(ii)	Electrical work including wiring	Complete		100%	
	(iii)	Plumbing work	Complete		100%	
12	<b>Status of Wall Plastering</b>					
	(i)	External Plaster	Complete		100%	
	(ii)	Internal Plaster	Complete		100%	
13	<b>Status of Wall Tiling</b>					
	(i)	In Bath Rooms	Complete		100%	
	(ii)	In Kitchen	Complete		100%	
14	<b>Status of Flooring</b>					
	(i)	Common Areas	Complete		100%	
	(ii)	Units/Flats	Complete		100%	
15	<b>Status of White Washing</b>					
	(i)	Internal Walls	Complete		100%	
	(ii)	External Walls	Complete		100%	
16	<b>Status of Finishing</b>					
	(i)	Staircase with Railing	Complete		100%	
	(ii)	Lift Wells	Complete		100%	
	(iii)	Lift Lobbies/Common areas floor wise	Complete		100%	
17	<b>Status of installation</b>					
	<b>( within Flats/ Units)</b>					
	(i)	Doors & Windows Panels	Complete		100%	
	(ii)	Sanitary Fixtures	Complete		100%	
	(iii)	Modular Kitchen	NA		NA	
	(iv)	Electrical Fittings/ Lightings	NA		NA	
	(v)	Gas Piping ( if any)	NA		NA	
	<b>( other than Flats/ Units)</b>					
	(vi)	Lift Installations	Complete		100%	
	(vii)	Over Head Tanks	Complete		100%	
	(viii)	Under Ground Water Tanks	NA		NA	
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL		NIL	
	(x)	Electrical Fittings in Common Areas	Complete		100%	
	(xi)	Compliance to condition of environment/CRZ NOC	Complete		100%	
18	Water Proofing of Terraces		Complete		100%	
19	Entrance Lobby Finishing		Complete		100%	
20	Status of Construction of Compound wall		NA		NA	




**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B2		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		0	32	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		0	585	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	129	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	48	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	87	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	275	100%
	4.2	External ( Plaster, Painting, Façade etc.)	0	82	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete		100%
	(ii)	Pile	NA		NA
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
	(ii)	Basement Level-2	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+14	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-302.85 ,LPH-227.46, UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%


 Ar. KAPIL SINGH  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/3160#



8	<b>Status of Laying of slabs floor wise</b>		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	<b>Status of Construction</b>			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	<b>Status of Flooring</b>			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	<b>Status of White Washing</b>			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	<b>Status of Finishing</b>			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of Installation</b>			
	<b>( within Flats/ Units)</b>			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B3		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	36	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	559	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	124	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	46	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	84	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	265	100%
	4.2	External ( Plaster, Painting, Façade etc.)	0	79	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete		100%
	(ii)	Pile	NA		NA
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+12	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-340.98 .LPH-310.06., UPH-263.96	100%
7	Stilt / Ground Floor			375.12	100%


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608

8	<b>Status of Laying of slabs floor wise</b>		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	<b>Status of Construction</b>			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	<b>Status of Flooring</b>			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	<b>Status of White Washing</b>			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	<b>Status of Finishing</b>			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation ( within Flats/ Units)</b>			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608



TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B4		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	36	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	559	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	124	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	46	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	84	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	265	100%
	4.2	External ( Plaster, Painting, Façade etc.)	0	79	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete		100%
	(ii)	Pile	NA		NA
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+12	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-340.98 .LPH-310.06., UPH-263.96	100%
7	Stilt / Ground Floor			375.12	100%


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31602

8	<b>Status of Laying of slabs floor wise</b>		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	<b>Status of Construction</b>			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work Internal ( with in Flat)
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	<b>Status of Flooring</b>			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	<b>Status of White Washing</b>			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	<b>Status of Finishing</b>			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation</b>			
	<b>( within Flats/ Units)</b>			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B5		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure { inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	36	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	559	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	124	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	46	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	84	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	265	100%
	4.2	External ( Plaster, Painting, Façade etc.)	0	79	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete	100%	
	(ii)	Pile	NA	NA	
3	Number of Basements ....				
	(i)	Basement Level-1	Complete	100%	
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+12	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-340.98 .LPH-310.06,, UPH-263.96	100%
7	Stilt / Ground Floor			375.12	100%

*Kapil*

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council  
of Architecture CA/2003/31609



8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal ( with in Flat)	External Work Internal ( with in Flat)
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of Installation			
	( within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	IN Progress	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	( other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA



**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B6		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	36	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	559	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	124	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	46	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	84	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	265	100%
	4.2	External ( Plaster, Painting, Façade etc.)	0	79	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete		100%
	(ii)	Pile	NA		NA
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+12	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-340.98 .LPH-310.06., UPH-263.96	100%
7	Stilt / Ground Floor			375.12	100%



**At: KAPIL SINGH**  
 B. Arch.  
 Regd. No. with Council  
 of Architecture CA/2003/31608

8	Status of Laying of slabs floor wise		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	Status of Construction			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	Status of MEP		Internal ( with in Flat)	External Work Internal ( with in Flat)
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	Status of Wall Plastering			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	Status of Wall Tiling			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	Status of Flooring			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	Status of White Washing			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	Status of Finishing			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	Status of installation			
	( within Flats/ Units)			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	( other than Flats/ Units)			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA

 **KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608



TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B7		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	32	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	657	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	144	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	53	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	97	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	307	100%
	4.2	External ( Plaster, Painting, Façade etc.)	0	91	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete		100%
	(ii)	Pile	NA		NA
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+16	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-302.85,LPH-227.46 , UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

8	<b>Status of Laying of slabs floor wise</b>		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	<b>Status of Construction</b>			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	<b>Status of Flooring</b>			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	<b>Status of White Washing</b>			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	<b>Status of Finishing</b>			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation</b>			
	<b>( within Flats/ Units)</b>			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B8		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	32	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	657	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	144	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	54	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	97	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	307	100%
	4.2	External ( Plaster, Painting, Façade etc.)	0	91	
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete		100%
	(ii)	Pile	NA		NA
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+16	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-302.85,LPH-227.46 , UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608



8	<b>Status of Laying of slabs floor wise</b>		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	<b>Status of Construction</b>			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	0%
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work Internal ( with in Flat) External Work
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	<b>Status of Flooring</b>			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	<b>Status of White Washing</b>			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	<b>Status of Finishing</b>			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation ( within Flats/ Units)</b>			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA




**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B9		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lac)	Cumulative Work done value till Date ( In Cr)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	32	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	657	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	144	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	54	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	97	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	307	100%
	4.2	External ( Plaster, Painting, Façade etc.)	0	91	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete	100%	
	(ii)	Pile	NA	NA	
3	Number of Basements ....				
	(i)	Basement Level-1	Complete	100%	
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+16	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-302.85,LPH-227.46 , UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%

 Ar. KAPIL SINGH  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

8	<b>Status of Laying of slabs floor wise</b>		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	<b>Status of Construction</b>			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	<b>Status of Flooring</b>			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	<b>Status of White Washing</b>			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	<b>Status of Finishing</b>			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation</b>			
	<b>( within Flats/ Units)</b>			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA



**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31609




TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER-B10		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( In Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	32	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	657	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	Nil	144	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	Nil	54	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	Nil	97	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	Nil	307	100%
	4.2	External ( Plaster, Painting, Façade etc.)	Nil	91	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	Complete	100%	
	(ii)	Pile	NA	NA	
3	Number of Basements ....				
	(i)	Basement Level-1	Complete	100%	
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+16	100%
6	Total Area on each floor ( Sq.Mtr.)			Typ.Floor-302.85,LPH-227.46 , UPH-214.44	100%
7	Stilt / Ground Floor			341.73	100%

 Ar. KAPIL SINGH  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608

8	<b>Status of Laying of slabs floor wise</b>		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	<b>Status of Construction</b>			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		Complete	100%
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	<b>Status of Flooring</b>			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	<b>Status of White Washing</b>			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	<b>Status of Finishing</b>			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation ( within Flats/ Units)</b>			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	NIL	NIL
	(x)	Electrical Fittings in Common Areas	NIL	NIL
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			TOWER- EWS		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	40	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	155	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	Nil	8	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	Nil	15	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	Nil	27	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	Nil	87	100%
	4.2	External ( Plaster, Painting, Façade etc.)	Nil	26	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	NA		NA
	(ii)	Pile	NA		NA
3	Number of Basements ....NA				
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			S+9	100%
6	Total Area on each floor ( Sq.Mtr.)			G.F-266.190,1st to 3rd-322.75,4th to 6th-	100%
7	Stilt / Ground Floor			266.19	100%


**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608



8	<b>Status of Laying of slabs floor wise</b>		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	<b>Status of Construction</b>			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		NIL	NIL
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work
	(i)	Mechanical Works	NIL	NIL
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	<b>Status of Flooring</b>			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	NIL	NIL
15	<b>Status of White Washing</b>			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	<b>Status of Finishing</b>			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation ( within Flats/ Units)</b>			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	Complete	100%
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	Complete	100%
	(x)	Electrical Fittings in Common Areas	Complete	100%
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NIL	NIL


 Ar. KAPIL SINGH  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			COMMUNITY BUILDING		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	21	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	66	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	Nil	19	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	Nil	7	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	Nil	12	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	Nil	34	100%
	4.2	External ( Plaster, Painting, Façade etc.)	Nil	12	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft	NA	NA	
	(ii)	Pile	NA	NA	
3	Number of Basements ....				
	(i)	Basement Level-1	Complete		100%
	(ii)	Basement Level-2	Complete		100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			G+1	100%
6	Total Area on each floor ( Sq.Mtr.)			GF=716.26 F.F=198.900	100%
7	Stilt / Ground Floor			716.26	100%


 At: KAPIL, SINGH  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31602

8	<b>Status of Laying of slabs floor wise</b>		Complete	100%
	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter		Complete	100%
9	<b>Status of Construction</b>			
	(i)	Walls on floors	Complete	100%
	(ii)	Staircase	Complete	100%
	(iii)	Liftwells along with water proofing	Complete	100%
	(iv)	Lift Lobbies/Common areas floor wise	Complete	100%
10	Fixing of Door & window frames in the Flats/Units		NIL	NIL
11	<b>Status of MEP</b>		Internal ( with in Flat)	External Work
	(i)	Mechanical Works	Complete	100%
	(ii)	Electrical work including wiring	Complete	100%
	(iii)	Plumbing work	Complete	100%
12	<b>Status of Wall Plastering</b>			
	(i)	External Plaster	Complete	100%
	(ii)	Internal Plaster	Complete	100%
13	<b>Status of Wall Tiling</b>			
	(i)	In Bath Rooms	Complete	100%
	(ii)	In Kitchen	Complete	100%
14	<b>Status of Flooring</b>			
	(i)	Common Areas	Complete	100%
	(ii)	Units/Flats	Complete	100%
15	<b>Status of White Washing</b>			
	(i)	Internal Walls	Complete	100%
	(ii)	External Walls	Complete	100%
16	<b>Status of Finishing</b>			
	(i)	Staircase with Railing	Complete	100%
	(ii)	Lift Wells	Complete	100%
	(iii)	Lift Lobbies/Common areas floor wise	Complete	100%
17	<b>Status of installation</b>			
	<b>( within Flats/ Units)</b>			
	(i)	Doors & Windows Panels	Complete	100%
	(ii)	Sanitary Fixtures	Complete	100%
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	Complete	100%
	(v)	Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>			
	(vi)	Lift Installations	Complete	100%
	(vii)	Over Head Tanks	NA	NA
	(viii)	Under Ground Water Tanks	NA	NA
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	Complete	100%
	(x)	Electrical Fittings in Common Areas	Complete	100%
	(xi)	Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces		Complete	100%
19	Entrance Lobby Finishing		Complete	100%
20	Status of Construction of Compound wall		NA	NA



**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No with Council  
 of Architecture CA/2003/31608



TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			NURSERY SCHOOL		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		0	25	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		0	85	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	0	1	100%
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	0	8	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	0	14	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	0	38	100%
	4.2	External ( Plaster, Painting, Façade etc.)	Nil	13	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			NIL	NIL
	(i)	Raft		NA	NA
	(ii)	Pile		NA	NA
3	Number of Basements ....01			Complete	100%
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			NIL	NIL
	Super-Structure Status				
5	Total Floors in the Tower/ Building			G+2	100%
6	Total Area on each floor ( Sq.Mtr.)			524.54	100%
7	Stilt / Ground Floor			271.27	100%
	Status of Laying of slabs floor wise			NIL	NIL



**Ar. KAPIL SINGH**  
 B. Arch.  
 Regs. No with Council  
 of Architects CA/2003/31602

8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	Complete	100%
9	<b>Status of Construction</b>		
	(i) Walls on floors	Complete	100%
	(ii) Staircase	Complete	100%
	(iii) Liftwells along with water proofing	NA	NIL
	(iv) Lift Lobbies/Common areas floor wise	NA	NIL
10	Fixing of Door & window frames in the Flats/Units	NIL	NIL
11	<b>Status of MEP</b>	Internal ( with in Flat)	External Work
	(i) Mechanical Works	In Progress	100%
	(ii) Electrical work including wiring	In Progress	100%
	(iii) Plumbing work	In Progress	100%
12	<b>Status of Wall Plastering</b>		
	(i) External Plaster	NIL	NIL
	(ii) Internal Plaster	NIL	NIL
13	<b>Status of Wall Tiling</b>		
	(i) In Bath Rooms	NIL	NIL
	(ii) In Kitchen	NIL	NIL
14	<b>Status of Flooring</b>		
	(i) Common Areas	NIL	NIL
	(ii) Units/Flats	NIL	NIL
15	<b>Status of White Washing</b>		
	(i) Internal Walls	NIL	NIL
	(ii) External Walls	NIL	NIL
16	<b>Status of Finishing</b>		
	(i) Staircase with Railing	Complete	100%
	(ii) Lift Wells	NA	NA
	(iii) Lift Lobbies/Common areas floor wise	NA	NA
17	<b>Status of installation</b>		
	<b>( within Flats/ Units)</b>		
	(i) Doors & Windows Panels	NA	NA
	(ii) Sanitary Fixtures	NA	NA
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>		
	(vi) Lift Installations	NA	NA
	(vii) Over Head Tanks	Complete	100%
	(viii) Under Ground Water Tanks	Complete	100%
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	Complete	100%
	(x) Electrical Fittings in Common Areas	Complete	100%
	(xi) Compliance to condition of environment/CRZ NOC	NA	NA
18	Water Proofing of Terraces	Complete	100%
19	Entrance Lobby Finishing	NIL	NIL
20	Status of Construction of Compound wall	Complete	10%

*Kapil Singh*

KAPIL SINGH  
B. Arch.  
Regn. No with Council  
of Architecture CA/2003/31608

TABLE-A					
Building No/Tower No. ( To be prepared seperately for each buildings/Tower in the project/phase of the project)			CONVENIENT SHOPPING		
A1	Cumulative Progress of the Project/Phase at the end of the Quarter				
Sr.No	Project Components		Work done value during the Quarter(In Lakh)	Cumulative Work done value till Date ( in Lakh)	Percentage of work done to the total proposed work
1	Sub Structure ( inclusive of excavation,Foundation,Basement, Water Proofing etc.)		Nil	6	100%
2	Super Structure ( Slab, Block work, Brick Work, Staircase, Lift wells ,Machine Rooms,Water Tank etc.)		Nil	12	100%
3	MEP				
	3.1	Mechanical ( Lifts, Ventilation etc.)	Nil	2	NA
	3.2	Electrical ( Conduiting,Wiring,Fixtures etc.)	Nil	1	100%
	3.3	Plumbing & Fire Fighting (Piping,Pumps & Pump Room Fixtures etc.)	Nil	3	100%
4	FINISHING				
	4.1	Internal ( Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	Nil	0.70	100%
	4.2	External ( Plaster, Painting, Façade etc.)	Nil	0.18	100%
Sr.No.	Tasks/ Activity			Description of Work Done	Percentage of total proposed work
	Sub-Structure Status				
1	Excavation			Complete	100%
2	Laying of Foundation			Complete	100%
	(i)	Raft		NA	NA
	(ii)	Pile		NA	NA
3	Number of Basements ....NA				
4	Water Proofing of the Above Sub-Structure ( wherever applicable)			Complete	100%
	Super-Structure Status				
5	Total Floors in the Tower/ Building			GROUND	100%
6	Total Area on each floor ( Sq.Mtr.)			188.57	100%
7	Stilt / Ground Floor			188.57	100%
	Status of Laying of slabs floor wise			NA	NA

 Ar. KAPIL SINGH  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608



8	Cumulative number of the slabs in the Building/Tower...Laid by end of the quarter	NA	NA
9	<b>Status of Construction</b>		
	(i) Walls on floors	COMPLETE	100%
	(ii) Staircase	NA	NA
	(iii) Liftwells along with water proofing	NIL	NA
	(iv) Lift Lobbies/Common areas floor wise	NA	NA
10	Fixing of Door & window frames in the Flats/Units	NA	NA
11	<b>Status of MEP</b>	Internal ( with in Flat)	External Work Internal ( with in Flat)
	(i) Mechanical Works	NIL	NA
	(ii) Electrical work including wiring	COMPLETE	100%
	(iii) Plumbing work	COMPLETE	100%
12	<b>Status of Wall Plastering</b>		
	(i) External Plaster	COMPLETE	100%
	(ii) Internal Plaster	COMPLETE	100%
13	<b>Status of Wall Tiling</b>		
	(i) In Bath Rooms	COMPLETE	100%
	(ii) In Kitchen	NA	NA
14	<b>Status of Flooring</b>		
	(i) Common Areas	COMPLETE	100%
	(ii) Units/Flats	COMPLETE	100%
15	<b>Status of White Washing</b>		
	(i) Internal Walls	COMPLETE	100%
	(ii) External Walls	COMPLETE	100%
16	<b>Status of Finishing</b>		
	(i) Staircase with Railing	NA	NA
	(ii) Lift Wells	NA	NA
	(iii) Lift Lobbies/Common areas floor wise	NA	NA
17	<b>Status of installation</b>		
	<b>( within Flats/ Units)</b>		
	(i) Doors & Windows Panels	Complete	100%
	(ii) Sanitary Fixtures	COMPLETE	100%
	(iii) Modular Kitchen	NA	NA
	(iv) Electrical Fittings/ Lightings	NA	NA
	(v) Gas Piping ( if any)	NA	NA
	<b>( other than Flats/ Units)</b>		
	(vi) Lift Installations	NA	NA
	(vii) Over Head Tanks	NA	NA
	(viii) Under Ground Water Tanks	NA	NA
	(ix) Fire Fighting Equipments & Fittings as per CFO NOC	COMPLETE	100%
	(x) Electrical Fittings in Common Areas	NA	NA
	(xi) Compliance to condition of environment/CRZ NOC	Complete	100%
18	Water Proofing of Terraces	Complete	100%
19	Entrance Lobby Finishing	NA	NA
20	Status of Construction of Compound wall	NA	NA



**Ar. KAPIL SINGH**  
 B. Arch.  
 Regn. No. with Council  
 of Architecture CA/2003/31608

TABLE-B ( Leaf-Dect-2023 )

Sr.No	Common Areas and Facilities Amenities	Proposed ( Yes/No)	Percentage of work done	Remarks
<b>B-1</b>	<b>Services</b>			
1	Internal Roads & Pavements	Yes	100%	
	Parkings			
2	Covered.....1005 Nos	Yes	100%	
	Open Nos....235	Yes	100%	
3	Water Supply	Yes	100%	
4	Sewarage ( Chambers,Lines,STP,Septic Tanks)	Yes	100%	
5	Storm Water Drains	Yes	100%	
6	Landscaping & Tree Plantations	Yes	100%	
	Parks & Playgrounds	Yes	100%	
7	Fixing of Children Play Equipments	Yes	100%	
	Benches	Yes	100%	
8	Shopping Areas	Yes	100%	
9	Street Lighting/Electrification	Yes	100%	
10	Treatment & Disposal of Sewage & Sludge water/STP	Yes	100%	
11	Solid waste Management & Disposal	Yes	100%	
12	Water Conservation,Rain water Harvesting,Percolating Well/Pit	Yes	100%	
13	Energy Management ( Solar)	Yes	100%	
14	Fire Protection & Fire safety Equipments	Yes	100%	
15	Electrical Meter Room,Sub-Station,Receiving Station	Yes	98%	
16	Under Ground Water Tank	Yes	100%	
<b>B-2</b>	<b>Community Building to be Transferred to RWA</b>			
17	Community Center	NA	NA	
18	Others.	NA	NA	
<b>B-2</b>	<b>Community Building not to be Transferred to RWA/Competent Authority</b>			
19	School	YES	100%	
20	Dispensary	NA	NA	
21	Club/Community Building	YES	100%	
22	Others.	NA	NA	
<b>B-3</b>	<b>Services/ Facilities to be Transferred to Competent Authority</b>			



Ar. KAPIL SINGH

B. Arch.

Rega. No. with Council  
of Architecture CA/2003/31608