		Architect's	s Certificate¹		
Repo	rt for q	uarter ending	31-12-2020		
Subje	ect		Certificate of progress of construction work		
1.	I/We const	have undertaken assignme ruction work in the below me	ent as architect for certifying progress of entioned project as per the approved plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	Conscient One		
	2. Location		Sector-109, Gurugram, Haryana		
	3.	Licensed area in acres	8.393 Acres		
	4.	Area for registration in acres	3.138 Acres		
	5. HARERA registration no.6. Name of licensee		RC/REP/HARERA/GGM/308/40/2019/0 /Dated-16-01-2019		
			M/S Shrimaya Buildcon Pvt. Ltd. And Others		
	7.	Name of collaborator	M/S Shrimaya Buildcon Pvt. Ltd.		
	8.	Name of developer	Conscient Infrastructure Private Limited		
2.	Detai	ils related to inspection are as	under		
	Date of certifying of percentage of construction work/ site inspection		31.12.2020		
	2.	Name of Architect/ Architect's firm	Ashwin Alva Associates		
	3.	Date of site inspection	29.12.2020		

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delhi-62,Ph //Fax 011 29555054,011 29555098 email: admin@alva.co.in

3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. Consultants Name		Name		
	1. Site engineer Sharad Chandra		Sharad Chandra		
	2.	Structural consultant	Civtech Consultant Pvt. Ltd.		
	3.	Proof consultant	Mehro Consultants		
	4.	MEP consultant	Plumbing & Fire Fighting- Soni Consultants, Electrical Consultant-Kanwar Krishen Associates Pvt Ltd		
	5.	Site supervisor/incharge	Naveen Sharma		
4.	I certify that the work has been executed as per approved drawings, statutory/mandatory approvals, Haryana Building Code, 2017/National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.				
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.				

Date : Yours faithfully,

Place Signature & name (in block letters) with stamp of architect

Council of architects (CoA) : registration no.

Council of architects (CoA) registration valid till (date)

31/12/2026

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delhi-62, Philifar all 20555054 011 29555098 email: admin@alva.co.in

		Ta	able – A						
(to build	be p	Tower no. repared separately for each tower in the project/ phase of			1 Nos				
A1	Cum	Cumulative progress of the project/phase at the end of the quarter.							
Sr. No.	Project components		Work done value during the quarter (In Lacs)	Cumulative work done value till date (in Lacs)	Percentage of work done to the total proposed work				
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0.0	1621.8	100%				
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		250.0	3300.9	100%				
3.	МЕР	•							
	3.1	Mechanical (lifts, ventilation, etc.)	0.0	1094.1	100%				
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	12.5	1124.6	77%				
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	15.7	1027.0	76%				
4.	Fini	shing							
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	398.1	2100.5	60%				
	4.2	External (plaster, painting, facade, etc.)	100.0	1721.8	100%				

SHOBHNA BATRA CA/2005/35496

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delni-bainithae 1 . or 5054 011 27:555098 email admin@alva.co.in

Sr.	Tasks/ Activity Sub-Structure Status		Description of work done		Percentage of total	
No.			dor	16	proposed work	
1.	Exca	vation	Completed		100	
2.	Laying of foundation					100
	(i)	Raft	(Completed	,	100%
#	(ii)	Pile				-10-
3.	Num	ber of basement(s) 3				
	(i)	Basement Level 1	(Completed		100%
	(ii)	Basement level 2	(Completed		100%
	(iii)	Basement level 3	(Completed		100%
4.	1	erproofing of the above sub- cture (wherever applicable)	(Completed		100%
		Super-Structure Status				
5.	Tota	l floors in the tower/ building		G+10		
6.	Tota	l area on each floor	FAR=2 6260. Service A FAR=10	mmercial 79.602 to 212 Sqm. Apartment 41.907 to .663 Sqm		
7.	Stilt	floor/ ground floor	(Completed	100	
8.	Statı	us of laying of slabs floor wise	Completed			1009
	build	ulative number of slabs in the ling/tower11 laid by of quarter			2	
9.	Statı	us of construction	-379			
	(i)	Walls on floors	(Completed		1009
	(ii)	Staircase	(Completed		1009
	(iii)	Lift wells along with water proofing	(Completed		1009
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	1	ng of door and window frames in / units	In Progress			959
11.	Statı	us of MEP	Internal (within flat)	External works	Internal (within flat)	Externa work
	(i)	Mechanical works	(Completed		1009
	(ii)	Electrical works including wiring		ASSOCI		969

N-93. South Avenue Sainik Farm, New Delhi-oz, rohan in 25-5054-011 29555098 email: admin@alva.co.in

	(iii)	Plumbing works	In Progress	97%		
12.	Statu	1 0, ,				
	(i)	External plaster/Façade Glazing	Completed	100%		
	(ii)	Internal plaster	In Progress	96%		
13.	Statu	is of wall tiling				
	(i)	In bathroom	In Progress	90%		
	(ii)	In kitchen	NA			
14.	Statu	is of flooring				
	(i)	Common areas	In Progress	90%		
	(ii)	Units/ flats	NA			
15.	Statu	ıs of white washing				
	(i)	Internal walls	In Progress	95%		
	(ii)	External walls	NA			
16.	Status of finishing					
	(i)	Staircase with railing	Completed	100%		
	(ii)	Lift wells	Completed	100%		
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%		
17.	Statu	ıs of installation		10.20		
	(with	nin flat/unit)				
	(i)	Doors and windows panels	In Progress	95%		
	(ii)	Sanitary fixtures	In Progress	90%		
	(iii)	Modular kitchen – Only in Service apartment	In Progress	25%		
	(iv)	Electrical fittings/ lighting	In Progress	85%		
	(v)	Gas piping (if any)	In Progress	90%		
	(oth	er than flat/units)		-		
	(vi)	Lifts installation	Completed	100%		
	(vii)	Overhead tanks	Completed	100%		
	(viii)	Underground water tank	Completed	100%		
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%		
	(x)	Electrical fittings in common areas	Completed	100%		
	(xi)	Compliance to conditions of environment/ CRZ NOC				
18.	Wate	erproofing of terraces	Completed	100%		

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delhi-62, Fh/Fax 611 2555054 011 29-55098 email: admin@alva.co.in

19.	Entrance lobby finishing	Completed	100%
20.	Status of construction of compound wall	Completed	100%

Note: (*) extend rows as per requirement.

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			
	Covered no 513	Yes	100%	
	Open no	No		
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	No		
	Fixing of children play equipment's	No		
	Benches	Yes	100%	
8.	Shopping area	No		
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)	NA	NA	
B-2	Community building to be transferred to	RWA		
17.	Community centre	NA		
18.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			

ASHWIN ALVA ASSOCIATES

N-93, South Avenue Sainik Farm, New Delhi-62,Phi/Fax 2012 555054 011 29555098 email: admin@alva.co.in

19.	Schools	NA	
20.	Dispensary	NA	
21.	Club	NA	
22.	Others	NA	
B-4	Services/ facilities to be transferred to competent authority		
23.	*		

Note: (*) extend as per requirement

SHOBHNA BATRA CA/2005/35496

ASHWIN ALVA ASSOCIATES

N-93. South Avenue Sainik Farm, New Delhi-ōz, Frifa 913 2955054 011 2955098 email: admin@alva.co.in