INDIVALUE ADVISORS PRIVATE LIMITED



Regd. Address: B1/H3, MOHAN CO-OPERATIVE INDUSTRIAL AREA MATHURA RD, BLOCK B NEW DELHI 110044

Email: Indivalueadvisors@gmail.com Mobile +91-7044091174

CIN: U74999DL2021PTC381050

IVAPL/03/012024/ SUSHANT CITY KARNAL 71.01 Acres

| | | Archite | ect's Certificate" | | |
|-----|--|---|---|--|--|
| _ | | Aicht | - Continuate | | |
| Rep | ort for | r quarter ending | Jan to March' 2024 | | |
| Sub | ject | | Certificate of percentage of completion of construction work of the project at the end of the quarter: | | |
| 1. | cons | engineer for certifying percentage of completion of ned project as per the approved plans and approved roof consultant. | | | |
| | Sr. No. | Particulars | Information | | |
| | 1. | Project/phase of the project | SUSHANT CITY (PLOTTED COLONY AREA 71.01 ACRES RESIDENTIAL) | | |
| | 2. | Location | Sector 36, Karnal | | |
| | 3. | Licensed area in acres | 71.01 Acres | | |
| | 4. | Area for registration in acres | 71.01 Acres | | |
| | 5. | HARERA registration no. | 140 of 2017 dated 28.08.2017 | | |
| | 6. | Name of licensee | Wrangler Builders (P) Ltd., Ansal Landmark Township (P) Ltd., Geo Connect Ltd., Maestro Promoters (P) Ltd. & Others | | |
| | 7. | Name of collaborator | N/A | | |
| | 8. | Name of developer | Ansal Landmark (Karnal) Township Pvt. Ltd. | | |
| 2. | Details related to inspection are as under | | | | |
| | 1. | Date of certifying of percentage of construction work/ site inspection | 31.03.2024 | | |
| | 2. | Name of engineering firm/ individual | Ar. Ashish Sawe | | |
| | 3. | Date of site inspection | 31.03.2024 | | |



| 3. | Following technical professionals are appointed by promoter:-(as applicable) | | | | |
|----|--|--|-------------------------------|--|--|
| | Sr. No. | Consultants | Name | | |
| | 1. | Site engineer | Mr. P.N. Singh N/A N/A N/A | | |
| | 2. | Structural consultant Proof consultant MEP consultant | | | |
| | 3. | | | | |
| | 4. | | | | |
| | 5. | Site supervisor / in charge | N/A | | |
| 4. | appro the n are a | I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard. | | | |
| 5. | I also certify that as on the date, the percentage of work done in the project or each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and table B. | | | | |

Date: 31.03.2024

Issued without prejudice,

Name :- Ar. ASHISH SAWE

ASHISH

Stamp:

Place : Gurugram

Council of Architecture (CoA)

Registration no.

:_CA/2001/28463

(CoA)

Registration valid till (date)

: 31-12-2033

| | | | Table-A | | |
|------------|---|--|---------|--|---|
| (to b | e prep | ower no. pared separately for each building/ e project/ phase of the project) | | lotted colony | |
| A1 | Cumulative progress of the project/ phase at the end of the quarter. | | | | |
| Sr. No. | Proje | ect components | | valueCumulative v narter done value date | vorkPercentage of tillwork done to the total proposed work |
| 1. | (incl | structure usive of excavation, foundation, ments, water proofing, etc.) | N.A. | N.A. | N.A. |
| 2. | Superstructure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.) | | | N.A. | N.A. |
| 3. | MEP | | | | |
| | 3.1 | N.A. | N.A. | N.A. | N.A. |
| | 3.2 | N.A. | N.A. | N.A. | N.A. |
| | 3.3 | N.A. | N.A. | N.A. | |
| 4. | Finishing | | | | |
| | 4.1 | N.A. | N.A. | N.A. | N.A. |
| | 4.2 | N.A. | N.A. | N.A. | N.A. |



| Sr. | Tasks/Activity Sub-Structure Status | | Description of work done | Percentage of tota proposed work | |
|-----|--------------------------------------|--|---|--------------------------------------|--|
| No. | | | | | |
| 1. | Excavation N.A. | | N.A. | | |
| 2. | Layir | ng of foundation | | | |
| | (1) | N.A. | N.A. | N.A. | |
| | (ii) | N.A. | N.A. | | |
| 3. | Num | ber of basement(s) | | | |
| | (1) | N.A. | N.A. | N.A. | |
| | (11) | N.A. | N.A. | | |
| 4. | 10001-1 | rproofing of the above sub-structure rever applicable) | N.A. | N.A. | |
| | Supe | r-Structure Status | N.A. | N.A. | |
| 5. | Total | floors in the tower/building | N.A. | N.A. | |
| 6. | Total | area on eachfloor | N.A. | N.A. | |
| 7. | Stiltf | loor/ ground floor | N.A. | N.A. | |
| 8. | Status of laying of slabs floor wise | | N.A. | N.A. | |
| | - | ulative number of slabs in the ling/tower laid by end of ter | | | |
| 9. | Statu | s of construction | | | |
| | (i) | Walls on floors | N.A. | N.A. | |
| | (ii) | Staircase | N.A. | N.A. | |
| | (111) | Liftwells along with waterproofing | N.A. | N.A. | |
| | (iv) | Lift lobbies/common areas floor wise | N.A. | N.A. | |
| 10. | Fixin | g of door and window frames in flats/ | | | |
| 11. | Statu | s of MEP | Internal External (withinflat) works | Internal External (withinflat) works | |
| | (1) | Mechanical works | N.A. | N.A. | |
| | (ii) | Electrical works includingwiring | | | |
| | (111) | Plumbing works | | | |
| 12. | Statu | s of wall plastering | N.A. | N.A. | |
| | (i) | External plaster | | | |
| | (ii) | Internal plaster | | | |
| 13. | Statu | is of wall tiling | N.A. | N.A. | |
| | (i) | In bathroom | | | |

4 Page

IVAPL/03/012024/ SUSHANT CITY KARNAL 71.01 Acres

| 14. | (11) | In kitchen | | | |
|-----|-------|----------------|------|------|--|
| | Stati | as of flooring | N.A. | N.A. | |
| | (1) | Common areas | | | |
| | (ii) | Units/flats | | | |

| Sr. | Tasks/Activity Sub-Structure Status | | | Percentage of total | |
|-----|-------------------------------------|---|------|---------------------|--|
| No. | | | done | proposed work | |
| 15. | Statu | s of white washing | | | |
| | (i) | Internal walls | N.A. | N.A. | |
| | (11) | External walls | N.A. | N.A. | |
| 16. | Statu | s of finishing | | | |
| | (i) | Stair case with railing | N.A. | N.A. | |
| | (11) | Lift wells | N.A. | N.A. | |
| | (iii) | Lift lobbies/common areas floo wise | r | | |
| 17. | Statu | s of installation | | | |
| | (with | in flat/unit) | | | |
| | (i) | Doors and windowspanels | N.A. | N.A. | |
| | (11) | Sanitary fixtures | N.A. | N.A. | |
| | (iii) | Modular kitchen | N.A. | N.A. | |
| | (iv) | Electrical fittings/lighting | | | |
| | (v) | Gas piping(if any) | N.A. | N.A. | |
| | (othe | rthanflat/units) | N.A. | N.A. | |
| | (vi) | Lifts installation | | | |
| | (vii) | Overhead tanks | N.A. | N.A. | |
| | (viii) | Underground watertank | N.A. | N.A. | |
| | (ix) | Firefighting fitting and equipment' as per CFO NOC | S | | |
| | (x) | Electrical fittings in common areas | N.A. | N.A. | |
| | (xi) | Compliance to conditions of environment/ CRZ NOC | N.A. | N.A. | |
| 18. | Wate | r proofing of terraces | N.A. | N.A. | |
| 19. | Entra | nce lobby finishing | N.A. | N.A. | |
| 20. | Statu | s of construction of compound wall | N.A. | N.A. | |

Note:(*) extend rows as per requirement.



Table-B

| Sr. | aria inclinit | Proposed (Yes/No) | % of work done | Remarks |
|-----|--|----------------------|-------------------|--|
| B. | pavements | Yes | 78% | The specifications for the state was used revised with an increase in thickness. Furthermore, the top layer is being reconstructed due to old construction and subsequent damage. |
| 2. | Parking | | | ECS for 989 no of Plots and 2 Nursing home |
| | Covered no | | | G |
| | Open no | | | |
| 3. | Water supply | Yes | 53% | Additional Cost of Dual plumbing line. |
| 4. | Sewerage (chamber, lines, septic tanks, STP) | Yes | 30% | Enhanced Capacity due to recent approvals. |
| 5. | Storm water drains | Yes | 85% | Scope of work increased due to recent approvals. |
| 5. | Landscaping & tree plantation | | | and the supplications of the s |
| | Parks and play grounds | Yes | 58% | Parks already completed. Main Gate Cost included |
| | Fixing of children play equipment's | | | |
| | Benches | | | |
| | Shopping area | | | |
| | Street lighting | Yes | 100% | Repainting and repairing work due to old construction. |
| 0. | Treatment and disposal of sewage and sullage water/ STP | | | construction. |
| 1. | Solid waste management & disposal | | | |
| 2. | Water conservation, rainwater, harvesting, percolating well/ pit | 141 | | |



CA/2001/28463

Bod. Archite

| 13. | Energy management (solar) & Other Misc. Compliances | Yes | 38% | Will be installed in phases as per Guidelines |
|-----|--|------|------|--|
| 14. | Fire protection and fire safety requirements | | | |
| 15. | Electrification, Electrical meter room, sub-station, receiving station | Yes | 20% | Revalidation of Electrification Plan awaited |
| 16. | Other (Option to add More) | | | |
| B-2 | | | | |
| 17. | Community centre | N.A. | N.A. | N.A. |
| 18. | Others | | | |
| B-3 | Community buildings not to be transferred to RWA/competent authority | N.A. | N.A. | N.A. |
| 19. | Schools | N.A. | N.A. | N.A. |
| 20. | Dispensary | N.A. | N.A. | N.A. |
| 21. | Club | | | |
| 22. | Others | | | |
| B-4 | Services/facilities to be transferred to competent authority | N.A. | N.A. | N.A. |
| 23. | + | | | |

-----End Of Report-----