

INDIVALUE ADVISORS PRIVATE LIMITED

Regd. Address: 81/H3; MOHAN CO-OPERATIVE INDUSTRIAL AREA MATHURA RD, BLOCK B NEW DELHI 110044

Email: Indivatueadvisor:@amail.com Mobile +91-7044091174

CIN: U74999DL2021PTC381050

IVPL/01/012024/ELAN EPIC

		Architec	t's Certificate			
Repo	rt for q	uarter ending	Up to 31st March 2024			
Subje	ect		Certificate of progress of construction work			
1.			s architect for certifying progress of tioned project as per the approved plans			
	Sr. No.	Particulars	Information			
	I,	Project/Phase of the project	Elan EPIC			
	2.	Location	Sector 70, Gurugram			
	3.	Licensed area in acres	4 Acres			
	4.	Area for registration in acres	3.525 Acres			
	5,	HARERA registration No.	RC/REP/HARERA/GGM/2018/30 Dated: 6/12/2018			
	6.	Name of licensee	Elan Limited			
	7.	Name of collaborator	NA			
	8.	Name of developer	Elan Limited			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	5 th April 2024			
	2.	Name of Architect/Architect's firm	Ar. Ashish Sawe			
	3.	Date of site inspection	31st March 2024			
3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultan ts	Name			
	1.	Site engineer	Anil Kumar Gautam			
	2.	Structural consultant	Perceptive Idea			
	3.	Proof consultant	Isha Consultant (P) Ltd.			
	4.	MEP consultant	CP Vidya Associates, Dew point Consultants Pv Ltd., Ampower Consultancy Services.			
	5.	Site supervisor/incharge	Saurabh Gupta			



- 4. I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
- 5. Ialso certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date: 31.03.2024

Yours faithfully.

Name: - Ar. ASHISH SAWE

Po Archit

Stamp:

Place : Gurugram

Council of Architecture (CoA)

Registration no.

:_CA/2001/28463

(CoA)

Registration valid till (date)

: 31.12-2033

-		T:	able – A				
(tob	е ргера	/ Tower no. red separately for each building/ project/phase of the project)	ELAN EPIC (Entire project is	one building 4	04 Units)		
A1		mulative progress of the projec	t/phase at the en	ne end of the quarter. (In Lacs)			
Sr. No.	. Project components		Work done value during the quarter (Sqmt) Cumula work do value til date (Sq		e Percentage of work done to the total		
1.	(incl	usive of excavation, foundation, ments, water proofing, etc.)	-	20125	100%		
2.	Sup (slab	er structure as, brick work, block work, stair case, cells, machine rooms, water tank, etc.)		28695	100%		
3.	ME	P					
	3.1	Mechanical (lifts, ventilation, etc.)		28695	100%		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	-	28695	100%		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	28695	100%		
1.	Finishing		_				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)		28695	100%		
	4.2	External (plaster, painting, facade, etc.)	•	28695	100%		
r.	Tasks/ Activity		Descriptio		Percentage of total		
	Sub-Structure Status		don	e	proposed		
	Exca	vation Completed		ted	work 100%		
	Laying of foundation				- 0.00		
	(i) Raft		Completed		100%		
	(ii) Pile		Completed		100%		
	Num	ber of basement(s)					
	(i)	Basement Level 1	Comple SHISH 8	ted	100%		

Paga. Archite

(ii)	Basement level 2	Completed	100%

4.		erproofing of the above sub-structure erever applicable)	In Pro	ogress	98	3%	
		Super-Structure Status					
5.	Tota	al floors in the tower/ building	6		10	100%	
6.	Tota	d area on each floor	GF 64:	28.897	100	0%	
7.	Stilt	floor/ ground floor	Comp	oleted	100	0%	
8.	State	Status of laying of slabs floor wise		Completed		100%	
		ulative number of slabs in the building/ r laid by end of quarter	Comp	leted	100	0%	
9.	Statu	is of construction					
	(i)	Walls on floors	Completed		100	19 %	
	(ii)	Staircase	Completed		100%		
	(iii)	Lift wells along with water proofing	Completed		100%		
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%		
10.	Fixin units	g of door and window frames in flats/	NI	L	NI	L	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External	
	(i)	Mechanical works	Comp	leted	100	%	
	(ii)	Electrical works including wiring	Comp	leted	100	%	
	(iii)	Plumbing works	Completed		100%		
12.	Statu	s of wall plastering					
	(i)	External plaster	Completed		100%		
	(ii)	Internal plaster	Completed		100%		
13.	Status	s of wall tiling					
	(i)	In bathroom	In progress		95%		
	(ii)	In kitchen	NA		NA		
14.	Status	s of flooring					
	(i)	Common areas	In progress		90%		
	(ii)	Units/ flats	NA		NA		
5.	Status	of white washing					
	(i)	Internal walls	Completed		100%		
	(ii)	External walls	Completed		100%		
6.	Status	of finishing SHISH 8					

Fagd, Architec

41D vac

	(i)	Staircase with railing	Completed	100%		
	(ii)	Lift wells	Completed	100%		
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%		
17.	Status of installation					
	(within flat/unit)					
	(i)	Doors and windows panels	Completed	100%		
	(ii)	Sanitary fixtures	Completed	100%		
	(iii)	Modular kitchen	NA	NA		
	(iv)	Electrical fittings/ lighting	Completed	100%		
	(v)	Gas piping (if any)	NA	NA		
	(other	than flat/units)				
	(vi)	Lifts installation	Completed	100%		
	(vii)	Overhead tanks	Completed	100%		
	(viii)	Underground water tank	Completed	100%		
	(ix)	Firefighting fitting and equipment's as per CFO NOC	In progress	85%		
	(x)	Electrical fittings in common areas	In progress	85%		
	(xi)	Compliance to conditions of environment/ CRZ NOC	NIL	NIL		
18.	Water	proofing of terraces	Completed	100%		
19.	Entrar	nce lobby finishing	Completed	100%		
20.	Status	of construction of compound wall	Completed	100%		

Note: (*) extend rows as per requirement



Table-B

Sr. No.	Common areas and facilities amenities	Propose d (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			
	Covered no572	Yes	100%	
	Open no Nil	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	NA	NIL	
	Fixing of children play equipment's	NA	NIL	
	Benches	NA	NIL	
8.	Shopping area	YES	NIL	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)		NIL	
B-2	Community building to	be transfer	red to RWA	
17.	Community centre	NO	NO	
18.	Others 3H6H			

B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NO	NO	
20.	Dispensary	NO	NO	
21.	Club	NO	NO	
22,	Others			
B-4	Services/ facilities to be transferred to competent authority	-	-	
23.				

-----END REPORT-----