FORM R-1 [see Regulation3(4)]

CERTIFICATE BY ARCHITECT

(To be uploaded by the Promoter on his webpage on the RERA website before withdrawal of money from separate account)

To,

Subject: Certificate of percentage of completion of construction work of project, Cosmos Express99/ Cascade Gardens (RERA Registration Number GRG-PROJ-276-2019) situated on Sector no.-99 admeasuring 22128.211 sq.mts. being developed by M/s Cosmos infra Engineering India Pvt. Ltd.

Sir,

I **Shailender Singh Senger** have undertaken assignment as Architect of certifying percentage of completion of construction work of the Building(s) of (RERA Registration Number GRG-PROJ-276-2019), Situated on the Sector No.99. admeasuring 22128.211 sq.mts. are being developed by M/s Cosmos infra Engineering India Pvt. Ltd.

Based on site inspection, with respect to each of the Building of the aforesaid Real Estate Project, I certify that as on the date 31st Mar. 2021, the percentage of work done for each of the building of the Real Estate Project (registration number GRG-PROJ-276-2019 under Gurugram RERA), is as per TABLE-A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in TABLE-B.

TABLE-A

Building Number -TOWER-B (to be prepared separately for each Building of the Project)

Sr. No.	Tasks /Activity	Percentage of work done(Approximat ely)
(1)	(2)	(3)
1	Excavation	100%
2	P.C.C. and Plinth	100%
3	Stilt Floor	100%
4	14 number of Slabs of Super Structure	100%

Architect Shalfandra Singh Sengar B.Arch M.C.A., F.I.V., A.I.I.D.

Regd. Architect COA No.: 2008/43675

5	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/ Premises.	30%
6		0%
7	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	70%
8	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	50%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	0%

Building Number -TOWER -C

Sr. No.	Tasks /Activity	Percentage of work done(Approximat ely)
(1)	(2)	(3)
1	Excavation	100%
2	P.C.C. and Plinth	100%
3	Stilt Floor	100%
4	14 number of Slabs of Super Structure	100%
5	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/ Premises.	50%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	10%
7	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	90%
8	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	70%

Architect Shailandra Singh Sengar B.Arch M.C.A., F.I.V., A.I.I.D. Regd. Architect COA No.: 2008/43675

9	Installation of lifts, water pumps, Fire Fighting	0%
	Fittings and Equipment as per CFO NOC, Electrical	
	fittings to Common Areas, electro, mechanical	
	equipment, Compliance to conditions of	
	environment /CRZ NOC, Finishing to entrance	
	lobby/s, plinth protection, paving of areas	
	appurtenant to Building, Compound Wall and all	
	other requirements as may	
	be required to obtain Completion Certificate.	

Building Number –TOWER-D (to be prepared separately for each Building of the Project)

Sr. No.	Tasks /Activity	Percentage of work done(Approximat ely)
(1)	(2)	(3)
1	Excavation	100%
2	P.C.C. and Plinth	100%
3	Stilt Floor	100%
4	14 number of Slabs of Super Structure	100%
5	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/ Premises.	50%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	10%

7	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	90%
8	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	70%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	0%

a Sharan

Building Number -TOWER-E (to be prepared separately for each Building of the Project)

Sr. No.	1 40110	Percentage of work done(Approximat ely)
(1)	(2)	(3)
1	Excavation	100%
2	P.C.C. and Plinth	100%
3	Stilt Floor	100%
4	14 number of Slabs of Super Structure	100%
5	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/ Premises.	50%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	10%

7	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	90%	
8	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	70%	
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	0%	

Building Number -TOWER-S (to be prepared separately for each Building of the Project)

Sr. No.	T CLOTED	Percentage of work done(Approximat
(1)	(2)	(3)
1	Excavation	100%
2	P.C.C. and Plinth	100%

Architect Shailand a Singh Sengar B.Arch M. C.A., F.I.V., A.I.I.D. Regd. Architect COA No.: 2008/43675

3	Stilt Floor	100%
4	8 number of Slabs of Super Structure	100%
5	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/ Premises.	35%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0%

7	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	70%	
8	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	90%	
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building, Compound Wall and all other requirements as may be required to obtain Completion Certificate.	0%	

TABLE-B

Internal and External Development Works in respect of the entire Registered Phase/Project.

Sr.	Common areas and	Proposed	Percentage	Detail
No.	Facilities/Amenities	(Yes/No)	of Work done	S
(1)	(2)	(3)	(4)	(5)
1	Internal Roads & Footpaths.	Y	90%	
2	Water Supply	Y	0%	
3	Sewerage (chamber, lines, Septic Tank, STP).	Y	60%	
4	Storm Water Drains	Y	90%	
5	Landscaping& Tree Planting.	Y	80%	
6	Street Lighting	Y	0%	
7	Community Buildings	Y	20%	
8	Treatment and disposal of sewage and sullage water.	Y	0%	
9	Solid Waste management &		0%	

Architect Shall dra Singh Sengar B.Arch. M.C.A., F.I.V., A.I.I.D. Regd. Architect COA No.: 2008/43675

	Disposal.			
10	Water conservation, Rain water harvesting.	Y	85%	
11	Energy management	Y	0%	
12	Fire protection and fire safety requirements	Y	10%	
13	Electrical meter room, sub-station, receiving station.	Y	0%	
14	Others (Option to Add more).			

Date: 31 03 2021

Place: GURGAON

Architect Shallandra Singh Sengar B.Arch, M.C.A., F.I.V., A.I.J.D. Regd. Architect COA No.: 2008/43675