R K & ASSOCIATES

Architects, Engineers & Planners E 31 Green Park Main, New Delhi 110016. Phone: +91-11-26862540 <<u>rka.architects@gmail.com</u>> ; <u>contact@rkaindia.net</u> Website : www.rkaindia.net

ANNEXURE 6-A

ARCHITECT'S CERTIFICATE

To whom so ever it may concern

Report for quarter ending 31.12.2023 to 31.03.2024

Subject: Certificate of progress of construction work:

| Sr. | Particulars | Information |
|-----|------------------------------|--|
| No. | | |
| 1. | Project/Phase of the project | SMART HOMES, KARNAL |
| 2. | Location | Village-Budhakhera ,Sec-32 A,KARNAL, Haryana |
| 3. | Area in acres | 5.6534 Acre |
| 4. | HARERA Registration No. | 265 of 2017 dated 09.10.2017 |
| 5. | Name of Licensee | Aegis Value Homes Ltd. |
| 6. | Name of Collaborator | N/A |
| 7. | Name of Developer | Aegis Value Homes Ltd. |

Sir,

I/ We have undertaken assignment as architect for certifying progress of construction work in the above mentioned project as per the approved plans.

| 1. | Date of certifying of percentage of construction work/ site inspection | 31/03/2024 |
|----|---|-------------------|
| 2. | Name of Architect/Architect's firm | R.K. & ASSOCIATES |
| 3. | Date of site inspection | 31/03/2024 |

Following technical professionals are appointed by Promoter: - (as applicable)

| Sr.No. | Consultants | Name |
|--------|-----------------------|----------------------------|
| 1. | Site Engineer | Mr. Rajesh Kumar |
| 2. | Structural Consultant | Global Design Engineers |
| 3. | Proof Consultant | |



| , | 4. | MEP Consultant | Acrobat Engineers Pvt. Ltd |
|---|----|---------------------------|-------------------------------|
| | 5. | Site Supervisor/in charge | Mr. Rajinder Kumar |

I certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and B

Table – A

Building/Tower no. <u>Tower-A-1</u> (to be prepared separately for each building/tower in the project/phase of the project)

| Sr. No. | Tasks / Activity | Description of work done | Percentage of total proposed work |
|------------|--|-----------------------------|--------------------------------------|
| A1 | SUB- STRUCTURE STATUS | | |
| 1. | Excavation | Completed | |
| | Laying of foundation | | |
| 2. | i. Raft | Completed | |
| | ii. Pile | NA | |
| | Number of basement(s) <u>Nil</u> | | |
| 3. | i. Basement level 1 | NA | |
| | ii. Basement level 2* | NA | |
| 4. | Waterproofing of the above sub- | | |
| 4. | structure (wherever applicable) | NA | |
| <u>A1</u> | SUPER- STRUCTURE STATUS | | |
| 5. | Total floors in the tower/building | G+14 | |
| 6. | Total area on each floor | 558.072Sqm | |
| 7. | Stilt Floor/ Ground Floor | Complete | |
| 8. | Status of laying of slabs floor wise | G+14 | |
| | Cumulative number of slabs in the | | |
| | building/tower <u>A-1</u> laid by end of quarter | 15 | |
| | Status of construction | 15 | |
| | i. Walls on floors | G+14 floors | |
| 9. | | | |
| ש. | ii. Staircase | G+14 floors | |
| | iii. Lift wells along with water | | |
| | proofing | Done | |

Relit Garg

R K & ASSOCIATES

| | iv. Lift lobbies /common areas floor wise | Do | ne | | |
|-----|--|---|-------------------|------------------------------|-------------------|
| 10. | Fixing of door and window frames in flats/units | Com | Complete | | |
| | Status of MEP | Internal (within Flat) | External works | Internal (within Flat) | External works |
| 11. | i. Mechanical works | Complete | complete | Complete | Complete |
| | ii. Electrical works conduiting and Box Fixing | Completed | Complete | Completed | Complete |
| | iii. Plumbing works | Completed | Completed | Completed | Completed |
| 12. | StatusofwallFinishing(Plaster/Paint/WhitewashingCoating) | | | | |
| | i. External | Com | plete | Paint Co | omplete |
| | ii. Internal | Com | plete | 2nd coat | complete |
| | Status of wall tiling | | | | |
| 13. | i. In bathroom | G.F to 14 th Floor Complete | | | |
| | ii. In Kitchen | G.F to 14 th Floor Complete | | | |
| | Status of flooring | | | | |
| 14. | i. Common areas | G.F to 14 th Floor Complete | | | |
| | ii. Units/flats | G.F to 14 th Floor Complete | | | |
| | Status of finishing | | | | |
| | i. Staircase with railing | Complete | | | |
| 15. | ii. Lift wells | Complete | | | |
| | iii. Lift lobbies / common area | Complete | | | |
| | floor wise Status of Installation | Com | piete | | |
| | (Within flat/unit) | | | | |
| | i. Doors and windows panels | Cor | nplete | | |
| | ii. Sanitary Fixtures | | plete | | |
| 16. | iii. Modular Kitchen | N | A | | |
| 10. | iv. Electrical fittings/Lighting | G.F to 14 th floor complete | | | |
| | v. Gas piping (if any) | NA | | | |
| | (Other than flat/units) | | | | |
| | vi. Lifts installation | Complete | | | |
| | vii. Overhead tanks | Complete | | | |

Roblint Gorg

| | viii. Underground water tank | Complete |
|-----|------------------------------------|---------------|
| | ix. Firefighting fittings and | |
| | equipment's as per CFO NOC | Complete |
| | x. Electrical fittings in common | |
| | areas | Complete |
| | xi. Compliance to conditions of | |
| | environment /CRZ NOC | To be started |
| 17. | Waterproofing of terraces | Complete |
| 18. | Entrance lobby finishing | Complete |
| 19. | Status of construction of Compound | |
| 19. | wall | Completed |

Building/Tower no. <u>Tower-A-2</u> (to be prepared separately for each building/tower in the project/phase of the project)

| Sr. No. | Tasks / Activity | Description of work done | Percentage of total proposed work |
|------------|--|-----------------------------|--------------------------------------|
| A1 | SUB- STRUCTURE STATUS | | |
| 1. | Excavation | Completed | |
| | Laying of foundation | | |
| 2. | i. Raft | Completed | |
| | ii. Pile | NA | |
| | Number of basement(s) <u>Nil</u> | | |
| 3. | i. Basement level 1 | NA | |
| | ii. Basement level 2* | NA | |
| 4. | Waterproofing of the above sub- structure (wherever applicable) | NA | |
| <u>A2</u> | SUPER- STRUCTURE STATUS | | |
| 5. | Total floors in the tower/building | G+14 | |
| 6. | Total area on each floor | 558.072 sqm | |
| 7. | Stilt Floor/ Ground Floor | Complete | |
| 8. | Status of laying of slabs floor wise | G+14 | |
| | Cumulative number of slabs in the building/tower <u>A-2</u> laid by end of quarter | 15 | |
| | Status of construction | | |
| 9. | i. Walls on floors | G+14 Floors | |
| | ii. Staircase | G+14 floors | |

Roblint Garg

| | iii. Lift wells along with water proofing | Completed | | | |
|-----|---|---|----------|------------------------------|-------------------|
| | iv. Lift lobbies /common areas floor | | | | |
| | wise | Complete | | | |
| 10. | Fixing of door and window frames in flats/units | Complete | | | |
| | Status of MEP | Internal (within Flat) External works | | Internal (within Flat) | External works |
| 11. | i. Mechanical works | Complete | Complete | Complete | Complete |
| | ii. Electrical works conduiting and Box Fixing | complete | Complete | complete | Complete |
| | iii. Plumbing works | complete | Complete | complete | Complete |
| 10 | Status of wall Finishing (Plaster/Paint/White washing Coating) | | | | |
| 12. | i. External | Com | plete | Paint comple | ete |
| | ii. Internal | Com | plete | 2 nd coat com | plete |
| | Status of wall tiling | • | | | |
| 13. | i. In bathroom | G.F to 14 th Floor Complete | | | |
| | ii. In Kitchen | G.F to 14 th Floor Complete | | | |
| | Status of flooring | | | | |
| 14. | i. Common areas | G.F to 14 th Floor Complete | | | |
| | ii. Units/flats | G.F to 14 th Floor Complete | | | |
| | Status of finishing | | | | |
| 15. | i. Staircase with railing | G.F to 14 th Floor Complete | | | |
| 15. | ii. Lift wells | Complete | | | |
| | iii. Lift lobbies / common area floor wise | G.F to 14 th Floor Complete | | | |
| | Status of Installation | Com | | | |
| | (Within flat/unit) | | | | |
| | i. Doors and windows panels | Com | plete | | |
| | ii. Sanitary Fixtures | | plete | | |
| 16. | iii. Modular Kitchen | | IA | | |
| | iv. Electrical fittings/Lighting | Complete | | | |
| | v. Gas piping (if any) | NA | | | |
| | (Other than flat/units) | · · · | | | |
| | vi. Lifts installation | Complete | | | |
| | vii. Overhead tanks | | pleted | | |

Roblint Gorg

| | viii. Underground water tank | Complete |
|-----|---|---------------|
| | ix. Firefighting fittings and equipment's | |
| | as per CFO NOC | Complete |
| | x. Electrical fittings in common areas | Complete |
| | xi. Compliance to conditions of | |
| | environment /CRZ NOC | To be started |
| 17. | Waterproofing of terraces | Complete |
| 18. | Entrance lobby finishing | Complete |
| 19. | Status of construction of Compound wall | Completed |

Building/Tower no. <u>Tower-A-3</u> (to be prepared separately for each building/tower in the project/phase of the project)

| Sr. No. | Tasks / Activity | Description of work done | Percentage of total proposed work |
|------------|--|-----------------------------|---|
| A1 | SUB- STRUCTURE STATUS | | |
| 1. | Excavation | Completed | |
| | Laying of foundation | | |
| 2. | i. Raft | Completed | |
| | ii. Pile | NA | |
| | Number of basement(s) <u>Nil</u> | | |
| 3. | i. Basement level 1 | NA | |
| | ii. Basement level 2* | NA | |
| 4. | Waterproofing of the above sub- structure (wherever applicable) | NA | |
| <u>A3</u> | SUPER- STRUCTURE STATUS | | |
| 5. | Total floors in the tower/building | G+14 | |
| 6. | Total area on each floor | 558.072 sqm | |
| 7. | Stilt Floor/ Ground Floor | Complete | |
| 8. | Status of laying of slabs floor wise | G+14 | |
| | Cumulative number of slabs in the building/tower <u>A-3</u> laid by end of quarter | 15 | |
| | Status of construction | | |
| | i. Walls on floors | G+14 floors | |
| 9. | ii. Staircase | G+14 floors | |
| | iii. Lift wells along with water proofing | Complete | |

Relit Gorg

| | iv. Lift lobbies /common areas floor wise | G+14 | floors | | |
|-----|--|---|-------------------|------------------------------|-------------------|
| 10. | Fixing of door and window frames in flats/units | Complete | | | |
| | Status of MEP | Internal (within Flat) | External works | Internal (within Flat) | External works |
| 11. | i. Mechanical works | Complete | Complete | Complete | Complete |
| | ii. Electrical works conduiting and Box Fixing | complete | Complete | Complete | Complete |
| | iii. Plumbing works | complete | Complete | Complete | complete |
| 12. | StatusofwallFinishing(Plaster/Paint/White washing Coating) | | | | |
| 12. | i. External | Com | plete | Com | olete |
| | ii. Internal | Com | plete | 2nd coat | Complete |
| | Status of wall tiling | | - 44 - 4 | | |
| 13. | i. In bathroom | G.F to 14 th Floor Complete | | | |
| | ii. In Kitchen | G.F to 14 th Floor Complete | | | |
| | Status of flooring | | | | |
| 14. | i. Common areas | G.F to 14 th Floor Complete | | | |
| | ii. Units/flats | G.F to 14 th Floor Complete | | | |
| | Status of finishing | | | | |
| 1 5 | i. Staircase with railing | G.F to 14 th Floor Complete | | | |
| 15. | ii. Lift wells | Complete | | | |
| | iii. Lift lobbies / common area floor wise | complete | | | |
| | Status of Installation | | | | |
| | (Within flat/unit) | | | | |
| | i. Doors and windows panels | Com | plete | | |
| | ii. Sanitary Fixtures | Com | plete | | |
| 16. | iii. Modular Kitchen | | Α | | |
| 101 | iv. Electrical fittings/Lighting | G.F to 14 th floor comp. | | | |
| | v. Gas piping (if any) | NA | | | |
| | (Other than flat/units) | | | | |
| | vi. Lifts installation | Complete | | | |
| | vii. Overhead tanks Completed | | oleted | | |
| | viii. Underground water tank | Com | plete | | |

Roblint Gorg

| | ix. Firefighting fittings and equipment's as per CFO NOC | Complete |
|-----|--|---------------|
| | x. Electrical fittings in common areas | Complete |
| | xi. Compliance to conditions of | |
| | environment /CRZ NOC | To be started |
| 17. | Waterproofing of terraces | Complete |
| 18. | Entrance lobby finishing | Complete |
| 19. | Status of construction of Compound wall | Completed |

Note: (*) Extend rows as per requirement

Building/Tower no. <u>Tower-A-4</u> (to be prepared separately for each building/tower in the project/phase of the project)

| Sr. No. | Tasks / Activity | Description of work done | Percentage of total proposed work |
|------------|--|-----------------------------|--------------------------------------|
| A1 | SUB- STRUCTURE STATUS | | |
| 1. | Excavation | Completed | |
| | Laying of foundation | | |
| 2. | i. Raft | Completed | |
| | ii. Pile | NA | |
| | Number of basement(s) <u>Nil</u> | | |
| 3. | i. Basement level 1 | NA | |
| | ii. Basement level 2* | NA | |
| 4. | Waterproofing of the above sub- structure | | |
| 4. | (wherever applicable) | NA | |
| <u>A4</u> | SUPER- STRUCTURE STATUS | | |
| 5. | Total floors in the tower/building | G+14 | |
| 6. | Total area on each floor | 558.072 sqm | |
| 7. | Stilt Floor/ Ground Floor | Complete | |
| 8. | Status of laying of slabs floor wise | G+14 | |
| | Cumulative number of slabs in the building/tower <u>A-4</u> laid by end of quarter | 15 | |
| | Status of construction | | |
| | i. Walls on floors | Complete | |
| 9. | ii. Staircase | Complete | |
| <i>.</i> | iii. Lift wells along with water proofing | Complete | |
| | iv. Lift lobbies /common areas floor | | |
| | wise | Complete | |

Roblint Gorg

| 10. | Fixing of door and window frames in flats/units | Complete | | | |
|-----|---|------------------------------|---|------------------------------|-------------------|
| | Status of MEP | Internal (within Flat) | External works | Internal (within Flat) | External works |
| 11. | i. Mechanical works | Complete | Complete | Complete | Complete |
| | ii. Electrical works conduiting and Box Fixing | Complete | Complete | Complete | Complete |
| | iii. Plumbing works | Complete | Complete | Complete | Complete |
| 12. | Status of wall Finishing (Plaster/Paint/White washing Coating) | | | | |
| 12. | i. External | Com | plete | Comp | olete |
| | ii. Internal | Com | plete | 2 nd coat o | complete |
| | Status of wall tiling | | | | |
| 13. | i. In bathroom | Com | G.F to 14 th Floor Complete | | |
| | ii. In Kitchen | | G.F to 14 th Floor Complete | | |
| | Status of flooring | | | | |
| 14. | i. Common areas | Com | G.F to 14 th Floor Complete | | |
| | ii. Units/flats | | G.F to 14 th Floor Complete | | |
| | Status of finishing | | | | |
| 15 | i. Staircase with railing | | G.F to 14 th Floor Complete | | |
| 15. | ii. Lift wells | Com | Complete | | |
| | iii. Lift lobbies / common area floor wise | | G.F to 14 th Floor Complete | | |
| | Status of Installation | | | | |
| | (Within flat/unit) | | | | |
| | i. Doors and windows panels | Com | plete | | |
| | ii. Sanitary Fixtures | Com | plete | | |
| 16. | iii. Modular Kitchen | N | IA | | |
| 10. | iv. Electrical fittings/Lighting | | 4 th floor plete | | |
| | v. Gas piping (if any) | Ν | IA | | |
| | (Other than flat/units) | | | | |
| | vi. Lifts installation | Com | plete | | |
| | vii. Overhead tanks | | plete | | |
| | viii. Underground water tank | Com | plete | | |



| | ix. Firefighting fittings and equipment's as per CFO NOC | Complete |
|-----|--|---------------|
| | x. Electrical fittings in common areas | Complete |
| | xi. Compliance to conditions of | |
| | environment /CRZ NOC | To be started |
| 17. | Waterproofing of terraces | Complete |
| 18. | Entrance lobby finishing | Complete |
| 19. | Status of construction of Compound wall | Completed |

Note: (*) Extend rows as per requirement

Building/Tower no. <u>Tower-A-5</u> (to be prepared separately for each building/tower in the project/phase of the project)

| Sr. No. | Tasks / Activity | Description of work done | Percentage of total proposed work |
|------------|--|-----------------------------|-----------------------------------|
| A1 | SUB- STRUCTURE STATUS | | |
| 1. | Excavation | Completed | |
| | Laying of foundation | | |
| 2. | i. Raft | Completed | |
| | ii. Pile | NA | |
| | Number of basement(s) <u>Nil</u> | | |
| 3. | i. Basement level 1 | NA | |
| | ii. Basement level 2* | NA | |
| 4. | Waterproofing of the above sub- structure (wherever applicable) | NA | |
| <u>A5</u> | SUPER- STRUCTURE STATUS | | |
| 5. | Total floors in the tower/building | G+14 | |
| 6. | Total area on each floor | 558.072 sqm | |
| 7. | Stilt Floor/ Ground Floor | Complete | |
| 8. | Status of laying of slabs floor wise | G+14 | |
| | Cumulative number of slabs in the building/tower <u>A-5</u> laid by end of quarter | 15 | |
| | Status of construction | | |
| | i. Walls on floors | complete | |
| 9. | ii. Staircase | complete | |
| | iii. Lift wells along with water proofing | complete | |
| | iv. Lift lobbies /common areas floor wise | complete | |

Relit Gorg

| Internal Externa | l Internal | |
|---|---------------------|-------------------|
| Status of MEP (within Flat) | " (within Flat) | External works |
| 11. i. Mechanical works Complete Complete | e Complete | Complete |
| ii. Electrical works conduiting and Box Fixing complete Complete | Complete ce | Complete |
| iii. Plumbing works complete Complete | e complete | Complete |
| 12. Status of wall Finishing (Plaster/Paint/White washing Coating) | | |
| i. External Complete | comp | olete |
| ii. Internal Complete | 2 nd coa | at paint |
| Status of wall tiling | | |
| 13.In bathroomG.F. to 14th Floor Complete | | |
| ii. In Kitchen G.F to 14 th Floor Complete | | |
| Status of flooring | | |
| 14.i.Common areascomplete | | |
| ii. Units/flats complete | | |
| Status of finishing | | |
| i. Staircase with railing complete | | |
| 15. ii. Lift wells Complete | | |
| iii. Lift lobbies / common area floor wise complete | | |
| Status of Installation | | |
| (Within flat/unit) | | |
| i. Doors and windows panels complete | | |
| ii. Sanitary Fixtures In progress | | |
| 16. iii. Modular Kitchen NA | | |
| iv. Electrical fittings/Lighting complete | | |
| v. Gas piping (if any) NA | | |
| (Other than flat/units) | | |
| vi. Lifts installation Complete | | |
| vii. Overhead tanks Complete | | |
| viii. Underground water tank Complete | | |
| ix. Firefighting fittings and equipment's as per CFO NOC Complete | | |
| x. Electrical fittings in common areas Complete | | |

Reluliit Gorg

| | xi. Compliance to conditions of environment /CRZ NOC | To be started |
|-----|--|---------------|
| 17. | Waterproofing of terraces | Complete |
| 18. | Entrance lobby finishing | Complete |
| 19. | Status of construction of Compound wall | Completed |

Building/Tower no. <u>Tower-A-6</u> (to be prepared separately for each building/tower in the project/phase of the project)

| Sr. No. | Tasks / Activity | Description of work done | Percentage of total proposed work |
|------------|---|-----------------------------|--------------------------------------|
| A1 | SUB- STRUCTURE STATUS | | |
| 1. | Excavation | Completed | |
| | Laying of foundation | | |
| 2. | i. Raft | Completed | |
| | ii. Pile | NA | |
| | Number of basement(s) <u>Nil</u> | | |
| 3. | i. Basement level 1 | NA | |
| | ii. Basement level 2* | NA | |
| 4. | Waterproofing of the above sub- structure (wherever applicable) | NA | |
| <u>A6</u> | SUPER- STRUCTURE STATUS | | |
| 5. | Total floors in the tower/building | G+14 | |
| 6. | Total area on each floor | 558.072 sqm | |
| 7. | Stilt Floor/ Ground Floor | complete | |
| 8. | Status of laying of slabs floor wise | G+14 | |
| | Cumulative number of slabs in the building/tower A-6 laid by end of quarter | 15 | |
| | Status of construction | | |
| | i. Walls on floors | complete | |
| 9. | ii. Staircase | complete | |
| | iii. Lift wells along with water proofing | complete | |
| | iv. Lift lobbies /common areas floor wise | complete | |
| 10. | Fixing of door and window frames in flats/units | G+14 floor | |



| | Status of MEP | Internal (within Flat) | External works | Internal (within Flat) | External works |
|-----|--|------------------------------|-------------------|------------------------------|-------------------|
| 11. | i. Mechanical works | Complete | Complete | Complete | Complete |
| | ii. Electrical works conduiting and Box | | | complete | |
| | Fixing | complete | Complete | | Complete |
| | iii. Plumbing works | complete | complete | complete | complete |
| 12. | Status of wall Finishing (Plaster/Paint/White washing Coating) | | | | |
| 12. | i. External | Com | plete | | |
| | ii. Internal | Com | plete | 2 nd co | at Paint |
| | Status of wall tiling | | | | |
| 13. | i. In bathroom | Com | plete | | |
| | ii. In Kitchen | Com | plete | | |
| | Status of flooring | | | | |
| 14. | i. Common areas | Complete | | | |
| | ii. Units/flats | Com | plete | | |
| | Status of finishing | | | | |
| 15. | i. Staircase with railing | complete | | | |
| 15. | ii. Lift wells | complete | | | |
| | iii. Lift lobbies / common area floor wise | complete | | | |
| | Status of Installation | | | | |
| | (Within flat/unit) | | | | |
| | i. Doors and windows panels | Com | plete | | |
| | ii. Sanitary Fixtures | Com | plete | | |
| 16. | iii. Modular Kitchen | NA | | | |
| | iv. Electrical fittings/Lighting | Com | plete | | |
| | v. Gas piping (if any) | N | IA | | |
| | (Other than flat/units) | | | | |
| | vi. Lifts installation | | plete | | |
| | vii. Overhead tanks | com | plete | | |
| | viii. Underground water tank | Com | plete | | |
| | ix. Firefighting fittings and equipment's as per CFO NOC | Com | plete | | |
| | x. Electrical fittings in common areas | com | plete | | |
| | xi. Compliance to conditions of environment /CRZ NOC | To be started | | | |
| 17. | | | | | |
| | Waterproofing of terraces | | plete | | |
| 18. | Entrance lobby finishing | Com | plete | | |

Roblint Gorg

| 19. | Status of construction of Compound wall | Completed | |
|------|---|-----------|--|
| Noto | (*) Extand rows as nor requirement | | |

Building/Tower no. <u>Tower-A-7</u> (to be prepared separately for each building/tower in the project/phase of the project)

| Sr. No. | Tasks / Activity | Description of work done | | total pr | itage of coposed ork | |
|------------|--|---|-------------------|------------------------------|----------------------------|--|
| A1 | SUB- STRUCTURE STATUS | | | | | |
| 1. | Excavation | Comp | oleted | | | |
| | Laying of foundation | | | | | |
| 2. | i. Raft | Comp | oleted | | | |
| | ii. Pile | N | IA | | | |
| | Number of basement(s) <u>Nil</u> | | | | | |
| 3. | i. Basement level 1 | N | IA | | | |
| | ii. Basement level 2* | NAG+11G+11558.072 sqmIn progressG+11A12completecompletecompletecomplete | | | | |
| 4. | Waterproofing of the above sub- structure (wherever applicable) | N | IA | | | |
| <u>A7</u> | SUPER- STRUCTURE STATUS | | | | | |
| 5. | Total floors in the tower/building | G+11 | | | | |
| 6. | Total area on each floor | 558.07 | 72 sqm | | | |
| 7. | Stilt Floor/ Ground Floor | In pro | ogress | | | |
| 8. | Status of laying of slabs floor wise | G+ | -11 | | | |
| | Cumulative number of slabs in the building/tower <u>A-7</u> laid by end of quarter | 12 | | | | |
| | Status of construction | | | | | |
| | i. Walls on floors | com | plete | | | |
| 9. | ii. Staircase | com | plete | | | |
| | iii. Lift wells along with water proofing | com | plete | | | |
| | iv. Lift lobbies /common areas floor wise | com | plete | | | |
| 10. | Fixing of door and window frames in flats/units | complete | | | | |
| 11. | Status of MEP | Internal (within Flat) | External works | Internal (within Flat) | External works | |
| | i. Mechanical works | Complete | Complete | Complete | Complete | |



| | ii. Electrical works conduiting and Box | | | | |
|------|--|-------------------------|-------------------------|-------------------------|----------|
| | Fixing | Complete | Complete | Complete | Complete |
| | iii. Plumbing works | Complete | Complete | Complete | Complete |
| 12. | Status of wall Finishing (Plaster/Paint/White washing Coating) | | | | |
| 12. | i. External | Complete | | Paint Complete | |
| | ii. Internal | com | plete | 2 nd coat pa | aint |
| | Status of wall tiling | | | | |
| 13. | i. In bathroom | G.F to 12 | L th Floors | | |
| | ii. In Kitchen | G.F to & | 11 th Floors | | |
| | Status of flooring | | | | |
| 14. | i. Common areas | Com | plete | | |
| | ii. Units/flats | G.F to 11 | L th Floors | | |
| | Status of finishing | | | | |
| 15. | i. Staircase with railing | complete. | | | |
| 15. | ii. Lift wells | Completed. | | | |
| | iii. Lift lobbies / common area floor wise | complete | | | |
| | Status of Installation | | | | |
| | (Within flat/unit) | | | | |
| | i. Doors and windows panels | complete | | | |
| | ii. Sanitary Fixtures | Complete | | | |
| 16. | iii. Modular Kitchen | N | A | | |
| | iv. Electrical fittings/Lighting | G.f to 11 th | floor | | |
| | v. Gas piping (if any) | N | A | | |
| | (Other than flat/units) | | | | |
| | vi. Lifts installation | Com | plete | | |
| | vii. Overhead tanks | Com | plete | | |
| | viii. Underground water tank | Com | plete | | |
| | ix. Firefighting fittings and equipment's as per CFO NOC | Com | plete | | |
| | x. Electrical fittings in common areas | Com | plete | | |
| | xi. Compliance to conditions of environment /CRZ NOC | To be : | started | | |
| 17. | Waterproofing of terraces | | plete | | |
| 18. | Entrance lobby finishing | | plete | | |
| 19. | Status of construction of Compound wall | Completed | | | |
| Nota | (*) Extend rows as per requirement | | | • | |



Building/Tower no. <u>Tower-B-1</u> (to be prepared separately for each building/tower in the project/phase of the project)

| Sr. No. | Tasks / Activity | - | ption of done | Percentag propose | |
|------------|--|------------------------------|-------------------|------------------------------|-------------------|
| A1 | SUB- STRUCTURE STATUS | | | | |
| 1. | Excavation | Completed | | | |
| | Laying of foundation | | | | |
| 2. | i. Raft | Completed | | | |
| | ii. Pile | Ν | NA | | |
| | Number of basement | | | | |
| 3. | i. Basement level 1 | Ν | IA | | |
| | ii. Basement level 2* | N | IA | | |
| 4. | Waterproofing of the above sub- structure (wherever applicable) | N | IA | | |
| <u>B1</u> | SUPER- STRUCTURE STATUS | | | | |
| 5. | Total floors in the tower/building | G | +9 | | |
| 6. | Total area on each floor | 356.2 | 01Sqm | | |
| 7. | Stilt Floor/ Ground Floor | Complete | | | |
| 8. | Status of laying of slabs floor wise | G+9 | | | |
| | Cumulative number of slabs in the building/tower <u>B-1</u> laid by end of quarter | 10 | | | |
| | Status of construction | | | | |
| | i. Walls on floors | 9 floors | | | |
| | ii. Staircase | 10 floors | | | |
| 9. | iii. Lift wells along with water proofing | Complete | | | |
| | iv. Lift lobbies /common areas floor wise | Complete | | | |
| 10. | Fixing of door and window frames in flats/units | Complete | | | |
| 11. | Status of MEP | Internal (within Flat) | External works | Internal (within Flat) | External works |
| | i. Mechanical works | Complete | Complete | Complete | Complete |
| | ii. Electrical works conduiting and Box Fixing | Complete | Complete | Complete | Complete |
| | iii. Plumbing works | Complete | Complete | Complete | Complete |



| 12. | Status of wall Finishing (Plaster/Paint/White washing Coating) | | |
|-----|---|---------------|----------------|
| 12. | i. External | Complete | |
| | ii. Internal | 10 Floors | 1st coat paint |
| | Status of wall tiling | | |
| 13. | i. In bathroom | Completed | |
| 15. | ii. In Kitchen | Completed | |
| | Status of flooring | | |
| 14. | i. Common areas | Completed | |
| | ii. Units/flats | Completed | |
| | Status of finishing | | |
| | i. Staircase with railing | Complete | |
| 15. | ii. Lift wells | Complete | |
| | iii. Lift lobbies / common area floor | | |
| | wise | Complete | |
| | Status of Installation | | |
| | (Within flat/unit) | | |
| | i. Doors and windows panels | Complete | |
| | ii. Sanitary Fixtures | Complete | |
| 16. | iii. Modular Kitchen | NA | |
| | iv. Electrical fittings/Lighting | Complete | |
| | v. Gas piping (if any) | NA | |
| | (Other than flat/units) | | |
| | vi. Lifts installation | Complete | |
| | vii. Overhead tanks | Complete | |
| | viii. Underground water tank | Complete | |
| | ix. Firefighting fittings and | | |
| | equipment's as per CFO NOC | To be started | |
| | x. Electrical fittings in common areas | Complete | |
| | xi. Compliance to conditions of | | |
| | environment /CRZ NOC | To be started | |
| 17. | Waterproofing of terraces | Complete | |
| 18. | Entrance lobby finishing | Complete | |
| 19. | Status of construction of Compound wall | Completed | |

Building/Tower no. <u>**Commercial**</u> (to be prepared separately for each building/tower in the project/phase of the project)



| Sr. No. | Tasks/Activity | Description of work done | Percentage of total proposed work |
|---------|---|---------------------------------|-----------------------------------|
| | SUB- STRUCTURE STATUS | | |
| 1. | Excavation | Complete | |
| 2. | Laying of foundation | Complete | |
| | i. Raft | Complete | |
| | ii. Pile | N/A | |
| | iii. Isolate footing | N/A | |
| 3. | Number of basement(s) | N/A | |
| | i. Basement level 1 | N/A | |
| | ii. Basement level 2* | N/A | |
| 4. | Waterproofing of the above sub- structure (wherever applicable) | N/A | |
| | SUPER- STRUCTURE STATUS | | |
| 5. | Total floors in the tower/building | G+1 | |
| 6. | Total area on each floor | 2158.708 Sqm (Covered Area). | |
| 7. | Stilt Floor/ Ground Floor | Complete | |
| 8. | Status of laying of slabs floor wise | Complete | |
| | Cumulative number of slabs in the building/tower $\underline{1}$ laid by end of quarter | Complete | |
| 9. | Status of construction | | |
| | i. Walls on floors | Complete | |
| | ii. Staircase | Complete | |
| | iii. Lift wells along with water proofing | Complete | |
| | iv. Lift lobbies /common areas floor wise | Complete | |
| 10. | Fixing of door and window frames in flats/units | Complete | |



| 11. | Stat | us of MEP | Internal (within Flat) | External works | Internal (within Flat) | External works |
|-----|--|--|------------------------------|-------------------|------------------------------|-------------------|
| | i. | Mechanical works | N/A | N/A | | |
| | ii. | Electrical works including wiring | In progress | In progress | | |
| | iii. | Plumbing works | In progress | In progress | | |
| 12. | . Status of wall Finishing (Plaster/Paint/White washing Coating) | | | | | |
| | i. | External | In progress | | | |
| | ii. | Internal | In progress | | | |
| 13. | State | us of wall tiling | Complete | | | |
| | i. | In bathroom | Complete | | | |
| | ii. | In Kitchen | Complete | | | |
| 14. | State | us of flooring | | | | |
| | i. | Common areas | Complete | | | |
| | ii. | Units/flats | To be starte | ed | | |
| 15. | State | us of finishing | | | | |
| | i. | Staircase with railing | Complete | | | |
| | ii. | Lift wells | Complete | | | |
| | iii. | Lift lobbies /common areas floor wise | Complete | | | |
| 16. | State | us of Installation | | | | |
| | (Wit | hin flat/unit) | | | | |
| | i. | Doors and windows panels | Complete | | | |
| | ii. | Sanitary Fixtures | Complete | | | |
| | iii. | Modular Kitchen | N/A | | | |
| | iv. | Electrical fittings/Lighting | In progress | | | |
| | v. | Gas piping (if any) | N/A | | | |
| | (Oth | er than flat/units) | | | | |
| | vi. | Lifts installation | In progress | | | |



| | vii. Overhead tanks | In progress |
|-----|--|---------------|
| | viii. Underground water tank | N/A. |
| | ix. Firefighting fittings and equipment's as per CFO NOC | |
| | x. Electrical fittings in common areas | Complete |
| | xi. Compliance to conditions of environment /CRZ NOC | |
| 17. | Waterproofing of terraces | In progress |
| 18. | Entrance lobby finishing | In progress |
| 19. | Status of construction of Compound wall | To be started |

Table - B

| Sr. No. | Common areas and Facilities Amenities | Proposed (Yes/No) | Percentage of Work Done | Remarks |
|---------|--|----------------------|-------------------------------|------------------|
| | B-1 Services | | | |
| 1. | Internal roads & pavements | Yes | 100% | |
| 2. | Parking | | | |
| | Covered no | Yes | 80% | Scooter Parking. |
| | Open no | Yes | 20% | Scooter Parking. |
| 3. | Water supply | Yes | | |
| 4. | Sewerage (Chamber, Lines, Septic Tank, STP) | Yes | 98% | |
| 5. | Storm water drains | Yes | 98% | |
| 6. | Landscaping & tree plantation | Yes | 90% | |
| 7. | Parks and playgrounds | Yes | 90% | |
| | Fixing of children play equipment's | Yes | 100% | |
| | Benches | Yes | 100% | |

Robbit Garg

| 8. | Shopping Area | Yes | | |
|-----|--|-----|------|-----|
| 9. | Street Lighting/Electrification | Yes | 99% | |
| 10. | Treatment and disposal of sewage and sullage water/STP | Yes | 99% | |
| 11. | Solid Waste Management & disposal | Yes | | |
| 12. | Water Conservation, Rainwater Harvesting, Percolating Well/Pit | Yes | 100% | |
| 13. | Energy management (Solar) | Yes | 100% | |
| 14. | Fire Protection and Fire Safety Requirements | Yes | 100% | |
| 15. | Electrical meter room, Sub-Station, Receiving station | Yes | 99% | |
| 16. | Other (Security System) | Yes | 50% | |
| B-2 | Community building to be transferred to RWA | | | |
| 17. | Community centre | Yes | | |
| 18. | Creche. | Yes | | |
| B-3 | Community buildings not to be transferred to RWA/Competent Authority | | | |
| 19. | Schools | No | | N/A |
| 20. | Dispensary | No | | N/A |
| 21. | Club | No | | N/A |
| 22. | Commercial | Yes | | |
| B-4 | Services /facilities to be transferred to Competent Authority | | | |
| 23. | * | N/A | | |

