Architects & Engineers

APURBA BORAH

Annexure A

		Architect	's Certificate*		
Repor	t for qua	rter ending	31 MARCH- 2021 Certificate of progress of construction work		
Subjec	ct				
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans				
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	Project Area 12.537 Acres, Group Housing Colony		
	2.	Location	Sector-4A, Village Kassar, Tehsil Bahadurgarh, Haryana		
	3.	Licensed area in acres	12.537 acres.		
	4.	Area for registration in acres	12.537 acres		
	5.	HARERA registration no.	202 of 2017		
	6.	Name of licensee	Omaxe Limited		
	7.	Name of collaborator			
	8.	Name of developer	Omaxe Limited		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection			
	2.	Name of Architect/ Architect's firm			
	3.	Date of site inspection			



Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

Architects & Engineers

1692

APURBA BORAH

3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No. Consultants Name 1. Site engineer Mr. Vivek Kumar		Name			
			Mr. Vivek Kumar			
	2.	Structural consultant	Mr. T.D Aneja			
	3.	Proof consultant				
	4.	MEP consultant	Mr, Digamber Singh			
	5.	Site incharge	Mr. Amit Pratap			
4.	Haryan constru	a Building Code, 2017/ National Buil ction, infrastructure works and inter- ged in the registration and brochure, pu	as per approved drawings, statutory/ mandatory approvals, ding Code (wherever applicable) and the material used in the nal development works are as per the projected standard as blication material and other documents shared with the buyers			
5.	of the below.	real estate project/phase of the project	ge of work done in the project for each of the building/ tower t under HARERA is as per table A and table B given herein with respect to each of the activity of the entire project/ phase			

Date : Yours faithfully,

Place Signature & name (in block letters) with stamp of architect

Council of architects (CoA) : registration no.

Council of architects (CoA) registration valid till (date)

Architects & Engineers

APURBA BORAH

			Table – A				
(to be	prepare	wer no. ed separately for each building/ tower / phase of the project)					
A1	Cum	nulative progress of the project/phase at the end of the quarter.					
Sr. No.	Project components Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.) Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1.				1303	100%		
2.				4933			
663.	MEP						
	3.1	Mechanical (lifts, ventilation, etc.)	70	301	40%		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	65	544.48	71%		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	18	1182.46	84%		
4.	Finishing						
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	100	4318.1	94%		
	4.2	External (plaster, painting, facade, etc.)	41	1233	90%		

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

Architects & Engineers

1694

APURBA BORAH

Sr.	Tasks/ Activity Sub-Structure Status		Description of work done		Percentage of total proposed work	
No.			do	ne 	propose	ed work
1.	Excav	ration				
2.	Layin	g of foundation				
	(i)	Raft	Yes		100%	
	(ii)	Pile				
3.	Numb	per of basement(s)				
	(i)	Basement Level 1	N/A			
	(ii)	Basement level 2*	N/A			
4.	Waterproofing of the above sub-structure (wherever applicable)		Yes		100%	
		Super-Structure Status				
5.	Total	floors in the tower/ building	273/27			
6.	Total	area on each floor	4080.43			
7.	Stilt f	loor/ ground floor	Yes		100%	
8.	Status	s of laying of slabs floor wise				
		lative number of slabs in the building/laid by end of quarter	Yes		100%	
9.	Status	s of construction				
	(i)	Walls on floors	Yes		100%	
	(ii)	Staircase	Yes		100%	
	(iii)	Lift wells along with water proofing	Yes		92%	
	(iv)	Lift lobbies/ common areas floor wise	Yes		75%	
10.	Fixing units	g of door and window frames in flats/	Yes		97%	
11.	Status	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Yes		30%	h,
	(ii)	Electrical works including wiring	Yes		68%	
	(iii)	Plumbing works	Yes		75%	
12.	Status	s of wall plastering				
	(i)	External plaster	Yes		100%	
	(ii)	Internal plaster	Yes		100%	
13.	Status	s of wall tiling				
	(i)	In bathroom	Yes		90%	
	(ii)	In kitchen	Yes		90%	
14.	Status	s of flooring				
	(i)	Common areas	Yes		95%	
	(ii)	Units/ flats	Yes		95%	

[🗣] Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

Architects & Engineers

APURBA BORAH

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total proposed work	
			done		
15.	Status of white washing				
	(i)	Internal walls	Yes	70%	
	(ii)	External walls	Yes	70%	
16.	Status of finishing				
	(i)	Staircase with railing	Yes	94%	
	(ii)	Lift wells	Yes	100%	
	(iii)	Lift lobbies/ common areas floor wise	Yes	72%	
17.	Status	of installation			
	(within	n flat/unit)			
	(i)	Doors and windows panels	Yes	85%	
	(ii)	Sanitary fixtures	Yes	32%	
	(iii)	Modular kitchen	N/A		
	(iv)	Electrical fittings/ lighting	N/A		
	(v)	Gas piping (if any)	N/A		
	(other	than flat/units)			
	(vi)	Lifts installation	Yes	22%	
	(vii)	Overhead tanks	Yes	100%	
	(viii)	Underground water tank	Yes	99%	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yes	36%	
	(x)	Electrical fittings in common areas	Yes	40%	
	(xi)	Compliance to conditions of environment/ CRZ NOC			
18.	Water	proofing of terraces	Yes	90%	
19.	Entra	nce lobby finishing	Yes	40%	
20.	Status	s of construction of compound wall	Yes	100%	

Note: (*) extend rows as per requirement.



Architects & Engineers

APURBA BORAH

1696

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services		110111 40110	
1.	Internal roads & pavements	Yes	92%	
2.	Parking			
	Covered no	Yes	92%	
	Open no	Yes	75%	
3.	Water supply	Yes	95%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	95%	
5.	Storm water drains	Yes	92%	
6.	Landscaping & tree plantation	Yes	82%	
7.	Parks and playgrounds	Yes	75%	
	Fixing of children play equipment's	Yes		To be ordered
	Benches	Yes		To be ordered
8.	Shopping area	Yes		
9.	Street lighting/ electrification	Yes	71%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	80%	
11.	Solid waste management & disposal			
12.	Water conservation, rain water, harvesting, percolating well/ pit			
13.	Energy management (solar)	Yes	100%	NOC BALANCE
14.	Fire protection and fire safety requirements	Yes	30%	NOC BALANCE
15.	Electrical meter room, sub-station, receiving station	Yes	62%	BALAIVEE
16.	Other (option to add more)			
B-2	Community building to be transferred to RWA			
17.	Community centre			
18.	Others			
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	Yes		
20.	Dispensary			
21.	Club	Yes		
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006