Annexure A

Architect's Certificate*

Report for quarter ending			March 2024
Subject			Certificate of progress of construction work
1.	**I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans**		
	Sr. No.	**Particulars**	**Information**
	1.	Project/Phase of the project	ILD GREEN, Residential Group Housing (Towers 2, 6 & 7)
	2.	Location	Sector 37C, Gurugram
	3.	Licensed area in acres	15.4829
	4.	Area for registration in acres	9.1490
	5.	HARERA registration no.	60/2017 Dated 18.08.2017
	6.	Name of licensee	13 of2008
	7.	Name of collaborator	Jubiliant Malls Pvt Ltd
	8.	Name of developer	ILD Millannium Private Limited
2.	**Details related to inspection are as under**		
	1.	Date of certifying of percentage of construction work/ site inspection	05.04.2024
	2.	Name of Architect/ Architect's firm	Chetanpal Singh
	3.	Date of site inspection	05.04.2024

*On the letter head of the architect firm

Ar. Chetan Pal Singh
CA/2018/91026

Annexure A

3.	**Following technical professionals are appointed by promoter: - (as applicable)**		
	Sr. No.	**Consultants**	**Name**
	1.	Site engineer	Anand Sharma
	2.	Structural consultant	R.K. Bhola
	3.	Proof consultant	nil
	4.	MEP consultant	nil
	5.	Site in charge	nil
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date	05.04.2024	Yours faithfully,
Place	: Gurugram	Ar. Chetan Pal Singh CA/2018/91026
Council of architects (CoA) registration no.	: CA/2018/91026	
Council of architects (CoA) registration valid till (date)	: 31/12/2030	

Annexure A

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**2**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter (Lac)**	**Cumulative work done value till date (Lac)**	**Percentage of work done to the total proposed work**
1.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	2543	100%
2.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0	11047	100%
3.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	1220	100%
	3.2	Electrical (Conduiting, wiring, fixtures, etc.)	0	1220	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	1220	100%
4.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	2491	95%
	4.2	External (plaster, painting, facade, etc.)	0	2150	95%

Ar. Chetan Pal Singh
CA/2018/91026

Annexure A

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	Completed		100%	
3.	Number of basement(s)					
	(i)	Basement Level 1	Completed		100%	
4.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
5.	Total floors in the tower/ building		Completed		100%	
6.	Total area on each floor		Completed		100%	
7.	Stilt floor/ ground floor		Completed		100%	
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower 1B laid by end of quarter		Completed		100%	
9.	Status of construction					
	(i)	Walls on floors	Completed		100%	
	(ii)	Staircase	Completed		100%	
	(iii)	Lift wells along with water proofing	Completed		100%	
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%	
10.	Fixing of door and window frames in flats/ units					
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Work in Progress		100%	
	(ii)	Electrical works including wiring	Work in Progress		100%	
	(iii)	Plumbing works	Work in Progress		100%	
12.	Status of wall plastering					
	(i)	External plaster	Work in Progress		100%	
	(ii)	Internal plaster	Work in Progress		100%	
13.	Status of wall tiling					
	(i)	In bathroom	Work in Progress		100%	

Ar. Chetan Pal Singh
CA/2018/91026

	(ii)	In kitchen	Work in Progress	100%
14.	Status of flooring			
	(i)	Common areas	Work in Progress	100%
	(ii)	Units/ flats	Work in Progress	100%
15.	Status of white washing			
	(i)	Internal walls	Work in Progress	100%
	(ii)	External walls	Work in Progress	100%
16.	Status of finishing			
	(i)	Staircase with railing	Work in Progress	100%
	(ii)	Lift wells	Work in Progress	100%
	(iii)	Lift lobbies/ common areas floor wise	Work in Progress	100%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Work in Progress	100%
	(ii)	Sanitary fixtures	Work in Progress	100%
	(iii)	Modular kitchen	Work in Progress	100%
	(iv)	Electrical fittings/ lighting	Work in Progress	100%
	(v)	Gas piping (if any)	Work in Progress	100%
	(other than flat/units)			
	(vi)	Lifts installation	Work in Progress	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Work in Progress	100%
	(x)	Electrical fittings in common areas	Work in Progress	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Work in Progress	100%
18.	Waterproofing of terraces		Work in Progress	100%
19.	Entrance lobby finishing		Work in Progress	100%
20.	Status of construction of compound wall		Work in Progress	100%

Note: (*) extend rows as per requirement.

Ar. Chetan Pal Singh
CA/2018/91026

Annexure A

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			**6**		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter (Lac)**	**Cumulative work done value till date (Lac)**	**Percentage of work done to the total proposed work**
5.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	848	100%
6.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0	3695	100%
7.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	407	100%
	3.2	Electrical (Conduiting, wiring, fixtures, etc.)	0	407	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	407	100%
8.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0	686	95%
	4.2	External (plaster, painting, facade, etc.)	0	613	95%

Ar. Chetan Pal Singh
CA/2018/91026

Annexure A

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
21.	Excavation		Completed		100%	
22.	Laying of foundation					
	(iii)	Raft	Completed		100%	
	(iv)	Pile	Completed		100%	
23.	Number of basement(s)					
	(ii)	Basement Level 1	Completed		100%	
24.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
25.	Total floors in the tower/ building		Completed		100%	
26.	Total area on each floor		Completed		100%	
27.	Stilt floor/ ground floor		Completed		100%	
28.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower 1B laid by end of quarter		Completed		100%	
29.	Status of construction					
	(v)	Walls on floors	Completed		100%	
	(vi)	Staircase	Completed		100%	
	(vii)	Lift wells along with water proofing	Completed		100%	
	(viii)	Lift lobbies/ common areas floor wise	Completed		100%	
30.	Fixing of door and window frames in flats/ units					
31.	Status of MEP		Internal (within flat)	External works		Status of MEP
	(iv)	Mechanical works	Work in Progress		100%	
	(v)	Electrical works including wiring	Work in Progress		100%	
	(vi)	Plumbing works	Work in Progress		100%	
32.	Status of wall plastering					
	(iii)	External plaster	Work in Progress		100%	
	(iv)	Internal plaster	Work in Progress		100%	
33.	Status of wall tiling					
	(iii)	In bathroom	Work in Progress		100%	

Ar. Chetan Pal Singh
CA/2018/91026

Annexure A

	(iv)	In kitchen	Work in Progress	100%
34.	Status of flooring			
	(iii)	Common areas	Work in Progress	100%
	(iv)	Units/ flats	Work in Progress	100%
35.	Status of white washing			
	(iii)	Internal walls	Work in Progress	100%
	(iv)	External walls	Work in Progress	100%
36.	Status of finishing			
	(iv)	Staircase with railing	Work in Progress	100%
	(v)	Lift wells	Work in Progress	100%
	(vi)	Lift lobbies/ common areas floor wise	Work in Progress	100%
37.	Status of installation			
	(within flat/unit)			
	(xii)	Doors and windows panels	Work in Progress	100%
	(xiii)	Sanitary fixtures	Work in Progress	100%
	(xiv)	Modular kitchen	Work in Progress	100%
	(xv)	Electrical fittings/ lighting	Work in Progress	100%
	(xvi)	Gas piping (if any)	Work in Progress	100%
	(other than flat/units)			
	(xvii)	Lifts installation	Work in Progress	100%
	(xviii)	Overhead tanks	Completed	100%
	(xix)	Underground water tank	Completed	100%
	(xx)	Firefighting fitting and equipment's as per CFO NOC	Work in Progress	100%
	(xxi)	Electrical fittings in common areas	Work in Progress	100%
	(xxii)	Compliance to conditions of environment/ CRZ NOC	Work in Progress	100%
38.	Waterproofing of terraces		Work in Progress	100%
39.	Entrance lobby finishing		Work in Progress	100%
40.	Status of construction of compound wall		Work in Progress	100%

Ar. Chetan Pal Singh
CA/2018/91026

Annexure A

Table – A					
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			7		
A1	**Cumulative progress of the project/phase at the end of the quarter.**				
Sr. No.	**Project components**		**Work done value during the quarter (Lac)**	**Cumulative work done value till date (Lac)**	**Percentage of work done to the total proposed work**
9.	**Sub structure** (inclusive of excavation, foundation, basements, water proofing, etc.)		0	848	100%
10.	**Super structure** (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0	3695	100%
11.	**MEP**				
	3.1	Mechanical (lifts, ventilation, etc.)	0	407	100%
	3.2	Electrical (Conduiting, wiring, fixtures, etc.)	0	407	100%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0	407	100%
12.	**Finishing**				
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	30	686	95%
	4.2	External (plaster, painting, facade, etc.)	25	613	95%

Ar. Chetan Pal Singh
CA/2018/91026

Annexure A

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
41.	Excavation		Completed		100%	
42.	Laying of foundation					
	(v)	Raft	Completed		100%	
	(vi)	Pile	Completed		100%	
43.	Number of basement(s)					
	(iii)	Basement Level 1	Completed		100%	
44.	Waterproofing of the above sub-structure (wherever applicable)		Completed		100%	
	Super-Structure Status					
45.	Total floors in the tower/ building		Completed		100%	
46.	Total area on each floor		Completed		100%	
47.	Stilt floor/ ground floor		Completed		100%	
48.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower 1B laid by end of quarter		Completed		100%	
49.	Status of construction					
	(ix)	Walls on floors	Completed		100%	
	(x)	Staircase	Completed		100%	
	(xi)	Lift wells along with water proofing	Completed		100%	
	(xii)	Lift lobbies/ common areas floor wise	Completed		100%	
50.	Fixing of door and window frames in flats/ units					
51.	Status of MEP		Internal (within flat)	External works		Status of MEP
	(vii)	Mechanical works	Work in Progress		100%	
	(viii)	Electrical works including wiring	Work in Progress		100%	
	(ix)	Plumbing works	Work in Progress		100%	
52.	Status of wall plastering					
	(v)	External plaster	Work in Progress		100%	
	(vi)	Internal plaster	Work in Progress		100%	
53.	Status of wall tiling					
	(v)	In bathroom	Work in Progress		100%	

Ar. Chetan Pal Singh
CA/2018/91026

	(vi)	In kitchen	Work in Progress	100%
54.	Status of flooring			
	(v)	Common areas	Work in Progress	100%
	(vi)	Units/ flats	Work in Progress	100%
55.	Status of white washing			
	(v)	Internal walls	Work in Progress	100%
	(vi)	External walls	Work in Progress	100%
56.	Status of finishing			
	(vii)	Staircase with railing	Work in Progress	100%
	(viii)	Lift wells	Work in Progress	100%
	(ix)	Lift lobbies/ common areas floor wise	Work in Progress	100%
57.	Status of installation			
	(within flat/unit)			
	(xxiii	Doors and windows panels	Work in Progress	100%
	(xxiv	Sanitary fixtures	Work in Progress	100%
	(xxv)	Modular kitchen	Work in Progress	100%
	(xxvi	Electrical fittings/ lighting	Work in Progress	100%
	(xxvi	Gas piping (if any)	Work in Progress	100%
	(other than flat/units)			
	(xxvi	Lifts installation	Work in Progress	100%
	(xxix	Overhead tanks	Completed	100%
	(xxx)	Underground water tank	Completed	100%
	(xxxi	Firefighting fitting and equipment's as per CFO NOC	Work in Progress	100%
	(xxxi	Electrical fittings in common areas	Work in Progress	100%
	(xxxi	Compliance to conditions of environment/ CRZ NOC	Work in Progress	100%
58.	Waterproofing of terraces		Work in Progress	100%
59.	Entrance lobby finishing		Work in Progress	100%
60.	Status of construction of compound wall		Work in Progress	100%

Ar. Chetan Pal Singh
CA/2018/91026

Annexure A

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	**Services**			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			
	Covered no.		100%	
	Open no.		-NA-	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes		
7.	Parks and playgrounds			
	Fixing of children play equipment's			
	Benches			
8.	Shopping area			
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal			
12.	Water conservation, rainwater, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes		
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)			
B-2	**Community building to be transferred to RWA**			
17.	Community centre			
18.	others			
B-3	**Community buildings not to be transferred to RWA/competent authority**			
19.	Schools			
20.	Dispensary			
21.	Club			
22.	Others			
B-4	**Services/ facilities to be transferred to competent authority**			
23.	*			

Note: (*) extend as per requirement

Ar. Chetan Pal Singh
CA/2018/91026