## BEE BEE ARCHITECT

Architects & Enginee

### APURBA BORA

Annexure A

		Architect	's Certificate*			
Repor	Report for quarter ending		31 MAR 2021			
Subject			Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Project Area 53013.82 sq mtr , Omaxe City Faridabad			
	2.	Location	Village Kheri Kalan , Taju Pur Road Sector-97 Faridabad			
	3.	Licensed area in acres	13.10 acres			
	4.	Area for registration in acres	13.10 acres			
	.5.	HARERA registration no.	HRERA-PKL-FBD-130-2019			
	6.	Name of licensee	Harthal Builders & Developers Private Ltd.			
	7.	Name of collaborator	E			
	8.	Name of developer	Harthal Builders & Developers Private Ltd.			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection				
	2.	Name of Architect/ Architect's firm	BEE BEE Architects			
	3.	Date of site inspection				

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

### Architects & Engineers

### APURBA BORAH

3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name		
	1.	Site engineer	Mr. D.C Pant		
	2.	Structural consultant	Mr. Pankaj Varshney		
	3.	Proof consultant			
	4.	MEP consultant	Mr. Digambar Singh		
	5.	Site incharge	Mr. D.C Pant		
4.	Haryan constru envisag	a Building Code, 2017/ National Buction, infrastructure works and interest and inte	d as per approved drawings, statutory/ mandatory approvals, uilding Code (wherever applicable) and the material used in the ernal development works are as per the projected standard as re, publication material and other documents shared with the		
5.	of the below.	real estate project/phase of the project	ntage of work done in the project for each of the building/ tower ect under HARERA is as per table A and table B given herein atted with respect to each of the activity of the entire project/		

Date : Yours faithfully,

Signature & name (in block letters) with Place : stamp of architect

Council of architects (CoA) registration no. : CA/2013/61618 Council of architects (CoA) registration valid till (date)

PURBA BORAH Reg Architect Reg 013/61618

# BEE BEE ARCHITECT Architects & Engine

APURBA BORA

	Table – A						
(to be	prepar	ower no. ed separately for each building/ tower // phase of the project)					
A1	rter.						
Sr. No.	Project components  Sub structure (Inclusive of excavation, foundation, basements, water proofing, etc.)		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1.			N/A	-	-		
2.	Super structure (Slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		N/A	-			
3.	MEP						
	3.1	Mechanical (Lifts, ventilation, etc.)	N/A				
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	N/A	-			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	N/A	-			
4.	Finishing						
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	N/A	-			
	4.2	External (plaster, painting, facade, etc.)	N/A	-			



Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

BEE BEE ARCHITECTS

**Architects & Engineers** 

4

#### APURBA BORAH

Sr.	Tasks/ Activity Sub-Structure Status		Description of work done		Percentage of total proposed work	
No.						
1.	Excar	vation.	N		N/A	
2.	Layin	ng of foundation	N	/A	N	/A
	(i)	Raft				
	(ii)	Pile				
3.	Number of basement(s)		N	/A ·	N/	/A
	(i)	Basement Level 1				
	(ii)	Basement level 2*				
	(iii)	Basement Level 3				
	(iv)	Basement Level 4				
4.	Water (when	rproofing of the above sub-structure rever applicable)				
	Super-Structure Status		N/A		N/A	
5.	Total	floors in the tower/ building				
6.	Total	area on each floor				
7.	Stilt f	loor/ ground floor				
8.	Status	s of laying of slabs floor wise				
		ulative number of slabs in the building/				
9.	Status	s of construction				
	(i)	Walls on floors				
	(ii)	Staircase				
	(iii)	Lift wells along with water proofing				
	(iv)	Lift lobbies/ common areas floor wise				
10.	Fixing units	g of door and window frames in flats/				
11.	Status	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works		-		
	(ii)	Electrical works including wiring		-		
	(iii)	Plumbing works		-		
12.	Status	s of wall plastering				
	(i)	External plaster		-		
	(ii)	Internal plaster		-		
13.	Status	s of wall tiling				
	(i)	In bathroom		-		
	(ii)	In kitchen		-		
14.	Status	s of flooring				
	(i)	Common areas		-		
	(ii)	Units/ flats	7		11	ma /

# BEE BEE ARCHIT

APURBA

Sr.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total
No.			done	proposed work
15.	Status	of white washing		
	(i)	Internal walls	-	
	(ii)	External walls	-	
16.	Status of finishing			
	(i)	Staircase with railing	•	
7	(ii)	Lift wells	-	
	(iii)	Lift lobbies/ common areas floor wise	-	
7.	Status	of installation		
	(within flat/unit)			
	(i)	Doors and windows panels	-	
	(ii)	Sanitary fixtures	-	
	(iii)	Modular kitchen	<u>-</u>	
	(iv)	Electrical fittings/ lighting	-	
	(v)	Gas piping (if any)	-	
	(other than flat/units)			
	(vi)	Lifts installation	-	
	(vii)	Overhead tanks	-	
	(viii)	Underground water tank	-	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	-	
	·(x)	Electrical fittings in common areas	-	
	(xi)	Compliance to conditions of environment/ CRZ NOC	-	
18.	Water	proofing of terraces	-	
19.	Entra	nce lobby finishing	-	
20.	Status	s of construction of compound wall	-	

PURBA BORAN Architect Reg. Architect CAI2013I61618

Pragati Pathi, Mathura Nagar, Dispur, Guwahati Kamrup, Assam-781006

### **Architects & Engineers**

#### APURBA BORAH

Table – B

r. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements		-	
2.	Parking	-	-	
	Covered no	-	-	
	Open no		-	
3.	Water supply	YES	70%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	10%	
5.	Storm water drains	YES	85%	
6.	Landscaping & tree plantation	YES	-	
7.	Parks and playgrounds	-		
	Fixing of children play equipment's	-		
	Benches	-		
8.	Shopping area	N/A	1	
9.	Street lighting/ electrification	YES	50%	l.
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%	
11.	Solid waste management & disposal	-		
12.	Water conservation, rain water, harvesting, percolating well/ pit	-		
13.	Energy management (solar)	-		
14.	Fire protection and fire safety requirements			
15.	Electrical meter room, sub-station, receiving station	-		
16.	Other (option to add more)	-		
B-2	Community building to be transferred to RWA			91
17.	Community center	-		
18.	Others	-		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	-		
20.	Dispensary	-		
21.	Club	-		
22.	Others	-		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (\*) extend as per requirement

PURBA BORAN PURBA rohitect Reg 013/61618