Architecture Planning Urban Design Interiors

	Architect's Certificate ¹				
Repor	eport for quarter ended		30 th June 2024		
Subje	Subject		Certificate of progress of construction work		
1.	1 '		nt as architect for certifying progress of ntioned project as per the approved plans		
	Sr. Particulars No.		Information		
	1.	Project/Phase of the project	Elevate Phase – I		
	2.	Location	Village Behrampur, Sector-59, Gurugram		
	3.	Licensed area in acres	8.91875		
	4.	Area for registration in acres	5.95		
	5.	HARERA registration no.	19 of 2019		
	6.	Name of licensee	License no. 16 of 2008 : 1) BTVS Buildwell Pvt. Ltd.		
			1,51,65 2010 4011 101 200		



Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Page **1** of **25**

			2) Adson Software Pvt. Ltd. 3) Bulls Realtors Pvt. Ltd. 4) Commander Realtors Pvt. Ltd. 5) Fiverivers Developers Pvt. Ltd. 6) Fiverivers Townships Pvt. Ltd. 7) Ornamental Realtors Pvt. Ltd. 8) Aspirant Builders Pvt. Ltd. License no. 28 of 2008: 1) BTVS Buildwell Pvt. Ltd. 2) Golden View Builders Pvt. Ltd. 3) Hi Energy Realtors Pvt. Ltd. 4) Base Exports Pvt. Ltd. 5) Adson Software Pvt. Ltd. 6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. License no. 44 of 2011: 1) Commander Realtors Pvt. Ltd. 2) BTVS Buildwell Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd. 7) Bulls Realtors Pvt. Ltd.
ļ	7.	Name of collaborator	Heritage Max Realtech Pvt. Ltd.
	8.	Name of developer	Heritage Max Realtech Pvt. Ltd.
2.	Detail	s related to inspection are as	under
	1.	Date of certifying of percentage of construction work/ site inspection	30 th June 2024
	•	*	

2.	Name of Architect/ Architect's firm	Arcop associates Private Limited
3.	Date of site inspection	30 th June 2024

	Sr. No.	Consultants	Name
	1.	Site engineer	Vijayant Singh
	2.	Structural consultant	Vintech Consultant (Mr. Vinod Jain)
	3.	Proof consultant	Mehro Consultants
	4.	MEP consultant	Sanelac Consultants Pvt Ltd
	5.	Site supervisor/incharge	Avinash Nagpal
4.	manda applic develo	atory approvals, Haryana Buildir able) and the material used in th opment works are as per the pro ochure, publication material and	decuted as per approved drawings, statutory, ag Code, 2017/National Building Code (wherever e construction, infrastructure works and internablected standard as envisaged in the registration dother documents shared with the buyers in this
5.	the bu	ilding/ tower of the real estate p	ercentage of work done in the project for each or project/phase of the project under HARERA is as elow. The percentage of the work executed with

respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date

Yours faithfully,

Place

: N. DECHI

Signature & name (in block letters) with stamp of architect

Registration No.: CA/2001/27447

Council of architects (CoA) : CA/2001/27447

Labib Alam, Architect Council of Architecture

registration no.

Council of architects (CoA): registration valid till (date)

31-12-2027

		· •	Гable - A		
(to build	be p	Tower no. repared separately for each tower in the project/ phase of t)	Tower-A	¥	
A1	Cun	nulative progress of the projec	t/phase at the e	nd of the quarte	r.
Sr. No.	Proj	ject components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	(incl	structure lusive of excavation, idation, basements, water ofing, etc.)	0	35.00	100%
2.	(slat	er structure os, brick work, block work, case, lift wells, machine rooms, er tank, etc.)	0	56.00	100%
3.	MEP)			
	3.1	Mechanical (lifts, ventilation, etc.)	1.16	16.70	100 %
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1.15	9.76	100 %

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.15	9.88	100%
4.	Finis	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	1.16	15.02	100%
	4.2	External (plaster, painting, facade, etc.)	1.17	12.45	100%

Sr. No.		Tasks/ Activity Sub-Structure Status	Description of work done	Percentage of total proposed work
1.	Exca	vation	Complete	100 %
2.	Layi	ng of foundation		
	(i)	Raft	Complete	100 %
	(ii)	Pile	NA	NA
3.	Num	ber of basement(s)	÷	
	(i)	Basement Level 1	Structure under Tower Footprint Complete	100%
	(ii)	Basement level 2*	Structure under Tower Footprint Complete	100%
4.	1	erproofing of the above sub- cture (wherever applicable)	Above deck waterproofing	100%

		Super-Structure Status		
5.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 31 Apt Floors	100%
6.	Tota	l area on each floor	785 Sqm	100%
7.	Stilt	floor/ ground floor	Structure Tower Entrance	100%
8.	Statu	s of laying of slabs floor wise	Upto terrace Level Completed	100%
	1	ulative number of slabs in the	Total Slabs	100%
		ling/ tower laid by of quarter	1Stilt+1Service Floor+31 Apt Floor	
9.	Statu	s of construction		
	(i)	Blockwork	100% Completed	100%
	(ii)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(iii)	Lift Well including Machine room	100% Completed	100%
	(iv)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
10.		g of door and window frames in / units		
11.	Statu	s of MEP	Internal (within flat)	External works
	(i)	NA	NA	0
	(ii)	Apartment Electrical Wiring	100% Completed	100%.
	(iii)	UPVC/ RWP Piping	100% Completed	100%
12.	Statu	s of wall plastering		

	(i)	RCC External Wall	NA	0
	(ii)	Gypsum Plaster	100% (31 of 31 Floor completed)	100%
13.	Statı	us of wall tiling		
	(i)	Bathroom Tiles	100% Completed	
	(ii)	Kitchen Wall Tile	100% Completed	
14.	Statı	us of flooring		
	(i)	Lift Lobby Flooring	100% Completed	
	(ii)	Apt Stone Flooring	100% Completed	
15.	Statı	us of white washing		
	(i)	Apartment Prefinal Paint	100% Completed	
	(ii)	Putty+1stCoat+2nd Coat	100% Completed	
16.	Statu	us of finishing		
	(i)	MS Railing		100% Completed in staircase
	(ii)	Lift Well HO for Lift Installation	100% Completed	0
	(iii)	Lobby Wall Tiling	100% Completed	
17.	Statu	s of installation		
	(with	nin flat/unit)		
	(i)	UPVC Windows	100% Completed	
	(ii)	Bathroom Chinaware	100% Completed	
	(iii)	Modular Kitchen Cabinet Installation (Without Panels)	100% Completed	

Labib Alam, Architect
Council of Architecture

Council of Architecture
Registration No.: CA/2001/27447
Page 8 of 25

1 3	(iv)	Switch & Sockets	100% Completed	
	(v)	NA	NA	0
	(othe	er than flat/units)		
	(vi)	Guide Rail+ Floor Door+ Car Installation	100%	
	(vii)	RCC Work	100% Completed	0
	(viii)	RCC Work	100% Completed	0
	(ix)	Fire Pump Installation	100% Completed	0
	(x)	Staircase & Lobby Wiring	100% Completed	0
	(xi)	Six Monthly Compliance	100% Compliance	0
18.	Wate	erproofing of terraces	PU Waterproofing	100% Completed
19.	Entra	ance lobby finishing	Gypsum False ceiling	100% Completed
20.	Statu wall	s of construction of compound	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower-A

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking	Yes		-
	Covered no	Yes	100%	
	Open no	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	-
8.	Shopping area	Yes	0%	(F)
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	

16.	Other (option to add more)	NA		
B-2	Community building to be transferred	to RWA		
17.	Community centre	Yes	100%	
18.	Others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	Yes	100%	
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	NA		
23.	*			

Note: (*) extend as per requirement

	Table – A						
(to build	be p	Tower no. repared separately for each tower in the project/ phase of t)	Tower-B				
A1	Cun	nulative progress of the projec	t/phase at the en	nd of the quarte	r.		
Sr. No.	-		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
5.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0	35.00	100%		
6.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0	60.05	100%		
7.	MEP)					
	3.1	Mechanical (lifts, ventilation, etc.)	0.80	14.80	100%		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.98	9.41	100%		

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.90	9.91	100%
8.	Finis	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.92	15.87	100%
	4.2	External (plaster, painting, facade, etc.)	0.40	11.26	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status			
21.	Exca	vation	Complete	100 %	
22.	Laying of foundation				
	(iii)	Complete	100 %	100 %	
	(iv)	NA	NA	0	
23.	Number of basement(s)				
	(iii)	Structure under Tower Footprint Complete	Complete	100%	
	(iv)	Structure under Tower Footprint Complete	Complete	100%	
24.	Waterproofing of the above substructure (wherever applicable)		Deck Water Proofing	100%	
		Super-Structure Status		. 0	

25.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 33 Apt Floors	100%
26.	Total area on each floor		772 Sqm	100%
27.	Stilt	floor/ ground floor	Structure Tower Entrance	100% Completed
28.	Statı	us of laying of slabs floor wise	Upto terrace Level Completed	100%
	build	ulative number of slabs in the ling/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
29.	Status of construction			
	(v)	Blockwork	Completed	100%
	(vi)	Staircase Concreting upto Terrace Slab		100%
	(vii)	Lift Well including Machine room		100%
	(viii)	Structure lift lobbies and other common area upto 31 Floor		100%
30.	1	g of door and window frames in units	Door Frame	100% Completed
31.	Statu	s of MEP	Internal (within flat)	External works
	(iv)	NA	NA	
	(v)	Apartment Electrical Wiring	100% Completed	100% Completed
	(vi)	UPVC/ RWP Piping	100% Completed	
32.	Statu	s of wall plastering		
	(iii)	RCC External Wall	NA	()

11 41 9	(iv)	Gypsum Plaster	100%	
33.	Statu	ls of wall tiling		
	(iii)	Bathroom Tiles	100% Completed	
	(iv)	Kitchen Wall Tile	100% Completed	
34.	Statu	s of flooring		
	(iii)	Lift Lobby Flooring	100% Completed	
	(iv)	Apt Stone Flooring	100% Completed	
35.	Statu	s of white washing		
	(iii)	Apartment Prefinal Paint	100% Completed	
	(iv)	Putty+1stCoat+2nd Coat	100% Completed	
36.	Statu	s of finishing		
	(iv)	MS Railing	100% Completed	
	(v)	Lift Well HO for Lift Installation	100% Completed	
	(vi)	Lobby Wall Tiling	100% Completed	
37.	Statu	s of installation		
	(with	in flat/unit)		
	(xii)	UPVC Windows	100% Completed	
	(xiii)	Bathroom Chinaware	100% Completed	
	(xiv)	Modular Kitchen Cabinet Installation (Without Panels)	100% Completed	
	(xv)	Switch & Sockets	100% Completed	
	(xvi)	NA	NA	
	(othe	r than flat/units)		10-

Labib Alam, Architect
Council of Architecture
Registration No. Page 95 27 25

	(xvii	Guide Rail+ Floor Door+ Car Installation	100 % Complete	
	(xvii	RCC Work	100% Completed	
	(xix)	RCC Work	100% Completed	
¥.	(xx)	Fire Pump Installation	100% Completed	
	(xxi)	Staircase & Lobby Wiring	100% Completed	
	(xxii)	Six Monthly Compliance	100% Compliance	
38.	Wate	erproofing of terraces	PU Waterproofing	100% Completed
39.	Entra	ance lobby finishing	Gypsum False ceiling	100% Completed
40.	Status of construction of compound wall		Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks
B-1	Services	1		
24.	Internal roads & pavements	Yes	100%	
25.	Parking	Yes		
	Covered no	Yes	100%	
	Open no	Yes	100%	
26.	Water supply	Yes	100%	
27.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
28.	Storm water drains	Yes	100%	
29.	Landscaping & tree plantation	Yes	100%	
30.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
31.	Shopping area	Yes	0%	
32.	Street lighting/ electrification	Yes	100%	
33.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
34.	Solid waste management & disposal	Yes	100%	
35.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
36.	Energy management (solar)	Yes	100%	
37.	Fire protection and fire safety requirements	Yes	100%	
38.	Electrical meter room, sub-station, receiving station	Yes	100%	,

39.	Other (option to add more)	NA		W
B-2	Community building to be transferred	to RWA	•	
40.	Community centre	Yes	100%	
41.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
42.	Schools	NA		
43.	Dispensary	NA		
44.	Club	Yes	100%	
45.	Others	NA	= =	
B-4	Services/ facilities to be transferred to competent authority	NA		
46.	*			

Note: (*) extend as per requirement

			Гable – A		
(to build	be p	Tower no. repared separately for each tower in the project/ phase of	Tower-C		ı
A1	Cum	ulative progress of the projec	t/phase at the en	nd of the quarte	r.
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
9.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0	24.96	100%
10.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0	40.02	100%
11.	МЕР			r è	
	3.1	Mechanical (lifts, ventilation, etc.)	0.12	9.11	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.13	6.76	100%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.14	7.12	100%
12.	Finis	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.15	12.79	100%
	4.2	External (plaster, painting, facade, etc.)	0.16	4.61	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
		Sub-Structure Status		
41.	Exca	vation	Complete	100 %
42.	Layi	ng of foundation		
	(v)	Complete		100%
	(vi)	NA	NA	0
43.	Number of basement(s)			
	(v)	Structure under Tower Footprint Complete		100%
	(vi)	Structure under Tower Footprint Complete		100%
44.	Waterproofing of the above substructure (wherever applicable)		Deck Water Proofing	100%
		Super-Structure Status		

Labib Alam, Architect

Registration No.: CA/2001/27447

45.	Total floors in the tower/ building 1Stilt+1Service Floor + 30 Apt Floors		100%	
46.	Total area on each floor		549 Sqm	100%
47.	Stilt	floor/ ground floor	Structure Tower Entrance	100% Completed
48.	Statu	s of laying of slabs floor wise	Upto terrace Level Completed	100%
	building/ tower laid by end of quarter		Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
49.	Status of construction			
	(ix)	Blockwork	100% Completed	
	(x)	Staircase Concreting upto Terrace Slab	100% Completed	
	(xi)	Lift Well including Machine room	100% Completed	
	(xii)	Structure lift lobbies and other common area upto 30 Floor	100% Completed	
50.	1	g of door and window frames in units	Door Frame	100% Completed
51.	Statu	s of MEP	Internal (within flat)	External works
	(vii)	NA	NA	
	(viii)	Apartment Electrical Wiring	100% Completed	100% Completed
	(ix)	UPVC/ RWP Piping	100% Completed	
52.	Statu	s of wall plastering	., .	
	(v)	RCC External Wall	NA ,	

Labib Alam, Architect

Council of Architecture
Registration No.: CA/2001/2Páge 21 of 25

				,
	(vi)	Gypsum Plaster	100%	
53.	Statu	is of wall tiling		
	(v)	Bathroom Tiles	100% Completed	
	(vi)	Kitchen Wall Tile	100% Completed	
54.	Status of flooring			
	(v)	Lift Lobby Flooring	100% Completed	
İ	(vi)	Apt Stone Flooring	100% Completed	
55.	Statu	is of white washing		
	(v)	Apartment Prefinal Paint	100% Completed	
	(vi)	Putty+1stCoat+2nd Coat	100% Completed	
56.	Status of finishing			
91	(vii)	MS Railing	100% Completed	
	(viii)	Lift Well HO for Lift Installation	100% Completed	
	(ix)	Lobby Wall Tiling	100% Completed	
57.	. Status of installation			
	(with	nin flat/unit)		
	(xxiii	UPVC Windows	100% Completed	
	(xxiv	Bathroom Chinaware	100%	
	(xxv)	Modular Kitchen Cabinet Installation (Without Panels)	100%	
	(xxvi	Switch & Sockets	100% Completed	
	(xxvi	NA	NA	
	(othe	er than flat/units)	1	N.O.
				ンメン

(2)	(xxvi Guide Rail+ Floor Door+ Car Installation	100% Complete	
	(xxix RCC Work	100% Completed	
	(xxx) RCC Work	100% Completed	
	(xxxi Fire Pump Installation	100% Completed	
	(xxxi Staircase & Lobby Wiring	100% Completed	
	(xxxi Six Monthly Compliance	100% Compliance	
58.	Waterproofing of terraces	PU Waterproofing	100% Completed
59.	Entrance lobby finishing	Gypsum False ceiling	100% Completed
60.	Status of construction of compound wall	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower C

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks		
B-1	Services					
47.	Internal roads & pavements	Yes	100%			
48.	Parking	Yes		-		
	Covered no	Yes	100%			
	Open no	Yes	100%			
49.	Water supply	Yes	100%	Ē		
50.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%			
51.	Storm water drains	Yes	100%	-		
52.	Landscaping & tree plantation	Yes	100%			
53.	Parks and playgrounds	Yes	100%			
	Fixing of children play equipment's	Yes	100%			
	Benches	Yes	100%			
54.	Shopping area	Yes	0%			
55.	Street lighting/ electrification	Yes	100%			
56.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%			
57.	Solid waste management & disposal	Yes	100%			
58.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%			
59.	Energy management (solar)	Yes	100%			
60.	Fire protection and fire safety requirements	Yes	100%			
61.	Electrical meter room, sub-station, receiving station	Yes	100%			

62.	Other (option to add more)	NA ·		A	
B-2	Community building to be transferred to RWA				
63.	Community centre	Yes	100%		
64.	others	NA			
B-3	Community buildings not to be transferred to RWA/competent authority				
65.	Schools	NA			
66.	Dispensary	NA			
67.	Club	Yes	100%		
68.	Others	NA			
B-4	Services/ facilities to be transferred to competent authority	NA			
69.	*				

Note: (*) extend as per requirement