Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

	Architect's Certificate ¹						
Repo	rt for q	uarter ended	30st September 2024				
Subje	Subject		Certificate of progress of construction work				
1.	I/We have undertaken assignme construction work in the below me		nt as architect for certifying progress of ntioned project as per the approved plans				
	Sr. No.	Particulars	Information				
	1.	Project/Phase of the project	Elevate Phase – I				
	2.	Location	Village Behrampur, Sector-59, Gurugram				
	3.	Licensed area in acres	8.91875				
	4.	Area for registration in acres	5.95				
	5.	HARERA registration no.	19 of 2019				
	6.	Name of licensee	License no. 16 of 2008 : 1) BTVS Buildwell Pvt. Ltd.				

	1.	Date of certifying of percentage of construction work/ site inspection	30st September 2024
2.	Detai	ls related to inspection are as	under
	8.	Name of developer	Heritage Max Realtech Pvt. Ltd.
	7.	Name of collaborator	Heritage Max Realtech Pvt. Ltd.
			License no. 44 of 2011: 1) Commander Realtors Pvt. Ltd. 2) BTVS Buildwell Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd. 7) Bulls Realtors Pvt. Ltd. 8) Fiverivers Buildcon Pvt. Ltd.
			6) Fiverivers Townships Pvt. Ltd. 7) Ornamental Realtors Pvt. Ltd. 8) Aspirant Builders Pvt. Ltd. License no. 28 of 2008: 1) BTVS Buildwell Pvt. Ltd. 2) Golden View Builders Pvt. Ltd. 3) Hi Energy Realtors Pvt. Ltd. 4) Base Exports Pvt. Ltd. 5) Adson Software Pvt. Ltd. 6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd.
			2) Adson Software Pvt. Ltd.3) Bulls Realtors Pvt. Ltd.4) Commander Realtors Pvt. Ltd.5) Fiverivers Developers Pvt. Ltd.

	2.	Name of Architect/ Architect's firm	Arcop associates Private Limited			
	3.	Date of site inspection	30st September 2024			
3.	Follo	wing technical professionals a	re appointed by promoter: - (as applicable)			
	Sr. No.	Consultants	Name			
	1.	Site engineer	Vijayant Singh			
	2.	Structural consultant	Vintech Consultant (Mr. Vinod Jain)			
	3.	Proof consultant	Mehro Consultants			
	4.	MEP consultant	Sanelac Consultants Pvt Ltd			
	5.	Site supervisor/incharge	Vijayant Singh			
4.	I certify that the work has been executed as per approved drawings, statuto mandatory approvals, Haryana Building Code, 2017/ National Building Code (where applicable) and the material used in the construction, infrastructure works and interdevelopment works are as per the projected standard as envisaged in the registrat and brochure, publication material and other documents shared with the buyers in regard.					
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with					

respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date

.

Yours faithfully,

Place

.

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) : CA/2001/274447

registration no.

-A/2001/27447 Labib Alam, Architecture

Registration No.: CA/2001/27447

Council of architects (CoA) : 3/-12-2027

registration valid till (date)

	Table - A						
(to build	be pr	Tower no. repared separately for each cower in the project/ phase of	Tower-A				
A1	Cum	ulative progress of the projec	t/phase at the e	nd of the quarte	r.		
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0	35.00	100%		
2.	Super structure (slabs, brick work, block work, staircase, lift wells, machine rooms, water tank, etc.)		0	56.00	100%		
3.	МЕР				44		
	3.1	Mechanical (lifts, ventilation, etc.)	1.20	17.90	100 %		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.91	10.67	100 %		

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.40	11.28	100%
4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.10	17.12	100%
	4.2	External (plaster, painting, facade, etc.)	1.40	13.85	100%

Sr. No.		Tasks/ Activity Description of work done		Percentage of total proposed work
		Sub-Structure Status		
1.	Exca	vation	Complete	100 %
2.	2. Laying of foundation			
	(i)	Raft	Complete	100 %
	(ii)	Pile	NA	NA
3.	Num	ber of basement(s)		
	(i)	Basement Level 1	Structure under Tower Footprint Complete	100%
	(ii)	Basement level 2*	Structure under Tower Footprint Complete	100%
4.		erproofing of the above sub- cture (wherever applicable)	Above deck waterproofing	100%

		Super-Structure Status		
5.	Tota	I floors in the tower/ building	1Stilt+1Service Floor + 31 Apt Floors	100%
6.	Total area on each floor 785 Sq		785 Sqm	100%
7.	Stilt floor/ ground floor Structure To Entrance			100%
8.	Statu	us of laying of slabs floor wise	Upto terrace Level Completed	100%
	Cumulative number of slabs in the building/ tower laid by end of quarter		Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
9.	Status of construction			
	(i)	Blockwork	100% Completed	100%
	(ii)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(iii)	Lift Well including Machine room	100% Completed	100%
	(iv)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
10.		g of door and window frames in / units		
11.	Statu	s of MEP	Internal (within flat)	External works
	(i)	NA	NA	0
	(ii)	Apartment Electrical Wiring	100% Completed	100%
	(iii)	UPVC/ RWP Piping	100% Completed	100%
12.	Statu	s of wall plastering		Callo)

	(i)	RCC External Wall	NA	0
	(ii)	Gypsum Plaster	100% (31 of 31 Floor completed)	100%
13.	Statı	is of wall tiling		
	(i)	Bathroom Tiles	100% Completed	
	(ii)	Kitchen Wall Tile	100% Completed	
14.	Statu	us of flooring		
	(i)	Lift Lobby Flooring	100% Completed	
	(ii)	Apt Stone Flooring	100% Completed	
15.	Statu	us of white washing		
	(i)	Apartment Prefinal Paint	100% Completed	
	(ii)	Putty+1stCoat+2nd Coat	100% Completed	
16.	Statu	us of finishing		
	(i)	MS Railing		100% Completed in staircase
	(ii)	Lift Well HO for Lift Installation	100% Completed	
	(iii)	Lobby Wall Tiling	100% Completed	
17.	Statı	us of installation		
	(with	nin flat/unit)		
	(i)	UPVC Windows	100% Completed	
	(ii)	Bathroom Chinaware	100% Completed	
	(iii)	Modular Kitchen Cabinet Installation (Without Panels)	100% Completed	John Archite

	(iv)	Switch & Sockets	100% Completed	
	(v)	NA	NA	0
	(othe	er than flat/units)		
	(vi)	Guide Rail+ Floor Door+ Car Installation	100%	
	(vii)	RCC Work	100% Completed	0
	(viii)	RCC Work	100% Completed	0
	(ix)	Fire Pump Installation	100% Completed	0
	(x)	Staircase & Lobby Wiring	100% Completed	0
	(xi)	Six Monthly Compliance	100% Compliance	0
18.	Wate	rproofing of terraces	PU Waterproofing	100% Completed
19.	Entra	nnce lobby finishing	Gypsum False ceiling	100% Completed
20.	Statu wall	s of construction of compound	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Labib Alam, Architect
Council of Architecture

Registration No.: CA/2001/27447

Table - B Tower-A

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking	Yes		
	Covered no	Yes	100%	
	Open no	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	-,
	Benches	Yes	100%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	Alam, Arch

16.	Other (option to add more)	NA			."
B-2	Community building to be transferred to RWA				
17.	Community centre	Yes	100%		
18.	others	NA			
В-3	Community buildings not to be transferred to RWA/competent authority				
19.	Schools	NA			
20.	Dispensary	NA			
21.	Club	Yes	100%		
22.	Others	NA			
B-4	Services/ facilities to be transferred to competent authority	NA			
23.	*				Q

Note: (*) extend as per requirement

		•	Гable – А				
Building/Tower no. (to be prepared separately for each building/tower in the project/phase of the project)			Tower-B				
A1	Cum	ulative progress of the projec	progress of the project/phase at the end of the quarter.				
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
5.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0	35.00	100%		
6.	(slat	er structure os, brick work, block work, case, lift wells, machine os, water tank, etc.)	0	60.05	100%		
7.	МЕР			,			
	3.1	Mechanical (lifts, ventilation, etc.)	1.72	16.52	100%		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1.01	10.42	100%		

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.31	11.22	100%
8.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.02	17.89	100%
	4.2	External (plaster, painting, facade, etc.)	1.01	12.27	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status			
21.	Exca	vation	Complete	100 %	
22.	Layi	ng of foundation			
	(iii)	Complete	100 %	100 %	
	(iv)	NA	NA	0	
23.	Number of basement(s)				
	(iii)	Structure under Tower Footprint Complete	Complete	100%	
	(iv)	Structure under Tower Footprint Complete	Complete	100%	
24.	Waterproofing of the above sub- structure (wherever applicable) Super-Structure Status		Deck Water Proofing	100%	
				Labib Alam, Ard	

25.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 33 Apt Floors	100%
26.	Total area on each floor		772 Sqm	100%
27.	Stilt floor/ ground floor		Structure Tower Entrance	100% Completed
28.	Statu	s of laying of slabs floor wise	Upto terrace Level Completed	100%
	Cumulative number of slabs in the building/ tower laid by end of quarter		Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
29.	Status of construction			
	(v)	Blockwork	Completed	100%
	(vi)	Staircase Concreting upto Terrace Slab		100%
	(vii)	Lift Well including Machine room		100%
	(viii)	Structure lift lobbies and other common area upto 31 Floor		100%
30.		g of door and window frames in units	Door Frame	100% Completed
31.	Statu	is of MEP	Internal (within flat)	External works
	(iv)	NA	NA	
	(v)	Apartment Electrical Wiring	100% Completed	100% Completed
	(vi)	UPVC/ RWP Piping	100% Completed	
32.	Statu	s of wall plastering		
	(iii)	RCC External Wall	NA	Law 1

	(iv)	Gypsum Plaster	100%	
33.	Statu	s of wall tiling		
	(iii)	Bathroom Tiles	100% Completed	
	(iv)	Kitchen Wall Tile	100% Completed	·
34.	Statu	s of flooring		
	(iii)	Lift Lobby Flooring	100% Completed	
	(iv)	Apt Stone Flooring	100% Completed	
35.	Statu	s of white washing		
	(iii)	Apartment Prefinal Paint	100% Completed	
	(iv)	Putty+1stCoat+2nd Coat	100% Completed	
36.	Status of finishing			
	(iv)	MS Railing	100% Completed	
	(v)	Lift Well HO for Lift Installation	100% Completed	
	(vi)	Lobby Wall Tiling	100% Completed	
37.	Status of installation			
	(with	nin flat/unit)		
	(xii)	UPVC Windows	100% Completed	
	(xiii)	Bathroom Chinaware	100% Completed	
	(xiv)	Modular Kitchen Cabinet Installation (Without Panels)	100% Completed	
	(xv)	Switch & Sockets	100% Completed	
	(xvi)	NA	NA	<u> </u>
	(othe	er than flat/units)		Labib Alam, Arch

	(xvii Guide Rail+ Floor Door+ Installation	Car 100 % Complete
	(xviii RCC Work	100% Completed
	(xix) RCC Work	100% Completed
	(xx) Fire Pump Installation	100% Completed
	(xxi) Staircase & Lobby Wiring	100% Completed
	(xxii Six Monthly Compliance	100% Compliance
38.	Waterproofing of terraces	PU Waterproofing 100% Completed
39.	Entrance lobby finishing	Gypsum False ceiling 100% Completed
40.	Status of construction of compoundable	und Boundary Wall RCC and 100% Completed Brick Work

Note: (*) extend rows as per requirement.

Table - B Tower B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
24.	Internal roads & pavements	Yes	100%	
25.	Parking	Yes		
	Covered no	Yes	100%	
	Open no	Yes	100%	
26.	Water supply	Yes	100%	
27.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
28.	Storm water drains	Yes	100%	
29.	Landscaping & tree plantation	Yes	100%	
30.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
31.	Shopping area	Yes	0%	
32.	Street lighting/ electrification	Yes	100%	
33.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
34.	Solid waste management & disposal	Yes	100%	
35.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
36.	Energy management (solar)	Yes	100%	
37.	Fire protection and fire safety requirements	Yes	100%	
38.	Electrical meter room, sub-station, receiving station	Yes	100%	عاه

39.	Other (option to add more)	NA				
B-2	Community building to be transferred to RWA					
40.	Community centre	Yes	100%			
41.	others	NA				
B-3	Community buildings not to be transferred to RWA/competent authority					
42.	Schools	NA				
43.	Dispensary	NA				
44.	Club	Yes	100%			
45.	Others	NA				
B-4	Services/ facilities to be transferred to competent authority	NA				
46.	*					

Note: (*) extend as per requirement

		7	Гable – А		
(to build	be pr	Tower no. repared separately for each tower in the project/ phase of	Tower-C		
A1	Cum	ulative progress of the projec	t/phase at the e	nd of the quarte	r.
Sr. No.	•		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
9.	(incl	structure usive of excavation, dation, basements, water fing, etc.)	0	24.96	100%
10.	(slat	er structure os, brick work, block work, case, lift wells, machine os, water tank, etc.)	0	40.02	100%
11.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	0.40	9.51	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.79	7.55	100%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.40	7.52	100%
12.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.30	15.09	100%
	4.2	External (plaster, painting, facade, etc.)	0.11	4.72	100%

Sr. No.		Tasks/ Activity	Description of work done	Percentage of total proposed work	
	Sub-Structure Status				
41.	Exca	vation	Complete	100 %	
42.	Layiı	ng of foundation			
	(v)	Complete		100%	
	(vi)	NA	NA	0	
43.	Num	ber of basement(s)			
	(v)	Structure under Tower Footprint Complete		100%	
	(vi)	Structure under Tower Footprint Complete		100%	
44.		erproofing of the above sub- cture (wherever applicable)	Deck Water Proofing	100%	
	Super-Structure Status			Labib Alam, Architecture	

45.	Tota	l floors in the tower/ building	1Stilt+1Service Floor + 30 Apt Floors	100%
46.	Total area on each floor		549 Sqm	100%
47.	Stilt floor/ ground floor		Structure Tower Entrance	100% Completed
48.	Statı	us of laying of slabs floor wise	Upto terrace Level Completed	100%
E.	build	ulative number of slabs in the ling/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
49.	Status of construction			
	(ix)	Blockwork	100% Completed	
	(x)	Staircase Concreting upto Terrace Slab	100% Completed	
	(xi)	Lift Well including Machine room	100% Completed	
	(xii)	Structure lift lobbies and other common area upto 30 Floor	100% Completed	
50.		g of door and window frames in units	Door Frame	100% Completed
51.	Statu	s of MEP	Internal (within flat)	External works
	(vii)	NA	NA	
	(viii)	Apartment Electrical Wiring	100% Completed	100% Completed
	(ix)	UPVC/ RWP Piping	100% Completed	
52.	Statu	s of wall plastering		
	(v)	RCC External Wall	NA	Ship Man Antitoni

	(vi)	Gypsum Plaster	100%	
53.	Statu	s of wall tiling		
	(v)	Bathroom Tiles	100% Completed	
	(vi)	Kitchen Wall Tile	100% Completed	
54.	Statu	s of flooring		
	(v)	Lift Lobby Flooring	100% Completed	
	(vi)	Apt Stone Flooring	100% Completed	
55.	Statu	s of white washing		
	(v)	Apartment Prefinal Paint	100% Completed	
	(vi)	Putty+1stCoat+2nd Coat	100% Completed	
56.	Statu	s of finishing		
	(vii)	MS Railing	100% Completed	
	(viii)	Lift Well HO for Lift Installation	100% Completed	
	(ix)	Lobby Wall Tiling	100% Completed	
57.	Statu	s of installation		
	(with	in flat/unit)		
	(xxiii	UPVC Windows	100% Completed	
	(xxiv	Bathroom Chinaware	100%	
	(xxv)	Modular Kitchen Cabinet Installation (Without Panels)	100%	
	(xxvi	Switch & Sockets	100% Completed	
	(xxvi	NA	NA	. 0
	(othe	r than flat/units)		abib Alam, Architect

	(xxvi Guide Rail+ Floor Door+ Car Installation	100% Complete	
	(xxix RCC Work	100% Completed	
	(xxx) RCC Work	100% Completed	
	(xxxi Fire Pump Installation	100% Completed	
	(xxxi Staircase & Lobby Wiring	100% Completed	
i	(xxxi Six Monthly Compliance	100% Compliance	
58.	Waterproofing of terraces	PU Waterproofing	100% Completed
59.	Entrance lobby finishing	Gypsum False ceiling	100% Completed
60.	Status of construction of compound wall	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower C

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks		
B-1	Services					
47.	Internal roads & pavements	Yes	100%			
48.	Parking	Yes				
	Covered no	Yes	100%			
	Open no	Yes	100%			
49.	Water supply	Yes	100%			
50.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%			
51.	Storm water drains	Yes	100%			
52.	Landscaping & tree plantation	Yes	100%	,		
53.	Parks and playgrounds	Yes	100%			
	Fixing of children play equipment's	Yes	100%			
	Benches	Yes	100%			
54.	Shopping area	Yes	0%			
55.	Street lighting/ electrification	Yes	100%			
56.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%			
57.	Solid waste management & disposal	Yes	100%			
58.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%			
59.	Energy management (solar)	Yes	100%			
60.	Fire protection and fire safety requirements	Yes	100%			
61.	Electrical meter room, sub-station, receiving station	Yes	100%			

62.	Other (option to add more)	NA				
B-2	Community building to be transferred to RWA					
63.	Community centre	Yes	100%			
64.	others	NA				
B-3	Community buildings not to be transferred to RWA/competent authority					
65.	Schools	NA	-			
66.	Dispensary	NA				
67.	Club	Yes	100%			
68.	Others	NA				
B-4	Services/ facilities to be transferred to competent authority	NA				
69.	*					
		·				

Note: (*) extend as per requirement