

+91 - 9718046151, +91 - 7253998778designrc@outlook.com 240/19 PARTAPURI, WESTEND ROAD, MEERUT, 250001 GSTIN :- 09BDWPD4964Q1ZF

		Architect'	s Certificate*		
Report	t for quar	ter ending	30-June-21		
Subject			Certificate of progress of construction work		
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans				
	Sr. Particulars No.		Information		
	1.	Project/Phase of the project	Signature Global Prime		
	2.	Location	Sector-63A		
	3.	Licensed area in acres	5.0 Acre		
	4.	Area for registration in acres	5.0 Acre		
	5.	HARERA registration no.	68 of 2019 Dated 14-11-2019		
	6.	Name of licensee	M/s Signature Global India Pvt. Ltd		
	7.	Name of collaborator	NA		
	8.	Name of developer	M/s Signature Global India Pvt. Ltd		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	30-June-21		
	2.	Name of Architect/ Architect's firm	M/s Design Rethink Consultants		
	3.	Date of site inspection	30-June-21		

*On the letter head of the architect firm

3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultants Site engineer	Name			
	1.		Mr. Anurag aggarwal			
	2.	Structural consultant	NNC Design International			
	3.	Proof consultant	M/s Chordia Techno consultants			
	4.	MEP consultant	M/s V Consulting			
	5.	Site supervisor/incharge	Mr. Anurag aggarwal			
4.	I certify that the work has been executed as per approved drawings, statutory/ mandator Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material construction, infrastructure works and internal development works are as per the projected envisaged in the registration and brochure, publication material and other documents share buyers in this regard.					
5.	of the below	the state of the pro-	ntage of work done in the project for each of the building/ tower ject under HARERA is as per table A and table B given here buted with respect to each of the activity of the entire project			

Date

: 30/06/2021

Yours faithfully,

ABHISHEK DWIVEDI

Signature & name (in block letters) with

Place

: VAISHALI, GHAZIABAD.

stamp of architect

architects Council of

(CoA) : CA/2017/86517

registration no.

Council of registration valid till (date)

architects

(CoA) : DEC., 2029

CA/2017/86517

Ar. ABHISHEK DWIVEDI



		7	Гable – А				
(to be	ing/ To		Cowers-(6+1)nos.				
A1	Cumulative progress of the project/phase at the end of the quarter.						
Sr. No.	1 2		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1.	(inclu	tructure sive of excavation, foundation, nents, water proofing, etc.)	6%	66%	70%		
2.	(slabs	r structure s, brick work, block work, stair case, ells, machine rooms, water tank, etc.)	0%	3%	10%		
3.	MEP						
	3.1	Mechanical (lifts, ventilation, etc.)	0%	0%	0%		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0%	0%	0%		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0%	0%	0%		
4.	Finis	shing					
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0%	0%	0%		
	4.2	External (plaster, painting, facade, etc.)	0%	0%	0%		



Sr.	Tasks/ Activity Sub-Structure Status		Description of work done		Percentage of total proposed work		
No.							
1.	Excav	ation	Excavation in ordinary Soil		100%		
2.	Laying	g of foundation	7.00 CD 11	1' - D - Ct	1000		
	(i)	Raft	RCC of Building Raft		100% NA		
	(ii)	Pile	N A	A	INA		
3.	Numb	er of basement(s)			N/ A		
	(i) Basement Level 1		NA		NA NA		
	(ii)	Basement level 2*	N/		NA		
4.		proofing of the above sub-structure ever applicable)	Applying Water Proofing Compound		0%)	
		Super-Structure Status					
5.	Total	floors in the tower/ building	109 1	Nos.	6%	ó	
6.		area on each floor	6%of RCC wo		6%		
				on total area Work in progress		33%	
7.		loor/ ground floor		-			
8.		Status of laying of slabs floor wise		(45% to 55%)		45%	
	Cumulative number of slabs in the building/ towerlaid by end of quarter						
9.	Status of construction				(0)		
	(i)	Walls on floors	Work in progress		6%		
	(ii)	Staircase	Work in progress		6%		
	(iii)	Lift wells along with water proofing	Yet to be started		0%		
	(iv)	Lift lobbies/ common areas floor wise	Work in progress		6%		
10.	Fixin units	ng of door and window frames in flats/	Yet to b	e started	0%		
11.	Statu	Status of MEP		External works	Internal (within flat)		
	(i)	Mechanical works	NA	Pumps & Electrical Panels	NA	0%	
	(ii)	Electrical works including wiring	Yet to be started	Yet to be started	0%	0%	
	(iii)	Plumbing works	Yet to be started	Yet to be started	0%	0%	
12.	Statu	is of wall plastering	X7_1 = 1 = -/ 3		0	0/0	
	(i)	External plaster	Yet to be started		0%		
	(ii)	Internal plaster	Yet to be started		i e		
13.	Stati	Status of wall tiling				0% CHIN	
	(i)	In bathroom	Yet to be started			or not n	
	(ii)	In kitchen	Yet to be started			12 M 97	
14.	Stati	us of flooring			,	MEET	
	(i)	(i) Common areas		Yet to be started		% [[]	
	(ii)	Units/ flats	Yet to be started		(0%	

Abhishell Awivedi

Sr.	Tasks/ Activity Sub-Structure Status		Description of work done	Percentage of total proposed work	
No.			done		
15.	Status of white washing				
	(i)	Internal walls	Yet to be started	0%	
	(ii)	External walls	Yet to be started	0%	
16.	Status of finishing				
	(i)	Staircase with railing	Yet to be started	0%	
	(ii)	Lift wells	Yet to be started	0%	
	(iii)	Lift lobbies/ common areas floor wise	Yet to be started	0%	
17.	Status of installation				
	(within flat/unit)				
	(i)	Doors and windows panels	Yet to be started	0%	
	(ii)	Sanitary fixtures	Yet to be started	0%	
	(iii)	Modular kitchen	NA	NA	
	(iv)	Electrical fittings/ lighting	Yet to be started	0%	
	(v)	Gas piping (if any)	NA	NA	
	(other than flat/units)				
	(vi)	Lifts installation	Yet to be started	0%	
	(vii)	Overhead tanks	Yet to be started	0%	
	(viii)	Underground water tank	Yet to be started	0%	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yet to be started	0%	
	(x)	Electrical fittings in common areas	Yet to be started	0%	
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yet to be started	0%	
18.	Wate	rproofing of terraces	Yet to be started	0%	
 19.		nce lobby finishing	Yet to be started	0%	
20.	Status of construction of compound wall(Fencing Work)		Work in progress	100%	

Note: (*) extend rows as per requirement.

An ADUIGUEK DWIVE



Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			T
1.	Internal roads & pavements(Temporary)	Yes	75%	
2.	Parking	NA		
	Covered no	NA		
	Open no	NA		
3,	Water supply	Yes	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0%	
5.	Storm water drains	Yes	0%	
6.	Landscaping & tree plantation(Temporary)	Yes	85%	
7.	Parks and playgrounds	Yes	0%	
	Fixing of children play equipment's	Yes	0%	
	Benches	Yes	0%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0%	
11.	Solid waste management & disposal	Yes	0%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	No		
13.	Energy management (solar)	Yes	0%	
14.	Fire protection and fire safety requirements	Yes	0%	
15.	Electrical meter room, sub-station, receiving station	Yes	0%	
16.	Site Office(Temporary)	Yes	100%	
B-2	Community building to be transferred to RWA			
17.	Community centre	Yes	0%	
18.	Others		aun .	
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	NA		
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

