

	*	Architect's Ce	rtificate [*]			
Repo	rt for qu	narter ending	30-June-21			
Subje	ect		Certificate of progress of construction work			
1.	I/We in the	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans				
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Golf Greens-79			
	2.	Location	Sector-79			
	3.	Licensed area in acres	5.9125 Acre			
	4.	Area for registration in acres	5.9125 Acre			
	5.	HARERA registration no.	15 of 2020 Dated 23-06-2020			
	6.	Name of licensee	M/s Signature Global (India) Pvt. Ltd			
	7.	Name of collaborator	NA			
	8.	Name of developer	M/s Signature Global (India) Pvt. Ltd			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	30-June-21			
	2.	Name of Architect/ Architect's firm	M/s Gian P Mathur & Associates			
	3.	Date of site inspection	30-June-21			



GIAN P. MATHUR & ASSOCIATES

C-55, East Of Kailash, New Delhi-110065 46599599 | 46599512

info@gpmindia.com | W: www.gpmindia.com

3.	Follow	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. Consultants		Name			
	1.	1. Site engineer	Mr. Dinesh Singh			
	2.	Structural consultant	M/s Optimum Design Pvt. Ltd.			
	3.	Proof consultant	RD Consultants			
	4.	MEP consultant	M/s Krim Engineering Services Pvt. Ltd.			
	5.	Site supervisor/in-charge	Mr. Dinesh Singh			
4.	I certify that the work has been executed as per approved drawings, statutory/ manda approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and material used in the construction, infrastructure works and internal development works ar per the projected standard as envisaged in the registration and brochure, publication material other documents shared with the buyers in this regard.					
5.	building and ta	ng/ tower of the real estate project	percentage of work done in the project for each of the pt/phase of the project under HARERA is as per table A reentage of the work executed with respect to each of the stailed in table A and table B.			

Date

:30/06/2021

Yours faithfully,

Place

.

B. Arch.., M.C.A. I.I.A CA No. 80/5769

Signature & name (in block letters) with stamp of architect

Councilof

architects

(CoA):

CA/80/05769

Registration No.

Councilof

architects

(CoA):

31/12/2025

Registration valid till (date)

Table – A

Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		5+1 No's (Towers)						
A1	Cum	Cumulative progress of the project/phase at the end of the quarter.						
Sr. No.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		components Work done value during the quarter Cumulative work done value till date		Percentage of work done to the total proposed worl			
1.			6%	66%	80%			
2.	Supe (slab	er structure s, brick work, block work, stair lift wells, machine rooms, water	3%	6%	10%			
3.	MEP							
	3.1	Mechanical (lifts, ventilation, etc.)	0%	0%	0%			
	3.2	Electrical (conducting, wiring, fixtures, etc.)	0%	0%	0%			
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0%	0%	0%			
4.	Finis	shing						
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0%	0%	0%			
	4.2	External (plaster, painting, facade, etc.)	0%	0%	0%			

B. Arch.., M.C.A. I.I.A CA No. 80/5769

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work done		Percentage of total proposed	
					work	
1.	Excav	vation	Excavation in ordinary Soil		100%	
2.	Layin	g of foundation				
	(i)	Raft	RCC of Bu	ilding Raft	100)%
	(ii)	Pile	NA		NA	
3.	Numl	per of basement(s)				
	(i) Basement Level 1		NA		NA	
	(ii)	Basement level 2*	NA		N	A
4.		rproofing of the above sub-structure rever applicable)		ater Proofing pound	0%	
		Super-Structure Status				
5.	Total	floors in the tower/ building	126	Nos.	11%	
6.	Total	area on each floor	11% of RCC works completed on total area		11%	
7.	Stilt f	floor/ ground floor	Work in progress		60%	
8.	Statu	s of laying of slabs floor wise				
	1	ulative number of slabs in the ing/ tower laid by end of quarter	(29% to 35%)		30%	
9.	Statu	s of construction				
	(i)	Walls on floors	Work in	progress	1 1	%
	(ii)	Staircase	Work in progress		11%	
	(iii)	Lift wells along with water proofing	Yet to b	oe started	0	%
	(iv)	Lift lobbies/ common areas floor wise	Work in progress		11%	
10.		g of door and window frames in units	Yet to be started		0%	
11.	Statu	s of MEP	Internal (within flat)	External works	Internal (within flat)	Externa 1 works
	(i)	Mechanical works	NA	Pumps & Electrical Panels	NA	0%
	(ii)	Electrical works including wiring	Yet to be started	Yet to be started	0%	0%
	(iii)	Plumbing works	Yet to be started	Yet to be started	0%	0%



12.	Status	of wall plastering		
	(i)	External plaster	Yet to be started	0%
	(ii)	Internal plaster	Yet to be started	0%
13.	Status	s of wall tiling		
	(i)	In bathroom	Yet to be started	0%
	(ii)	In kitchen	Yet to be started	0%
14.	Status	s of flooring		
	(i)	Common areas	Yet to be started	0%
	(ii)	Units/ flats	Yet to be started	0%
15.	Status	s of white washing		
	(i)	Internal walls	Yet to be started	0%
	(ii)	External walls	Yet to be started	0%
16.	Status	s of finishing		
	(i)	Staircase with railing	Yet to be started	0%
	(ii)	Lift wells	Yet to be started	0%
	(iii)	Lift lobbies/ common areas floor wise	Yet to be started	0%
17.	Status	s of installation		
	(with	in flat/unit)		
	(i)	Doors and windows panels	Yet to be started	0%
	(ii)	Sanitary fixtures	Yet to be started	0%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting	Yet to be started	0%
	(v)	Gas piping (if any)	NA	NA
	(other	r than flat/units)		
	(vi)	Lifts installation	Yet to be started	0%
	(vii)	Overhead tanks	Yet to be started	0%
	(viii)	Underground water tank	Yet to be started	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yet to be started	0%
	(x)	Electrical fittings in common areas	Yet to be started	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yet to be started	0%
18.	Wate	rproofing of terraces	Yet to be started	0%
19.	-	nce lobby finishing	Yet to be started	0%
20.	Statu	s of construction of compound Fencing Work)	Completed	100%

Note: (*) extend rows as per requirement.

GIAN P. MATHUE ARCHITECT B. Arch.., M.C.A. I.I. CA No. 80/5769

Table – B

Sr. No.	Common areas and facilities amenities	Propose d (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements(Temporary)	Yes	95%	
2.	Parking	NA		
	Covered no	NA		
	Open no	NA		
3.	Water supply	Yes	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0%	
5.	Storm water drains	Yes	0%	
6.	Landscaping & tree plantation(Temporary)	Yes	95%	
7.	Parks and playgrounds	Yes	0%	
	Fixing of children play equipment's	Yes	0%	
	Benches	Yes	0%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0%	
11.	Solid waste management & disposal	Yes	0%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	No		
13.	Energy management (solar)	Yes	0%	
14.	Fire protection and fire safety requirements	Yes	0%	
15.	Electrical meter room, sub-station, receiving station	Yes	0%	
16.	Site Office(Temporary)	Yes	100%	
B-2	Community building to be transferred to I	RWA		
17.	Community centre	Yes	0%	
18.	others			
В-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	NA		
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

