Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

| Architect's Certificate ¹ | | | | | |
|--------------------------------------|------------|--------------------------------|--|--|--|
| Repo | rt for q | uarter ended | 31st December 2024 | | |
| Subje | ubject | | Certificate of progress of construction work | | |
| 1. | | | ent as architect for certifying progress of entioned project as per the approved plans | | |
| | Sr. No. | | Information | | |
| | 1. | Project/Phase of the project | Elevate Phase – I | | |
| | 2. | Location | Village Behrampur, Sector-59, Gurugram | | |
| | 3. | Licensed area in acres | 8.91875 | | |
| | 4. | Area for registration in acres | 5.95 | | |
| | 5. | HARERA registration no. | 19 of 2019 | | |
| | 6. | Name of licensee | License no. 16 of 2008 : 1) BTVS Buildwell Pvt. Ltd. | | |

DCWAB

Council of Architecture Registration No.: CA/2061/27447

Page 1 of 25

| | _ | | ···· |
|----|--------|--|--|
| | | | 2) Adson Software Pvt. Ltd. 3) Bulls Realtors Pvt. Ltd. 4) Commander Realtors Pvt. Ltd. 5) Fiverivers Developers Pvt. Ltd. 6) Fiverivers Townships Pvt. Ltd. 7) Ornamental Realtors Pvt. Ltd. 8) Aspirant Builders Pvt. Ltd. License no. 28 of 2008: 1) BTVS Buildwell Pvt. Ltd. 2) Golden View Builders Pvt. Ltd. 3) Hi Energy Realtors Pvt. Ltd. 4) Base Exports Pvt. Ltd. 5) Adson Software Pvt. Ltd. 6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 8) Fiverivers Developers Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. License no. 44 of 2011: 1) Commander Realtors Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd. 7) Bulls Realtors Pvt. Ltd. |
| | 7. | Name of collaborator | Heritage Max Realtech Pvt. Ltd. |
| f | 8. | Name of developer | Heritage Max Realtech Pvt. Ltd. |
| 2. | Detail | s related to inspection are as | under |
| | 1. | Date of certifying of percentage of construction work/ site inspection | 31st December 2024 |
| L | | | 1 100 |

| 2. | Name of Architect/ Architect's firm | Arcop associates Private Limited |
|----|--|----------------------------------|
| 3. | Date of site inspection | 31st December 2024 |

| | Sr. No. | Consultants | Name | | |
|----|--------------------------|--|---|--|--|
| | 1. | Site engineer | Balbant Indolia | | |
| | 2. | Structural consultant | Vintech Consultant (Mr. Vinod Jain) | | |
| | 3. | Proof consultant | Mehro Consultants | | |
| | 4. | MEP consultant | Sanelac Consultants Pvt Ltd | | |
| | 5. | Site supervisor/incharge | Sunil Chauhan | | |
| 4. | mand applic develo | atory approvals, Haryana Build able) and the material used in t opment works are as per the p rochure, publication material a | executed as per approved drawings, statutory/ ing Code, 2017/ National Building Code (wherever the construction, infrastructure works and internal rojected standard as envisaged in the registration nd other documents shared with the buyers in this | | |
| 5. | the bu | ilding/ tower of the real estate | percentage of work done in the project for each of project/phase of the project under HARERA is as below. The percentage of the work executed with | | |

respect to each of the activity of the entire project/ phase is detailed in table A and table

Date

ċ

Place

Labib Alam, Architect Council of Architecture Registration No.: CA/2001/27447

Signature & name (in block letters) with stamp of architect

Council of architects (CoA):

registration no.

31-12-2027 CA/2001/27447

Council of architects (CoA):

registration valid till (date)

| | | • | Гable - A | | |
|--------------|----------------|---|--|---|--|
| (to buile | be p | Tower no. repared separately for each tower in the project/ phase of t) | Tower-A | | |
| A1 | Cun | nulative progress of the projec | t/phase at the e | nd of the quarte | ı*. |
| Sr. No. | 1 | | Work done value during the quarter | Cumulative work done value till date | Percentage of work done to the total proposed work |
| 1. | (incl | structure lusive of excavation, idation, basements, water ofing, etc.) | 0 | 35.00 | 100% |
| 2. | (slat stair | er structure os, brick work, block work, case, lift wells, machine rooms, er tank, etc.) | 0 | 56.00 | 100% |
| 3. | MEP | | | | |
| | 3.1 | Mechanical (lifts, ventilation, etc.) | 1.20 | 18.80 | 100 % |
| | 3.2 | Electrical (conduiting, wiring, fixtures, etc.) | 0.91 | 11.75 | 100 % |

| | 3.3 | Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.) | 1.40 | 12.69 | 100% |
|----|------|---|------|-------|------|
| 4. | Fini | shing | | | |
| | 4.1 | Internal (plaster, tilling, flooring, painting, etc. within units and common areas) | 2.10 | 19.02 | 100% |
| | 4.2 | External (plaster, painting, facade, etc.) | 1.40 | 15.26 | 100% |

| Sr. No. | | Tasks/ Activity Sub-Structure Status | Description of work done | Percentage of total proposed work |
|------------|------|---|--|-----------------------------------|
| 1. | Exca | vation | Complete | 100 % |
| 2. | Layi | ng of foundation | | |
| | (i) | Raft | Complete | 100 % |
| | (ii) | Pile | NA | NA |
| 3. | Num | ber of basement(s) | | |
| | (i) | Basement Level 1 | Structure under Tower Footprint Complete | 100% |
| | (ii) | Basement level 2* | Structure under Tower Footprint Complete | 100% |
| 4. | 1 | erproofing of the above sub- cture (wherever applicable) | Above deck waterproofing | 100% |

| | | Super-Structure Status | | |
|-----|-------------------------------------|--|--|----------------|
| 5. | Total floors in the tower/ building | | 1Stilt+1Service Floor + 31 Apt Floors | 100% |
| 6. | Total area on each floor | | 785 Sqm | 100% |
| 7. | Stilt | floor/ ground floor | Structure Tower Entrance | 100% |
| 8. | Statı | us of laying of slabs floor wise | Upto terrace Level Completed | 100% |
| | build | ulative number of slabs in the ling/tower laid by of quarter | Total Slabs 1Stilt+1Service Floor+31 Apt Floor | 100% |
| 9. | Status of construction | | | |
| | (i) | Blockwork | 100% Completed | 100% |
| | (ii) | Staircase Concreting upto Terrace Slab | 100% Completed | 100% |
| | (iii) | Lift Well including Machine room | 100% Completed | 100% |
| | (iv) | Structure lift lobbies and other common area upto 31 Floor | 100% Completed | 100% |
| 10. | | g of door and window frames in / units | | |
| 11. | Statu | us of MEP | Internal (within flat) | External works |
| | (i) | NA | NA | 0 |
| | (ii) | Apartment Electrical Wiring | 100% Completed | 100% |
| | (iii) | UPVC/ RWP Piping | 100% Completed | 100% |
| 12. | Statu | s of wall plastering | | Sul |

| | (i) | RCC External Wall | NA | 0 |
|-----|-------|---|---------------------------------|-----------------------------|
| | (ii) | Gypsum Plaster | 100% (31 of 31 Floor completed) | 100% |
| 13. | Stati | us of wall tiling | | |
| • | (i) | Bathroom Tiles | 100% Completed | |
| | (ii) | Kitchen Wall Tile | 100% Completed | |
| 14. | Statı | us of flooring | | |
| | (i) | Lift Lobby Flooring | 100% Completed | |
| | (ii) | Apt Stone Flooring | 100% Completed | |
| 15. | Statı | us of white washing | | |
| | (i) | Apartment Prefinal Paint | 100% Completed | |
| | (ii) | Putty+1stCoat+2nd Coat | 100% Completed | |
| 16. | Statı | us of finishing | | |
| | (i) | MS Railing | | 100% Completed in staircase |
| | (ii) | Lift Well HO for Lift Installation | 100% Completed | |
| | (iii) | Lobby Wall Tiling | 100% Completed | |
| 17. | Statı | us of installation | | |
| | (with | nin flat/unit) | | |
| | (i) | UPVC Windows | 100% Completed | |
| | (ii) | Bathroom Chinaware | 100% Completed | _ |
| | (iii) | Modular Kitchen Cabinet Installation (Without Panels) | 100% Completed | 1 3/10 |

| | (iv) | Switch & Sockets | 100% Completed | |
|-----|---------------|---|-------------------------------------|----------------|
| | (v) | NA | NA | 0 |
| | (othe | er than flat/units) | | |
| į | (vi) | Guide Rail+ Floor Door+ Car Installation | 100% | |
| | (vii) | RCC Work | 100% Completed | 0 |
| i | (viii) | RCC Work | 100% Completed | 0 |
| | (ix) | Fire Pump Installation | 100% Completed | 0 |
| | (x) | Staircase & Lobby Wiring | 100% Completed | 0 |
| | (xi) | Six Monthly Compliance | 100% Compliance | 0 |
| 18. | Wate | rproofing of terraces | PU Waterproofing | 100% Completed |
| 19. | Entra | nce lobby finishing | Gypsum False ceiling | 100% Completed |
| 20. | Statu wall | s of construction of compound | Boundary Wall RCC and Brick Work | 100% Completed |

Note: (*) extend rows as per requirement.

Table - B Tower-A

| Sr. No. | Common areas and facilities amenities | Proposed (Yes/ No) | Percentage of work done | remarks |
|---------|---|-----------------------|----------------------------|---------|
| B-1 | Services | - | | |
| 1. | Internal roads & pavements | Yes | 100% | |
| 2. | Parking | Yes | | |
| | Covered no | Yes | 100% | |
| | Open no | Yes | 100% | |
| 3. | Water supply | Yes | 100% | |
| 4. | Sewerage (chamber, lines, septic tanks, STP) | Yes | 100% | |
| 5. | Storm water drains | Yes | 100% | |
| 6. | Landscaping & tree plantation | Yes | 100% | |
| 7. | Parks and playgrounds | Yes | 100% | |
| | Fixing of children play equipment's | Yes | 100% | |
| | Benches | Yes | 100% | |
| 8. | Shopping area | Yes | 0% | |
| 9. | Street lighting/ electrification | Yes | 100% | |
| 10. | Treatment and disposal of sewage and sullage water/STP | Yes | 100% | |
| 11. | Solid waste management & disposal | Yes | 100% | |
| 12. | Water conservation, rain water, harvesting, percolating well/ pit | Yes | 100% | |
| 13. | Energy management (solar) | Yes | 100% | |
| 14. | Fire protection and fire safety requirements | Yes | 100% | |
| 15. | Electrical meter room, sub-station, receiving station | Yes | 100% | |

| 16. | Other (option to add more) | NA | | | |
|-----|--|--------|------|---------|-----|
| B-2 | Community building to be transferred | to RWA | | | |
| 17. | Community centre | Yes | 100% | | |
| 18. | others | NA | | | |
| B-3 | Community buildings not to be transferred to RWA/competent authority | | | | |
| 19. | Schools | NA | | - | |
| 20. | Dispensary | NA | | <u></u> | |
| 21. | Club | Yes | 100% | | |
| 22. | Others | NA | | - | |
| B-4 | Services/ facilities to be transferred to competent authority | NA | | | |
| 23. | * | | | 1 | Mg_ |

Note: (*) extend as per requirement

| | | | Table - A | | |
|--------------|---|---|--|---|--|
| (to build | be p | Tower no. repared separately for each tower in the project/ phase of t) | 1 | | |
| A1 | Cumulative progress of the project/phase at the end of the quarter. | | | | |
| Sr. No. | Project components | | Work done value during the quarter | Cumulative work done value till date | Percentage of work done to the total proposed work |
| 5. | (incl | structure usive of excavation, dation, basements, water ofing, etc.) | 0 | 35.00 | 100% |
| 6. | Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.) | | 0 | 60.05 | 100% |
| 7. | МЕР | | | | |
| | 3.1 | Mechanical (lifts, ventilation, etc.) | 1.72 | 18.93 | 100% |
| | 3.2 | Electrical (conduiting, wiring, fixtures, etc.) | 1.01 | 12.73 | 100% |

| | 3.3 | Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.) | 1.31 | 13.23 | 100% |
|----|------|---|------|-------|------|
| 8. | Fini | shing | | | |
| | 4.1 | Internal (plaster, tilling, flooring, painting, etc. within units and common areas) | 2.02 | 19.90 | 100% |
| | 4.2 | External (plaster, painting, facade, etc.) | 1.01 | 14.23 | 100% |

| Sr. No. | Tasks/ Activity | | Description of work done | Percentage of total proposed work | |
|------------|-----------------------|---|--------------------------|-----------------------------------|--|
| | | Sub-Structure Status | | | |
| 21. | Exca | vation | Complete | 100 % | |
| 22. | Layii | ng of foundation | | | |
| | (iii) | Complete | 100 % | 100 % | |
| | (iv) | NA | NA | 0 | |
| 23. | Number of basement(s) | | | | |
| | (iii) | Structure under Tower Footprint Complete | Complete | 100% | |
| | (iv) | Structure under Tower Footprint Complete | Complete | 100% | |
| 24. | 1 | erproofing of the above sub- cture (wherever applicable) | Deck Water Proofing | 100% | |
| | | Super-Structure Status | | CAP | |

| 25. | Tota | l floors in the tower/ building | 1Stilt+1Service Floor + 33 Apt Floors | 100% |
|-----|--------------------------|--|--|-----------------|
| 26. | Total area on each floor | | 772 Sqm | 100% |
| 27. | Stilt | floor/ ground floor | Structure Tower Entrance | 100% Completed |
| 28. | Statı | as of laying of slabs floor wise | Upto terrace Level Completed | 100% |
| | build | ulative number of slabs in the ling/tower laid by of quarter | Total Slabs 1Stilt+1Service Floor+31 Apt Floor | 100% |
| 29. | Status of construction | | | |
| | (v) | Blockwork | Completed | 100% |
| | (vi) | Staircase Concreting upto Terrace Slab | | 100% |
| | (vii) | Lift Well including Machine room | | 100% |
| | (viii) | Structure lift lobbies and other common area upto 31 Floor | | 100% |
| 30. | | g of door and window frames in units | Door Frame | 100% Completed |
| 31. | Statu | s of MEP | Internal (within flat) | External works |
| | (iv) | NA | NA | |
| | (v) | Apartment Electrical Wiring | 100% Completed | 100% Completed |
| | (vi) | UPVC/ RWP Piping | 100% Completed | |
| 32. | Statu | s of wall plastering | | |
| | (iii) | RCC External Wall | NA | Alam, Architect |

| | (iv) | Gypsum Plaster | 100% | |
|-----|--------|--|----------------|----------------------|
| 33. | Statu | s of wall tiling | | |
| | (iii) | Bathroom Tiles | 100% Completed | |
| | (iv) | Kitchen Wall Tile | 100% Completed | |
| 34. | Statu | s of flooring | | - |
| | (iii) | Lift Lobby Flooring | 100% Completed | |
| | (iv) | Apt Stone Flooring | 100% Completed | |
| 35. | Statu | s of white washing | | |
| | (iii) | Apartment Prefinal Paint | 100% Completed | |
| | (iv) | Putty+1stCoat+2nd Coat | 100% Completed | |
| 36. | Statu | s of finishing | | |
| | (iv) | MS Railing | 100% Completed | |
| | (v) | Lift Well HO for Lift Installation | 100% Completed | |
| | (vi) | Lobby Wall Tiling | 100% Completed | |
| 37. | Statu | s of installation | | |
| | (with | nin flat/unit) | | |
| | (xii) | UPVC Windows | 100% Completed | |
| | (xiii) | Bathroom Chinaware | 100% Completed | |
| | (xiv) | Modular Kitchen Cabinet Installation (Without Panels) | 100% Completed | |
| | (xv) | Switch & Sockets | 100% Completed | |
| | (xvi) | NA | NA | |
| | (othe | er than flat/units) | | Saib Alam, Architect |

Council of Architecture
Registration No.: CA/2001/27447

| | (xvii Guide Rail+ Floor Door+ Installation | r+ Car 100 % Complete | |
|-----|---|---|---|
| | (xviii RCC Work | 100% Completed | |
| | (xix) RCC Work | 100% Completed | |
| | (xx) Fire Pump Installation | 100% Completed | |
| | (xxi) Staircase & Lobby Wiring | 100% Completed | |
| | (xxii Six Monthly Compliance | 100% Compliance | |
| 38. | Waterproofing of terraces | PU Waterproofing 100% Completed | 1 |
| 39. | Entrance lobby finishing | Gypsum False ceiling 100% Completed | |
| 40. | Status of construction of comp wall | Boundary Wall RCC and 100% Completed Brick Work | |

Note: (*) extend rows as per requirement.

Table - B Tower B

| Sr. No. | Common areas and facilities amenities | Proposed (Yes/ No) | Percentage of work done | remarks |
|---------|---|-----------------------|----------------------------|----------|
| B-1 | Services | | | <u> </u> |
| 24. | Internal roads & pavements | Yes | 100% | |
| 25. | Parking | Yes | | |
| | Covered no | Yes | 100% | |
| | Open no | Yes | 100% | |
| 26. | Water supply | Yes | 100% | |
| 27. | Sewerage (chamber, lines, septic tanks, STP) | Yes | 100% | |
| 28. | Storm water drains | Yes | 100% | |
| 29. | Landscaping & tree plantation | Yes | 100% | |
| 30. | Parks and playgrounds | Yes | 100% | |
| | Fixing of children play equipment's | Yes | 100% | |
| | Benches | Yes | 100% | |
| 31. | Shopping area | Yes | 0% | |
| 32. | Street lighting/ electrification | Yes | 100% | |
| 33. | Treatment and disposal of sewage and sullage water/ STP | Yes | 100% | |
| 34. | Solid waste management & disposal | Yes | 100% | |
| 35. | Water conservation, rain water, harvesting, percolating well/ pit | Yes | 100% | |
| 36. | Energy management (solar) | Yes | 100% | |
| 37. | Fire protection and fire safety requirements | Yes | 100% | |
| 38. | Electrical meter room, sub-station, receiving station | Yes | 100% | 0 |

| 39. | Other (option to add more) | NA | | |
|-----|--|--------|------|--|
| B-2 | Community building to be transferred | to RWA | | |
| 40. | Community centre | Yes | 100% | |
| 41. | others | NA | | |
| B-3 | Community buildings not to be transferred to RWA/competent authority | | | |
| 42. | Schools | NA | | |
| 43. | Dispensary | NA | | |
| 44. | Club | Yes | 100% | |
| 45. | Others | NA | | |
| B-4 | Services/ facilities to be transferred to competent authority | NA | | |
| 46. | * | | | |

Note: (*) extend as per requirement

| | | • | Fable - A | | |
|--------------|---|---|--|---|--|
| (to build | be p | Tower no. repared separately for each tower in the project/ phase of t) | Tower-C | | |
| A1 | Cumulative progress of the project/phase at the end of the quarter. | | | | |
| Sr. No. | Proj | ect components | Work done value during the quarter | Cumulative work done value till date | Percentage of work done to the total proposed work |
| 9. | (incl | structure usive of excavation, dation, basements, water fing, etc.) | 0 | 24.96 | 100% |
| 10. | (slat | er structure os, brick work, block work, case, lift wells, machine ns, water tank, etc.) | 0 | 40.02 | 100% |
| 11. | МЕР | | | | |
| | 3.1 | Mechanical (lifts, ventilation, etc.) | 0.40 | 9.71 | 100% |
| | 3.2 | Electrical (conduiting, wiring, fixtures, etc.) | 0.79 | 7.98 | 100% |

| | 3.3 | Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.) | 0.40 | 7.94 | 100% |
|-----|-------|--|------|-------|------|
| 12. | Finis | shing | | | |
| | 4.1 | Internal (plaster, tilling, flooring, painting, etc. within units and common areas) | 2.30 | 16.24 | 100% |
| | 4.2 | External (plaster, painting, facade, etc.) | 0.11 | 5.62 | 100% |

| Sr. No. | Tasks/ Activity | | Description of work done | Percentage of total proposed work | |
|------------|-----------------------|---|--------------------------|-----------------------------------|--|
| | | Sub-Structure Status | | | |
| 41. | Exca | vation | Complete | 100 % | |
| 42. | Layi | ng of foundation | | | |
| | (v) | Complete | | 100% | |
| | (vi) | NA | NA | 0 | |
| 43. | Number of basement(s) | | | | |
| | (v) | Structure under Tower Footprint Complete | | 100% | |
| | (vi) | Structure under Tower Footprint Complete | | 100% | |
| 44. | 1 | erproofing of the above sub- cture (wherever applicable) | Deck Water Proofing | 100% | |
| | | Super-Structure Status | | Jahih Alam, Architec | |

Council of Architecture
Registration No.: CA/2001/27447

| 45. | Tota | l floors in the tower/ building | 1Stilt+1Service Floor + 30 Apt Floors | 100% |
|-----|---|--|--|----------------|
| 46. | Total area on each floor | | 549 Sqm | 100% |
| 47. | Stilt | floor/ ground floor | Structure Tower Entrance | 100% Completed |
| 48. | Cumulative number of slabs in the building/ tower laid by | | Upto terrace Level Completed | 100% |
| | | | Total Slabs 1Stilt+1Service Floor+31 Apt Floor | 100% |
| 49. | Statu | s of construction | | |
| | (ix) | Blockwork | 100% Completed | |
| | (x) | Staircase Concreting upto Terrace Slab | 100% Completed | |
| | (xi) | Lift Well including Machine room | 100% Completed | |
| | (xii) | Structure lift lobbies and other common area upto 30 Floor | 100% Completed | |
| 50. | | g of door and window frames in / units | Door Frame | 100% Completed |
| 51. | Statu | s of MEP | Internal (within flat) | External works |
| | (vii) | NA | NA | |
| | (viii) | Apartment Electrical Wiring | 100% Completed | 100% Completed |
| | (ix) | UPVC/ RWP Piping | 100% Completed | |
| 52. | Statu | s of wall plastering | | |
| | (v) | RCC External Wall | NA (| ollo- |

| | (vi) | Gypsum Plaster | 100% | | |
|-----|-------------------------|---|----------------|-----|--|
| 53. | Status of wall tiling | | | | |
| | (v) | Bathroom Tiles | 100% Completed | | |
| | (vi) | Kitchen Wall Tile | 100% Completed | | |
| 54. | Status of flooring | | | | |
| | (v) | Lift Lobby Flooring | 100% Completed | | |
| | (vi) | Apt Stone Flooring | 100% Completed | | |
| 55. | Status of white washing | | | | |
| | (v) | Apartment Prefinal Paint | 100% Completed | | |
| | (vi) | Putty+1stCoat+2nd Coat | 100% Completed | 101 | |
| 56. | Statu | as of finishing | | | |
| | (vii) | MS Railing | 100% Completed | | |
| | (viii) | Lift Well HO for Lift Installation | 100% Completed | | |
| | (ix) | Lobby Wall Tiling | 100% Completed | | |
| 57. | Statu | s of installation | | | |
| | (with | nin flat/unit) | | | |
| | (xxii | UPVC Windows | 100% Completed | | |
| | (xxiv | Bathroom Chinaware | 100% | | |
| | (xxv) | Modular Kitchen Cabinet Installation (Without Panels) | 100% | | |
| | (xxvi | Switch & Sockets | 100% Completed | | |
| | (xxvi | NA | NA | | |
| | (othe | er than flat/units) | | | |

| | (xxvi Guide Rail+ Floor Door+ Car Installation | 100% Complete | |
|-----|---|-------------------------------------|----------------|
| | (xxix RCC Work | 100% Completed | |
| | (xxx) RCC Work | 100% Completed | |
| | (xxxi Fire Pump Installation | 100% Completed | |
| | (xxxi Staircase & Lobby Wiring | 100% Completed | |
| | (xxxi Six Monthly Compliance | 100% Compliance | |
| 58. | Waterproofing of terraces | PU Waterproofing | 100% Completed |
| 59. | Entrance lobby finishing | Gypsum False ceiling | 100% Completed |
| 60. | Status of construction of compound wall | Boundary Wall RCC and Brick Work | 100% Completed |

Note: (*) extend rows as per requirement.

Table - B Tower C

| Sr. No. | Common areas and facilities amenities | Proposed (Yes/ No) | Percentage of work done | remarks |
|---------|---|-----------------------|----------------------------|---------|
| B-1 | Services | | <u></u> | |
| 47. | Internal roads & pavements | Yes | 100% | |
| 48. | Parking | Yes | | |
| | Covered no | Yes | 100% | |
| | Open no | Yes | 100% | |
| 49. | Water supply | Yes | 100% | |
| 50. | Sewerage (chamber, lines, septic tanks, STP) | Yes | 100% | |
| 51. | Storm water drains | Yes | 100% | |
| 52. | Landscaping & tree plantation | Yes | 100% | |
| 53. | Parks and playgrounds | Yes | 100% | |
| | Fixing of children play equipment's | Yes | 100% | |
| | Benches | Yes | 100% | |
| 54. | Shopping area | Yes | 0% | |
| 55. | Street lighting/ electrification | Yes | 100% | |
| 56. | Treatment and disposal of sewage and sullage water/ STP | Yes | 100% | |
| 57. | Solid waste management & disposal | Yes | 100% | |
| 58. | Water conservation, rain water, harvesting, percolating well/ pit | Yes | 100% | |
| 59. | Energy management (solar) | Yes | 100% | |
| 60. | Fire protection and fire safety requirements | Yes | 100% | |
| 61. | Electrical meter room, sub-station, receiving station | Yes | 100% | |

| 62. | Other (option to add more) | NA | | | |
|-----|--|-----|------|--|--|
| B-2 | Community building to be transferred to RWA | | | | |
| 63. | Community centre | Yes | 100% | | |
| 64. | others | NA | | | |
| B-3 | Community buildings not to be transferred to RWA/competent authority | | | | |
| 65. | Schools | NA | | | |
| 66. | Dispensary | NA | | | |
| 67. | Club | Yes | 100% | | |
| 68. | Others | NA | | | |
| B-4 | Services/ facilities to be transferred to competent authority | NA | | | |
| 69. | * | | | | |

Note: (*) extend as per requirement