Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

		Architect'	s Certificate¹		
Repo	ort for q	uarter ending	30th June 2021		
Subje	ect				
1.			ent as architect for certifying progress of entioned project as per the approved plans		
	Sr. Particulars No.		Information		
	1.	Project/Phase of the project	2.425 Acres Commercial Colony (by the name of "3Roads" and "MY Tower")		
	2.	Location	Village Badshahpur, Tehsil & District Gurugram, Sector 70, Haryana.		
	3.	Licensed area in acres	2.425 Acres		
	4.	Area for registration in acres	2.425 Acres		
	5.	HARERA registration no.	38 of 2017		
	6.	Name of licensee	Ojos Developers Private Limited		
,	7.	Name of collaborator	N.A.		
	8.	Name of developer	Ojos Developers Private Limited		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	30th June 2021		
	2.	Name of Architect/ Architect's firm	ARCOP		

¹ On the letter head of the architect firm

Jasvinder Singh Khurana, Architect Council of Architecture

Plot No. 36 B, Sector 32, Institutional Area, Gurgaor H220019Hdts 170 CIN/LLPIN - U45201DL1985 PT C021337 Tel.:+91-124-4595500 Fax: +91-124-459550 Email : info@arcop.co.in Website : www.arcop.co.in

3,	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name		
	1.	Site engineer	Rajesh Kumar		
	2. Structural consultant Manish Consultant				
	3.	Proof consultant	Vintech Consultant UCA, Envirotech, KEPL		
	4.	MEP consultant			
	5.	Site supervisor/incharge	Jitender Kumar Singh		
4.	I certify that the work has been executed as per approved drawings, statutory mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and intern development works are as per the projected standard as envisaged in the registratic and brochure, publication material and other documents shared with the buyers in the regard.				
5.	I also certify that as on the date, the percentage of work done in the project for each the building/ tower of the real estate project/phase of the project under HARERA is a per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.				

Date

Yours faithfully,

Place

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) :CA/92/154970

registration no.

Council of architects (CoA) :31/12/2028 registration valid till (date)

Jasvinder Singh Khurana, Architect

Council of Architecture Registration No.: CA/92/15470

Table - A Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project) Cumulative progress of the project/phase at the end of the quarter. 100%**A1** Sr. **Project components** Work done Cumulative Percentage of No. value during work done work done to the quarter value till the total date proposed work 1. Sub structure NA 100% (inclusive of excavation, foundation, basements, water proofing, etc.) 2. Super structure NA 100% (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.) 3. **MEP** 3.1 Mechanical NA 100% (lifts, ventilation, etc.) 3.2 Electrical NA 100% (conduiting, wiring, fixtures, Plumbing & Firefighting 3.3 NA 100% (piping, pumps and pump room, fixtures, etc.) 4. **Finishing** 4.1 Internal NA 100% (plaster, tilling, flooring, painting, etc. within units and common areas) 4.2 External NA 100% (plaster, painting, facade,

Jasvinder Sirgh Khurana, Architect Council of Architecture

Registration No.: CA/92/15470

1.	Sr. No.	Sub-Structure Status		_	ion of work one	Percentage of total proposed work	
100% NA	1.	Exca	Excavation			100%	
(ii) Pile	2.	Laying of foundation				100%	
Number of basement(s) 2 Nos 100%		(i)	Raft			100%	
(i) Basement Level 1 100% 100%		(ii)	Pile			NA	
(ii) Basement level 2* 4. Waterproofing of the above substructure (wherever applicable) Super-Structure Status 5. Total floors in the tower/ building 6. Total area on each floor 7. Stilt floor/ ground floor 8. Status of laying of slabs floor wise Cumulative number of slabs in the building/ tower A, B and C laid by end of quarter 9. Status of construction (i) Walls on floors (ii) Staircase (iii) Lift wells along with water proofing (iv) Lift lobbies/ common areas floor wise 100% 100% 11. Status of MEP Internal (within flat) (ii) Mechanical works (iii) Electrical works including wiring (iii) Plumbing works 12. Status of wall plastering (i) External plaster (iii) Internal plaster (iiii) Internal plaster (iiii) Internal plaster (iiii) Internal plaster (iiiii) Internal plaster (iiiii) Internal plaster (iiiii) Internal plaster (iiiiiiiii) Internal plaster (iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	3.	Number of basement(s) 2 Nos		2 Nos 100%			
4. Waterproofing of the above substructure (wherever applicable) Super-Structure Status 5. Total floors in the tower/ building 6. Total area on each floor 7. Stilt floor/ ground floor 8. Status of laying of slabs floor wise Cumulative number of slabs in the building/ tower A, B and C laid by end of quarter 9. Status of construction (i) Walls on floors (ii) Staircase (iii) Lift wells along with water proofing (iv) Lift lobbies/ common areas floor wise 10. Fixing of door and window frames in flats/ units 11. Status of MEP Internal (within flat) (ii) Mechanical works (iii) Electrical works including wiring (iii) Plumbing works 12. Status of wall tiling 13. Status of wall tiling 14. Status of wall tiling 15. Status of wall tiling 16. Total area on each floor 10. Hoo% 10. Fixing of door and window frames in flats/ units 10. Hoo% 10. Hoo		(i)	(i) Basement Level 1			100%	
Super-Structure (Wherever applicable) Super-Structure Status 100%		(ii)	Basement level 2*			100%	
Total floors in the tower/ building	4.					100%	
6. Total area on each floor 7. Stilt floor/ ground floor 8. Status of laying of slabs floor wise			Super-Structure Status				
7. Stilt floor/ ground floor 8. Status of laying of slabs floor wise Cumulative number of slabs in the building/ tower A, B and C laid by end of quarter 9. Status of construction (i) Walls on floors (iii) Staircase (iii) Lift wells along with water proofing (iv) Lift lobbies/ common areas floor wise 10. Fixing of door and window frames in flats/ units 11. Status of MEP Internal (within flat) (i) Mechanical works (ii) Electrical works including wiring (iii) Plumbing works 12. Status of wall plaster in floow (ii) Internal plaster (ii) Internal plaster (iii) Internal plaster (iii) Internal plaster (iii) Internal plaster (ivi) Internal plaster	5.	Tota	l floors in the tower/ building			100%	
8. Status of laying of slabs floor wise Cumulative number of slabs in the building/ tower A, B and C laid by end of quarter 9. Status of construction (i) Walls on floors (iii) Lift wells along with water proofing (iv) Lift lobbies/ common areas floor wise 100% 100% Fixing of door and window frames in flats/ units 1. Status of MEP Internal (within flat) (i) Mechanical works (ii) Electrical works including wiring (iii) Plumbing works 1. Status of wall plaster in floow (ii) External plaster (ii) Internal plaster (iii) Internal plaster (iii) Internal plaster (iv) External plaster (iv) External plaster (iv) Internal plaster (iv) Internal plaster (iv) External plaster (iv) Internal plaster	6.	Tota	l area on each floor			100%	
Cumulative number of slabs in the building/ tower A, B and C laid by end of quarter 9. Status of construction (i) Walls on floors (iii) Lift wells along with water proofing (iv) Lift lobbies/ common areas floor wise 10. Fixing of door and window frames in flats/ units 11. Status of MEP (i) Mechanical works (ii) Electrical works including wiring (iii) Plumbing works 12. Status of wall plastering (i) External plaster (ii) Internal plaster (iii) Internal plaster	7.	Stilt	floor/ ground floor			100%	
building/ tower A, B and C laid by end of quarter 9.	8.	Stati				100%	
(i) Walls on floors (ii) Staircase (iii) Lift wells along with water proofing (iv) Lift lobbies/ common areas floor wise 10. Fixing of door and window frames in flats/ units 11. Status of MEP Internal (within flat) (i) Mechanical works (ii) Electrical works including wiring (iii) Plumbing works 12. Status of wall plaster (i) External plaster (ii) Internal plaster (ii) Internal plaster (iii) Internal plaster		build	ling/tower A, B and C laid by end			19 NOS DONE	
(ii) Staircase (iii) Lift wells along with water proofing (iv) Lift lobbies/ common areas floor wise 100% 100% 100% 100% 100% 100% 100% 100% 100% 11. Status of MEP Internal (within flat) (i) Mechanical works (ii) Electrical works including wiring (iii) Plumbing works 12. Status of wall plastering (i) External plaster (ii) Internal plaster (iii) Internal plaster (iii) Internal plaster (iii) Internal plaster 100% 100% 100%	9.	Status of construction					
[iii] Lift wells along with water proofing (iv) Lift lobbies/ common areas floor wise 10. Fixing of door and window frames in flats/ units 11. Status of MEP (i) Mechanical works (ii) Electrical works including wiring (iii) Plumbing works 12. Status of wall plastering (i) External plaster (ii) Internal plaster (iii) Internal plaster (iii) Internal plaster (iv) External plaster (iv) Lift wells along with water proofing 100% 100% 100% 100% 100% 100% 100% 100% 100%		(i)	Walls on floors			100%	
The proofing Proof		(ii)	Staircase			100%	
floor wise 10. Fixing of door and window frames in flats/ units 11. Status of MEP (i) Mechanical works (ii) Electrical works including wiring (iii) Plumbing works 12. Status of wall plaster (i) External plaster (ii) Internal plaster (iii) Internal plaster (ivithin flat) External works (within flat) 100% 100% 100% 100% 100% 100% 100% 100% 100%		(iii)	_			100%	
flats/ units 11. Status of MEP (i) Mechanical works (ii) Electrical works including wiring (iii) Plumbing works (i) External plaster (i) External plaster (ii) Internal plaster (ii) Internal plaster (iii) Internal plaster (iiii) Internal plaster (iiii) Internal plaster (iiii) Internal plaster (iiii) Internal plaster (iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii		(iv)	,			100%	
(within flat) works (i) Mechanical works (ii) Electrical works including wiring (iii) Plumbing works 100% 100% 100% 100% 12. Status of wall plastering (i) External plaster (ii) Internal plaster 13. Status of wall tiling 100%	10.		O			100%	
(ii) Electrical works including wiring (iii) Plumbing works 100% 100% 100% 12. Status of wall plastering (i) External plaster (ii) Internal plaster 100% 13. Status of wall tiling	11.	Statu	s of MEP	(within			
Wiring 100% 100% 100% 100% 12. Status of wall plastering 100%		(i)	Mechanical works			100%	100%
12. Status of wall plastering (i) External plaster (ii) Internal plaster 100% 13. Status of wall tiling 100%		(ii)	9			100%	100%
(i) External plaster 100% (ii) Internal plaster 100% 13. Status of wall tiling 100%		(iii)	Plumbing works			100%	100%
(ii) Internal plaster 100% 13. Status of wall tiling 100%	12.	Status of wall plastering					
13. Status of wall tiling 100%		(i) External plaster				100%	
						100%	
(i) In bathroom 100%	13.					100%	
		(i)	In bathroom			100%	

fashinder Singh Khurana, Architect
Council of Architecture
Registration No.: CA/92/15470

	(ii)	In kitchen		NA
14.	Status of flooring			
	(i)	Common areas		100%
	(ii)	Units/ flats		NA
15.	Status of white washing			
	(i)	Internal walls		100%
	(ii)	External walls		100%
16.	Stati	is of finishing		
	(i)	Staircase with railing		100%
	(ii)	Lift wells		100%
	(iii)	Lift lobbies/ common areas floor wise		100%
17.	Statu	s of installation		
	(with	nin flat/unit)		
	(i)	Doors and windows panels	N/A	
	(ii)	Sanitary fixtures	N/A	
	(iii)	Modular kitchen	N/A	
	(iv)	Electrical fittings/ lighting	N/A	
	(v)	Gas piping (if any)	N/A	
	(othe	er than flat/units)		
	(vi)	Lifts installation		100%
	(vii)	Overhead tanks		100%
	(viii)	Underground water tank		100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC		100%
	(x)	Electrical fittings in common areas		100%
	(xi)	Compliance to conditions of environment/ CRZ NOC		FILED
18.	Wate	rproofing of terraces		100%
19.	Entra	ance lobby finishing		NA
20.	Status of construction of compound wall			100%

Note: (*) extend rows as per requirement.

Jasvinder Singh Khunera, Architect Council of Architecture Registration No.: CA/92/15470

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remark
B-1	Services	(****)	or work done	
1.	Internal roads & pavements	YES	100%	
2.	Parking	YES	100%	
	Covered no 282	YES	100%	
	Open no21	YES	100%	
3.	Water supply	YES	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	100%	
5.	Storm water drains	YES	100%	
6.	Landscaping & tree plantation	YES	100%	
7.	Parks and playgrounds	NO	NA NA	
	Fixing of children play equipment's	NO	NA	
	Benches	NO	NA	
8.	Shopping area	YES	100%	
9.	Street lighting/ electrification	YES	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	100%	
11.	Solid waste management & disposal	YES	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	YES	100%	
13.	Energy management (solar)	YES	NA	
14.	Fire protection and fire safety requirements	YES	100%	
15.	Electrical meter room, sub-station, receiving station	YES	100%	
16.	Other (option to add more)		100%	
B-2	Community building to be transferred	to RWA		
17.	Community centre	NO .	NA	
18.	others	NO	NA	
B-3	Community buildings not to be transferred to RWA/competent authority	·		
19.	Schools	NO	NA	
20.	Dispensary	NO	NA	
21.	Club	NO	NA	
22.	Others	NO	NA	
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

Jasvinder Singh Kharana, Architect Council of Architecture Registration No.: CA/92/15470