

### ARCHITECTS & ENGINEER'S

Annexure A

		Architect <sup>2</sup>	's Certificate <sup>*</sup>			
Report	for quar	ter ending	30 SEPTEMBER 2021			
Subject	ubject		Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	San Francisco Street			
	2.	Location	Omaxe World Street, Sector-79, Faridabad			
	3.	Licensed area in acres	2.66 acres			
	4.	Area for registration in acres	2.66 acres			
	5.	HARERA registration no.	HRERA-PKL-FBD-216-2020			
Y kan	6.	Name of licensee	FBD REAL GROW PVT LTD			
	7.	Name of collaborator	8			
	8.	Name of developer	FBD REAL GROW PVT LTD			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	10.07.2021			
	2.	Name of Architect/ Architect's firm	ABMS DESIGN ASSOCIATES			
	3.	Date of site inspection	05.07.2021			





### ARCHITECTS & ENGINEER'S

3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. Consultants		Name			
	1.	Site engineer	Mr. D.C Pant			
	2.	Structural consultant	Mr. Pankaj Varshney			
	3.	Proof consultant				
	4.	MEP consultant	Mr, Digambar Singh			
	5.	Site incharge	Mr. D.C Pant			
4.	Haryar constru envisas	na Building Code, 2017/ National Buction, infrastructure works and int	ed as per approved drawings, statutory/ mandatory approvals, uilding Code (wherever applicable) and the material used in the ternal development works are as per the projected standard as re, publication material and other documents shared with the			
5.	of the below.	real estate project/phase of the proj	ntage of work done in the project for each of the building/ tower ject under HARERA is as per table A and table B given herein uted with respect to each of the activity of the entire project/			

Date 1/10/2021

Yours faithfully,

Place DELIAI

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) registration no. : CA/2013/61618 Council of architects (CoA) registration valid till (date)

> PURBA BORAN Reg. Architect GA/2013/61618

7812013/01618



#### ARCHITECTS & ENGINEER'S

			Table – A		<u> </u>		
Building/ Tower no.  (to be prepared separately for each building/ tower in the project/ phase of the project)							
A1	Cum	ulative progress of the project/phase a	at the end of the qua	rter.			
Sr. No.	Project components  Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1.			1.2 CR	6.10 CR	83 %		
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0.95 CR	1.70 Cr	8%		
3.	MEP						
	3.1	Mechanical (lifts, ventilation, etc.)	5 a =	-			
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	y Si=		,		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)					
4.	Finishing						
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	O LACS	0 CR	0%		
	4.2	External (plaster, painting, facade, etc.)	O LACS	0 CR	0%		





Sr.	Tasks/ Activity		Description of work done		Percentag	Percentage of total proposed work	
No.		Sub-Structure Status					
1.	Excav	vation	Comp	leted	100	)%	
2.	Layin	g of foundation					
	(i)	Raft	83	%			
	(ii)	Pile	N/	'A			
3.	Number of basement(s)						
	(i) Basement Level 1				60'	%	
	(ii)	Basement level 2*	N.	A			
	(iii)	Basement Level 3					
	(iv)	Basement Level 4					
4.		rproofing of the above sub-structure ever applicable)			0%		
		Super-Structure Status					
5.	Total	floors in the tower/ building	4	1			
6.	Total	area on each floor	11355	0 SFT			
7.	Stilt f	loor/ ground floor	11355	0 SFT			
8.	Status of laying of slabs floor wise			10%		%	
	Cumulative number of slabs in the building/ towerlaid by end of quarter				7/ 9		
9.	Status of construction		12.	Tar "."	# #		
	(i)	(i) Walls on floors				0%	
	(ii)	Staircase				0%	
	(iii)	Lift wells along with water proofing	-		-	-	
	(iv)	Lift lobbies/ common areas floor wise	-		-		
10.	Fixin units	g of door and window frames in flats/			0	%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works		•			
	(ii)	Electrical works including wiring		-			
	(iii)	Plumbing works		-			
12.	Statu	s of wall plastering					
	(i)	External plaster			0%		
	(ii)	Internal plaster			0%		
13.	Statu	s of wall tiling					
	(i)	In bathroom		-			
	(ii)	In kitchen		-			
14.	Statu	s of flooring					
FLA	TNO. 3	A <sup>C</sup> AMMOTRI SAPARTMENTS, POCKET-	-14, KALKAJI F	XTENSION	, NEW DELHI-1	10017	
	(ii)	Units/ flats		-		-	





### ARCHITECTS & ENGINEER'S

Sr.	Tasks/ Activity Sub-Structure Status		Description of work	Percentage of total	
No.			done	proposed work	
15.	Status of white washing				
	(i)	Internal walls		0%	
	(ii)	External walls		0%	
16.	Status of finishing				
	(i)	Staircase with railing			
	(ii)	Lift wells	N/A		
	(iii)	Lift lobbies/ common areas floor wise	N/A		
17.	Status	of installation			
	(withi	n flat/unit)			
	(i)	Doors and windows panels		0%	
	(ii)	Sanitary fixtures	N/A		
	(iii)	Modular kitchen	N/A		
	(iv)	Electrical fittings/ lighting	N/A		
	(v)	Gas piping (if any)	N/A		
	(other than flat/units)		4		
	(vi)	Lifts installation	N/A	the company of the contract of	
	(vii)	Overhead tanks	N/A		
	(viii)	Underground water tank	N/A		
•	(ix)	Firefighting fitting and equipment's as per CFO NOC	N/A	×	
	(x)	Electrical fittings in common areas	N/A		
	(xi)	Compliance to conditions of environment/ CRZ NOC	N/A	145	
18.	Water	proofing of terraces		0%	
19.	Entra	nce lobby finishing	N/A		
20.	Status	of construction of compound wall	-		

Note: (\*) extend rows as per requirement.

PURBA BORAL Reg. Architect 3A/2013/61618



### ARCHITECTS & ENGINEER'S

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	YES	0%	
2.	Parking	-		
	Covered no	YES	0%	
	Open no	YES	0%	
3.	Water supply	YES	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	YES	0%	
5.	Storm water drains	YES	0%	
6.	Landscaping & tree plantation	YES	0%	
7.	Parks and playgrounds	NA		
	Fixing of children play equipment's	NA		
	Benches	NA		
8.	Shopping area	YES	0%	
9.	Street lighting/ electrification	YES	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	YES	0%	
11.	Solid waste management & disposal	NA		
12.	Water conservation, rain water, harvesting, percolating well/ pit	NA		
13.	Energy management (solar)	NA		
14.	Fire protection and fire safety requirements	NA		
15.	Electrical meter room, sub-station, receiving station	NA		
16.	Other (option to add more)	NA		
B-2	Community building to be transferred to RWA		'	
17.	Community center	NA		
18.	Others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	NA		
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	ì		
23.	*			

Note: (\*) extend as per requirement

PURBA BORAL Reg. Architect 3A/2013/61618