Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

		Architect'	s Certificate ¹	
Repo	rt for q	uarter ended	31st March 2025	
Subje	iubject 1. I/We have undertaken assignme		Certificate of progress of construction work	
1.	I/We have undertaken assignme construction work in the below men		ent as architect for certifying progress of ntioned project as per the approved plans	
	Sr. No.	Particulars	Information	
	1.	Project/Phase of the project	Elevate Phase – I	
	2.	Location	Village Behrampur, Sector-59, Gurugram	
	3.	Licensed area in acres	8.91875	
	4.	Area for registration in acres	5.95	
	5.	HARERA registration no.	19 of 2019	

	6.	Name of licensee	License no. 16 of 2008 :
			1) BTVS Buildwell Pvt. Ltd.
	!		2) Adson Software Pvt. Ltd.
			3) Bulls Realtors Pvt. Ltd.
			4) Commander Realtors Pvt. Ltd.
			5) Fiverivers Developers Pvt. Ltd.
			6) Fiverivers Townships Pvt. Ltd.
			7) Ornamental Realtors Pvt. Ltd.
			8) Aspirant Builders Pvt. Ltd.
 			License no. 28 of 2008 :
ļ			1) BTVS Buildwell Pvt. Ltd.
			2) Golden View Builders Pvt. Ltd.
1			3) Hi Energy Realtors Pvt. Ltd.
			4) Base Exports Pvt. Ltd.
			5) Adson Software Pvt. Ltd.
		=	6) Bulls Realtors Pvt. Ltd.
			7) Commander Realtors Pvt. Ltd.
		1	8) Fiverivers Developers Pvt. Ltd.
			9) Ornamental Realtors Pvt. Ltd.
			10) Aspirant Builders Pvt. Ltd.
			License no. 44 of 2011 :
			1) Commander Realtors Pvt. Ltd.
			2) BTVS Buildwell Pvt. Ltd.
			3) Golden View Builders Pvt. Ltd.
{			4) Hi Energy Realtors Pvt. Ltd.
			5) Base Exports Pvt. Ltd.
			6) Adson Software Pvt. Ltd.
			7) Bulls Realtors Pvt. Ltd.
			8) Fiverivers Buildcon Pvt. Ltd.
			oj riverivers duliucoli Pvt. Ltu.
	7.	Name of collaborator	Heritage Max Realtech Pvt. Ltd.
	-		
	8.	Name of developer	Heritage Max Realtech Pvt. Ltd.
2.	Detai	ls related to inspection are as	sunder
	1.	Date of certifying of percentage of construction work/ site inspection	31st March 2025
			I M

2.	Name of Architect/ Architect's firm	Arcop associates Private Limited
3.	Date of site inspection	31st March 2025

3.	Follor	wing technical professionals a	are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name		
	1.	 Site engineer Structural consultant Proof consultant MEP consultant 	Balbant Indolia		
	2.		Vintech Consultant (Mr. Vinod Jain) Mehro Consultants Sanelac Consultants Pvt Ltd		
	3.				
	4.				
	5.	Site supervisor/incharge	Sunil Chauhan		
4.	I certify that the work has been executed as per approved drawings, statutory/mandatory approvals, Haryana Building Code, 2017/National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.				
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with				

respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date

:

Yours faithfully,

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Place

.

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) :

registration no.

CA|2001 | 27447

Council of architects (CoA) :

registration valid till (date)

31-12-2027

		7	Table - A		
(to build	be pi	Tower no. repared separately for each tower in the project/ phase of	Tower-A		
A1	Cum	ulative progress of the projec	t/phase at the e	nd of the quarte	r.
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	(incl	structure usive of excavation, dation, basements, water fing, etc.)	0	35.00	100%
2.	(slab	er structure os, brick work, block work, case, lift wells, machine rooms, er tank, etc.)	0	56.00	100%
3.	MEP	,			
	3.1	Mechanical (lifts, ventilation, etc.)	1.20	18.80	100 %
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.91	11.75	100 %

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.40	12.69	100%
4.	Finis	shing			
, and the second se	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.10	19.02	100%
	4.2	External (plaster, painting, facade, etc.)	1.40	15.26	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status			
1.	Exca	vation	Complete	100 %	
2.	Layi	ng of foundation			
	(i)	Raft	Complete	100 %	
	(ii)	Pile	NA	NA	
3.	Num	ber of basement(s)			
	(i)	Basement Level 1	Structure under Tower Footprint Complete	100%	
	(ii)	Basement level 2*	Structure under Tower Footprint Complete	100%	
4.		erproofing of the above sub- cture (wherever applicable)	Above deck waterproofing	100%	

		Super-Structure Status			
5.	Total	floors in the tower/ building	1Stilt+1Service Floor + 31 Apt Floors	100%	
6.	Total area on each floor 785 Sqm		785 Sqm	100%	
7.	Stilt	floor/ ground floor	Structure Tower Entrance	100%	
8.	Statu	s of laying of slabs floor wise	Upto terrace Level Completed	100%	
	build	ulative number of slabs in the ling/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%	
9.	Status of construction				
	(i)	Blockwork	100% Completed	100%	
	(ii)	Staircase Concreting upto Terrace Slab	100% Completed	100%	
	(iii)	Lift Well including Machine room	100% Completed	100%	
	(iv)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%	
10.		ng of door and window frames in / units			
11.	Statı	as of MEP.	Internal (within flat)	External works	
	(i)	NA	NA	0	
	(ii)	Apartment Electrical Wiring	100% Completed	100%	
	(iii)	UPVC/ RWP Piping	100% Completed	100%	
12.	Statı	us of wall plastering		1 JAC	

_	(i)	RCC External Wall	NA	0
	(ii)	Gypsum Plaster	100% (31 of 31 Floor completed)	100%
13.	Statu	s of wall tiling		
	(i)	Bathroom Tiles	100% Completed	100%
	(ii)	Kitchen Wall Tile	100% Completed	100%
14.	Statu	s of flooring		
	(i)	Lift Lobby Flooring	100% Completed	100%
	(ii)	Apt Stone Flooring	100% Completed	100%
15.	Statu	is of white washing		
	(i)	Apartment Prefinal Paint	100% Completed	100%
	(ii)	Putty+1stCoat+2nd Coat	100% Completed	100%
16.	Statu	is of finishing		
	(i)	MS Railing		100% Completed in staircase
	(ii)	Lift Well HO for Lift Installation	100% Completed	100%
	(iii)	Lobby Wall Tiling	100% Completed	100%
17.	Statı	us of installation		
	(with	nin flat/unit)		
	(i)	UPVC Windows	100% Completed	100%
	(ii)	Bathroom Chinaware	100% Completed	100%
	(iii)	Modular Kitchen Cabinet Installation (Without Panels)	100% Completed	100%

	(iv)	Switch & Sockets	100% Completed	
	(v)	NA	NA	0
	(othe	er than flat/units)		
	(vi)	Guide Rail+ Floor Door+ Car Installation	100%	100% Completed
	(vii)	RCC Work	100% Completed	100% Completed
	(viii)	RCC Work	100% Completed	100% Completed
	(ix)	Fire Pump Installation	100% Completed	100% Completed
	(x)	Staircase & Lobby Wiring	100% Completed	100% Completed
!	(xi)	Six Monthly Compliance	100% Compliance	100% Completed
18.	Wate	erproofing of terraces	PU Waterproofing	100% Completed
19.	Entra	ance lobby finishing	Gypsum False ceiling	100% Completed
20.	Statu	s of construction of compound	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower-A

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking	Yes		
	Covered no	Yes	100%	
	Open no	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%)

16.	Other (option to add more)	NA		
B-2	Community building to be transferred	to RWA		
17.	Community centre	Yes	100%	
18.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	Yes	100%	
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	NA		
23.	*			

Note: (*) extend as per requirement

		1	Table - A		
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)			Tower-B		<u> </u>
A1	Cum	ulative progress of the projec	t/phase at the er	nd of the quarte	r.
Sr. No.	Proje	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
5.	(incl foun	structure usive of excavation, dation, basements, water fing, etc.)	0	35.00	100%
6.	(slab	er structure es, brick work, block work, case, lift wells, machine es, water tank, etc.)	0	60.05	100%
7.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	1.72	18.93	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1.01	12.73	100%

Council of Architecture
Registration No.: CA/2001/27447

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.31	13.23	100%
8.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.02	19.90	100%
	4.2	External (plaster, painting, facade, etc.)	1.01	14.23	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status			
21.	Exca	vation	Complete	100 %	
22.	Layir	ng of foundation			
	(iii)	Complete	100 %	100 %	
	(iv)	NA	NA	0	
23.	Num	ber of basement(s)			
	(iii)	Structure under Tower Footprint Complete	Complete	100%	
	(iv)	Structure under Tower Footprint Complete	Complete	100%	
24.	1	erproofing of the above sub- cture (wherever applicable)	Deck Water Proofing	100%	
		Super-Structure Status	1	Mo Labib Ala	

25.	Total floors in the tower/ building		1Stilt+1Service Floor + 33 Apt Floors	100%
26.	Total	area on each floor	772 Sqm	100%
27.	Stilt f	loor/ ground floor	Structure Tower Entrance	100% Completed
28.	Statu	s of laying of slabs floor wise	Upto terrace Level Completed	100%
	build	ulative number of slabs in the ing/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
29.	Statu	s of construction		
	(v)	Blockwork	Completed	100%
	(vi)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(vii)	Lift Well including Machine room	100% Completed	100%
	(viii)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
30.	Fixing of door and window frames in flats/ units		Door Frame	100% Completed
31.	Statu	as of MEP	Internal (within flat)	External works
	(iv)	NA	NA	
	(v)	Apartment Electrical Wiring	100% Completed	100% Completed
	(vi)	UPVC/ RWP Piping	100% Completed	100% Completed
32.	Statu	s of wall plastering		
	(iii)	RCC External Wall	NA	Sabib Alam,

	(iv)	Gypsum Plaster	100%	100% Completed
33.	Statu	s of wall tiling		
	(iii)	Bathroom Tiles	100% Completed	100% Completed
	(iv)	Kitchen Wall Tile	100% Completed	100% Completed
34.	Statu	s of flooring		
	(iii)	Lift Lobby Flooring	100% Completed	100% Completed
	(iv)	Apt Stone Flooring	100% Completed	100% Completed
35.	Statu	s of white washing	_	
	(iii)	Apartment Prefinal Paint	100% Completed	100% Completed
	(iv)	Putty+1stCoat+2nd Coat	100% Completed	100% Completed
36.	Status of finishing			
	(iv)	MS Railing	100% Completed	100% Completed
	(v)	Lift Well HO for Lift Installation	100% Completed	100% Completed
	(vi)	Lobby Wall Tiling	100% Completed	100% Completed
37.	Statu	s of installation		
	(with	nin flat/unit)		
	(xii)	UPVC Windows	100% Completed	100% Completed
	(xiii)	Bathroom Chinaware	100% Completed	100% Completed
	(xiv)	Modular Kitchen Cabinet Installation (Without Panels)	100% Completed	100% Completed
	(xv)	Switch & Sockets	100% Completed	100% Completed
	(xvi)	NA	NA	
	(oth	er than flat/units)		Alapio Alam, A

	(xvii Guide Rail+ Floor Door+ Car Installation	100 % Complete	100% Completed
	(xviii RCC Work	100% Completed	100% Completed
	(xix) RCC Work	100% Completed	100% Completed
	(xx) Fire Pump Installation	100% Completed	100% Completed
	(xxi) Staircase & Lobby Wiring	100% Completed	100% Completed
	(xxii) Six Monthly Compliance	100% Compliance	100% Completed
38.	Waterproofing of terraces	PU Waterproofing	100% Completed
39.	Entrance lobby finishing	Gypsum False ceiling	100% Completed
40.	Status of construction of compound wall	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower B

ir. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
24.	Internal roads & pavements	Yes	100%	
25.	Parking	Yes	100%	-
	Covered no	Yes	100%	
	Open no	Yes	100%	
26.	Water supply	Yes	100%	_
27.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
28.	Storm water drains	Yes	100%	
29.	Landscaping & tree plantation	Yes	100%	3
30.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	7
	Benches	Yes	100%	
31.	Shopping area	Yes	0%	
32.	Street lighting/ electrification	Yes	100%	
33.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
34.	Solid waste management & disposal	Yes	100%	
35.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
36.	Energy management (solar)	Yes	100%	
37.	Fire protection and fire safety requirements	Yes	100%	
38.	Electrical meter room, sub-station, receiving station	Yes	100%	abib Alam

39.	Other (option to add more)	NA		
B-2	Community building to be transferred	to RWA		
40.	Community centre	Yes	100%	
41.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
42.	Schools	NA		
43.	Dispensary	NA		
44.	Club	Yes	100%	
45.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	NA		
46.	*	18		

Note: (*) extend as per requirement

			Table – A		
(to build	uilding/ Tower no. Tower-C to be prepared separately for each uilding/ tower in the project/ phase of the project) Tower-C				
A1	Cum	ulative progress of the projec	t/phase at the e	nd of the quarte	r.
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
9.	(incl foun	structure usive of excavation, dation, basements, water fing, etc.)	0	24.96	100%
10.	(slab	er structure os, brick work, block work, case, lift wells, machine os, water tank, etc.)	0	40.02	100%
11.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	0.40	9.71	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.79	7.98	100%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.40	7.94	100%
12.	Finis	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.30	16.24	100%
	4.2	External (plaster, painting, facade, etc.)	0.11	5.62	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
		Sub-Structure Status		
41. I	Exca	vation	Complete	100 %
42. I	Layir	ng of foundation		
((v)	Complete	100% Completed	100%
	(vi)	NA	NA	0
43.	Number of basement(s)			
	(v)	Structure under Tower Footprint Complete	100% Completed	100%
	(vi)	Structure under Tower Footprint Complete	100% Completed	100%
	Waterproofing of the above sub- structure (wherever applicable)		Deck Water Proofing	100%
		Super-Structure Status		Labib Alam,

45.	Total f	floors in the tower/ building	1Stilt+1Service Floor + 30 Apt Floors	100%
46.	Total area on each floor		549 Sqm	100%
47.	Stilt fl	oor/ ground floor	Structure Tower Entrance	100% Completed
48.	Status	of laying of slabs floor wise	Upto terrace Level Completed	100%
	buildi	lative number of slabs in the ng/tower laid by f quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
49.	Status of construction			
	(ix)	Blockwork	100% Completed	100% Completed
	(x)	Staircase Concreting upto Terrace Slab	100% Completed	100% Completed
	(xi)	Lift Well including Machine room	100% Completed	100% Completed
	(xii)	Structure lift lobbies and other common area upto 30 Floor	100% Completed	100% Completed
50.	1	g of door and window frames in units	Door Frame	100% Completed
51.	Status of MEP		Internal (within flat)	External works
	(vii)	NA	NA	
	(viii)	Apartment Electrical Wiring	100% Completed	100% Completed
	(ix)	UPVC/ RWP Piping	100% Completed	100% Completed
52.	Statu	s of wall plastering		
	(v)	RCC External Wall	NA	and .

	(vi)	Gypsum Plaster	100%	100% Completed
53.	Statu	s of wall tiling		
	(v)	Bathroom Tiles	100% Completed	100% Completed
	(vi)	Kitchen Wall Tile	100% Completed	100% Completed
54.	Status of flooring			
	(v)	Lift Lobby Flooring	100% Completed	100% Completed
	(vi)	Apt Stone Flooring	100% Completed	100% Completed
55.	Statu	s of white washing		
	(v)	Apartment Prefinal Paint	100% Completed	100% Completed
	(vi)	Putty+1stCoat+2nd Coat	100% Completed	100% Completed
56.	Status of finishing			
	(vii)	MS Railing	100% Completed	100% Completed
	(viii)	Lift Well HO for Lift Installation	100% Completed	100% Completed
	(ix)	Lobby Wall Tiling	100% Completed	100% Completed
57.	Statu	s of installation		
	(with	nin flat/unit)		
	(xxiii	UPVC Windows	100% Completed	100% Completed
	(xxiv	Bathroom Chinaware	100%	100% Completed
	(xxv)	Modular Kitchen Cabinet Installation (Without Panels)	100%	100% Completed
	(xxv	Switch & Sockets	100% Completed	100% Completed
	(xxv	NA	NA	\ \ \ \ \ \
	(oth	er than flat/units)		J. Mil

	(xxvi Guide Rail+ Floor Door+ Car Installation	100% Complete	100% Completed
1	(xxix RCC Work	100% Completed	100% Completed
	(xxx) RCC Work	100% Completed	100% Completed
	(xxxi Fire Pump Installation	100% Completed	100% Completed
	(xxxi Staircase & Lobby Wiring	100% Completed	100% Completed
	(xxxi Six Monthly Compliance	100% Compliance	100% Completed
58.	Waterproofing of terraces	PU Waterproofing	100% Completed
59.	Entrance lobby finishing	Gypsum False ceiling	100% Completed
60.	Status of construction of compound wall	Boundary Wall RCC and Brick Work	100% Completed

Note: (*) extend rows as per requirement.

Table - B Tower C

. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
47.	Internal roads & pavements	Yes	100%	
48.	Parking	Yes	100%	
	Covered no	Yes	100%	
	Open no	Yes	100%	
49.	Water supply	Yes	100%	
50.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
51.	Storm water drains	Yes	100%	
52.	Landscaping & tree plantation	Yes	100%	
53.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
54.	Shopping area	Yes	0%	
55.	Street lighting/ electrification	Yes	100%	
56.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
57.	Solid waste management & disposal	Yes	100%	
58.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
59.	Energy management (solar)	Yes	100%	
60.	Fire protection and fire safety requirements	Yes	100%	
61.	Electrical meter room, sub-station, receiving station	Yes	100%	-kih Alam

62.	Other (option to add more)	NA				
B-2	Community building to be transferred to RWA					
63.	Community centre	Yes	100%			
64.	others	NA				
B-3	Community buildings not to be transferred to RWA/competent authority					
65.	Schools	NA				
66.	Dispensary	NA				
67.	Club	Yes	100%	_		
68.	Others	NA				
B-4	Services/ facilities to be transferred to competent authority	NA				
69.	*					

Note: (*) extend as per requirement