

INDIVALUE ADVISORS PRIVATE LIMITED

Regd. Address: B1/H3, MOHAN CO-OPERATIVE INDUSTRIAL AREA MATHURA RD, BLOCK B NEW DELHI 110044 Email: Indivalueadvisors@gmail.com Mobile +91-7044091174

CIN: U74999DL2021PTC381050

IVPL/05/03/2025/ELAN EPIC

		Architect	t's Certificate			
Repo	rt for q	uarter ending	Jan to March' 2025			
Subject			Certificate of progress of construction work			
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans					
	Sr. No.	Particulars	Information			
	1.	Project/Phase of the project	Elan EPIC			
	2.	Location	Sector 70, Gurugram			
	3.	Licensed area in acres	4 Acres			
	4.	Area for registration in acres	3.525 Acres			
	5.	HARERA registration No.	RC/REP/HARERA/GGM/2018/30 Dated: 6/12/2018			
	6.	Name of licensee	Elan Limited			
	7.	Name of collaborator	NA			
	8.	Name of developer	Elan Limited			
2.	Details related to inspection are as under					
	1.	Date of certifying of percentage of construction work/ site inspection	31.03.2025			
	2.	Name of Architect/Architect's firm	Ar. Ashish Sawe			
	3.	Date of site inspection	31.03.2025			
3.	Following technical professionals are appointed by promoter: - (as applicable)					
	Sr. No.	Consultan ts	Name			
	1.	Site engineer	Vikram Singh			
	2.	Structural consultant	Perceptive Idea			
	3.	Proof consultant	Isha Consultant (P) Ltd.			
	4.	MEP consultant	CP Vidya Associates, Dew point Consultants Pvt. Ltd.,Ampower Consultancy Services.			
	5.	Site supervisor/incharge	Saurabh Gupta			



- 4. I certify that the work has been executed as per approved drawings, statutory/mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
- I also certify that as on the date, the percentage of work done in the project for each of the building/tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

CN/2001/28463

Date: 31.03.2025

Yours faithfully,

Name: - Ar. ASHISH SAWE

Stamp:

Place : Gurugram

Council of Architecture (CoA)

Registration no.

:.CA/2001/28463

(CoA)

Registration valid till (date) : 31.12-2033

		Та	ble – A			
(to be	prepare	Fower no. d separately for each building/ roject/phase of the project)	ELAN EPIC (Entire project is	one building 40	4 Units)	
A1	Cun	ulative progress of the project	t/phase at the end	l of the quart	er. (In Lacs)	
Sr. No.	Project components		Work done value during the quarter (Sqmt)	Cumulative work done value till date (Sqmt	work done to the total	
1.	(inclu	structure sive of excavation, foundation, ments, water proofing, etc.)	-	20125	100%	
2.	(slabs	er structure s, brick work, block work, staircase, ells, machine rooms, water tank, etc.)	-	28695	100%	
3.	MEI	9				
	3.1	Mechanical (lifts, ventilation, etc.)	-	28695	100%	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)		28695	100%	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	nbing & Firefighting (piping, aps and pump room, fixtures,		100%	
4.	Finishing		A			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	28695	100%	
ь.	4.2 External (plaster, painting, facade, etc.)			28695	100%	
Sr. No.				ork	Percentage of total proposed	
	Sub-Structure Status			one	work 100%	
1.	Exc	eavation	Comp	Completed		
2.	Lay	ring of foundation				
	(i)	Raft	Completed		100%	
	(ii)	Pile	Comp	Completed		
3.	Nui	mber of basement(s)		SHISH		
	(i)	Basement Level 1	Completed 100%			

	(ii)	Basement level 2	Comp	leted	100)%	
4.		proofing of the above sub-structure rever applicable)	Work in Progress		98%		
		Super-Structure Status			÷		
5.	Total	floors in the tower/ building	6		- 6		
6.	Total	area on each floor	N/	A	NA		
7.	Stilt	floor/ ground floor	Comp	leted	100%		
8.	Statu	s of laying of slabs floor wise	Completed		100%		
		lative number of slabs in the building/ laid by end of quarter	Comp	leted	100%		
9.	Statu	s of construction					
	(i)	Walls on floors	Comp	leted	100)%	
	(ii)	Staircase	Comp	leted	100%		
	(iii)	Lift wells along with water proofing	Completed		100%		
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%		
10.	Fixin units	g of door and window frames in flats/	NIL		NI	IL	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works	Completed		100%		
	(ii)	Electrical works including wiring	Completed		100%		
	(iii)	Plumbing works	Completed		100%		
12.	Statu	s of wall plastering					
	(i)	External plaster	Completed		100%		
	(ii)	Internal plaster	Comp	leted	100	100%	
13.	Statu	s of wall tiling					
	(i)	In bathroom	Completed		100%		
	(ii)	In kitchen	NA		NA		
14.	Status of flooring						
	(i)	Common areas	Completed		100%		
	(ii)	Units/ flats	NA		NA		
15.	Statu	s of white washing					
	(i)	Internal walls	Completed		100%		
	(ii)	External walls	Completed		100%		
						5	
16.	Statu	s of finishing		USU			

IVPL/05/03/2025/ELAN EPIC

	(ii)	Lift wells	Completed	100%	
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%	
17.	Status of installation				
	(withi	in flat/unit)			
	(i)	Doors and windows panels	Completed	100%	
	(ii)	Sanitary fixtures	Completed	100%	
	(iii)	Modular kitchen	NA	NA	
	(iv)	Electrical fittings/ lighting	Completed	100%	
	(v)	Gas piping (if any)	NA	NA	
	(other	than flat/units)			
	(vi)	Lifts installation	Completed	100%	
	(vii)	Overhead tanks	Completed	100%	
	(viii)	Underground water tank	Completed	100%	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%	
	(x)	Electrical fittings in common areas	Completed	100%	
	(xi)	Compliance to conditions of environment/ CRZ NOC	NIL	NIL	
18.	Water	rproofing of terraces	Completed	100%	
19.	Entra	nce lobby finishing	Completed	100%	
20.	Status	s of construction of compound wall	Completed	100%	

Note: (*) extend rows as per requirement

Table-B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking			
	Covered no572	Yes	100%	
	Open no Nil	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	NA	NIL	
	Fixing of children play equipment's	NA	NIL	
	Benches	NA	NIL	
8.	Shopping area	YES	NIL	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)		NIL	



B-2	Community building to be transferred to RWA					
17.	Community centre	NO	NO	ij		
18.	Others					
B-3	Community buildings not to be transferred to RWA/competent authority					
19.	Schools	NO	NO			
20.	Dispensary	NO	NO			
21.	Club	NO	NO			
22.	Others					
B-4	Services/ facilities to be transferred to competent authority					
23.	*					

-----END REPORT-----

Pegd. Archi