LINE OF FORCE Architects

F-3 FIRST FLOOR, SHARAN APPARTMENTS, SOUTHCITY-1, GURGAON, HARYANA EMAIL : $\underline{lofarchitectsgurgaon@gmail.com}$

Annexure A

		Architect	t's Certificate*		
Report	t for qua	rter ending	31.03.2025		
Subject			Certificate of progress of construction work		
1.	I/We have undertaken assignment as arch below mentioned project as per the approv		nitect for certifying progress of construction work in the red plans		
	Sr. No.	Particulars	Information		
	1.	Project/Phase of the project	SS HIGH POINT		
	2.	Location	Vill- Badha, Sector-86, Tehsil-Manesar, Gurugram		
	3.	Licensed area in acres	2.80625		
	4.	Area for registration in acres	2.80625		
	5.	HARERA registration No.	36 of 2019		
	6.	Name of licensee	Shiva Profins Pvt. Ltd., Matrix Buildwell Pvt. Ltd. North Star Towers Pvt. Ltd.		
	7.	Name of collaborator	SS Group Pvt. Ltd.		
	8.	Name of developer	SS Group Pvt. Ltd.		
2.	Details related to inspection are as under				
	1.	Date of certifying of percentage of construction work/ site inspection	01.04.2025		
	2.	Name of Architect/ Architect's firm			
	3.	Date of site inspection	03.04.2025		
3.	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name		
	1.	Site engineer	Saurabh Joshi		
	2.	Structural consultant	DESMAN		
	3.	Proof consultant	Arvind Gupta		
	4.	MEP consultant	ASHOK GANGWAR (ARK Consultants)		
	5.	Site supervisor/in charge	Dev Kumar Dutta Ar. KAPIL SINGH		

LINE OF FORCE Architects

4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals,	
	Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the	
	construction, infrastructure works and internal development works are as per the projected standard as	
	envisaged in the registration and brochure, publication material and other documents shared with the buyers	
	in this regard.	

I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/phase is detailed in table A and table B.

Yours Faithfully

Signature & Name (in block letters)

With stamp of Architect

KAPIL SINGH

RAPIL SINGH

B. Arch.

Regn. No with Council of Architecture CA/2003/31608

Date 03.04.2025

Place Grusgam

Council of Architects (CoA):

Registration No. CA/2003/31608

Council of Architects (CoA) :

Registration valid till (Date) 31 De4 2031

- C			TABLE-A (MAR-25))			
Buildi	ng No/Tov	wer No.	SS HIGH POINT				
A1	Cumulative Progress of the Project/Phase at the end of the Quarter						
Sr.No	Project Co		Work done value during the Quarter (In Lakh)	7		Percentage done to the proposed w	total
1	Sub Struct	ure	2.06	683	l.11	9.9	1%
2	Super Stru	cture	120.28	168	3.89	24.	50%
3	MEP						
	3.1	Mechanical Work	0.00	412	2.38	6.0	00%
	3.2	Electrical Work	0.00	515	5.48	7.5	50%
	3.3	Plumbing & Fire Fighting Work	0.00	386	5.61	5.6	53%
4	FINISHING						
	4.1	Internal (Plaster, Tiling,Flooring,Painting etc. within Unit & common areas)	131.19	930).69	13.	54%
	4.2	External (Plaster, Painting, Façade etc.)	82.48	494	1.86	7.2	20%
Sr.No.		Tasks/ Activity	У		on of Work one	Percentage proposed w	
	Sub-Struct	ure Status					
1	Excavation			Com	plete	0.2	20%
2	Laying of F	oundation					
	(i)	Raft		Com	plete	5.9	00%
3	Number of	Basements					
	(i)	Basement Level-1		Com	plete	1.2	20%
	(ii)	Basement Level-2		Com	plete	1.2	20%
	(iii)	Basement Level-3		Com	plete	1.2	20%
4	Water Prod applicable)	ofing of the Above Sub-Struc)	cture (wherever	In Progress		0.21%	
	Super-Stru	icture Status					
5	Total Floor	s in the Tower/ Building		G+	-18		
6		on each floor (Sq.Mtr.)		2760	0.368		
7	Stilt / Grou			4964	1.783		
		aying of slabs floor wise					
8	Cumulative the quarte	e number of the slabs in the r	Building Laid by end of	of 3		24.5%	
9	Status of C	Construction					
	(i)	Walls on floors		In Pro	gress	24.	50%
	(ii)	Staircase		In Pro	gress	24.	50%
	(iii)	Liftwells along with water	proofing	In Pro	gress	24.	50%
	(iv)	Lift Lobbies/Common area		In Pro	gress	24.	50%
10		Fixing of Door & window frames in the Units			gress	13.	54%
11	Status of N	ЛЕР		Internal (with in Flat)	External Work	Internal (with in Flat)	External Work
	(i) Mechanical Work			In Progress		6.00%	
	(ii)	Electrical work including w	riring	In Pro	gress	7.5	0%

4.0	(iii)	Plumbing & Fire Fighting Work	In Progress	5.63%
12	Status of \	Wall Plastering		
	(i)	External Plaster	In Progress	7.20%
	(ii)	Internal Plaster	In Progress	13.54%
13	Status of \	Wall Tiling		
	(i)	In Toilets	In Progress	13.54%
14	Status of Flooring			
	(i)	Common Areas	In Progress	13.54%
	(ii)	Units/Flats	In Progress	13.54%
15	Status of \	White Washing		
	(i)	Internal Walls	In Progress	7.20%
	(ii)	External Walls	In Progress	7.20%
16	Status of F	inishing		
	(i)	Staircase with Railing	In Progress	13.54%
	(ii)	Lift Wells	In Progress	13.54%
	(iii)	Lift Lobbies/Common areas floor wise	In Progress	13.54%
17	Status of i	nstallation		
	(within Fl	ats/ Units)		
	(i)	Doors & Windows Panels	NA	NA
	(ii)	Sanitary Fixtures	NA	NA
	(iii)	Modular Kitchen	NA	NA
	(iv)	Electrical Fittings/ Lightings	NA	NA
	(v)	Gas Piping (if any)	NA	NA
	(other tha	an Flats/ Units)		
	(vi)	Lift Installations	In Progress	6%
	(vii)	Over Head Tanks	In Progress	24.5%
	(viii)	Under Ground Water Tanks	In Progress	9.91%
	(ix)	Fire Fighting Equipments & Fittings as per CFO NOC	In Progress	5.63%
	(x)	Electrical Fittings in Common Areas	In Progress	7.50%
	(xi)	Compliance to condition of environment/CRZ NOC	NA	NA
18	Water Pro	ofing of Terraces	In Progress	0%
19	Entrance L	obby Finishing	In Progress	13.54%
20	Status of C	Construction of Compound wall	Nil	0%

Ar. KAPIL SINGH B. Arch.

Regn. No with Council of Architecture CA/2003/31608

	TABLE-B (SSH-MAR-25)					
Sr.No	Common Areas and Facilities	Proposed	Percentage of work	Remarks		
	Amenities	(Yes/No)	done			
B-1	Services					
1	Internal Roads & Pavements	Yes	37%			
2	Parkings	Yes				
	Covered	Yes	10%			
	Open NoS	NA	NA			
3	Water Supply	Yes	30%			
4	Sewarage(Chambers, Lines, STP, Septic Tanks)	Yes	30%			
5	Storm Water Drains	Yes	30%			
6	Landscaping & Tree Plantations	Yes	0%			
7	Parks & Playgrounds	NA	NA			
8	Shopping Areas	NA	NA			
9	Street Lighting/Electrification	Yes	30%			
10	Treatment & Disposal of Sewage & Sludge water/STP	Yes	90%			
11	Solid waste Management &					
12	Rain water Harvesting	Yes	30%			
13	Energy Management (Solar)	Yes	0%			
14	Fire Protection & Fire safety Equipments	Yes	10%			
15	Electrical Meter Room,Sub- Station,Receiving Station	Vos 28%				
16	Under Ground Water Tank	Yes	100%			
B-2	Community Building to be Transfer	red to RWA				
17	Community Center	NA	NA	NA		
18	Others.	NA	NA			
B-2	Community Building not to be Transferred to RWA/Competent Authority					
19	School	NA	NA			
20	Milk Booth	NA NA				
21	Club/Community Building	NA	NA			

Ar. KAPIL SINGH

B. Arch.

Regn. No with Council of Architecture CA/2003/31608