Design and Development Atelier

B 99 Sushant Lok 1, Gurgaon Haryana 122002 India

t: +01191 0124 4040076 w: www.dadapartners.com

tners.com

			e : contact@dadapar
		Architect'	s Certificate*
Repo	rt for q	uarter ending	Q4 (FY 2024-25)
Subject Certificate of progress of construction v			Certificate of progress of construction work
1.			as architect for certifying progress of ntioned project as per the approved plans
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	Godrej Meridien Phase-III
	2.	Location	Sec 106, Gurugram, Haryana
	3.	Licensed area in acres	14.793
	4.	Area for registration in acres	5.06
	5.	HARERA registration no.	RC/REP/HARERA/GGM/393/125/2020/ 09
	6.	Name of licensee	Godrej Real View Developers Private Limited
	7.	Name of collaborator	Not Applicable
	8.	Name of developer	Godrej Real View Developers Private Limited
2.	Detai	ls related to inspection are as	under
	1.	Date of certifying of percentage of construction work/ site inspection	02-Apr-2025
	2.	Name of Architect/ Architect's firm	M/s DADA & Partners
	3.	Date of site inspection	02-Apr-2025

3.	Follov	Following technical professionals are appointed by promoter: - (as applicable)				
	Sr. No.	Consultants	Name			
	1.	Site engineer	GPL			
	2.	Structural consultant	M/s BMSF & M/s PPS			
	3.	Proof consultant				
	4.	MEP consultant	M/s PROION			
	5.	Site supervisor/incharge				
4.	I certify that the work has been executed as per approved drawings, statutory/mandatory approvals, Haryana Building Code, 2017/National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.					
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.					

Yours faithfully, Date : 4th April, 2025 **ADITI ARORA**

: B-99, Sushant Lok 1, Place

Sector 43, Gurugram,

Haryana, 122001

Council of architects (CoA) registration

no.

:CA/2000/25713

Council of architects : 12/31

(CoA) registration valid till (date)



Signature & name (in block letters) with stamp of architect

			Table - A		
(to build	be p	Tower no. repared separately for each tower in the project/ phase of t)			
A1	Cum	ulative progress of the projec	t/phase at the en	nd of the quarter	•
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		0.0	6.01	100%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0.2	26.2	99%
3.	MEP	,			
	3.1	Mechanical (lifts, ventilation, etc.)	0.5	2.0	20%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.6	2.80	22%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.60	2.40	22%
4.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.5	2.07	23%
	4.2	External (plaster, painting, facade, etc.)	0.5	1.2	10%

Sr.		Tasks/ Activity		on of work	Percentage of total	
No.		Sub-Structure Status	do	one	propos	ed work
1.	Exca	vation			100%	
2.	Layiı	ng of foundation			100%	
	(i)	Raft				
	(ii)	Pile			NA	
3.	Num	ber of basement(s) 2				
	(i)	Basement Level 1			100%	
	(ii)	Basement level 2*			100%	
4.		erproofing of the above sub- cture (wherever applicable)			100%	
		Super-Structure Status				
5.	Tota	l floors in the tower/building			34 excludi	ng Ground
6.	Tota	l area on each floor			805 Sq m	
7.	Stilt	floor/ ground floor			Ground Flo	oor
8.	Statı	is of laying of slabs floor wise				
	build	ulative number of slabs in the ling/towerlaid by of quarter			34	
9.	Statı	us of construction				
	(i)	Walls on floors			100%	
	(ii)	Staircase			100%	
	(iii)	Lift wells along with waterproofing			100%	
	(iv)	Lift lobbies/ common areas floor-wise			-	
10.		g of door and window frames in / units			0%	
11.	Statı	us of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works			18%	
	(ii)	Electrical works including wiring			12%	
	(iii)	Plumbing works			12%	
12.	Statu	is of wall plastering				
	(i)	External plaster			0%	
	(ii)	Internal plaster			55%	

13.	Statı	us of wall tiling	
	(i)	In bathroom	5%
	(ii)	In kitchen	5%
14.	Statı	us of flooring	
	(i)	Common areas	0%
	(ii)	Units/ flats	2%
15.	Statı	us of white washing	
	(i)	Internal walls	0%
	(ii)	External walls	5%
16.	Statu	us of finishing	
	(i)	Staircase with railing	65%
	(ii)	Lift wells	0%
	(iii)	Lift lobbies/ common areas floor wise	0%
17.	Statu	is of installation	
	(witl	nin flat/unit)	
	(i)	Doors and windows panels	0%
	(ii)	Sanitary fixtures	0%
	(iii)	Modular kitchen	0%
	(iv)	Electrical fittings/ lighting	0%
	(v)	Gas piping (if any)	NA
	(oth	er than flat/units)	
	(vi)	Lifts installation	5%
	(vii)	Overhead tanks	0%
	(viii)	Underground water tank	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	0%
	(x)	Electrical fittings in common areas	 0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	100%
18.	Wate	erproofing of terraces	0%
19.	Entr	ance lobby finishing	 0%
20.	Statı wall	us of construction of compound	65%

Note: (*) extend rows as per requirement.

		7	Гable – A		
(to build	be p	Tower no. repared separately for each tower in the project/ phase of	5 (B+G+25)		
A1	Cum	ulative progress of the project	/phase at the end	of the quarter.	
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
5.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)			3.23 Cr	100%
6.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)			14.6 Cr	100%
7.	МЕР	,			
	3.1	Mechanical (lifts, ventilation, etc.)	0.7	2.3	16%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.4	1.6	16%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.4	1.6	18%
8.	Fini	shing			
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.6	3.12	65%
	4.2	External (plaster, painting, facade, etc.)	0.5	1.5	18%

					1	
Sr. No.	Tasks/ Activity De Sub-Structure Status			on of work one		ge of total ed work
21.	Exca	vation			100%	
22.	Layir	ng of foundation				
	(iii)	Raft			100%	
	(iv)	Pile			NA	
23.	Num	ber of basement(s)				
	(iii)	Basement Level 1			100%	
	(iv)	Basement level 2*			NA	
24.		erproofing of the above sub- eture (wherever applicable)			100%	
		Super-Structure Status				
25.	Tota	l floors in the tower/building			25 excludi	ng Ground
26.	Tota	l area on each floor			714.72 Sq	m
27.	Stilt	floor/ ground floor			Ground Fl	oor
28.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ towerlaid by end of quarter				25	
29.	Statu	us of construction				
	(v)	Walls on floors			100%	
	(vi)	Staircase			100%	
	(vii)	Lift wells along with water proofing			99%	
	(viii)	Lift lobbies/ common areas floor wise			99%	
30.		g of door and window frames in / units			-	
31.	Statu	us of MEP	Internal (within flat)	External works	Internal (within flat)	External works
	(iv)	Mechanical works			15%	
	(v)	Electrical works including wiring			15%	
	(vi)	Plumbing works			15%	
32.	Statu	s of wall plastering				
	(iii)	External plaster			NA	

	(iv)	Internal plaster	99%
33.	Statı	us of wall tiling	
	(iii)	In bathroom	52%
	(iv)	In kitchen	52%
34.	Statı	us of flooring	
	(iii)	Common areas	-
	(iv)	Units/ flats	40%
35.	Statı	us of white washing	
	(iii)	Internal walls	-
	(iv)	External walls	-
36.	Statı	us of finishing	
	(iv)	Staircase with railing	70%
	(v)	Lift wells	-
	(vi)	Lift lobbies/ common areas floor wise	-
37.	Statı	is of installation	-
	(witl	nin flat/unit)	
	(xii)	Doors and windows panels	-
	(xiii)	Sanitary fixtures	-
	(xiv)	Modular kitchen	-
	(xv)	Electrical fittings/ lighting	-
	(xvi)	Gas piping (if any)	NA
	(oth	er than flat/units)	
	(xvii	Lifts installation	-
	(xvii	Overhead tanks	-
	(xix)	Underground water tank	-
	(xx)	Firefighting fitting and equipment's as per CFO NOC	-
	(xxi)	Electrical fittings in common areas	-
	(xxii	Compliance to conditions of environment/ CRZ NOC	100%
38.	Wate	erproofing of terraces	-
39.	Entr	ance lobby finishing	 -
40.	Statı wall	us of construction of compound	80%

	Table – A						
(to build	be p	Tower no. repared separately for each tower in the project/ phase of	6 (B+G+23)				
A1	Cum	ulative progress of the project	z/phase at the end	of the quarter.			
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
9.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)			3.13	100%		
10.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)			15.4	100%		
11.	МЕР						
	3.1	Mechanical (lifts, ventilation, etc.)	0.5	1.7	10%		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.4	1.6	15%		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.4	1.6	15%		
12.	Finis	shing					
	4.1	Internal	0.4	2.4	34%		
		(plaster, tilling, flooring, painting, etc. within units and common areas)					

	4.2	External (plaster, painting, facade, etc.)	0.4		1.2		16%	
Sr. No.		Tasks/ Activity Sub-Structure Status		Descriptio do			_	e of total d work
41.	Exc	avation				100%	l	
42.	Lay	ing of foundation				-		
	(v)	Raft				100%		
	(vi)	Pile				NA		
43.	Nun	nber of basement(s)						
	(v)	Basement Level 1				100%	ı	
	(vi)	Basement level 2*				NA		
44.		erproofing of the above sub- cture (wherever applicable)				-		
		Super-Structure Status						
45.	Tota	al floors in the tower/building				23 exc	cludin	g Ground
46.	Tota	al area on each floor				699 Sq m		
47.	Stilt	floor/ground floor				Ground Floor		or
48.	Stat	us of laying of slabs floor wise						
	buil	nulative number of slabs in the ding/ towerlaid of quarter	d by			23		
49.	Stat	us of construction						
	(ix)	Walls on floors				100%	١	
	(x)	Staircase				100%	١	
	(xi)	Lift wells along with water proofing				99%		
	(xii)	Lift lobbies/ common areas floor wise				99%		
50.	Fixing of door and window frames in flats/ units				-			
51.	Stat	us of MEP		Internal (within flat)	External works	Intern (withi flat)		External works
	(vii)	Mechanical works				12%		
	(viii	Electrical works include wiring	ling			15%		

	(ix)	Plumbing works	-	15%
52.	Statu	is of wall plastering		-
	(v)	External plaster	-	-
	(vi)	Internal plaster	-	95%
53.	Statu	us of wall tiling		-
	(v)	In bathroom		-
	(vi)	In kitchen		-
54.	Statu	us of flooring		
	(v)	Common areas		-
	(vi)	Units/ flats		-
55.	Stati	us of white washing		
	(v)	Internal walls		-
	(vi)	External walls		-
56.	Statu	s of finishing		
	(vii)	Staircase with railing		60%
	(viii)	Lift wells		-
	(ix)	Lift lobbies/ common areas floor wise		-
57.	Statu	s of installation		
	(with	nin flat/unit)		
	(xxii	Doors and windows panels		-
	(xxiv	Sanitary fixtures		-
	(xxv)	Modular kitchen		-
	(xxvi	Electrical fittings/lighting		-
	(xxvi	Gas piping (if any)		NA
	(othe	er than flat/units)		
	(xxvi	Lifts installation		-
	(xxix	Overhead tanks		-
	(xxx)	Underground water tank		-
	(xxxi	Firefighting fitting and equipment's as per CFO NOC		-
	(xxxi	Electrical fittings in common areas	_	-

	(xxxi Compliance to conditions of environment/ CRZ NOC	100%
58.	Waterproofing of terraces	-
59.	Entrance lobby finishing	-
60.	Status of construction of compound wall	80%

	Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project) 7 (B+G+19)					
A1	Cum	ulative progress of the project	t/phase at the end	of the quarter.	
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
13.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)		-	2.97 Cr	100%
14.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		-	5.7 Cr	100%
15.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	0.2	3.10	98%
	3.2	Electrical (conducting, wiring, fixtures,etc.)	0.5	3.9 cr	97%
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.3	3.2	97%
16.	16. Finishing				

	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0.6	5.6	96%
	4.2	External (plaster, painting, facade, etc.)	0.6	3.6	88%

Sr.	Tasks/ Activity	Description of work	Percentage of total	
No.	Sub-Structure Status	done	proposed work	
61.	Excavation		100%	
62.	Laying of foundation		-	
	(vii) Raft		100%	
	(viii) Pile		NA	
63.	Number of basement(s)			
	(vii) Basement Level 1		100%	
	(viii) Basement level 2*		NA	
64.	Waterproofing of the above substructure (wherever applicable)		100%	
	Super-Structure Status			
65.	Total floors in the tower/ building		19 excluding Ground	
66.	Total area on each floor		759 Sq m	
67.	Stilt floor/ ground floor		Ground Floor	
68.	Status of laying of slabs floor wise		19	
	Cumulative number of slabs in the building/ towerlaid by end of quarter		19	
69.	Status of construction			
	(xiii) Walls on floors		100%	
	(xiv) Staircase		100%	
	(xv) Lift wells along with water proofing		100%	
	(xvi) Lift lobbies/ common areas floor wise		100%	
70.	Fixing of door and window frames in flats/ units		-	
71.	Status of MEP	Internal External (within flat)	Internal External (within works flat)	

	(x) Mechanical works	96%
	(xi) Electrical works including wiring	96%
	(xii) Plumbing works	96%
72.	Status of wall plastering	
	(vii) External plaster	NA
	(viii) Internal plaster	100%
73.	Status of wall tiling	
	(vii) In bathroom	100%
	(viii) In kitchen	100%
74.	Status of flooring	
	(vii) Common areas	95%
	(viii) Units/ flats	95%
75.	Status of white washing	
	(vii) Internal walls	90%
	(viii) External walls	100%
76.	Status of finishing	
	(x) Staircase with railing	100%
	(xi) Lift wells	100%
	(xii) Lift lobbies/ common areas floor wise	96%
77.	Status of installation	
	(within flat/unit)	
	(xxxi Doors and windows panels	99%
	(xxx Sanitary fixtures	10%
	(xxx Modular kitchen	NA
	(xxx Electrical fittings/ lighting	95%
	(xxx Gas piping (if any)	NA
	(other than flat/units)	
	(xxxi Lifts installation	100%
	(xl) Overhead tanks	99%
	(xli) Underground water tank	-
	(xlii) Firefighting fitting and equipment's as per CFO NOC	100%
	(xliii Electrical fittings in common areas	90%

	(xliv	Compliance to conditions of environment/ CRZ NOC	100%
78.	Wate	erproofing of terraces	15%
79.	Entrance lobby finishing		95%
80.	Status of construction of compound wall		100%

Table - B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	-	
2.	Parking			
	Covered no	Yes	-	
	Open no	Yes	-	
3.	Water supply	Yes	50%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	50%	
5.	Storm water drains	Yes	-	
6.	Landscaping & tree plantation	Yes	-	
7.	Parks and playgrounds	Yes	-	
	Fixing of children play equipment's	Yes	-	
	Benches	Yes	-	
8.	Shopping area	NA	-	
9.	Street lighting/ electrification	Yes	-	
10.	Treatment and disposal of sewage and sullage water/ STP	NA	-	
11.	Solid waste management & disposal	Yes	-	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	-	
13.	Energy management (solar)	Yes	-	
14.	Fire protection and fire safety requirements	Yes	-	
15.	Electrical meter room, sub-station, receiving station	Yes	-	
16.	Other (option to add more)			
B-2	Community building to be transferred	to RWA		•
17.	Community centre	No	-	
18.	others			
B-3	Community buildings not to be transferred to RWA/competent authority			

19.	Schools	Yes	-	
20.	Dispensary	NA		
21.	Club	NA		
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	Cumulative Progress		55.0 %	

Note: (*) extend as per requirement