

		Architect	es Certificate*		
Repor	t for qua	rter ending	30-Sep-21		
Subject			Certificate of progress of construction work		
1,	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans				
	Sr. No.	Particulars	Information		
	1,	Project/Phase of the project	Signature Global City-2		
	2.	Location	Sector-28, Karnal		
	3.	Licensed area in acres	15 acre		
	4.	Area for registration in acres	15 acre		
	5.	HARERA registration no.	HRERA-PKL-KNL-26-2018 Dated 20-July-2018		
	6.	Name of licensee	M/s Fantabulous Town Developers Pvt. Ltd.		
	7.	Name of collaborator	NA		
	8.	Name of developer	M/s Fantabulous Town Developers Pvt. Ltd.		
2.	Details related to inspection are as under				
	1,	Date of certifying of percentage of construction work/ site inspection	30-Sep-21		
	2.	Name of Architect/ Architect's firm	M/s Gian P. Mathur & Associates		
	3.	Date of site inspection	30-Sep-21		

3.	Follow	ring technical professionals are appoi	nted by promoter: - (as applicable)		
	Sr. No.	Consultants	Name  M/s RDC India Projects.		
	1.	Site engineer			
	2.	Structural consultant	M/s Gian P. Mathur & Associates		
	3	Proof consultant	NA		
	4.	MEP consultant	M/s Gian P. Mathur & Associates		
	5.	Site supervisor/incharge	M/s RDC India Projects.		
4.	Haryan constru envisag	a Building Code, 2017/ National Build ction, infrastructure works and international control of the control of t	s per approved drawings, statutory/ mandatory approvals, ing Code (wherever applicable) and the material used in the all development works are as per the projected standard as publication material and other documents shared with the		
5.	of the r	eal estate project/phase of the project	e of work done in the project for each of the building/ tower under HARERA is as per table A and table B given herein with respect to each of the activity of the entire project/		

Date

: 30/09/2021

Yours faithfully,

Signature & name (in block letters) with stamp of architect

Place

: New Delhi

Council of architect (CoA): CA/80/5769 registration no.

 $Council\ of\ architects (CoA): 31/12/2025$ 

registration valid till (date)

B. Arch.., M.C.AVI.I.A

Buil	ding/ T	ower no.	272 Nos				
(to b	e prepa	ared separately for each building/ tower ct/ phase of the project)					
A1	Cun	nulative progress of the project/phase	at the end of the quarter.				
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work		
1.	(incl	structure usive of excavation, foundation, ments, water proofing, etc.)	4%	31%	40%		
2.	(slab	er structure s, brick work, block work, stair case, vells, machine rooms, water tank, etc.)	10%	16%	20%		
3.	MEI						
	3.1	Mechanical (lifts, ventilation, etc.)	0%	0%	0%		
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0%	0%	0%		
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0%	0%	0%		
4.	Finishing						
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	0%	0%	0%		
	4.2	External (plaster, painting, facade, etc.)	0%	0%	0%		

GIAN P. MATHUR ARCVITECT B. Arch.., M.C.Apr.I.A CA No. 80/5/69

Sr. No.	Tasks/ Activity Sub-Structure Status			Description of work done		Percentage of total proposed work	
110.							
1.	Exca	avation	Excavation i	Excavation in ordinary Soil		0%	
2.	Laying of foundation						
	(i)	Raft	RCC of B	RCC of Building Raft		40%	
	(ii)	Pile		NA		NA	
3.	Num	ber of basement(s)					
	(i)	Basement Level 1	NA		NA		
	(ii)	Basement level 2*	NA		NA		
4.0		erproofing of the above sub-structure rever applicable)	Applying Water Proofing Compound		3	%	
		Super-Structure Status					
5.	Tota	l floors in the tower/ building	816	5 Nos	32	2%	
6.	Total	area on each floor		CC works in	32	2%	
7.	Stilt	floor/ ground floor		progress Work in progress		15%	
8.		s of laying of slabs floor wise					
0,4	Cum	ulative number of slabs in the building/	(15% to 25%)		15%		
9.	Status of construction						
	(i)	Walls on floors	RCC work in progress		32%		
	(ii)	Staircase	RCC work	RCC work in progress		32%	
	(iii)	Lift wells along with water proofing	N	NA		NA	
	(iv)	Lift lobbies/ common areas floor wise	N	NA		NA	
10.	Fixin units	g of door and window frames in flats/	Work in progress		5%		
11.	Status	s of MEP	Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works	NA	Pumps & Electrical Panels	NA	0%	
	(ii)	Electrical works including wiring	Yet to be started	Yet to be started	0%	0%	
	(iii)	Plumbing works	Yet to be started	Yet to be started	0%	0%	
12.	Status of wall plastering						
	(i)	External plaster	Yet to be started		0%		
	(ii)	Internal plaster	Yet to be started		0%		
13.	Status	of wall tiling					
	(i)	In bathroom	Yet to be started		0%		
	(ii)	In kitchen	Yet to be started		00	2/0	
14.	Status	of flooring					
	(i)	Common areas	Yet to be started		09	V <sub>0</sub>	
	(ii)	Units/ flats	Yet to be started P.		TA TURO	Vo.	

B. Arch.., M.C. 1.I.A

Sr. No.	Tasks/ Activity Sub-Structure Status		Description of work done	Percentage of total proposed work	
140.			uone		
15.	Statu	s of white washing			
	(i)	Internal walls	Yet to be started	0%	
	(ii)	External walls	Yet to be started	0%	
16.	Status	s of finishing			
	(i)	Staircase with railing	Yet to be started	0%	
	(ii)	Lift wells	NA	NA	
	(iii)	Lift lobbies/ common areas floor wise	NA	NA	
17.	Status	s of installation			
	(withi	n flat/unit)			
	(i)	Doors and windows panels	Yet to be started	0%	
	(ii)	Sanitary fixtures	Yet to be start	0%	
	(iii)	Modular kitchen		NA	
	(iv)	Electrical fittings/ lighting	Yet to be start	0%	
	(v)	Gas piping (if any)		NA	
	(other	than flat/units)			
	(vi)	Lifts installation	NA	NA	
	(vii)	Overhead tanks	Yet to be start	0%	
	(viii)	Underground water tank	Yet to be start	0%	
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Yet to be start	0%	
	(x)	Electrical fittings in common areas	Yet to be start	0%	
	(xi)	Compliance to conditions of environment/ CRZ NOC	Yet to be start	0%	
18.	Water	proofing of terraces	Yet to be started	0%	
19.	Entrar	ice lobby finishing	Yet to be start	0%	
20.	Status	of construction of compound wall	Yet to be start	0%	

Note: (\*) extend rows as per requirement.

B. Arch.., M.C. III.A CA No. 803369

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1,,	Internal roads & pavements	Yes	90%	
2,	Parking	NA		
	Covered no	NA		
	Open no	NA		
3,	Water supply	Yes	88%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	90%	
5.	Storm water drains	Yes	90%	
6.	Landscaping & tree plantation	Yes	60%	
7.	Parks and playgrounds	Yes	0%	
	Fixing of children play equipment's	Yes	0%	
	Benches	Yes	0%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	60%	
11.	Solid waste management & disposal	Yes	0%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	No		
13.	Energy management (solar)	Yes	0%	
14.	Fire protection and fire safety requirements	Yes	0%	
15.	Electrical meter room, sub-station, receiving station	Yes	0%	
16.	Other (option to add more)	NA		
B-2	Community building to be transferred to RWA			
17*	Community centre	Yes	0%	
18.	Others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	NA		
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (\*) extend as per requirement

GIAN P. MATHUR ARCHITACT B. Arch.., M.C.AMI.I.A CA No. 80/7/89