

## INDIVALUE ADVISORS PRIVATE LIMITED

Regd. Address: B1/H3, MOHAN CO-OPERATIVE INDUSTRIAL AREA MATHURA RD, BLOCK B NEW DELHI 110044 Email: Indivalueadvisors@gmail.com Mobile +91-7044091174

CIN: U74999DL2021PTC381050

## IVPL/06/06/2025/ELAN EPIC

		Architect	's Certificate				
Repo	ort for q	uarter ending	April to June' 2025				
Subject			Certificate of progress of construction work				
1	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans						
	Sr. No.	Particulars	Information				
	1.	Project/Phase of the project	Elan EPIC				
	2.	Location	Sector 70, Gurugram				
	3.	Licensed area in acres	4 Acres				
	4.	Area for registration in acres	3.525 Acres				
	5.	HARERA registration No.	RC/REP/HARERA/GGM/2018/30 Dated: 6/12/2018				
	6.	Name of licensee	Elan Limited				
	7.	Name of collaborator	NA				
	8.	Name of developer	Elan Limited				
2	Detai	Details related to inspection are as under					
.*	1.	Date of certifying of percentage of construction work/ site inspection	07.07.2025				
	2.	Name of Architect/ Architect's firm	Ar. Ashish Sawe				
	3.	Date of site inspection	30.06.2025				
3	Following technical professionals are appointed by promoter: - (as applicable)						
	Sr. No.	Consulta nts	Name				
	1.	Site engineer	Vikram Singh				
	2.	Structural consultant	Perceptive Idea				
	3.	Proof consultant	Isha Consultant (P) Ltd.				
	4.	MEP consultant	CP Vidya Associates, Dew point Consultants F Ltd.,Ampower Consultancy Services.				
	5.	Site supervisor/incharge ISH o	Saurabh Gupta				

- I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.
- I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.

CA/2001/284

Date: 07.07.2025

Yours faithfully,

Name: - Ar. ASHISH SAWE

Stamp:

Place : Gurugram

Council of Architecture (CoA)

Registration no.

:.CA/2001/28463

(CoA)

Registration valid till (date) : 31.12-2033

		T	able – A		<del>5</del> 74	
(to be	prepa	Tower no. red separately for each ver in the project/ phase of	ELAN EPIC (Entire project is	one building 4	04 Units)	
A1	Cun	nulative progress of the pro	ect/phase at th	e end of the	quarter. (In Lacs)	
Sr. No.	Project components		Work done value during the quarter (Sqmt)	Cumulative work done value till date (Sqmt)	Percentage of work done to the total proposed work	
1.	Sub	structure				
	found	sive of excavation, dation, basements, water fing, etc.)	-	20125	100%	
2.	(slab	er structure s, brickwork, blockwork, stair , lift wells, machine rooms, water etc.)	. <b>-</b>	28695	100%	
3.	MEF	oʻ.	= 원			
	3.1	Mechanical (lifts, ventilation, etc.)	-	28695	100%	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)		28695	100%	
	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	-	28695	100%	
4.	Finishing					
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	-	28695	100%	
	4.2	External (plaster, painting, facade, etc.)	-	28695	100%	
					0	
Sr. No.	Tasks/ Activity		Description of work done		Percentage of total	
	Sub-Structure Status				proposed work	
1.	Exc	cavation	Completed		100%	
2.	Lay	ring of foundation				

IVPL06/06/2025/ELAN EPIC -

					TVPL06/06/20	UZ3/ELAN	
	(i)	Raft	Comp	leted	100	0%	
	(ii)	Pile	Comp	leted	100	0%	
3.	Num	ber of basement(s)		9			
	(i)	Basement Level 1	Completed		100	0%	
	(ii)	Basement level 2	Comp	leted	100	0%	
4.		rproofing of the above sub- ture (wherever applicable)	Comp	leted	100	0%	
		Super-Structure Status					
5.	Tota	I floors in the tower/ building	6		6		
6.	Tota	l area on each floor	N/	A	N	Α	
7.	Stilt	floor/ ground floor	Comp	leted	100	0%	
8.	Statu	us of laying of slabs floor wise	Comp	leted	100	0%	
-		ulative number of slabs in the ing/ tower laid by end of quarter	Comp	Completed		100%	
9.	Status of construction						
	(i)	Walls on floors	Completed		100%		
	(ii)	Staircase	Completed		100%		
	(iii)	Lift wells along with water proofing	Completed		100%		
	(iv)	Lift lobbies/ common areas floor wise	Completed		100%		
10.		g of door and window frames in units	NIL		N	IL	
11.	Statu	us of MEP	Internal (within flat)	External works	Internal (within flat)	External works	
	(i)	Mechanical works	Comp	leted	100	0%	
	(ii)	Electrical works including wiring	Completed		100%		
	(iii)	Plumbing works	Completed		100%		
12.	Statu	us of wall plastering					
20.	(i)	External plaster	Completed		100%		
	(ii)	Internal plaster	Completed		100%		
13.	Statu	us of wall tiling					
	(i)	In bathroom	Completed		100%		
	(ii)	In kitchen	NA		N.	A	
14.	Statu	us of flooring					
	(i)	Common areas	Completed		100%		
	(ii)	Units/ flats	NA NA		NA		

15.	Stat	us of white washing		
	(i)	Internal walls	Completed	100%
	(ii)	External walls	Completed	100%
16.	Stat	us of finishing		
	(i)	Staircase with railing	Completed	100%

	(ii)	Lift wells	Completed	100%
	(iii)	Lift lobbies/ common areas floor wise	Completed	100%
17.	Statu	s of installation		
	(with	in flat/unit)		
	(i)	Doors and windows panels	Completed	100%
	(ii)	Sanitary fixtures	Completed	100%
	(iii)	Modular kitchen	NA	NA
	(iv)	Electrical fittings/ lighting	Completed	100%
	(v)	Gas piping (if any)	NA	NA
	(othe	r than flat/units)		
	(vi)	Lifts installation	Completed	100%
	(vii)	Overhead tanks	Completed	100%
	(viii)	Underground water tank	Completed	100%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Completed	100%
	(x)	Electrical fittings in common areas	Completed	100%
	(xi)	Compliance to conditions of environment/ CRZ NOC	NIL	NIL
18.	Wate	rproofing of terraces	Completed	100%
19.	Entra	ince lobby finishing	Completed	100%
20.	Statu	s of construction of compound wall	Completed	100%

Note: (\*) extend rows as per requirement



Table-B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	Remarks
B-1	Services		-	-
1.	Internal roads & pavements	Yes	100%	
2.	Parking			1.5
	Covered no572	Yes	100%	
	Open no Nil	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	NA	NIL	
	Fixing of children play equipment's	NA	NIL	
	Benches	NA	NIL	
8.	Shopping area	YES	NIL	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	
16.	Other (option to add more)		NIL	

B-2 Community building to be transferred to RWA				
17.	Community centre	NO	NO	
18.	Others			
B-3	Community buildings not to be transferred to RWA/competent authority	r		
19.	Schools	NO	NO	
20.	Dispensary	NO	NO	
21.	Club	NO	NO	
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	*			



