Arcop Associates Private Limited

Architecture Planning Urban Design Interiors

	_	Architect's	s Certificate¹
Repo	rt for q	uarter ended	30th June 2025
Subject		-	Certificate of progress of construction work
1.	I/We const	have undertaken assignme ruction work in the below me	ent as architect for certifying progress of ntioned project as per the approved plans
	Sr. No.	Particulars	Information
	1.	Project/Phase of the project	Elévate Phase – I
	2.	Location	Village Behrampur, Sector-59, Gurugram
	3.	Licensed area in acres	8.91875
	4.	Area for registration in acres	5.95
	5.	HARERA registration no.	19 of 2019

<sup>&</sup>lt;sup>1</sup> On the letter head of the architect firm

Labib Alam, Architect
Council of Architecture
Registration No.: CA/2001/27447

Page 1 of 25

	Name of licenses	License no. 16 of 2008:
6.	Name of licensee	1) BTVS Buildwell Pvt. Ltd. 2) Adson Software Pvt. Ltd. 3) Bulls Realtors Pvt. Ltd. 4) Commander Realtors Pvt. Ltd. 5) Fiverivers Developers Pvt. Ltd. 6) Fiverivers Townships Pvt. Ltd. 7) Ornamental Realtors Pvt. Ltd. 8) Aspirant Builders Pvt. Ltd. License no. 28 of 2008:  1) BTVS Buildwell Pvt. Ltd. 2) Golden View Builders Pvt. Ltd. 3) Hi Energy Realtors Pvt. Ltd. 4) Base Exports Pvt. Ltd. 5) Adson Software Pvt. Ltd. 6) Bulls Realtors Pvt. Ltd. 7) Commander Realtors Pvt. Ltd. 9) Ornamental Realtors Pvt. Ltd. 10) Aspirant Builders Pvt. Ltd. License no. 44 of 2011:  1) Commander Realtors Pvt. Ltd. 3) Golden View Builders Pvt. Ltd. 4) Hi Energy Realtors Pvt. Ltd. 5) Base Exports Pvt. Ltd. 6) Adson Software Pvt. Ltd.
		7) Bulls Realtors Pvt. Ltd. 8) Fiverivers Buildcon Pvt. Ltd.
7.	Name of collaborator	Heritage Max Realtech Pvt. Ltd.
8.	Name of developer	Heritage Max Realtech Pvt. Ltd.
2. Deta	ails related to inspection are a	sunder
1.	Date of certifying of percentage of construction work/ site inspection	30 <sup>th</sup> June 2025

Council of Architecture
Registration No.: CA/2001/27447

2.	Name of Architect/ Architect's firm	Arcop associates Private Limited
3.	Date of site inspection	30 <sup>ւ</sup> June 2025

	Sr. No.	Consultants	Name
	1.	Site engineer	Sunil Chauhan
	2.	Structural consultant	Vintech Consultant
			(Mr. Vinod Jain)
-	3.	Proof consultant	Mehro Consultants
	4.	MEP consultant	Sanelac Consultants Pvt Ltd
	5.	Site supervisor/incharge	Sunil Chauhan
	manda applic develo	atory approvals, Haryana Buildi able) and the material used in tl opment works are as per the pr rochure, publication material ar	executed as per approved drawings, statutory/ ng Code, 2017/ National Building Code (wherever the construction, infrastructure works and internal rojected standard as envisaged in the registration and other documents shared with the buyers in this
-	I also	certify that as on the date, the p	percentage of work done in the project for each of project/phase of the project under HARERA is as

respect to each of the activity of the entire project/ phase is detailed in table A and table B.

Date

Yours faithfully,

Place

10 DECHI

Signature & name (in block letters) with stamp of architect

Council of architects (CoA) : CA/2001/274447

Labib Alam, Architect Council of Architecture Registration No.: CA/2001/27447

Council of architects (CoA):

31.12.2027

registration valid till (date)

registration no.

		7	able - A		
(to build	be pr	Tower no.  repared separately for each rower in the project/ phase of	Tower-A		
A1	Cum	ulative progress of the projec	t/phase at the e	nd of the quarte	r.
Sr. No.	Project components		Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure  (inclusive of excavation, foundation, basements, water proofing, etc.)		0	35.00	100%
2.	(slab	er structure os, brick work, block work, case, lift wells, machine rooms, er tank, etc.)	0	56.00	100%
3.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	1.20	18.80	100 %
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.91	11.75	100 %

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.40	12.69	100%	
4.	Finishing					
	4.1	Internal (plaster, tilling, flooring, painting, etc. within units and common areas)	2.10	19.02	100%	
	4.2	External (plaster, painting, facade, etc.)	1.40	15.26	100%	

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status			
1.	Exca	vation	Complete	100 %	
2.	Layi	ng of foundation			
	(i)	Raft	Complete	100 %	
	(ii)	Pile	NA	NA	
3.	Num	ber of basement(s)			
	(i)	Basement Level 1	Structure under Tower Footprint Complete	100%	
	(ii)	Basement level 2*	Structure under Tower Footprint Complete	100%	
4.		erproofing of the above sub- cture (wherever applicable)	Above deck waterproofing	100%	

		Super-Structure Status		
5.	Total floors in the tower/ building		1Stilt+1Service Floor + 31 Apt Floors	100%
6.	Total	area on each floor	785 Sqm	100%
7.	Stilt f	floor/ ground floor	Structure Tower Entrance	100%
8.	Statu	s of laying of slabs floor wise	Upto terrace Level Completed	100%
	build	ulative number of slabs in the ling/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
9.	Status of construction			
	(i)	Blockwork	100% Completed	100%
	(ii)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(iii)	Lift Well including Machine room	100% Completed	100%
	(iv)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
10.	1	ng of door and window frames in / units		
11.	Statu	as of MEP	Internal (within flat)	External works
	(i)	NA	NA NA	0
	(ii)	Apartment Electrical Wiring	100% Completed	100%
	(iii)	UPVC/ RWP Piping	100% Completed	100%
12.	Statı	us of wall plastering		

Council of Architecture Registration No.: CA/2001/27447

	(i)	RCC External Wall	NA	0
	(ii)	Gypsum Plaster	100% (31 of 31 Floor completed)	100%
13.	Statu	s of wall tiling		
	(i)	Bathroom Tiles	100% Completed	100%
	(ii)	Kitchen Wall Tile	100% Completed	100%
14.	Statu	is of flooring		
	(i)	Lift Lobby Flooring	100% Completed	100%
	(ii)	Apt Stone Flooring	100% Completed	100%
15.	Statu	us of white washing	3	
	(i)	Apartment Prefinal Paint	100% Completed	100%
	(ii)	Putty+1stCoat+2nd Coat	100% Completed	100%
16.	Statu	us of finishing		
	(i)	MS Railing		100% Completed in staircase
	(ii)	Lift Well HO for Lift Installation	100% Completed	100%
	(iii)	Lobby Wall Tiling	100% Completed	100%
17.	Statı	us of installation		
	(with	hin flat/unit)		
	(i)	UPVC Windows	100% Completed	100%
	(ii)	Bathroom Chinaware	100% Completed	100%
	(iii)	Modular Kitchen Cabinet Installation (Without Panels)	100% Completed	100%

Council of Architecture
Registration No.: CA/2001/27447

-	(iv)	Switch & Sockets	100% Completed	
	(v)	NA	NA	0
	(othe	er than flat/units)		
	(vi)	Guide Rail+ Floor Door+ Car Installation	100%	100% Completed
	(vii)	RCC Work	100% Completed	100% Completed
	(viii)	RCC Work	100% Completed	100% Completed
	(ix)	Fire Pump Installation	100% Completed	100% Completed
	(x)	Staircase & Lobby Wiring	100% Completed	100% Completed
	(xi)	Six Monthly Compliance	100% Compliance	100% Completed
18.	Wate	erproofing of terraces	PU Waterproofing	100% Completed
19.	Entra	ance lobby finishing	Gypsum False ceiling	100% Completed
20.	Statu	s of construction of compound	Boundary Wall RCC and Brick Work	100% Completed

Note: (\*) extend rows as per requirement.

Table - B Tower-A

Sr. No.	Common areas and facilities amenities	Proposed (Yes/No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	100%	
2.	Parking	Yes		
	Covered no	Yes	100%	
	Open no	Yes	100%	
3.	Water supply	Yes	100%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
5.	Storm water drains	Yes	100%	
6.	Landscaping & tree plantation	Yes	100%	
7.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	100%	
10.	Treatment and disposal of sewage and sullage water/STP	Yes	100%	
11.	Solid waste management & disposal	Yes	100%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
13.	Energy management (solar)	Yes	100%	
14.	Fire protection and fire safety requirements	Yes	100%	
15.	Electrical meter room, sub-station, receiving station	Yes	100%	

Labib Alam, Architect
Council of Architecture
Page 10 of 25

16.	Other (option to add more)	NA		
B-2	Community building to be transferred	to RWA		
17.	Community centre	Yes	100%	
18.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	Yes	100%	
22.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	NA		
23.	*			

Note: (\*) extend as per requirement

		ר	Table - A		
(to build	Building/ Tower no.  (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower-B		
A1	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
5.	(incl	structure usive of excavation, dation, basements, water fing, etc.)	0	35.00	100%
6.	Super structure  (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)		0	60.05	100%
7.	МЕР				
	3.1	Mechanical (lifts, ventilation, etc.)	1.72	18.93	100%
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	1.01	12.73	100%

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	1.31	13.23	100%
8.	Fini	shing			
	4.1	Internal  (plaster, tilling, flooring, painting, etc. within units and common areas)	2.02	19.90	100%
	4.2	External (plaster, painting, facade, etc.)	1.01	14.23	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status	al .		
21.	Exca	vation	Complete	100 %	
22.	Layir	ng of foundation			
	(iii)	Complete	100 %	100 %	
	(iv)	NA	NA	0	
23.	Num	ber of basement(s)			
	(iii)	Structure under Tower Footprint Complete	Complete	100%	
	(iv)	Structure under Tower Footprint Complete	Complete	100%	
24.		erproofing of the above sub- cture (wherever applicable)	Deck Water Proofing	100%	
_		Super-Structure Status		( NO -	

25.	Total	floors in the tower/ building	1Stilt+1Service Floor + 33 Apt Floors	100%
26.	Total area on each floor		772 Sqm	100%
27.	Stilt f	loor/ ground floor	Structure Tower Entrance	100% Completed
28.	.		Upto terrace Level Completed	100%
	build	ulative number of slabs in the ing/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
29.	Status of construction			
	(v)	Blockwork	Completed	100%
ļ.	(vi)	Staircase Concreting upto Terrace Slab	100% Completed	100%
	(vii)	Lift Well including Machine room	100% Completed	100%
	(viii)	Structure lift lobbies and other common area upto 31 Floor	100% Completed	100%
30.		g of door and window frames in / units	Door Frame	100% Completed
31.	Status of MEP		Internal (within flat)	External works
	(iv)	NA	NA	
	(v)	Apartment Electrical Wiring	100% Completed	100% Completed
	(vi)	UPVC/ RWP Piping	100% Completed	100% Completed
32.	Statu	is of wall plastering		
	(iii)	RCC External Wall	NA	L Ma

	(iv)	Gypsum Plaster	100%	100% Completed
33.	Statu	s of wall tiling		
	(iii)	Bathroom Tiles	100% Completed	100% Completed
	(iv)	Kitchen Wall Tile	100% Completed	100% Completed
34.	Statu	s of flooring		
	(iii)	Lift Lobby Flooring	100% Completed	100% Completed
	(iv)	Apt Stone Flooring	100% Completed	100% Completed
35.	Statu	s of white washing		
	(iii)	Apartment Prefinal Paint	100% Completed	100% Completed
	(iv)	Putty+1stCoat+2nd Coat	100% Completed	100% Completed
36.	Status of finishing			
	(iv)	MS Railing	100% Completed	100% Completed
	(v)	Lift Well HO for Lift Installation	100% Completed	100% Completed
	(vi)	Lobby Wall Tiling	100% Completed	100% Completed
37.	Statu	s of installation		
	(with	nin flat/unit)		
	(xii)	UPVC Windows	100% Completed	100% Completed
	(xiii)	Bathroom Chinaware	100% Completed	100% Completed
	(xiv)	Modular Kitchen Cabinet Installation (Without Panels)	100% Completed	100% Completed
	(xv)	Switch & Sockets	100% Completed	100% Completed
	(xvi)	NA	NA	
	(othe	er than flat/units)		AR A

	(xvii) Guide Rail+ Floor Door+ Car Installation	100 % Complete	100% Completed
	(xviii RCC Work	100% Completed	100% Completed
	(xix) RCC Work	100% Completed	100% Completed
	(xx) Fire Pump Installation	100% Completed	100% Completed
	(xxi) Staircase & Lobby Wiring	100% Completed	100% Completed
	(xxii) Six Monthly Compliance	100% Compliance	100% Completed
38.	Waterproofing of terraces	PU Waterproofing	100% Completed
39.	Entrance lobby finishing	Gypsum False ceiling	100% Completed
40.	Status of construction of compound wall	Boundary Wall RCC and Brick Work	100% Completed

Note: (\*) extend rows as per requirement.

Table - B Tower B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
24.	Internal roads & pavements	Yes	100%	
25.	Parking	Yes	100%	
	Covered no	Yes	100%	
	Open no	Yes	100%	
26.	Water supply	Yes	100%	
27.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
28.	Storm water drains	Yes	100%	
29.	Landscaping & tree plantation	Yes	100%	
30.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
31.	Shopping area	Yes	0%	
32.	Street lighting/ electrification	Yes	100%	
33.	Treatment and disposal of sewage and sullage water/ STP	Yes	100%	
34.	Solid waste management & disposal	Yes	100%	
35.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
36.	Energy management (solar)	Yes	100%	
37.	Fire protection and fire safety requirements	Yes	100%	
38.	Electrical meter room, sub-station, receiving station	Yes	100%	and

39.	Other (option to add more)	NA		
B-2	Community building to be transferred	to RWA		
40.	Community centre	Yes	100%	
41.	others	NA		
B-3	Community buildings not to be transferred to RWA/competent authority			
42.	Schools	NA		
43.	Dispensary	NA		
44.	Club	Yes	100%	
45.	Others	NA		
B-4	Services/ facilities to be transferred to competent authority	NA		
46.	*			

Note: (\*) extend as per requirement

Labib Alam, Architect Council of Architecture

Registration No.: CA/2001/27447

		7	Table – A			
Building/ Tower no.  (to be prepared separately for each building/ tower in the project/ phase of the project)		Tower-C				
A1	Cum	Cumulative progress of the project/phase at the end of the quarter.				
Sr. No.	Proj	ect components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work	
9.	(incl	structure usive of excavation, dation, basements, water fing, etc.)	0	24.96	100%	
10.	(slab	er structure os, brick work, block work, case, lift wells, machine os, water tank, etc.)	0	40.02	100%	
11.	МЕР	)				
	3.1	Mechanical (lifts, ventilation, etc.)	0.40	9.71	100%	
	3.2	Electrical (conduiting, wiring, fixtures, etc.)	0.79	7.98	100%	

	3.3	Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	0.40	7.94	100%
12.	Fini	shing			
	4.1	Internal  (plaster, tilling, flooring, painting, etc. within units and common areas)	2.30	16.24	100%
	4.2	External (plaster, painting, facade, etc.)	0.11	5.62	100%

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work	
		Sub-Structure Status			
41.	Exca	vation	Complete	100 %	
42.	Layir	ng of foundation			
	(v)	Complete	100% Completed	100%	
	(vi)	NA	NA	0	
43.	Num	ber of basement(s)			
	(v)	Structure under Tower Footprint Complete	100% Completed	100%	
	(vi)	Structure under Tower Footprint Complete	100% Completed	100%	
44.	1	erproofing of the above sub- cture (wherever applicable)	Deck Water Proofing	100%	
		Super-Structure Status		Labib Alam, Arch	

45.	Total	floors in the tower/ building	1Stilt+1Service Floor + 30 Apt Floors	100%
46.	Total area on each floor		549 Sqm	100%
47.	Stilt f	loor/ ground floor	Structure Tower Entrance	100% Completed
48.	, , , ,		Upto terrace Level Completed	100%
	build	ulative number of slabs in the ing/tower laid by of quarter	Total Slabs 1Stilt+1Service Floor+31 Apt Floor	100%
49.	Status of construction			
	(ix)	Blockwork	100% Completed	100% Completed
	(x)	Staircase Concreting upto Terrace Slab	100% Completed	100% Completed
	(xi)	Lift Well including Machine room	100% Completed	100% Completed
	(xii)	Structure lift lobbies and other common area upto 30 Floor	100% Completed	100% Completed
50.		g of door and window frames in / units	Door Frame	100% Completed
51.	Statu	is of MEP	Internal (within flat)	External works
	(vii)	NA	NA -	
	(viii)	Apartment Electrical Wiring	100% Completed	100% Completed
	(ix)	UPVC/ RWP Piping	100% Completed	100% Completed
52.	Statu	is of wall plastering		
	(v)	RCC External Wall	NA	CAMP.

	(vi)	Gypsum Plaster	100%	100% Completed		
53.	Status of wall tiling					
	(v)	Bathroom Tiles	100% Completed	100% Completed		
	(vi)	Kitchen Wall Tile	100% Completed	100% Completed		
54.	Status of flooring					
	(v)	Lift Lobby Flooring	100% Completed	100% Completed		
	(vi)	Apt Stone Flooring	100% Completed	100% Completed		
55.	Status of white washing					
	(v)	Apartment Prefinal Paint	100% Completed	100% Completed		
	(vi)	Putty+1stCoat+2nd Coat	100% Completed	100% Completed		
56.	Status of finishing					
	(vii)	MS Railing	100% Completed	100% Completed		
	(viii)	Lift Well HO for Lift Installation	100% Completed	100% Completed		
	(ix)	Lobby Wall Tiling	100% Completed	100% Completed		
57.	Statu	s of installation				
	(with	nin flat/unit)	-			
	(xxiii	UPVC Windows	100% Completed	100% Completed		
	(xxiv	Bathroom Chinaware	100%	100% Completed		
	(xxv)	Modular Kitchen Cabinet Installation (Without Panels)	100%	100% Completed		
	(xxvi	Switch & Sockets	100% Completed	100% Completed		
	(xxvi	NA	NA			
	(othe	er than flat/units)		( grape		

	(xxvi Guide Rail+ Floor Door+ Car Installation	100% Complete	100% Completed
	(xxix RCC Work	100% Completed	100% Completed
	(xxx) RCC Work	100% Completed	100% Completed
	(xxxi Fire Pump Installation	100% Completed	100% Completed
	(xxxi Staircase & Lobby Wiring	100% Completed	100% Completed
	(xxxi Six Monthly Compliance	100% Compliance	100% Completed
58.	Waterproofing of terraces	PU Waterproofing	100% Completed
59.	Entrance lobby finishing	Gypsum False ceiling	100% Completed
60.	Status of construction of compound wall	Boundary Wall RCC and Brick Work	100% Completed

Note: (\*) extend rows as per requirement.

( Shallo

Table - B Tower C

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			J
47.	Internal roads & pavements	Yes	100%	
48.	Parking	Yes	100%	
	Covered no	Yes	100%	
	Open no	Yes	100%	
49.	Water supply	Yes	100%	
50.	Sewerage (chamber, lines, septic tanks, STP)	Yes	100%	
51.	Storm water drains	Yes	100%	
52.	Landscaping & tree plantation	Yes	100%	
53.	Parks and playgrounds	Yes	100%	
	Fixing of children play equipment's	Yes	100%	
	Benches	Yes	100%	
54.	Shopping area	Yes	0%	
55.	Street lighting/ electrification	Yes	100%	
56.	Treatment and disposal of sewage and sullage water/STP	Yes	100%	
57.	Solid waste management & disposal	Yes	100%	
58.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	100%	
59.	Energy management (solar)	Yes	100%	
60.	Fire protection and fire safety requirements	Yes	100%	
61.	Electrical meter room, sub-station, receiving station	Yes	100%	MAR

62.	Other (option to add more)	NA			
B-2	Community building to be transferred to RWA				
63.	Community centre	Yes	100%		
64.	others	NA			
B-3	Community buildings not to be transferred to RWA/competent authority				
65.	Schools	NA			
66.	Dispensary	NA			
67.	Club	Yes	100%		
68.	Others	NA			
B-4	Services/ facilities to be transferred to competent authority	NA			
69.	*				

Note: (\*) extend as per requirement